

GFORCE AUTOTECH PRIVATE LIMITED

10 KAKI BUKIT ROAD 2 #01-34
 SINGAPORE 417868
 MOBILE: +65-9139 1448
 CO REGISTRATION NO: 201631929K



GFORCE
 AUTOTECHNIK

Owner: CFI TRANSPORT PTE LTD
 Vehicle Reg No.: GBF 5339A
 Make / Model: NISSAN NV350

Date: 20 AUGUST 2019

Dear Sirs,

ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

Cost price

<u>QTY</u>	<u>LIST ITEMS</u>	<u>AMOUNT(S\$)</u>
1	Front panels / <i>Buc</i>	\$ 858.60
1	Front corner panels LH / <i>Buc</i>	\$ 477.60
1	Front door L/H / <i>Buc</i>	\$1015.60
1	Front door inner board ?	\$481.70
2	Front door hinges X <i>nn</i>	\$58.10
1	Door Pillar X <i>depends</i>	\$152.80
1	Front door regulator motor X <i>nn</i>	\$147.90
1	Door Check link X <i>nn</i>	\$65.00
1	Front bumper / <i>CRA</i>	\$ 514.70
1	Front bumper fog lamps L/H ?	\$ 311.80
1	Front bumper fog lamp covers L/H / <i>CRA</i>	\$ 91.60
1	Front bumper reinforcement L/H ?	\$ 591.90
1	Front bumper reinforcement stays L/H ?	\$ 91.70
1	Front bumper bracket L/H ?	\$ 110.00
1	Front bumper tow hook cover X	\$ 19.40
1	Air con blower unit X	\$ 851.10
1	Air intake duct X	\$ 179.00
1	Front wiper motor X	\$ 242.40
1	Front wiper garnish (1 set) X	\$ 432.00
1	Front wiper link (1 set) X	\$ 210.00
1	Intercooler X	\$ 2121.60
1	Intercooler hose X	\$ 180.00
1	Front step panel L/H / <i>cut</i>	\$ 65.00
1	Front headlamp L/H / <i>cut</i>	\$ 380.00
1	Front grille / <i>Mis</i>	\$ 480.00
1	Front grille logo / <i>Mis</i>	\$ 65.00
1	Air con cooling coil (aircon housing) -Full set X <i>NN</i>	\$ 2,100.00

Total	\$ 12294.50
Additional 10%	\$ 1229.45
Total of List Items	\$ 13523.95

<u>QTY</u>	<u>SPECIAL NETT ITEMS</u>	<u>AMOUNT (SGD)</u>
1	Front grille clip (1 set) <i>MSC</i>	\$ 45.00
1	Front bumper clip (1 set)	\$ 25.00
1	Front car plate <i>BT</i>	\$ 30.00
Total		\$ 100.00
Additional 10%		\$ 10.00 X
Total List Items		\$ 110.00

<u>S/N</u>	<u>LABOUR CHARGES</u>	<u>AMOUNT</u>
1	To remove, replaced damaged lamps & checkup rear wiring	\$ 80.00 <i>30</i>
2	To remove & refit inner garnishes	\$ 150.00 <i>60</i>
3	To remove, replace air-con and conduct leakage test	\$ 200.00 <i>?</i>
4	To remove & refit dashboard to assist repair	\$ 250.00 <i>?</i>
5	To remove and refit front windscreen glass	\$ 180.00 <i>X</i>
6	To apply undercoating on repaired and repaired panel	\$ 350.00 <i>60</i>
7	Panel beating	\$ 2,000.00 <i>500</i>
8	To re-spray on the affected areas & polishing back	\$ 1,600.00 <i>800</i>
Total		\$ 4,810.00
GRAND TOTAL (Total Parts + Total Labour)		\$ 18443.95

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Not Authorised.

Excess: TBA
part by part.

~~Insurance report~~ 5 Days.

before/After repair photos.

Emo Qiang - 82880282

26/8/19.