

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Nor Azian Binte Noordin

Date: 27 Aug 2019

Preliminary Advice

Vehicle No	: GBH5339A	Accident Date	: 05/07/2019
Make	: NISSAN NV350	Policy No.	: 29087313MKC
Assignment Date	: 26/08/2019	Excess	: S\$600.00
Date of Inspection	: 26/08/2019	Est. Duration of Repair	: 5.00
Inspection At	: GFORCE AUTOTECH PRIVATE LIMITED (HQ) 10 KAKI BUKIT RD 2, #01-34 SINGAPORE 417868		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	18,443.95
Revised Amount	:S\$	5,892.91
Check Items (Estimated)	:S\$	2,195.81
Total	:S\$	8,088.72
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	54,000.00
COE / PARF Rebate	:S\$	26,438.00
Salvage Value	:S\$	
Margin for Repair	:S\$	27,562.00

Remarks

- (X) The vehicle is economical for repair.
- () The above survey was conducted on a 'without prejudice' basis.