

22/03/2002

ASS. REC. BY:

REF: CS/C1219014931/ktf3n2

Special Instruction:

SUNVAJOY: Kenneth

ASSIGNMENT (Office)

Merimen From (Person): Ong Chin Kiat of CTI Date/Time: 26/08/2019

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SGM 4681G

Insured: SMM 3037C

at Workshop m/s E M Solution Pte Ltd

Tel: 64560226

of 160 Sin Ming Autocity #103-18

Policy No: DMPCSN30522629000

Claim No: SNM19D203967C02

Sum Insured:

Excess:

Make of Veh:

D.O.A. 23/08/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 26/08/2019 03:22p.m. Person Contacted:

Josephine

Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SMM 3037C : NA/C1219014919/c3 D.O.A. 23/08/2019
	SGM 4681G : NA/C1219014919/c3 D.O.A. 23/08/2019
219	61 Emp & 1150L email & confirm (Recd: 3352.35; 7470)

Kenneth

REF: CT1

ASSIGNMENT

From

Date

28.8.2019

Estimated Cost:

OD TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No. SGM 4681G

at Workshop m/s EM solution

of 160 sin ming Drive #03-18/19

Insured

Policy No.

Claims No.

Sum Insured

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 02 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

mp"

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No.

SGM 4681G

Veh Reg:

19/10/2006

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota A115

G.C.

159P

Colour:

M. Green

A/C

Insured / Std / NI / NA

Sp. Reading

M. Green

T/Radio: Insured / Std / NI / NA

Eng/No:

412788

C/No:

NR053 ZEC 107133031

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD Air / or

Tyre Size: F:

F:

R:

185/70R14

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

NITTO

Front

Rear

R/Bal.

9

mm

R/Bal.

2

mm

L/Bal.

9

mm

L/Bal.

2

mm

D.O.A.

23/8/11P

D.O.I.

28/8/11P

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Rec door

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

28/8

GIA not ready

RECEIVED 05 SEP 2019

519 Typist

✓

TP

45

11501-

220

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	26 Aug 2019		26 Aug 2019 14:53 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS		[Created by insurer]							
Insured:	ANG TIONG HEE, ID: S6905547H								
Main Claimant:	SJ AUTOMOBILE TRADING, Co. Reg. No.: 53308751A								
Vehicle Reg. No.:	SGM4681G	Date of Loss:	23/08/2019 18:00 - :59 [154 Months and 4 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM19D203967C02	Policy/Cover Note No.:	DMPCSN30511619000						
Vehicle Reg. No. (Insured):	SMM3037C	Policy No. (Claimant):							
		Excess:	S\$0.00						
Repairer:	E M Solution Pte Ltd (HQ) 160 Sin Ming Drive,, #03-18, Sin Ming Autocity, 575722 Sin Ming - Tel: 64560226								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Ong Chin Kiat]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 04/09/2019]								
Driver/Custodian (Insured):	ANG TIONG HEE (50 / Male) , NRIC: S6905547H Email:								
Adj Asg. Remarks:	please assign Mr Kenneth Kong for SJE. thank you.								
ASSOCIATED MAIL RECEIVED		View All Compose Case Mail							
There are no mail for this case.									
ALL ASSOCIATED TASKS		View All Search Tasks Create New Task Complete							
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

E M SOLUTION PTE LTD

160, Sin Ming Drive, #03-18/19, Sin Ming Autocity, Singapore 575722

Tel: 64560226

Fax:

64584500

Registration No: 201016308K

28.08.2019

SJ Automobile Trading

*Not Notified
L1 Sur @ \$150k
Recovery After Pain*

REPAIR ESTIMATE FOR TOYOTA ALTIS - SGM 4681 C

2 days

1 pc	LH rear door	Rs	1,085.20	✓
1 pc	LH rear door outer handle	Rs	112.70	X
1 pc	LH rear door glass outer moulding	Rs	145.20	X
2 pcs	LH rear door hinges	89.50	Rs	179.00 X
1 pc	LH rear door stopper	Rs	86.60	X
1 pc	LH rear door regulator gear	Rs	243.30	X
1 pc	LH rear door regulator motor	Rs	595.60	X
1 pc	LH rear door inner lock w motor	Rs	616.30	X
1 pc	LH rear door rubber	Rs	173.40	X
1 pc	LH rear door inner trim	Rs	756.20	X
1 pc	LH rear door protector	Rs	93.90	✓
1 pc	LH rear door protector chrome	Rs	42.40	✓
			4,129.80	
		Less 25%	1,032.45	
			3,097.35	
1 set	LH rear door inner trim clips	Rs	45.00	SN X
1)	Check electrical wirings.		60.00	2ol
2)	Repair accident damages and renew above parts.		580.00	2ol
3)	Transfer LH rear door mechanisms.		100.00	6ol
4)	Spray paint on accident affected portions.		580.00	22ol
5)	Rust proofing on accident affected portions.		40.00	3ol
			<u>\$ 4,502.35</u>	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:
Signature: _____
Date: _____

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT119014971/KTF3N2

Date: 06/09/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN30511619000	
Claimant Vehicle No :	SGM4681G	Insured Vehicle No :	SMM3037C	
Date of Loss:	23/08/2019	Nature of Claim:	TP	Claim No: SNM19D203967C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGM4681G	Engine No:	3ZZ4608159
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 (A)	Chassis No:	MR053ZEC107133031
Reg. Date:	19/10/2006 (Man. Year: 2006)	Odometer:	412766 km
Colour:	Metallic Green		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/70R14	Rear Tyre Size:	185/70R14
Front Left Side:	West Lake 9 mm	Rear Left Side:	West Lake 2 mm
Front Right Side:	West Lake 9 mm	Rear Right Side:	West Lake 2 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	3,142.35	916.12	2,226.23	70.85
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,360.00	530.00	830.00	61.03
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	4,502.35	1,446.12	3,056.23	67.88
Approved Total (Overridden) (\$\$)		1,150.00		
Nett Amount (\$\$)	4,502.35	1,150.00	3,352.35	74.46

INSPECTION

Date of Assignment:	26/08/2019	
Date Inspected:	28/08/2019	Inspected At: E M Solution Pte Ltd (HQ) 160 Sin Ming Drive., #03-18, Sin Ming Autocity Singapore 575722
Estimated Period of Repair:	2.0 days	

Adjuster: KENNETH KONG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 06 Sep 2019)
Parts:	143	TOYOTA COROLLA ALTIS 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGM4681G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*LH REAR DOOR	Bent	1,085.20 FL	*1,085.20 FL
2	1		*LH REAR DOOR OUTER HANDLE	Serviceable	112.70 FL	*- FL
3	1		*LH REAR DOOR GLASS OUTER MOULDING	Serviceable	145.20 FL	*- FL
4	2		*LH REAR DOOR HINGES	Repair	179.00 FL	*- FL
5	1		*LH REAR DOOR STOPPER	Serviceable	86.60 FL	*- FL
6	1		*LH REAR DOOR REGULATOR GEAR	Repair	243.30 FL	*- FL
7	1		*LH REAR DOOR REGULATOR MOTOR	Serviceable	595.60 FL	*- FL
8	1		*LH REAR DOOR INNER LOCK W MOTOR	Serviceable	616.30 FL	*- FL
9	1		*LH REAR DOOR RUBBER	Serviceable	173.40 FL	*- FL
10	1		*LH REAR DOOR INNER TRIM	Serviceable	756.20 FL	*- FL
11	1		*LH REAR DOOR PROTECTOR	Necessary	93.90 FL	*93.90 FL
12	1		*LH REAR DOOR PROTECTOR CHROME	Necessary	42.40 FL	*42.40 FL
13	1		*SET LH REAR DOOR INNER TRIM CLIPS	Not Necessary	45.00 FS	*- FS
					Sub Total (\$\$)	4,174.80 1,221.50
					- List Item Discount on L Items 25.00/25.00% (\$\$)	1,032.45 305.38
					Total Parts (\$\$)	3,142.35 916.12

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	CHECK ELECTRICAL WIRINGS	New	60.00	20.00
2	REPAIR ACCIDENT DAMAGES AND RENEW ABOVE PARTS	New	580.00	200.00
3	TRANSFER LH REAR DOOR MECHANISMS	New	100.00	60.00
4	SPRAY PAINT ON ACCIDENT AFFECTED PORTIONS	New	580.00	220.00
5	RUST PROOFING ON ACCIDENT AFFECTED PORTIONS	New	40.00	30.00
Gross Labour Cost (\$\$)			1,360.00	530.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >