

INS. CASE OWNER:

Lionel Tan

CC4/FWD19014985/ Apa3

LKK:

IDAC:

Surveyor:

ADRIAN

DOI: 28/08/2019

Date / Time: 23/8/2019

Registered in Merimen: 26/08/2019

Pre-assign / CCU / FTE



Insured Vehicle No. : SJL 9507P

Name of Insured : TAN BOON LENG KENNETH

Insured Tel No. : HP: 9636 3621

Excess Sec II : S\$ D.O.A: 20/08/2019 17:25

Is driver the owner? (YES / NO) Nature of Accident :

If NO, Driver Name / Age :

Driver Tel No. :

(V/L, YES/ NO)

Claim No. : 1201900024765

Policy No. : PNPV2018-00015635

Make / Model : MITSUBISHI LANVER 1.6 GLX

Place of Accident : AYE TOWARDS CITY

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability : % Final ? Yes / No

SFA 3366Z

INSRS:
WSP: Ace Auto
Tel: Solution
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/ Time		STAGE	DATE / PIC
	SFA 3366Z - X	Non-Reporting ltr (1st):	
	SJL 9507P - CC3/AIG18012076/T1eb3q2; DOA: 23/6/18	Non-Reporting ltr (2nd):	
	- NA/FWD19014522/z4; DOA: 19/08/19	Non-Reporting ltr (Final):	
30/8/19	3 veh cc. CID and car	Notification ltr (if non-pickup):	
		Call OI:	20/8/19
		After call ltr to OI:	
		Documentation Check List: Handler Typist	
17/10/19	File -> type marchab	Notification ltr (if non-pickup):	
18/11/19	File -> su li to level av	After call ltr to OI:	
19/11/19	File pass to mk to close.	Authorisation To Act:	
		Release Voucher:	
		Final Repair Bill:	
		Car Rental Invoice:	
		Towing Invoice:	
		LTA / GIA :	
		Medical Bill:	
		PIR:	
		Mandate/Reject Instruction:	
		LOD:	
		Payment Breakdown Form:	
		Post-Repair Photos:	
		Others:	

PRELIMINARY ADVICE Date/Time: 17/11/19 Sent By: cm

FINALIZATION	Date/Time:	Confirm with:	Confirm by:
Repair Cost:	S\$	(days) Reduction:	% Email <input type="checkbox"/> Call <input type="checkbox"/>
FINAL SETTLEMENT	Date/Time: 16/11/19	Confirm with: Suharni	Email <input type="checkbox"/> Call <input type="checkbox"/>
Final Liability:	%	(Agreed / Assessed) BOLA S/N No. 28 C2cc CID2	If NO or B 28, Ass. Lia: C/Y.
Repair Cost:	S\$ 3500.00		
Loss of Rental (LOR):	S\$	(days)	
Loss of Use (LOU):	S\$ 150.00 (\$50 x 3 days)		
Loss of Income (LOI):	S\$	(\$ x days)	
LOR only <input type="checkbox"/> LOU only <input type="checkbox"/> LOR + LOU <input type="checkbox"/> LOR + LOI <input type="checkbox"/>		(Tick only one)	
GIA/LTA Search	S\$ 7.45		
Medical:	S\$ -		
Disbursement:	S\$ -	(e.g. Tow/ Independent)	
Legal Cost	S\$		
Total:	S\$ 3652.45	Global Sum S\$:	
FINAL PAYMENT	Date/Time:	Confirm with:	Email <input type="checkbox"/> Call <input type="checkbox"/>
Payee 1:	S\$ 3652.45	Name 1: Ace Auto Solution	
Payee 2: (Strike if N.A.)	S\$	Name 2:	
Payee 3: (Strike if N.A.)	S\$	Name 3:	

COPY SENT
26/11/19

Adrian

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 03 days Res.: Yes or No
 Lum Sum: 20 % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Vehicle: IN / OUT
 Person Contacted: _____

Veh No: SFA3366Z Yr Regn: 2016 / Feb.
 Type: MLC / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or

Make: Cherplet Orlando c.c. 1362
 Colour: Blue A/C: Insured / Std / NI / NA
 Sp. Reading: 87818 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: KLIYA7589GK333512

Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or
 Brake: Inorder / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/50 R17
 R: 225/50 R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or

Front		Rear	
R/Bal.	<u>06</u> mm	R/Bal.	<u>06</u> mm
L/Bal.	<u>06</u> mm	L/Bal.	<u>06</u> mm
D.O.A.		D.O.I.	<u>28/08/19</u>

Survey held at: Ace Auto Solution
 Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP FWD

US\$ 3500 (Real \$ 10894.73 / 76%)

MV:

PV:

Nett:

Date/Time, File Pass to? Date/Time, File Return to?

1)	2)
3)	4)
5)	6)
Prel. Report	
Final Report	

Part Prices Check:

IN OUT

Survey Fee:

Date:

Basic & Add.
 S + RS, _ \$
 Photos
 Others
 TOTAL

Ace Auto Solution
 Registration number : 53228991M
 23 Kaki Bukit Ave 4, #04-01 (South Wing) Singapore 415933

Repair Estimate

Date : 28/8/2019

Reference: SFA3366Z
 CHEVROLET
 Make: ORLANDO
 1.4AT TURBO

To Whom It May Concern

Dear Sir,

TP FWD
 Xico Tony.

RE: VEHICLE :SFA3366Z
 CHASSIS NO.:KL1YA7589GK333512
 ENGINE NO.A14NET153650303

Name of insured :CHEW KOK TOON
 Date of accident.: 20/08/2019

We append hereunder the estimated cost of repairs to be carried out to the above vehicle.

Parts

No.	Qty	Part Description	Price (SGD)	
1	1	REAR TAILGATE Repair	\$ 1,850.00	+
2	1	LHR TAILGATE LAMP 3 new	\$ 360.00	+
3	1	RHR TAILGATE LAMP 1 new	\$ 360.00	+
4	1	CHEVROLET LETTERING 2	\$ 50.00	✓
5	1	ORLANDO LETTERING	\$ 40.00	✓
6	1	LS LETTERING 1 new	\$ 25.00	✓
7	1	TURBO LETTERING	\$ 45.00	✓
8	1	CHEVROLET EMBLEM 1 new	\$ 120.00	x
9	1	REAR WINDSCREEN 2	\$ 698.00	+
10	1	REAR TAILGATE WEATHERSTRIP 1 new	\$ 240.00	+
11	1	REAR TAIL LID LATCH 1 new	\$ 220.00	+
12	1	REAR TAIL LID STRIKER	\$ 80.00	+
13	1	REAR BUMPER STEP PLATE Del'd.	\$ 160.25	✓
14	1	REAR BUMPER UPPER 2 Del'd	\$ 1,567.00	✓
15	1	REAR BUMPER LOWER	\$ 660.00	✓
16	1	REAR BUMPER SILL PLATE(SILVER) Del'd	\$ 370.00	✓
17	1	REAR BUMPER TOWING COVER 1 new	\$ 75.00	x

18	1	LHR TAILLAMP <i>3/11/18</i>	\$ 719.00	+
19	1	RHR TAILLAMP <i>3/11/18</i>	\$ 719.00	+
20	1	LHR BUMPER REFLECTOR <i>3/11/18</i>	\$ 95.00	✓
21	1	RHR BUMPER REFLECTOR <i>3/11/18</i>	\$ 95.00	✓
22	1	REAR REVERSE LIGHT AND BRAKE LIGHT <i>3/11/18</i>	\$ 401.00	✓
23	1	REAR BUMPER CENTRE GUIDE <i>3/11/18</i>	\$ 120.00	✓
24	1	RHR BUMPER GUIDE, OTR <i>3/11/18</i>	\$ 60.00	✓
25	1	LHR BUMPER GUIDE, OTR <i>3/11/18</i>	\$ 60.00	✓
26	1	REAR BUMPER LEFT CENTRE GUIDE, INR <i>3/11/18</i>	\$ 50.00	✓
27	1	REAR BUMPER RIGHT CENTRE GUIDE, INR <i>3/11/18</i>	\$ 50.00	✓
28	1	REAR BUMPER BEAM <i>3/11/18</i>	\$ 820.00	+
29	1	REAR END PANEL TRIM <i>3/11/18</i>	\$ 150.00	+
30	1	REAR END PANEL OUTER <i>3/11/18</i>	\$ 730.00	+
31	1	REVERSE SENSOR WIRING HARNESS <i>3/11/18</i>	\$ 325.00	+
32	1	RHR FENDER PROTECTOR <i>3/11/18</i>	\$ 113.00	+
33	1	LHR FENDER PROTECTOR <i>3/11/18</i>	\$ 113.00	+

384825

346342

Parts Total: \$ 11,540.25

Less 10%: \$ 1,154.03

Total: \$ 10,386.23

Labour

No.	Labour Description	Price (SGD)
Rear portion		
1	To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate and align repair / replacement parts. (\$200 PER DAY)	\$ 1,000.00 <i>200</i>
2	Carry out spray painting on accident affected area (\$200 PER PANEL)	\$ 1,000.00 <i>400</i>
3	To conduct anti rust of under carriage tuff coat	\$ 80.00 <i>+</i>
4	To disconnect wire harness of electrical component to facilitate repairs, reconnect and check electrical function after repair	\$ 30.00 <i>✓</i>
5	To remove and refix reverse sensor and conduct test	\$ 80.00 <i>50</i>
6	To remove and refix reverse camera and conduct test	\$ 80.00 <i>+</i>
7	To conduct transfer of parts from old tailgate to new tailgate	\$ 80.00 <i>+</i>
8	To conduct water leakage test after repairs of vehicle	\$ 80.00 <i>+</i>
9	To remove and refix rear tail gate windscreen	\$ 120.00 <i>+</i>

680

Labour Total: \$ 2,550.00

Others

Other Description

No. Qty

Price (SGD)

Rear portion

1	1	Rear number plate <i>new</i>	\$ 45.00	+
2	10	Rear bumper clip <i>new</i>	\$ 65.00	30
3	6	Rear fender liner clips <i>new</i>	\$ 39.00	+
4	10	Rear end panel trim clip <i>new</i>	\$ 65.00	+
5	1	Reverse sensor (1 set) <i>Day 2</i>	\$ 440.00	200
6	1	Rear reverse camera <i>new</i>	\$ 280.00	+
7	1	Rear end panel insulation seal <i>2</i>	\$ 120.00	+
8	13	Tail gate inner trim board clip <i>new</i>	\$ 84.50	+
9	1	Tailgate windscreen sealant <i>new</i>	\$ 120.00	+
10	1	Tailgate windscreen solar film	\$ 200.00	+

230

Other Total: \$ 1,458.50

GRAND TOTAL: \$ 14,394.73

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN. **PARTS PRICES ARE SUBJECT TO CHANGES.**

Yours faithfully



Service Advisor

Suhaimi

HP : 9189 2617 Email - aceautosolution@gmail.com



APPROVER DETAILS

SURVEYOR : _____

CONTACT NO : _____

PART BY PART / LUMP SUM

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display (damaged parts) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Admin King
4/5 28/08/19.

03 Days

total: 4373.42

4/5: 3 SIC

Finalisation

Ace Auto Solution

Registration number : 53228991M

23 Kaki Bukit Ave 4, #04-01 (South Wing) Singapore 415933

INVOICE

To : FWD Singapore Pte Ltd
6 Temasek Boulevard, #18-01
Suntec Tower 4
SINGAPORE 038986

Invoice No: ACC-2015001
Invoice Date:

Vehicle No: SFA3366Z
Chassis No: KL1YA7589GK333512
Engine No: A14NET153650303

DESCRIPTION			AMOUNT SGD
Parts			
No.	Qty.		Price (SGD)
<u>1</u>	1	CHEVROLET LETTERING	\$ 50.00
<u>2</u>	1	ORLANDO LETTERING	\$ 40.00
<u>3</u>	1	LS LETTERING	\$ 25.00
<u>4</u>	1	TURBO LETTERING	\$ 45.00
<u>5</u>	1	REAR BUMPER STEP PLATE	\$ 160.25
<u>6</u>	1	REAR BUMPER UPPER	\$ 1,567.00
<u>7</u>	1	REAR BUMPER LOWER	\$ 660.00
<u>8</u>	1	REAR BUMPER SILL PLATE(SILVER)	\$ 370.00
<u>9</u>	1	LHR BUMPER REFLECTOR	\$ 95.00
<u>10</u>	1	RHR BUMPER REFLECTOR	\$ 95.00
<u>11</u>	1	REAR REVERSE LIGHT AND BRAKE LIGHT	\$ 401.00
<u>12</u>	1	REAR BUMPER CENTRE GUIDE	\$ 120.00
<u>13</u>	1	RHR BUMPER GUIDE, OTR	\$ 60.00
<u>14</u>	1	LHR BUMPER GUIDE, OTR	\$ 60.00
<u>15</u>	1	REAR BUMPER LEFT CENTRE GUIDE, INR	\$ 50.00
<u>16</u>	1	REAR BUMPER RIGHT CENTRE GUIDE, INR	\$ 50.00

Total: \$ 3,848.25
Less 10%: \$ 384.83
Parts Total : \$ 3,463.43

Labour

No.		Price (SGD)
<u>1</u>	To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate and align repair / replacement parts. (\$200 PER DAY)	\$ 200.00
<u>2</u>	Carry out spray painting on accident affected area (\$200 PER PANEL)	\$ 400.00
<u>3</u>	To disconnect wire harness of electrical component to facilitate repairs, reconnect and check electrical function after repair	\$ 30.00
<u>4</u>	To remove and refix reverse sensor and conduct test	\$ 50.00

Labour Total : \$ 680.00

Other

No.			Price (SGD)
1	10	Rear bumper clip	\$ 30.00
2	1	Reverse sensor (1 set)	\$ 200.00

Other Total : \$ 230.00

Total : \$ 4,373.43
Less lump sum 20%: \$ 874.69
Grand Total: \$ 3,500.00

Yours Faithfully,



Suhaimi
Service Executive

Tel: 9189 2617 Fax: 6844 5185

Email : aceautosolution@gmail.com

E & O E

ALL CHEQUE PAYMENTS SHOULD BE CROSSED AND MADE PAYABLE TO "**ACE AUTO SOLUTION**".

PLEASE INDICATE THE INVOICE NO. ON THE REVERSE SIDE.

Please check and finalize with me this invoice

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Catherine Chong (LKK Auto)

From: lionel.tan@fwd.com
Sent: Friday, 23 August, 2019 3:00 PM
To: sur@lkkauto.com; assignments@lkkauto.com
Cc: motorclaims.sg@fwd.com
Subject: FW: Accident vehicle between our insured SFA3366Z and your insured SJL9507P (FWD) on 20/08/2019
Attachments: SFA3366Z.PDF

Hi

Email below for your attention.

Please arrange survey plus DS with repairer.

Best Regards,

Lionel Tan
Senior Executive, Claims



FWD Singapore Pte. Ltd.
6 Temasek Boulevard, #18-01 Suntec Tower Four, Singapore 038986
T (65) 6914 6824
E lionel.tan@fwd.com
W www.fwd.com.sg

From: Ace Auto Solution [<mailto:aceautosolution@gmail.com>]
Sent: Friday, 23 August, 2019 1:18 PM
To: Motor Claims SG - SG Common
Subject: Accident vehicle between our insured SFA3366Z and your insured SJL9507P on 20/08/2019

Re : Surveyors

We are instructed by our client(s) to put you on notice of the accident in which our clients' vehicle was involved in.

We are giving you 2 days notice that our clients' vehicle is in our workshop at this time and would require your appointed surveyor to attend at our workshop to conduct a survey prior to our commencement of repairs of our client(s) vehicle.

P: Suhaimi

T: 3.33p.m

V: Out

E: ✓

We look forward in having a direct settlement and request that the following named surveyor will not be attending to this survey due to finalization/processing of the claims after finalization not done promptly on the above said vehicle.

1) LKK AUTO CONSULTANTS

2)

3)

-

Take Notice : This notification is not an affirmation of your appointed surveyor's report neither does it imply that our client(s) are agreeable to your surveyor's assessment of the quantum for the repairs. For the avoidance of all doubt, we have been instructed by our client(s) that an independent surveyor shall be appointed for the survey of the repairs required to our client(s) vehicle.

Thanks & Regards

Suhami / Service Advisor

Ace Auto Solution

Hp : 9189 2617 / Fax : 6844 5165

23 Kaki Bukit Ave 4, #04-01 (South Wing), S'pore 415933

Please note that it is a condition of any settlement reached that it shall be without prejudice to any personal injury claim (if any) of the owner/ claimant.

ATTENTION:

The email and any attachments transmitted with it are private and confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error, please notify the sender immediately and delete this email and any attachments from your system. You should not use, disclose, copy or store this email and any attachments.

Messages and attachments are scanned for all viruses known. However, you are advised that you open any attachments at your own risk. If this message contains password-protected attachments, the files have NOT been scanned for viruses by our mail domain. Please always scan for viruses before opening any attachments.

Nivitha (LKK Auto)

From: lionel.tan@fwd.com
Sent: Friday, 23 August 2019 3:00 PM
To: sur@lkkauto.com; assignments@lkkauto.com
Cc: motorclaims.sg@fwd.com
Subject: FW: Accident vehicle between our insured SFA3366Z and your insured SJL9507P (FWD) on 20/08/2019
Attachments: SFA3366Z.PDF

Hi

Email below for your attention.

Please arrange survey plus DS with repairer.

Best Regards,

Lionel Tan
Senior Executive, Claims



FWD Singapore Pte. Ltd.
6 Temasek Boulevard, #18-01 Suntec Tower Four, Singapore 038986
T (65) 6914 6824
E lionel.tan@fwd.com
W www.fwd.com.sg

From: Ace Auto Solution [<mailto:aceautosolution@gmail.com>]
Sent: Friday, 23 August, 2019 1:18 PM
To: Motor Claims SG - SG Common
Subject: Accident vehicle between our insured SFA3366Z and your insured SJL9507P on 20/08/2019

Re : Surveyors

We are instructed by our client(s) to put you on notice of the accident in which our clients' vehicle was involved in.

We are giving you 2 days notice that our clients' vehicle is in our workshop at this time and would require your appointed surveyor to attend at our workshop to conduct a survey prior to our commencement of repairs of our client(s) vehicle.

We look forward in having a direct settlement and request that the following named surveyor will not be attending to this survey due to finalization/processing of the claims after finalization not done promptly on the above said vehicle.

1) LKK AUTO CONSULTANTS

2)

3)

-

Take Notice : This notification is not an affirmation of your appointed surveyor's report neither does it imply that our client(s) are agreeable to your surveyor's assessment of the quantum for the repairs. For the avoidance of all doubt, we have been instructed by our client(s) that an independent surveyor shall be appointed for the survey of the repairs required to our client(s) vehicle.

Thanks & Regards

Suhaimi / Service Advisor

Ace Auto Solution

Hp : 9189 2617 / Fax : 6844 5185

23 Kaki Bukit Ave 4, #04-01 (South Wing), S'pore 415933

Please note that it is a condition of any settlement reached that it shall be without prejudice to any personal injury claim (if any) of the owner/ claimant.

ATTENTION:

The email and any attachments transmitted with it are private and confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error, please notify the sender immediately and delete this email and any attachments from your system. You should not use, disclose, copy or store this email and any attachments.

Messages and attachments are scanned for all viruses known. However, you are advised that you open any attachments at your own risk. If this message contains password-protected attachments, the files have NOT been scanned for viruses by our mail domain. Please always scan for viruses before opening any attachments.

Claim Audit

AUDIT TRAIL					By
No.	On	Audit	Remarks		
1	26 Aug 2019 16:32	Cim Dtl Modified	Claimant's Name: -> CHEW KOK TOON, Claimant's ID: -> S1504509D.		[A] HOW MEI KWAN
2	26 Aug 2019 16:32	Cim Veh Model Changed	(205117) CHEVROLET ORLANDO 1.4 Turbo (A).		[A] HOW MEI KWAN
3	26 Aug 2019 16:32	Cim Created	Reg No: SFA3366Z, Acct Date: 2019/08/20, Claim Type: TP, Insurer: FWD Singapore Pte. Ltd, (HQ), TP Insurer: NTUC Income Insurance Co-operative Ltd (HQ), Workshop: Ace Auto Solution (kaki Bukit) (HQ)		[A] HOW MEI KWAN
4	26 Aug 2019 16:32	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ); RR Region: FWD - Ext Auto Adj Assignment, Suggested Adj. : AJAX Inspection Services Pte Ltd.		[A] HOW MEI KWAN
5	26 Aug 2019 16:32	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/09/04		[A] HOW MEI KWAN
6	26 Aug 2019 16:32	Adj Mandate Set	Approved:0.00.Reinsp:Adj decides.		[A] HOW MEI KWAN
7	26 Aug 2019 16:33	Label Added	(20005):Direct Settlement .		[A] HOW MEI KWAN
8	26 Aug 2019 16:33	Adj Adjuster Assigned	[None] -> MARCUS CHUA		[A] HOW MEI KWAN
9	26 Aug 2019 16:49	Cim Registration Modified	Pol No:->PNPV2018-00015635.		[T] Venessa Chan
10	29 Aug 2019 18:26	Adj Adjuster Assigned	MARCUS CHUA -> ADRIAN LING		[A] HOW MEI KWAN
11	17 Oct 2019 09:51	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2019/09/04		[A] CHEW HSIAO TONG
12	06 Nov 2019 10:23	Adj Rpt Initiated			[A] JOANNE LEE KHANG MIN
13	06 Nov 2019 10:23	Cim Dtl Modified	JPJ Reg. Date: -> 2016/02/26.		[A] JOANNE LEE KHANG MIN
14	06 Nov 2019 10:23	Cim Details Notified			[A] JOANNE LEE KHANG MIN
15	09 Nov 2019 14:55	Adj Mandate Request	Cur.Req:3687.45;LIABILITY: 100%(BOLA 28) QUANTUM: (a) COR: \$3,500.00 + (b) LO U: \$180.00 (3days x \$60) + (c) DISBURSEMENT: \$7.45 Total: a+b+c = \$3,687.45 *VE H MODEL: Chevrolet Orlando(1362cc). FOR YOUR APPROVAL/INSTRUCTION.		[A] CHEW HSIAO TONG

Date From



Date To



Audit Type None

Go

ACTIVITY

[29/08/2019 18:26] HOW MEI KWAN:
PENDING TP ESTIMATE

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Bill Type	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
2258073	26 Aug 2019 16:49:09	TP Case (Insurer)	Motor	FWD Singapore Pte. Ltd. (HQ)	FWD Singapore Pte. Ltd. (HQ)	SFA3366Z	TAN BOON LENG KENNETH	xx.xx
2316008	17 Oct 2019 09:51:00	OD/TP Case (Adjuster)	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SFA3366Z	SJL9507P	11.77

Print Received Message



This mail is associated with :

***SFA3366Z (1201900024765)**
[SJL9507P]
TP
CHEW KOK TOON
Aug 20 2019 5:00PM
[TAN BOON LENG KENNETH]
Ace Auto Solution (kaki Bukit)

From FWD Singapore Pte. Ltd. (HQ) (FWD_SG), sent on 13/11/2019 11:18 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$3687.45) - SFA3366Z - Claim Handler: Lionel Tan

Approved:3687.45.

Hsiao Tong (LKKAUTO)

From: Ace Auto Solution <aceautosolution@gmail.com>
Sent: Thursday, 14 November 2019 11:44 AM
To: Hsiao Tong (LKKAUTO)
Subject: Re: Accident case involving SFA3366Z and SJL9507P on 20/08/2019 *** LKK REF: CC4/FWD19014985/Apa3

Hi Hsiao Tong,

Without prejudice to any personal injury claim, we accept your settlement as

1. Cost of Repair	\$ 3,500.00
2. Loss of Use (3days x \$50.00)	\$ 150.00
3. LTA/GIA Search Fee	\$ 7.45
Total	\$ 3,657.45

Is there any DV for my customer to sign?

Thanks & Regards

Suhaimi / Service Advisor

Ace Auto Solution

Hp : 9189 2617 / Fax : 6844 5185

23 Kaki Bukit Ave 4, #04-01 (South Wing), S'pore 415933

Please note that it is a condition of any settlement reached that it shall be without prejudice to any personal injury claim (if any) of the owner/claimant.

On Thu, Nov 14, 2019 at 11:37 AM Hsiao Tong (LKKAUTO) <chewht@lkkauto.com> wrote:

Without Prejudice

Dear Sirs/Mdm,

We refer to the above matter.

We propose settlement as follows: -

1. Cost of Repair	\$ 3,500.00
-------------------	-------------

2. Loss of Use (3days x \$50.00)	\$ 150.00
3. LTA/GIA Search Fee	\$ 7.45
Total	\$ 3,657.45

Please confirm acceptance.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Hsiao Tong (LKKAuto)

Sent: Saturday, 9 November 2019 10:57 AM

To: Ace Auto Solution <aceautosolution@gmail.com>

Subject: RE: Accident case involving SFA3366Z and SJL9507P on 20/08/2019 *** LKK REF: CC4/FWD19014985/Apa3

Without Prejudice

Hi Suhaimi,

Yes, LOD & docs received on 08/11/2019.

We will seek mandate from FWD and get back to you.

Thanks.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement."

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Ace Auto Solution <aceautosolution@gmail.com>

Sent: Friday, 8 November 2019 4:44 PM

To: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>

Subject: Re: Accident case involving SFA3366Z and SJL9507P on 20/08/2019 *** LKK REF: CC4/FWD19014985/Apa3

Hi Hsiao Tong,

Adrian said he passed to your side a while ago. Can you please help me to recheck.

Thanks & Regards

Suhaimi / Service Advisor

Ace Auto Solution

Hp : 9189 2617 / Fax : 6844 5185

23 Kaki Bukit Ave 4, #04-01 (South Wing), S'pore 415933

Please note that it is a condition of any settlement reached that it shall be without prejudice to any personal injury claim (if any) of the owner/claimant.

On Thu, Nov 7, 2019 at 12:01 PM Ace Auto Solution <aceautosolution@gmail.com> wrote:

Hi Hsiao Tong,

Have you received all documents such as my LOD and invoices for this accident case?

Thanks & Regards

Suhaimi / Service Advisor

Ace Auto Solution

Hp : 9189 2617 / Fax : 6844 5185

23 Kaki Bukit Ave 4, #04-01 (South Wing), S'pore 415933

Please note that it is a condition of any settlement reached that it shall be without prejudice to any personal injury claim (if any) of the owner/claimant.

On Thu, Nov 7, 2019 at 10:47 AM Mei Kwan (LKKAuto) <Meikwan@lkkauto.com> wrote:

'WITHOUT PREJUDICE'

SAVE AS TO COSTS

Dear Sir / Madam,

Thank you for your email.

Our respective case handler will look into the matter and get back to you in due course.

Hi Hsiao Tong,

Kindly assist.

To check availability of the case handler, you may contact the undersigned.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Ace Auto Solution <aceautosolution@gmail.com>

Sent: Tuesday, 5 November, 2019 1:53 PM

To: Admin A <admin-a@lkkauto.com>

Subject: Accident case involving SFA3366Z and SJL9507P on 20/08/2019

Hi,

Can i know who the OIC is for this accident case as i would like to check if all documents such as my LOD and invoices has been received by the OIC.

Thanks & Regards

Suhaimi / Service Advisor

Ace Auto Solution

Hp : 9189 2617 / Fax : 6844 5185

23 Kaki Bukit Ave 4, #04-01 (South Wing), S'pore 415933

Please note that it is a condition of any settlement reached that it shall be without prejudice to any personal injury claim (if any) of the owner/ claimant.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	20 Aug 2019 Edit Reg		23 Aug 2019 00:00 Edit Adj Rpt	\$53,500.00 Edit Estimates	\$53,500.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: TAN BOON LENG KENNETH , ID: S1628031C									
Main Claimant: CHEW KOK TOON , ID: S1504509D									
Vehicle Reg. No.:	SFA3366Z	Date of Loss:	20/08/2019 17:00 - :59 [41 Months and 25 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 1201900024765	Policy/Cover Note No.:	PNPV2018-00015635 (Comprehensive) Coverage: 06/12/2018 - 16/12/2019						
Vehicle Reg. No. (Insured):	SJL9507P	Policy No. (Claimant):	5088172324-02						
		Excess:							
Repairer: Ace Auto Solution (kaki Bukit) (HQ) 23 KAKI BUKIT AVE 4, #04-01 (SOUTH WING), 415933 Kaki Bukit - Tel:									
Handling Insurer: FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700 ... [Handled by Lionel Tan]									
Claimant's Insurer: NTUC Income Insurance Co-operative Ltd (HQ) - Tel:									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 04/09/2019]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
• FWD_SG (13/11/2019): Alert - Adj Mandate Approved (\$53687.45) - SFA3366Z - Claim Handler: Lionel Tan									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SFA3366Z (1201900024765)
[SJL9507P]
TP
CHEW KOK TOON
Aug 20 2019 5:00PM
[TAN BOON LENG KENNETH]
Ace Auto Solution (kaki Bukit)

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View [View in Browser](#)

Letters/Correspondences				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	{Draft}	Third Party Express Settlement - Payment Breakdown		Edit	

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	17/10/19 09:51	Adjuster Immediate Advice		Load HTM	

Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	11/10/19 12:14	General View		Load JPG	<input checked="" type="checkbox"/>
2	11/10/19 12:14	General View		Load JPG	<input checked="" type="checkbox"/>
3	11/10/19 12:14	General View		Load JPG	<input checked="" type="checkbox"/>
4	11/10/19 12:14	General View		Load JPG	<input checked="" type="checkbox"/>
5	11/10/19 12:14	General View		Load JPG	<input checked="" type="checkbox"/>
6	11/10/19 12:14	General View		Load JPG	<input checked="" type="checkbox"/>
7	11/10/19 12:14	General View		Load JPG	<input checked="" type="checkbox"/>
8	11/10/19 12:14	General View		Load JPG	<input checked="" type="checkbox"/>
9	11/10/19 12:14	General View		Load JPG	<input checked="" type="checkbox"/>
10	11/10/19 12:14	General View		Load JPG	<input checked="" type="checkbox"/>
11	11/10/19 12:14	General View		Load JPG	<input checked="" type="checkbox"/>
12	11/10/19 12:14	General View		Load JPG	<input checked="" type="checkbox"/>
13	11/10/19 12:14	General View		Load JPG	<input checked="" type="checkbox"/>
14	11/10/19 12:14	General View		Load JPG	<input checked="" type="checkbox"/>
15	11/10/19 12:14	General View		Load JPG	<input checked="" type="checkbox"/>
16	11/10/19 12:14	General View		Load JPG	<input checked="" type="checkbox"/>
17	11/10/19 12:14	General View		Load JPG	<input checked="" type="checkbox"/>
18	11/10/19 12:14	General View		Load JPG	<input checked="" type="checkbox"/>
19	11/10/19 12:14	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
20	11/10/19 12:14	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
21	11/10/19 12:14	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
22	11/10/19 12:14	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
23	11/10/19 12:14	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
24	11/10/19 12:14	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
25	11/10/19 12:14	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
26	11/10/19 12:14	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
27	11/10/19 12:14	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
28	11/10/19 12:14	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
29	11/10/19 12:14	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
30	11/10/19 12:14	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
31	11/10/19 12:14	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
32	11/10/19 12:14	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
33	11/10/19 12:14	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
34	11/10/19 12:14	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
35	11/10/19 12:14	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
36	11/10/19 12:14	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>

Letters/Correspondences				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
37	11/10/19 12:14	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
38	11/10/19 12:14	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
39	11/10/19 12:14	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
40	11/10/19 12:14	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
41	11/10/19 12:14	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
42	11/10/19 12:14	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
43	11/10/19 12:14	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
44	11/10/19 12:14	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
Documentation				1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	26/08/19 16:33	ACKNOWLEDGEMENT EMAIL TO FWD DD 23.08.2019		Load PDF	
2	26/08/19 16:33	TP GIA REPORT		Load PDF	
3	17/10/19 09:49	TP ESTIMATE_MARKED		Load PDF	
4	09/11/19 14:54	LOD		Load PDF	
5	09/11/19 14:54	Workshop Invoice.		Load PDF	
6	09/11/19 14:54	LTA Search Fee.		Load PDF	
7	09/11/19 14:54	Authorisation to Act		Load PDF	
8	25/11/19 10:43	Release Voucher		Load PDF	
No	Finalized On	FWD Singapore Pte. Ltd. (HQ)		Thumbnail	Print
1	26/08/19 16:49	SJL9507P 01 GIA		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SJL9507P (Insd veh)	Model:	CHEVROLET ORLANDO 1.4
	SFA3366Z (TP veh)		TURBO (A)
Date of Accident:	20/08/2019		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Repair Estimate	:	\$	14,394.72
Final Repair Cost	:	\$	3,500.00
Loss of Use	:	\$	150.00
Rental (if any)	:	\$	0.00
LTA / GIA Search Fee	:	\$	7.45
Others:	:	\$	0.00
	:	\$	
Final Settlement Sum	:	\$	3,657.45

3.00 days at \$50.00 per day
days

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For **Non GIA Registered Workshop:** Agreed Liability ____ 100 ____ (%)

B) For **GIA Registered Workshop:** BOLA Applicable: Yes/ No BOLA Scenario No: ____

BOLA Liability: ____ (%) Assessed Liability (*): ____ 0 ____ (%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Ace Auto Solution	:	\$ 3,657.45
2)		:	\$
3)		:	\$

JOANNE LEE KHANG MIN

25 Nov
2019

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/FWD19014985/APA3Q2

Date: 25/11/2019

REFERENCE

Handling Insurer: FWD Singapore Pte. Ltd. Policy No: PNPV2018-00015635

Claimant SFA3366Z Insured Vehicle No : SJL9507P

Vehicle No : SFA3366Z Insured Vehicle No : SJL9507P
Date of Loss: 20/08/2019 Nature of Claim: TP Claim No: 1201900024765

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SFA3366Z	Engine No:	B14NET153650303
Make & Model:	CHEVROLET ORLANDO, 1.4 Turbo (A)	Chassis No:	KL1YA7589GK333512
Reg. Date:	26/02/2016 (Man. Year: 2015)	Odometer:	87818 km
Colour:	Blue		
Engine Capacity:	1362 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/50 R17	Rear Tyre Size:	225/50 R17
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,844.72	3,693.42	8,151.30	68.82
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,550.00	680.00	1,870.00	73.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,394.72	4,373.42	10,021.30	69.62
Approved Total (Overridden) (S\$)		3,500.00		
Nett Amount (S\$)	14,394.72	3,500.00	10,894.72	75.69
+ Loss of Use (3.0 x S\$50.00/day) (S\$)		150.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		3,657.45		

INSPECTION

Date of Assignment: 23/08/2019

Date Inspected: 28/08/2019 Inspected At:

Ace Auto Solution (kaki Bukit) (HQ)
23 KAKI BUKIT AVE 4, #04-01
(SOUTH WING)
Singapore 415933

Estimated Period of Repair: 3.0 days

Adjuster: ADRIAN LING

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 06 Nov 2019)
Parts:	M1-MPV	CHEVROLET ORLANDO 1.4 Turbo (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SFA3366Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Repair	1,850.00 FL	*- FL
2	1		*LHR TAILGATE LAMP	Not Necessary	360.00 FL	*- FL
3	1		*RHR TAILGATE LAMP	Not Necessary	360.00 FL	*- FL
4	1		*CHEVROLET LETTERING	Necessary	50.00 FL	*50.00 FL
5	1		*ORLANDO LETTERING	Necessary	40.00 FL	*40.00 FL
6	1		*LS LETTERING	Necessary	25.00 FL	*25.00 FL
7	1		*TURBO LETTERING	Necessary	45.00 FL	*45.00 FL
8	1		*CHEVROLET EMBLEM	Not Necessary	120.00 FL	*- FL
9	1		*REAR WINDSCREEN	Not Necessary	698.00 FL	*- FL
10	1		*REAR TAILGATE WEATHERSTRIP	Not Necessary	240.00 FL	*- FL
11	1		*REAR TAIL LID LATCH	Not Necessary	220.00 FL	*- FL
12	1		*REAR TAIL LID STRIKER	Not Necessary	80.00 FL	*- FL
13	1		*REAR BUMPER STEP PANEL	Deformed	160.25 FL	*160.25 FL
14	1		*REAR BUMPER UPPER	Deformed	1,567.00 FL	*1,567.00 FL
15	1		*REAR BUMPER LOWER	Deformed	660.00 FL	*660.00 FL
16	1		*REAR BUMPER SILL PLATE (SILVER)	Deformed	370.00 FL	*370.00 FL
17	1		*REAR BUMPER TOWING COVER	Not Necessary	75.00 FL	*- FL
18	1		*LHR TAILLAMP	Not Necessary	719.00 FL	*- FL
19	1		*RHR TAILLAMP	Not Necessary	719.00 FL	*- FL
20	1		*LHR BUMPER REFLECTOR	Cracked	95.00 FL	*95.00 FL
21	1		*RHR BUMPER REFLECTOR	Cracked	95.00 FL	*95.00 FL
22	1		*REAR REVERSE LIGHT AND BRAKE LIGHT	Cracked	401.00 FL	*401.00 FL
23	1		*REAR BUMPER CENTRE GUIDE	Cracked	120.00 FL	*120.00 FL
24	1		*RHR BUMPER GUIDE ,OTR	Necessary	60.00 FL	*60.00 FL
25	1		*LHR BUMPER GUIDE ,OTR	Necessary	60.00 FL	*60.00 FL
26	1		*REAR BUMPER LEFT CENTRE GUIDE ,INR	Necessary	50.00 FL	*50.00 FL
27	1		*REAR BUMPER RIGHT CENTRE GUIDE ,INR	Necessary	50.00 FL	*50.00 FL
28	1		*REAR BUMPER BEAM	Not Necessary	820.00 FL	*- FL
29	1		*REAR END PANEL TRIM	Not Necessary	150.00 FL	*- FL
30	1		*REAR END PANEL OUTER	Repair	730.00 FL	*- FL
31	1		*REVERSE SENSOR WIRING HARNESS	Not Necessary	325.00 FL	*- FL
32	1		*RHR FENDER PROTECTOR	Not Necessary	113.00 FL	*- FL
33	1		*LHR FENDER PROTECTOR	Not Necessary	113.00 FL	*- FL
34	1		*REAR NUMBER PLATE	Not Necessary	45.00 FS	*- FS
35	10		*REAR BUMPER CLIP	Necessary	65.00 FS	*30.00 FS
36	6		*REAR FENDER LINER CLIPS	Not Necessary	39.00 FS	*- FS
37	10		*REAR END PANEL TRIM CLIP	Not Necessary	65.00 FS	*- FS
38	1		*SET REVERSE SENSOR	Damaged	440.00 FS	*200.00 FS
39	1		*REAR REVERSE CAMERA	Not Necessary	280.00 FS	*- FS
40	1		*REAR END PANEL INSULATION SEAL	Not Necessary	120.00 FS	*- FS
41	13		*TAIL GATE INNER TRIM BOARD CLIP	Not Necessary	84.50 FS	*- FS
42	1		*TAILGATE WINDSCREEN SEALANT	Not Necessary	120.00 FS	*- FS
43	1		*TAILGATE WINDSCREEN SOLAR FILM	Not Necessary	200.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
				Sub Total (S\$)	12,998.75	4,078.25
				- List Item Discount on L Items 10.00/10.00% (S\$)	1,154.03	384.83
				Total Parts (S\$)	11,844.72	3,693.42

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE /RENEW THE ACCIDENT DAMAGED PORTION ,TO PANEL BEATING ,RESHAPE ,STRAIGHTEN ,ORIENTATE AND ALIGN REPAIR /REPLACEMENT PARTS	New	1,000.00	200.00
2	CARRY OUT SPRAY PAINTING ON ACCIDENT AFFECTED AREA	New	1,000.00	400.00
3	TO CONDUCT ANTI RUST OF UNDER CARRIAGE TUFF COAT	New	80.00	0.00
4	TO DISCONNECT WIRE HARNESS OF ELECTRICAL COMPONENT TO FACILITATE REPAIRS ,RECONNECT AND CHECK ELECTRICAL FUNCTION AFTER REPAIR	New	30.00	30.00
5	TO REMOVE AND REFIX REVERSE SENSOR AND CONDUCT TEST	New	80.00	50.00
6	TO REMOVE AND REFIX REVERSE CAMERA AND CONDUCT TEST	New	80.00	0.00
7	TO CONDUCT TRANSFER OF PARTS FROM OLD TAILGATE TO NEW TAILGATE	New	80.00	0.00
8	TO CONDUCT WATER LEAKAGE TEST AFTER REPAIRS OF VEHICLE	New	80.00	0.00
9	TO REMOVE AND REFIX REAR TAIL GATE WINDSCREEN	New	120.00	0.00
Gross Labour Cost (\$\$)			2,550.00	680.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >