

HT

Ace Auto Solution
 Registration number : 53228991M
 23 Kaki Bukit Ave 4, #04-01 (South Wing) Singapore 415933

Repair Estimate

Date : 28/8/2019

Reference: SFA3366Z
Make: CHEVROLET
 ORLANDO
 1.4AT TURBO

To Whom It May Concern

TP FWD.
 Xico Tony.

Dear Sir,

RE: VEHICLE :SFA3366Z
CHASSIS NO.:KL1YA7589GK333512
ENGINE NO.A14NET153650303

Name of insured :CHEW KOK TOON
 Date of accident.: 20/08/2019

We append hereunder the estimated cost of repairs to be carried out to the above vehicle.

Parts

No.	Qty	Part Description	Price (SGD)	
1	1	REAR TAILGATE <i>Repair</i>	\$ 1,850.00	x
2	1	LHR TAILGATE LAMP <i>3x</i>	\$ 360.00	+
3	1	RHR TAILGATE LAMP <i>3x</i>	\$ 360.00	+
4	1	CHEVROLET LETTERING <i>2</i>	\$ 50.00	✓
5	1	ORLANDO LETTERING	\$ 40.00	✓
6	1	LS LETTERING <i>2x</i>	\$ 25.00	✓
7	1	TURBO LETTERING	\$ 45.00	✓
8	1	CHEVROLET EMBLEM <i>2x</i>	\$ 120.00	x
9	1	REAR WINDSCREEN <i>2</i>	\$ 698.00	x
10	1	REAR TAILGATE WEATHERSTRIP <i>2x</i>	\$ 240.00	+
11	1	REAR TAIL LID LATCH <i>2x</i>	\$ 220.00	+
12	1	REAR TAIL LID STRIKER	\$ 80.00	+
13	1	REAR BUMPER STEP PLATE <i>del</i>	\$ 160.25	✓
14	1	REAR BUMPER UPPER <i>3x del</i>	\$ 1,567.00	✓
15	1	REAR BUMPER LOWER	\$ 660.00	✓
16	1	REAR BUMPER SILL PLATE(SILVER) <i>del</i>	\$ 370.00	✓
17	1	REAR BUMPER TOWING COVER <i>del</i>	\$ 75.00	x

18	1	LHR TAILLAMP <i>3 m</i>	\$ 719.00	+
19	1	RHR TAILLAMP <i>3 m</i>	\$ 719.00	+
20	1	LHR BUMPER REFLECTOR <i>3 m</i>	\$ 95.00	✓
21	1	RHR BUMPER REFLECTOR <i>3 m</i>	\$ 95.00	✓
22	1	REAR REVERSE LIGHT AND BRAKE LIGHT <i>assembled</i>	\$ 401.00	✓
23	1	REAR BUMPER CENTRE GUIDE <i>assembled</i>	\$ 120.00	✓
24	1	RHR BUMPER GUIDE, OTR <i>3 m</i>	\$ 60.00	✓
25	1	LHR BUMPER GUIDE, OTR <i>3 m</i>	\$ 60.00	✓
26	1	REAR BUMPER LEFT CENTRE GUIDE, INR <i>3 m</i>	\$ 50.00	✓
27	1	REAR BUMPER RIGHT CENTRE GUIDE, INR <i>3 m</i>	\$ 50.00	✓
28	1	REAR BUMPER BEAM <i>Not m</i>	\$ 820.00	+
29	1	REAR END PANEL TRIM <i>new</i>	\$ 150.00	+
30	1	REAR END PANEL OUTER <i>Regis</i>	\$ 730.00	+
31	1	REVERSE SENSOR WIRING HARNESS <i>3 m</i>	\$ 325.00	+
32	1	RHR FENDER PROTECTOR <i>3 m</i>	\$ 113.00	+
33	1	LHR FENDER PROTECTOR <i>3 m</i>	\$ 113.00	+

384825

346342

Parts Total: \$ 11,540.25

Less 10%: \$ 1,154.03

Total : \$ 10,386.23

Labour

No.	Labour Description	Price (SGD)
Rear portion		
1	To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate and align repair / replacement parts. (\$200 PER DAY)	\$ 1,000.00 <i>200</i>
2	Carry out spray painting on accident affected area (\$200 PER PANEL)	\$ 1,000.00 <i>400</i>
3	To conduct anti rust of under carriage tuff coat	\$ 80.00 <i>+</i>
4	To disconnect wire harness of electrical component to facilitate repairs, reconnect and check electrical function after repair	\$ 30.00 <i>✓</i>
5	To remove and refix reverse sensor and conduct test	\$ 80.00 <i>50</i>
6	To remove and refix reverse camera and conduct test	\$ 80.00 <i>+</i>
7	To conduct transfer of parts from old tailgate to new tailgate	\$ 80.00 <i>+</i>
8	To conduct water leakage test after repairs of vehicle	\$ 80.00 <i>+</i>
9	To remove and refix rear tail gate windscreen	\$ 120.00 <i>+</i>

680

Labour Total : \$ 2,550.00

Others

Other Description

No. Qty

Price (SGD)

Rear portion

1	1	Rear number plate <i>new</i>	\$ 45.00	+
2	10	Rear bumper clip <i>new</i>	\$ 65.00	30
3	6	Rear fender liner clips <i>new</i>	\$ 39.00	+
4	10	Rear end panel trim clip <i>new</i>	\$ 65.00	+
5	1	Reverse sensor (1 set) <i>Day 2</i>	\$ 440.00	200
6	1	Rear reverse camera <i>new</i>	\$ 280.00	+
7	1	Rear end panel insulation seal <i>2</i>	\$ 120.00	+
8	13	Tail gate inner trim board clip <i>new</i>	\$ 84.50	+
9	1	Tailgate windscreen sealant <i>new</i>	\$ 120.00	+
10	1	Tailgate windscreen solar film	\$ 200.00	+

230

Other Total: \$ 1,458.50

GRAND TOTAL: \$ 14,394.73

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN. **PARTS PRICES ARE SUBJECT TO CHANGES.**

Yours faithfully

Service Advisor

Suhaimi

HP : 9189 2617 Email - aceautosolution@gmail.com



APPROVER DETAILS

SURVEYOR : _____

CONTACT NO : _____

PART BY PART / LUMP SUM

Admin King.
4/5 28/08/19.

03 Days.

total: 4373.42

4/5: 3.5K

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Finalisation

Ace Auto Solution

Registration number : 53228991M
23 Kaki Bukit Ave 4, #04-01 (South Wing) Singapore 415933

INVOICE

To : FWD Singapore Pte Ltd
6 Temasek Boulevard, #18-01
Suntec Tower 4
SINGAPORE 038986

Invoice No: ACC-2015001
Invoice Date:

Vehicle No: SFA3366Z
Chassis No : KL1YA7589GK333512
Engine No: A14NET153650303

DESCRIPTION	AMOUNT SGD
-------------	---------------

Parts

No.	Qty.		Price (SGD)
<u>1</u>	1	CHEVROLET LETTERING	\$ 50.00
<u>2</u>	1	ORLANDO LETTERING	\$ 40.00
<u>3</u>	1	LS LETTERING	\$ 25.00
<u>4</u>	1	TURBO LETTERING	\$ 45.00
<u>5</u>	1	REAR BUMPER STEP PLATE	\$ 160.25
<u>6</u>	1	REAR BUMPER UPPER	\$ 1,567.00
<u>7</u>	1	REAR BUMPER LOWER	\$ 660.00
<u>8</u>	1	REAR BUMPER SILL PLATE(SILVER)	\$ 370.00
<u>9</u>	1	LHR BUMPER REFLECTOR	\$ 95.00
<u>10</u>	1	RHR BUMPER REFLECTOR	\$ 95.00
<u>11</u>	1	REAR REVERSE LIGHT AND BRAKE LIGHT	\$ 401.00
<u>12</u>	1	REAR BUMPER CENTRE GUIDE	\$ 120.00
<u>13</u>	1	RHR BUMPER GUIDE, OTR	\$ 60.00
<u>14</u>	1	LHR BUMPER GUIDE, OTR	\$ 60.00
<u>15</u>	1	REAR BUMPER LEFT CENTRE GUIDE, INR	\$ 50.00
<u>16</u>	1	REAR BUMPER RIGHT CENTRE GUIDE, INR	\$ 50.00

Total: \$ 3,848.25
Less 10%: \$ 384.83
Parts Total : \$ 3,463.43

Labour

No.		Price (SGD)
<u>1</u>	To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate and align repair / replacement parts. (\$200 PER DAY)	\$ 200.00
<u>2</u>	Carry out spray painting on accident affected area (\$200 PER PANEL)	\$ 400.00
<u>3</u>	To disconnect wire harness of electrical component to facilitate repairs, reconnect and check electrical function after repair	\$ 30.00
<u>4</u>	To remove and refix reverse sensor and conduct test	\$ 50.00

Labour Total : \$ 680.00


Other

<u>No.</u>			<u>Price (SGD)</u>
1	10	Rear bumper clip	\$ 30.00
2	1	Reverse sensor (1 set)	\$ 200.00

Other Total : \$ 230.00

Total : \$ 4,373.43
Less lump sum 20%: \$ 874.69
Grand Total: \$ 3,500.00

Yours Faithfully,


Suhaimi
Service Executive



Tel: 9189 2617 Fax: 6844 5185

Email : aceautosolution@gmail.com

E & O E

ALL CHEQUE PAYMENTS SHOULD BE CROSSED AND MADE PAYABLE TO "**ACE AUTO SOLUTION**".

PLEASE INDICATE THE INVOICE NO. ON THE REVERSE SIDE.

Please check and finalize with me this invoice