



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLL 7827E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Cost Price (\$)	Our Adjusted (\$)
	LABOUR				
	TO LABOUR CHARGE FOR KNOCKING OUT DENTS OF F/R FENDER AND F/R DOOR .		600.00	-	250.00
	TO RESPRAY F/R FENDER AND F/R DOOR .		600.00	-	500.00
			1,200.00	-	750.00
GRAND TOTAL			1,200.00	-	750.00
RECOMMENDED COST OF REPAIRS					750.00

Report Ref No. CC4/ASM19014986/Eps3q2

CHEN TSUE YEE

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.