

15/02/2011

INS. CASE OWNER:

Peter

CC 4 / AXA1901 4989

E of 22

LKK:

IDAC:

Surveyor:

Steve

DOI:

26/8/19

Date / Time:

26/8/19

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SCX 5A

Claim No.:

Samo 2496 / 122517

Name of Insured:

CHARL KERNAN Bin BAKERMAN

Policy No.:

6467673

Insured Tel No.:

HP:

Make / Model:

KERNAN

Excess Sec II :SS

D.O.A.:

23/8/19

Place of Accident:

DIE

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SLC 3731X

INSRS:
WSP:
Tel:
Liability:
RMKS:Raim
Car
bodyworksINSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/Time

SLC 3731X - X

SLC 5A - X

STAGE

DATE / PIC

3/10 - send LOI.

- Rec cor to TP (pending LOI)

- to seek mandate

2/11 - pending mandate approval

4/11 - offer \$7940 (pending acceptance)

24/2 - TP reject offer, propose \$8290, seek instruction

25/2 - Inform TP offer maintained

- Settle @ \$7940, DV send (pending DV)

27/2 - DV in, file pass ME to close

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

7 CPT 21/10/19

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Steve

Repair Cost:

US

SS 7000/-

(6 days)

Reduction: \$247.60 % 26

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No.:

27

If NO or B 28, Ass. Lia:

Repair Cost:

(WGS)

SS 7440.00

Loss of Rental (LOR):

SS

(days)

Loss of Use (LOU):

SS 450.00

(\$ 50 x 9 days)

Loss of Income (LOI):

SS

(\$ x days)

LOR only

LOU only

LOR + LOU

LOR + LO

[Tick only one]

GIA/LTA Search

SS

Medical:

SS

Disbursement:

SS

(e.g. Tow/ Independent)

Legal Cost

SS

Total:

SS

7440.00

Global Sum SS:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS

7440.00

Name 1:

Raim car bodyworks Pte Ltd

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

X GIA.

ASS. FILED BY:

Steve


REF:

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s Raam Car
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 6 days Res.: Yes or No
 Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLC 3731X Yr Regn: 05, 2016
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Mercedes-Benz 880 C.C. 1595
 Colour: Grey A/C: Insured / Std / NI / NA
 Sp. Reading: 65594 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: W00 2463422 J388785
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 205/55R16
 R: _____
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or
 Front Rear
 R/Bal. 5 mm R/Bal. 5 mm
 L/Bal. 5 mm L/Bal. 5 mm
 D.O.A. 23/8/19 D.O.I. 26/8/19
 Survey held at Raam Car
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

GIA report MR-92K

45 \$7000 - (Red - \$2427.60 / 26.1%)

* 6 repair days + 1 sunday + 1 PRS + 1 saturday = 9 days

Date/Time, File Pass to?

☐ : Prel. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Report Form 4:

Lump Sum / L.E.D.:

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Insp (\$

☐ : Weekend (\$

Survey Fee:

Transportation:

____ \$ + RS. ____ \$

Photos

Other:

10/31

CC4/ASM19014989/Eg63

Cecilia

利 汽 車 噴 漆 私 人 有 限 公 司
RAAIM CAR BODYWORKS PTE LTD

Blk 2 Kranji Loop #01-04 Singapore 739538

Tel: 6694 3197 Fax: 6694 3191

FINALIZATION FORM

ATTN TO: STEVE / LKK
Surveyor Name and Company

Date of Accident : 23-Aug-2019

BILL TO: AXA
TP Insurer

VEHICLE REG. NO.

TYPE OF CLAIM: TP

SLC3731X

Make / Model : B180 STYLE (R16 LED)

COST OF CLAIMS

Parts Cost / List : \$ 7,812.00

Supp. Parts : \$ 802.00

Special Nett : \$ 155.00

Total Parts : \$ 7,907.60

Total Labour : \$ 1,520.00

TOTAL REPAIR COST : \$ 9,427.60

Total Parts Cost/List :	\$	8,614.00
-------------------------	----	----------

Plus / Less : <u>10%</u>	\$	861.40
--------------------------	----	--------

Total :	\$	7,752.60
---------	----	----------

Lump Sum Discount : <u>20%</u>	\$	1,885.52
--------------------------------	----	----------

Lump Sum Amount:	\$	7,542.08
------------------	----	----------

Final Lump Sum Amount : \$ 7,500.00

No. of Repair Days: 6

Submitted by / Date : PAULO

Confirmed by / Date : _____

P- 6122.70
M- 155
L- 1720
Supp- 721.80
8719.50
L/S - 6975.60
= 7000

利汽車噴漆私人有限公司
RAAIM CAR BODYWORKS PTE LTD

Blk 2 Kranji Loop #01-04 Singapore 739538

Tel: 6694 3197 Fax: 6694 3191

Vehicle Reg. No.: **SLC3731X**
Vehicle Reg. Date: **12/5/2016**
Make / Model: **B180 STYLE (R16 LED)**
Engine No.: **.27091030912087.**
Chassis No.: **WDD2462422J388785**

Store (CLKK)

WHL Airin L

6 days

L/S

Roy AL

26/8/19, 12.00pm

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
1	1	Tail gate / DD		\$ 1,945.00		\$ 1,945.00
2	1	Tail gate lock / BT		\$ 292.00		\$ 292.00
3	1	Tail gate striker X		\$ 32.00		
4	2	Tail gate stay LH/RH X X		\$ 72.00		
5	1	Tail gate logo X		\$ 49.00		\$ 49.00
6	1	Tail gate emblem / NCC		\$ 83.00		\$ 83.00
7	1	Tail gate outer garnish chrome X		\$ 235.00		
8	1	Tail gate lamp LH/RH (LH) / CUT		\$ 890.00		\$ 445.00
9	1	Tailgate wiper motor X		\$ 265.00		
10	1	Tail gate weatherstrip / CR4		\$ 202.00		\$ 202.00
11	1	Tail gate inner board X		\$ 218.00		
12	1	Tail gate inner board Lamp X		\$ 55.00		
13	1	Tail gate inner handle X		\$ 85.00		
14	1set	Tailgate windscreen glass moulding / NCC		\$ 680.00		\$ 680.00
15	1	Tail lamp LH/RH (LH) / CUT		\$ 976.00		\$ 488.00
16	2	Tail lamp panel LH/RH X		\$ 410.00		
17	2	Plate Lamp LH/RH X		\$ 80.00		
18	1	Antenna sensor X				
19	1	Rear end panel outer / DD		\$ 1,004.00		\$ 1,004.00
20	1	Rear end panel inner X R		\$ 590.00		
21	1	Rear end panel garnish / CR4		\$ 382.00		\$ 382.00
22	1	Spare tyre well panel X		\$ 850.00		
23	1	Spare tyre board X		\$ 165.00		
24	1	Spare tyre bracket X				
25	1	Spare tyre insulator X		\$ 755.00		
26	1	Spare tyre tool tray X				
27	1	Rear bumper / DD		\$ 1,518.00		\$ 1,518.00
28	1	Rear bumper chrome garnish upper / CUT		\$ 245.00		\$ 245.00
29	1	Rear bumper chrome garnish lower / CRA		\$ 211.00		\$ 211.00
30	1set	Rear bumper clips / NCC		\$ 30.00		\$ 30.00
31	2	Rear bumper side retainer LH/RH / GR		\$ 50.00		\$ 50.00
32	2	Rear bumper bracket LH/RH X		\$ 112.00		
33	2	Rear fender LH/RH X		\$ 4,640.00		
34	2	Rear fender air duct LH/RH X		\$ 78.00		
35	1	Rear tow hook cover X		\$ 47.00		
36	1	Exhaust muffler X		\$ 1,180.00		
37	1Set	Exhaust muffler mounting X		\$ 74.00		
38	1	Exhaust heat shield X		\$ 132.00		
39	1SET	Reverse sensor (IPC) Short		\$ 188.00		\$ 188.00
40	1	Reverse Camera X		\$ 1,535.00		

1790

181

181

181

181

181

181

181

181

181

181

181

181

181

181

181

181

181

181

181

6893

- 10%
6122.70

利 汎 車 噴 漆 有 限 公 司
RAAIM CAR BODYWORKS PTE LTD

Blk 2 Kranji Loop #01-04 Singapore 739538

Tel: 6694 3197 Fax: 6694 3191

Vehicle Reg. No. : SLC3731X
Vehicle Reg. Date: 12/5/2016
Make / Model : B180 STYLE (R16 LED)
Engine No. : .27091030912087.
Chassis No. : WDD246242J388785

PAGE 2

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
41	1	Spare tyre panel sealant X			N/N	
42	1	Spare tyre sound damper X			N/N	
43	1	Sundries / NPC			\$ 30.00	/
44	1	Tail gate seal / NPC			\$ 30.00	/
45	1	Rear number plate with frame / CWT			\$ 35.00	/
46	1	Rear windscreen glass sealant / NPC			\$ 40.00	/
47	1	Rear windscreen glass primer & cleaner / NPC			\$ 20.00	/
48	1	Rear end panel sealant X			N/N	
49	0	0				
50	0	0				
51	0	0				
52	0	0				
53	0	0				
54	0	0				
55	0	0				
56	0	0				
57	0	0				
58	0	0				
59	0	0				
60	0	0				
61	0	0				
62	0	0				
63	0	0				
64	0	0				
65	0	0				
66	0	0				
67	0	0				
68	0	0				
69	0	0				
70	0	0				
71	0	0				
72	0	0				
73	0	0				
74	0	0				
75	0	0				
76	0	0				
77	0	0				
78	0	0				
79	0	0				
80	0	0				

\$ 155.00 /

Tel: 6694 3197 Fax: 6694 3191

PAGE 1

[illegible]

24166.304

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Date:

利 浣 車 噴 漆 有 限 公 司
RAAIM CAR BODYWORKS PTE LTD

Blk 2 Kranji Loop #01-04 Singapore 739538

Tel: 6694 3197 Fax: 6694 3191

Vehicle Reg. No.: SLC3731X
Vehicle Reg. Date: 12/5/2016
Make / Model: B180 STYLE (R16 LED)
Engine No.: .27091030912087.
Chassis No.: WDD246242J388785

PAGE 1

Supplementary Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
1	1	REAR BUMPER REINFORCEMENT / <i>DD</i>		\$ 480.00		\$ 480.00
2	1	REAR BUMPER LOWER (BLACK) / <i>CRU</i>		\$ 167.00		\$ 167.00
3	1	REAR BUMPER CENTER BRACKET / <i>CRU</i>		\$ 155.00		\$ 155.00
4						
5						
6						
7						
8						
9						
10						
11						
12						
13						
14						
15						
16						
17						
18						
19						
20						
21						
22						
23						
24						
25						
26						
27						
28						
29						
30						

802
-10%
721.80

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

利汽车喷漆私人有限公司
RAAIM CAR BODYWORKS PTE LTD

Raaim Car Bodyworks Pte Ltd (Co.Reg. No: 201327842N)
Blk 2 Kranji Loop #01-04 Singapore 739538
Tel: 6694 3197 Fax: 6694 3191

SLC3731X

ACCIDENT REPAIR ESTIMATE

TP INSURER : AXA
OWN INSURER : NTUC
CLAIM TYPE : TP
Date of Accident : 23/8/2019

Vehicle Reg. No. : SLC3731X
Vehicle Reg. Date :
Make / Model : MERCEDES. B180
Engine No. :
Chassis No. : WDD2462422J388785

Resurvey Steve
27/8/19

COST OF CLAIMS

Parts Cost / List Items : \$ -
Plus/Less 10% \$ -
Total Cost / List : \$ -
Special Nett Items : \$ 820.00
Total Parts Amount : \$ 820.00
Total Labour Amount : \$ 4,970.00
Gross Total : \$ 5,790.00
GST % : 7% \$ 405.30
Nett Amount : \$ 6,195.30

Surveyor Name and Company :

Date of survey :
Part by Part / Lump Sum : days
Resurvey Before Paint / After Paint
Authorize/Not Authorize/Without Prejudice
Email :
Fax No :
HP No :

This claim is handled by : PAULO

6/5/19/8/19

利汽车喷漆私人有限公司 RAAIM CAR BODYWORKS PTE LTD

Blk 2 Kranji Loop #01-04 Singapore 739538

Tel: 6694 3197 Fax: 6694 3191

Vehicle Reg. No.: **SLC3731X**
Vehicle Reg. Date: **0/1/1900**
Make / Model: **MERCEDES. B180**
Engine No.: **0**
Chassis No.: **WDD2462422J388785**

Steve (LKK)
5311 5513
Steve@lkk.com

WHL MKL 26/8/19, 12.00pm
6 \$ days
L/S
Ry AG
PAGE 1

Steve 27/8/19

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
1	1	Tail gate / DD				
2	1	Tail gate lock / BT				
3	1	Tail gate striker X				
4	2	Tail gate stay LH/RH X				
5	1	Tail gate logo / APC				
6	1	Tail gate emblem / APC				
7	1	Tail gate outer garnish chrome X				
8	1	Tail gate lamp LH/RH (LH) / CUT				
9	2	Tailgate wiper motor X				
10	1	Tail gate weatherstrip / CR4				
11	1	Tail gate inner board ? X				
12	1	Tail gate inner board Lamp X				
13	1	Tail gate inner handle X				
14	1set	Tailgate windscreen glass moulding / APC				
15	2	Tail lamp LH/RH (LH) / CUT				
16	2	Tail lamp panel LH/RH X				
17	2	Plate Lamp LH/RH X				
18	1	Antenna sensor ? X				
19	1	Rear end panel outer X R / DD				
20	1	Rear end panel inner X R				
21	1	Rear end panel garnish ? / CR4				
22	1	Spare tyre well panel X				
23	1	Spare tyre board X				
24	1	Spare tyre bracket X				
25	1	Spare tyre insulator X				
26	1	Spare tyre tool tray X				
27	1	Rear bumper / DD				
28	1	Rear bumper chrome garnish upper / CUT				
29	1	Rear bumper chrome garnish lower / CR4				
30	1set	Rear bumper clips / APC				
31	2	Rear bumper side retainer LH/RH / BR				
32	2	Rear bumper bracket LH/RH ? X				
33	2	Rear fender LH/RH X				
34	2	Rear fender air duct LH/RH X				
35	1	Rear tow hook cover X				
36	1	Exhaust muffler X				
37	1Set	Exhaust muffler mounting X				
38	1	Exhaust heat shield X				
39	1SET	Reverse sensor (1pc) SHH				
40	1	Reverse Camera X				

利汽车喷漆私人有限公司
RAAIM CAR BODYWORKS PTE LTD

Blk 2 Kranji Loop #01-04 Singapore 739538

Tel: 6694 3197 Fax: 6694 3191

Vehicle Reg. No. : SLC3731X
Vehicle Reg. Date: 0/1/1900
Make / Model : MERCEDES. B180
Engine No. : 0
Chassis No. : WDD2462422J388785

PAGE 2

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
41	1	Spare tyre panel sealant X			\$ 100.00	
42	1	Spare tyre sound damper X			\$ 250.00	
43	1	Sundries / N/C			\$ 60.00	30
44	1	Tail gate seal / N/C			\$ 100.00	30
45	1	Rear number plate with frame / (1/1)			\$ 50.00	35
46	1	Rear windscreen glass sealant / N/C			\$ 100.00	40
47	1	Rear windscreen glass primer & cleaner / N/C			\$ 60.00	20
48	1	Rear end panel sealant X			\$ 100.00	
49	0	0				
50	0	0				
51	0	0				
52	0	0				
53	0	0				
54	0	0				
55	0	0				
56	0	0				
57	0	0				
58	0	0				
59	0	0				
60	0	0				
61	0	0				
62	0	0				
63	0	0				
64	0	0				
65	0	0				
66	0	0				
67	0	0				
68	0	0				
69	0	0				
70	0	0				
71	0	0				
72	0	0				
73	0	0				
74	0	0				
75	0	0				
76	0	0				
77	0	0				
78	0	0				
79	0	0				
80	0	0				

\$ 820.00

Tel: 6694 3197 Fax: 6694 3191

PAGE 1

[illegible]

2

利 汽 车 喷 漆 有 限 公 司
RAAIM CAR BODYWORKS PTE LTD

Blk 2 Kranji Loop #01-04 Singapore 739538

Tel: 6694 3197 Fax: 6694 3191

Vehicle Reg. No. : **SLC3731X**
Vehicle Reg. Date: **12/5/2016**
Make / Model : **B180 STYLE (R16 LED)**
Engine No. : **.27091030912087.**
Chassis No. : **WDD2462422J388785**

Steve 27/5/19

PAGE 1

Supplementary Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
1	1	REAR BUMPER REINFORCEMENT / <i>CR4</i>				
2	1	REAR BUMPER LOWER (BLACK) / <i>CR4</i>				
3	1	REAR BUMPER CENTER BRACKET / <i>CR4</i>				
4						
5						
6						
7						
8						
9						
10						
11						
12						
13						
14						
15						
16						
17						
18						
19						
20						
21						
22						
23						
24						
25						
26						
27						
28						
29						
30						

利汽车喷漆私人有限公司
RAAIM CAR BODYWORKS PTE LTD

SLC3731X

Raaim Car Bodyworks Pte Ltd (Co.Reg. No: 201327842N)
Blk 2 Kranji Loop #01-04 Singapore 739538
Tel: 6694 3197 Fax: 6694 3191

ACCIDENT REPAIR ESTIMATE

TP INSURER : AXA
OWN INSURER : NTUC
CLAIM TYPE : TP
Date of Accident : 23/8/2019

Vehicle Reg. No. : SLC3731X
Vehicle Reg. Date:
Make / Model : MERCEDES. B180
Engine No. :
Chassis No. : WDD2462422J388785

COST OF CLAIMS

Parts Cost / List Items : \$ -
Plus/Less 10% \$ -
Total Cost / List : \$ -
Special Nett Items : \$ 820.00
Total Parts Amount : \$ 820.00
Total Labour Amount : \$ 4,970.00
Gross Total : \$ 5,790.00
GST % : 7% \$ 405.30
Nett Amount : \$ 6,195.30

Surveyor Name and Company :

Date of survey :
Part by Part / Lump Sum : days
Resurvey Before Paint / After Paint
Authorize/Not Authorize/Without Prejudice
Email :
Fax No :
HP No :

This claim is handled by : PAULO

利汽车喷漆私人有限公司 RAAIM CAR BODYWORKS PTE LTD

Blk 2 Kranji Loop #01-04 Singapore 739538

Tel: 6694 3197 Fax: 6694 3191

Vehicle Reg. No.: **SLC3731X**
Vehicle Reg. Date: **0/1/1900**
Make / Model: **MERCEDES. B180**
Engine No.: **0**
Chassis No.: **WDD2462422J388785**

Steve (LKK)
8377 8813
Steve.lm@lkkarb.com

HL ML 26/8/19, 12-03pm
5 days
L/S
Ry AC
PAGE 1

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
1	1	Tail gate / <i>DD</i>				
2	1	Tail gate lock / <i>DT</i>				
3	1	Tail gate striker X				
4	2	Tail gate stay LH/RH X				
5	1	Tail gate logo / <i>ML</i>				
6	1	Tail gate emblem / <i>ML</i>				
7	1	Tail gate outer garnish chrome X				
8	1	Tail gate lamp LH/RH (LH) / <i>CUT</i>				
9	2	Tailgate wiper motor X				
10	1	Tail gate weatherstrip / <i>CR4</i>				
11	1	Tail gate inner board ?				
12	1	Tail gate inner board Lamp X				
13	1	Tail gate inner handle X				
14	1set	Tailgate windscreen glass moulding / <i>ML</i>				
15	2	Tail lamp LH/RH (LH) / <i>CUT</i>				
16	2	Tail lamp panel LH/RH X				
17	2	Plate Lamp LH/RH X				
18	1	Antenna sensor ?				
19	1	Rear end panel outer X R				
20	1	Rear end panel inner X R				
21	1	Rear end panel garnish ?				
22	1	Spare tyre well panel X				
23	1	Spare tyre board X				
24	1	Spare tyre bracket X				
25	1	Spare tyre insulator X				
26	1	Spare tyre tool tray X				
27	1	Rear bumper / <i>DD</i>				
28	1	Rear bumper chrome garnish upper / <i>CUT</i>				
29	1	Rear bumper chrome garnish lower / <i>CRA</i>				
30	1set	Rear bumper clips / <i>ML</i>				
31	2	Rear bumper side retainer LH/RH / <i>BR</i>				
32	2	Rear bumper bracket LH/RH ?				
33	2	Rear fender LH/RH X				
34	2	Rear fender air duct LH/RH X				
35	1	Rear tow hook cover X				
36	1	Exhaust muffler X				
37	1Set	Exhaust muffler mounting X				
38	1	Exhaust heat shield X				
39	1SET	Reverse sensor (1pc) <i>shot</i>				
40	1	Reverse Camera X				

利汽车喷漆私人有限公司
RAAIM CAR BODYWORKS PTE LTD

Blk 2 Kranji Loop #01-04 Singapore 739538

Tel: 6694 3197 Fax: 6694 3191

Vehicle Reg. No. : SLC3731X
Vehicle Reg. Date: 0/1/1900
Make / Model : MERCEDES. B180
Engine No. : 0
Chassis No. : WDD2462422J388785

PAGE 2

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
41	1	Spare tyre panel sealant X			\$ 100.00	
42	1	Spare tyre sound damper X			\$ 250.00	
43	1	Sundries / MC			\$ 60.00	30
44	1	Tail gate seal / MC			\$ 100.00	30
45	1	Rear number plate with frame / (1/1)			\$ 50.00	35
46	1	Rear windscreen glass sealant / MC			\$ 100.00	40
47	1	Rear windscreen glass primer & cleaner / MC			\$ 60.00	20
48	1	Rear end panel sealant X			\$ 100.00	
49	0	0				
50	0	0				
51	0	0				
52	0	0				
53	0	0				
54	0	0				
55	0	0				
56	0	0				
57	0	0				
58	0	0				
59	0	0				
60	0	0				
61	0	0				
62	0	0				
63	0	0				
64	0	0				
65	0	0				
66	0	0				
67	0	0				
68	0	0				
69	0	0				
70	0	0				
71	0	0				
72	0	0				
73	0	0				
74	0	0				
75	0	0				
76	0	0				
77	0	0				
78	0	0				
79	0	0				
80	0	0				

\$ 820.00

Tel: 6694 3197 Fax: 6694 3191

PAGE 1

[illegible]

1

Date:



Service Request Details

Claim

S9M01Y9G

Reference

None 

Loss Date

August 23, 2019

Report Date

Aug 26, 2019 9:10:58 AM

Request Date

August 26, 2019

Due Date

September 2, 2019

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

P. Charlie

T: 9-289.m

V: Out

E: ✓

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

SLC3731X



MODEL

B180

Service Address

...

Primary Contact/Insured

BIN ZULKERNAIN KHAIRIL KERNAIN

5 JALAN KANDIS, #04-127 STRAITS GARDENS, 757694, Singapore

CSE@IPS-ONLINE.COM.SG

Claim Handler

WANG Peter

peter.wang@axa.com.sg

Additional Instructions

2

Messages

Invoices

History

Documents

Assessment

Metrics

Notes

[New Message](#)

Catherine Chong (LKK Auto)

From: juan paulo baldoz <paulovermogenace@gmail.com>
Sent: Saturday, 24 August, 2019 12:21 PM
To: SG AXA Insurance SM AXA SGP - Motor Survey
Subject: [EXTERNAL] Accident involving vehicle SLC3731X & SCX5A (Your Insured) DOA :
23/08/2019 - PLEASE ARRANGE TP SURVEY
Attachments: WhatsApp Image 2019-08-24 at 12.04.11.jpeg; WhatsApp Image 2019-08-24 at
12.04.00.jpeg; WhatsApp Image 2019-08-24 at 12.04.21.jpeg
Categories: Raghav

Dear officer-in-charge,

Refer to above attachment kindly arrange our client's vehicle for the pre-repair survey at **Raaim Car Bodyworks Pte Ltd** here at **60 Jalan Lam Huat #03-35/36 Singapore 737869**.

Besides, we would like to check for the liability on this matter.

Kindly check & revert to us as soon as possible.

Thanks & regards,

Charlie
Raaim Car Bodyworks Pte Ltd

1 Bukit Batok Crescent

#05-23 Wcega Plaza

Singapore 658064

Tel: 9128 8559

Fax: 6694 4929

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 397D

Vehicle Details

Vehicle No.: SLC3731X
Vehicle to be Exported: No
Intended Deregistration Date: 27 Aug 2019
Vehicle Make: MERCEDES BENZ
Vehicle Model: B180 STYLE (R16 LED)
Primary Colour: Grey
Manufacturing Year: 2016
Engine No.: 27091030912087
Chassis No.: WDD2462422J388785
Maximum Power Output: 90.0 kW (120 bhp)
Open Market Value: \$26,179.00
Original Registration Date: 12 May 2016
First Registration Date: 12 May 2016
Transfer Count: 0
Actual ARF Paid: \$23,651.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 11 May 2026
PARF Rebate Amount: \$17,738.00

Intended COE Rebate Details

COE Expiry Date: 11 May 2026
COE Category: A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$45,504.00
COE Rebate Amount: \$30,508.00
Total Rebate Amount: \$48,246.00

The information contained herein is correct as at 27 Aug 2019

OK

MR- 92K



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 02/11/2019

Survey Details:

Date of loss	23-Aug-19
Date of appointment	26-Aug-19
Date of survey	26-Aug-19
Location of survey	RAAIM CAR BODYWORKS PTE LTD

Vehicle Details:

Claim Type:	Third party
Vehicle number	SLL 7827E
Make and Model	MERCEDES BENZ B180
Date of registration	12/5/2016
Excess	
Market Value	\$92,000
Parf Rebate	\$48,246
Nett Loss	\$43,754

Repair details:

Initial Estimate	\$ 9,427.60
------------------	-------------

Proposed/Revised repair cost:

Parts	\$ 6,999.50
Check items (estimate)	\$ -
Labour	\$ 1,720.00
Total	\$ 8,719.50
Lump Sum(if applicable)	\$ 7,000.00
Number of days for repair	6



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Remarks:

06 RECOMMENDED REPAIR DAYS + 1 SUNDAY + 1 SATURDAY +
1 PRS = 9 DAYS

Mandate:

Liability(TP)		100%
Proposed repair cost	\$	7,490.00
Loss of use	\$	540.00
Loss of rental	\$	-
Loss of income	\$	-
LTA search fees	\$	-
Others	\$	-
Proposed Total	\$	8,030.00



<MANDATE IA> - S9M01Y9G {ACCIDENT INVOLVING SCX 5A (OI) & SLC 3731X (TP) ON 23/08/2019}

Type

🔗 Question

Message

LIABILITY: 100% BOLA S27-INFORMED OI ABOUT TP CLAIM AND NCD ISSUE. AGREED TO SETTLE AT BEST. WE SEEK YOUR MANDATE AT \$8,030.00 (CLAIMING LOU). MANDATE IA HAS BEEN UPLOADED IN SMARTCLAIM. KINDLY LET US HAVE YOUR APPROVAL/INSTRUCTION. THANKS - CCL

Reply

利汽车喷漆私人有限公司
RAAIM CAR BODYWORKS PTE LTD

Blk 2 Kranji Loop #01-04 Singapore 739538

Tel: 6694 3197 Fax: 6694 3191

CO. REG NO.:201327842N

Tax Invoice: 190007

AXA INSURANCE SINGAPORE PTE LTD

8 Shenton Way

#27-01/02 AXA Tower

SINGAPORE 068811

Tel: +65 6880 4741 Fax: +65 6880 4838

Bill Date: 10-09-19

Vehicle No: SLC3731X

Vehicle Model: MERCEDES BENZ

Date of Accident: 23-08-19

Claim No:

Attn: Motor Claims Dept

S/N	QTY	Descriptions	Unit Price	Amount S\$
1		Lumpsum repair		7000.00

E. & O.E.

Total	S\$	7000.00
GST 7%	S\$	490.00
Amount Due	S\$	7490.00

for Raaime Bodyworks Pte Ltd



Pls proceed DS with quantum as revised below

Type

🔗 Question

Message

COR: \$7490 (as proposed); LOU: \$450 (\$50/day for 9 days). Total: \$7940

Reply



Pls maintain my earlier offer

Type

🔗 Question

Message

LTA search shows that TP vehicle is 1600CC instead of 1800CC. Pls maintain my earlier offer with LOU at \$50/day.

Reply

利 汽 車 噴 漆 私 人 有 限 公 司
RAAIM CAR BODYWORKS PTE LTD

Blk 2 Kranji Loop #01-04 Singapore 739538

Tel: 6694 3197 Fax: 6694 3191

CO. REG NO.:201327842N

Yr Ref : SCX5A

Our Ref : SLC3731X

10 September 2019

Without Prejudice

Attn: Motor Claim Dept

AXA INSURANCE SINGAPORE PTE LTD

8 Shenton Way

#27-01/02 AXA Tower

SINGAPORE 068811

Dear Sir/Mdm,

Accident involving SLC3731X & SCX5A on 23/08/2019 16:00 hrs at along PIE CLOSE TO TOA PAYOH

We refer to the above said accident.

As instructed, we are claiming the following as stated below:-

1. Repair cost	\$	7,490.00
2. Loss of usage (\$200 x 9 days)	\$	1,800.00
Total	\$	9,290.00

We enclosed herewith relevant document as stated below:-

1. Accident report
2. Final Repair Bill
3. Letter of authority

We do not have the survey report and photographs as our client's motor vehicle was surveyed by your appointed surveyor.

Please kindly let us know whether you are prepared to settle our client's claim & we look forward to hear from you soonest.

Thank you.

Best Regards,

Charlie Toh (Claim dept)

Raaim Car Bodyworks Pte Ltd

Tel : 9128 8559 Fax: 6694 3191

Email: raaim.carbw@gmail.com



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD		Ref : CC4/ASM19014989/Ega3s2		
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN: PETER WANG		Date : 03-03-2020 Code : ASM		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SCX 5A	Veh. Inspected	SLC 3731X	
Policy No.	GA426273	Coverage (\$)	0.00	
Claim No.	S9M01Y9G	Excess (\$)	0.00	
Assign From	PETER WANG	Assign Date	26/08/2019	
2. Vehicle Particulars & Condition				
Make & Model	MERCEDES BENZ B180	c.c	1595	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	WDD2462422J388785	Colour	GREY	
Odometer	65594	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/55 R16	MICHELIN	5 mm	
L/H Front Tyre	205/55 R16	MICHELIN	5 mm	
R/H Rear Tyre	205/55 R16	MICHELIN	5 mm	
L/H Rear Tyre	205/55 R16	MICHELIN	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	23/08/2019	Inspection Date	26/08/2019	
Survey held at	RAAIM CAR BODYWORKS PTE LTD 2 KRANJI LOOP #01-04 SINGAPORE 739538			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLC 3731X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	TAIL GATE (CONSISTENT)	DENTED	1,945.00	1,790.00
1	TAIL GATE LOCK (CONSISTENT)	BENT	292.00	181.00
1	TAIL GATE STRIKER (CONSISTENT)	NOT NECESSARY	32.00	-
2	TAIL GATE STAY LH/RH (CONSISTENT)	NOT NECESSARY	72.00	-
1	TAIL GATE LOGO (CONSISTENT)	NECESSARY	49.00	49.00
1	TAIL GATE EMBLEM (CONSISTENT)	NECESSARY	83.00	83.00
1	TAIL GATE OUTER GARNISH CHROME (CONSISTENT)	NOT NECESSARY	235.00	-
2	TAIL GATE LAMP LH/RH (CONSISTENT)	N/S CUT	890.00	445.00
1	TAILGATE WIPER MOTOR (CONSISTENT)	NOT NECESSARY	265.00	-
1	TAIL GATE WEATHERSTRIP (CONSISTENT)	CRUSHED	202.00	202.00
1	TAIL GATE INNER BOARD (CONSISTENT)	NOT NECESSARY	218.00	-
1	TAIL GATE INNER BOARD LAMP (CONSISTENT)	NOT NECESSARY	55.00	-
1	TAIL GATE INNER HANDLE (CONSISTENT)	NOT NECESSARY	85.00	-
1	SET TAIL GATE WINDSCREEN GLASS MOULDING (CONSISTENT)	NECESSARY	680.00	210.00
2	TAIL LAMP LH/RH (CONSISTENT)	N/S CUT	976.00	488.00
2	TAIL LAMP PANEL LH.RH (CONSISTENT)	NOT NECESSARY	410.00	-
2	PLATE LAMP LH/RH (CONSISTENT)	NOT NECESSARY	80.00	-
1	ANTENNA SENSOR (NPA) (CONSISTENT)	NOT NECESSARY	-	-
1	REAR END PANEL OUTER (CONSISTENT)	DENTED	1,004.00	820.00
1	REAR END PANEL INNER (CONSISTENT)	TO REPAIR SEE LABOUR	590.00	-
1	REAR END PANEL GARNISH (CONSISTENT)	CRUSHED	382.00	382.00
1	SPARE TYRE WELL PANEL (CONSISTENT)	NOT NECESSARY	850.00	-
1	SPARE TYRE BOARD (CONSISTENT)	NOT NECESSARY	165.00	-
1	SPARE TYRE BRACKET (NPA) (CONSISTENT)	NOT NECESSARY	-	-
1	SPARE TYRE INSULATOR (CONSISTENT)	NOT NECESSARY	755.00	-
1	SPARE TYRE TOOL TRAY (NPA) (CONSISTENT)	NOT NECESSARY	-	-
1	REAR BUMPER (CONSISTENT)	DENTED	1,518.00	1,429.00
1	REAR BUMPER CHROME GARNISH UPPER (CONSISTENT)	CUT	245.00	245.00

Report Ref No. CC4/ASM19014989/Ega3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR BUMPER CHROME GARNISH LOWER (CONSISTENT)	CRACKED	211.00	211.00
2	REAR BUMPER SIDE RETAINER LH/RH (CONSISTENT)	BROKEN	50.00	50.00
2	REAR BUMPER BRACKET LH/RH (CONSISTENT)	NOT NECESSARY	112.00	-
2	REAR FENDER LH/RH (CONSISTENT)	NOT NECESSARY	4,640.00	-
2	REAR FENDER AIR DUCT LH/RH (CONSISTENT)	NOT NECESSARY	78.00	-
1	REAR TOW HOOK COVER (CONSISTENT)	NOT NECESSARY	47.00	-
1	EXHAUST MUFFLER (CONSISTENT)	NOT NECESSARY	1,180.00	-
1	SET EXHAUST MUFFLER MOUNTING (CONSISTENT)	NOT NECESSARY	74.00	-
1	EXHAUST HEAT SHIELD (CONSISTENT)	NOT NECESSARY	132.00	-
1	REVERSE SENSOR (CONSISTENT)	SHORTED	188.00	188.00
1	REVERSE CAMERA (CONSISTENT)	NOT NECESSARY	1,535.00	-
1	REAR BUMPER REINFORCEMENT (CONSISTENT) (ADDITIONAL)	DENTED	480.00	480.00
1	REAR BUMPER LOWER (BLACK) (CONSISTENT) (ADDITIONAL)	CRUSHED	167.00	167.00
1	REAR BUMPER CENTER BRACKET (CONSISTENT) (ADDITIONAL)	CRUSHED	155.00	155.00
1	SET REAR BUMPER CLIPS (CONSISTENT)	NECESSARY	30.00	30.00
	LESS 10% DISCOUNT		-2,115.70	-760.50
			19,041.30	6,844.50
SPECIAL NETT ITEMS				
1	SPARE TYRE PANEL SEALANT (NPA) (SN) (CONSISTENT)	NOT NECESSARY	-	-
1	SPARE TYRE SOUND DAMPER (NPA) (SN) (CONSISTENT)	NOT NECESSARY	-	-
1	SUNDRIES (SN) (CONSISTENT)	NECESSARY	30.00	30.00
1	TAIL GATE SEAL (SN) (CONSISTENT)	NECESSARY	30.00	30.00
1	REAR NUMBER PLATE WITH FRAME (SN) (CONSISTENT)	CUT	35.00	35.00
1	REAR WINDSCREEN GLASS SEALANT (SN) (CONSISTENT)	NECESSARY	40.00	40.00
1	REAR WINDSCREEN GLASS PRIMER & CLEANER (SN) (CONSISTENT)	NECESSARY	20.00	20.00
1	REAR END PANEL SEALANT (NPA) (SN) (CONSISTENT)	NOT NECESSARY	-	-
			155.00	155.00

Report Ref No. CC4/ASM19014989/Ega3s2

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	TO REMOVE AND REPLACE DAMAGED PARTS AND TO PANEL BEATING ACCIDENT AREA. TAILGATE, REAR BUMPER, REAR END PANEL, SPARE TYRE PANEL REAR FENDER LH/RH. INCLUSIVE OF THE REPAIR OF REAR END PANEL INNER.		2,000.00	750.00
	TO REMOVE AND REPLACE REVERSE SENSOR.		150.00	30.00
	TO REMOVE AND REFIT INNER TRIM, INNER SEAT, TRIM BOARD, TO ASSIST REPAIR.		180.00	30.00
	TO RUSTPROOF ACCIDENT REPAIR AREA.		150.00	30.00
	TO TRANSFER TAILGATE MECHANISM TO NEW TAILGATE.		180.00	50.00
	TO CHECK AND RECTIFY WIRING AFTER DISCONNECT AND CONNECT.		150.00	30.00
	TO REMOVE AND REFIT REAR WINDSCREEN.		180.00	100.00
	TO REMOVE & REFIT EXHAUST MUFFLER.	NOT NECESSARY	180.00	-
	TO PUTTY AND RESPRAY REPLACED PARTS AND ACCIDENT REPAIR AREA.		1,800.00	700.00
			4,970.00	1,720.00
	GRAND TOTAL		24,166.30	8,719.50
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			7,000.00

Report Ref No. CC4/ASM19014989/Ega3s2

CHEN TSUE YEE

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.