

利汽车喷漆私人有限公司
RAAIM CAR BODYWORKS PTE LTD

SLC3731X

Raaim Car Bodyworks Pte Ltd (Co.Reg. No: 201327842N)
Blk 2 Kranji Loop #01-04 Singapore 739538
Tel: 6694 3197 Fax: 6694 3191

ACCIDENT REPAIR ESTIMATE

TP INSURER : AXA
OWN INSURER : NTUC
CLAIM TYPE : TP
Date of Accident : 23/8/2019

Vehicle Reg. No. : SLC3731X
Vehicle Reg. Date:
Make / Model : MERCEDES. B180
Engine No. :
Chassis No. : WDD2462422J388785

COST OF CLAIMS

Parts Cost / List Items : \$ -
Plus/Less 10% \$ -
Total Cost / List : \$ -
Special Nett Items : \$ 820.00
Total Parts Amount : \$ 820.00
Total Labour Amount : \$ 4,970.00
Gross Total : \$ 5,790.00
GST % : 7% \$ 405.30
Nett Amount : \$ 6,195.30

Surveyor Name and Company :

Date of survey :
Part by Part / Lump Sum : days
Resurvey Before Paint / After Paint
Authorize/Not Authorize/Without Prejudice
Email :
Fax No :
HP No :

This claim is handled by : PAULO

利汽车喷漆私人有限公司
RAAIM CAR BODYWORKS PTE LTD

Blk 2 Kranji Loop #01-04 Singapore 739538

Tel: 6694 3197 Fax: 6694 3191

Vehicle Reg. No.: **SLC3731X**
Vehicle Reg. Date: **0/1/1900**
Make / Model: **MERCEDES. B180**
Engine No.: **0**
Chassis No.: **WDD246242J388785**

Steve (LKK)
8377 8813
Steve.chm@lkkarb.com

WHL MR 26/8/19, 12.00pm
5 days
L/S
Ry AG sm
PAGE 1

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
1	1	Tail gate / DD				
2	1	Tail gate lock / BT				
3	1	Tail gate striker X				
4	2	Tail gate stay LH/RH X				
5	1	Tail gate logo / APC				
6	1	Tail gate emblem / APC				
7	1	Tail gate outer garnish chrome X				
8	1	Tail gate lamp LH/RH (LH) / CUT				
9	2	Tailgate wiper motor X				
10	1	Tail gate weatherstrip / CR4				
11	1	Tail gate inner board ?				
12	1	Tail gate inner board Lamp X				
13	1	Tail gate inner handle X				
14	1set	Tailgate windscreen glass moulding / APC				
15	2/1	Tail lamp LH/RH (LH) / CUT				
16	2	Tail lamp panel LH/RH X				
17	2	Plate Lamp LH/RH X				
18	1	Antenna sensor ?				
19	1	Rear end panel outer X R				
20	1	Rear end panel inner X R				
21	1	Rear end panel garnish ?				
22	1	Spare tyre well panel X				
23	1	Spare tyre board X				
24	1	Spare tyre bracket X				
25	1	Spare tyre insulator X				
26	1	Spare tyre tool tray X				
27	1	Rear bumper / DD				
28	1	Rear bumper chrome garnish upper / CUT				
29	1	Rear bumper chrome garnish lower / CRA				
30	1set	Rear bumper clips / APC				
31	2	Rear bumper side retainer LH/RH / BR				
32	2	Rear bumper bracket LH/RH ?				
33	2	Rear fender LH/RH X				
34	2	Rear fender air duct LH/RH X				
35	1	Rear tow hook cover X				
36	1	Exhaust muffler X				
37	1Set	Exhaust muffler mounting X				
38	1	Exhaust heat shield X				
39	1SET	Reverse sensor (1pc) sm				
40	1	Reverse Camera X				

利 汽 車 噴 漆 私 人 有 限 公 司
RAAIM CAR BODYWORKS PTE LTD

Blk 2 Kranji Loop #01-04 Singapore 739538

Tel: 6694 3197 Fax: 6694 3191

Vehicle Reg. No. : SLC3731X
Vehicle Reg. Date: 0/1/1900
Make / Model : MERCEDES. B180
Engine No. : 0
Chassis No. : WDD2462422J388785

PAGE 2

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
41	1	Spare tyre panel sealant X			\$ 100.00	
42	1	Spare tyre sound damper X			\$ 250.00	
43	1	Sundries / MC			\$ 60.00	30
44	1	Tail gate seal / MC			\$ 100.00	30
45	1	Rear number plate with frame / MC			\$ 50.00	35
46	1	Rear windscreen glass sealant / MC			\$ 100.00	40
47	1	Rear windscreen glass primer & cleaner / MC			\$ 60.00	20
48	1	Rear end panel sealant X			\$ 100.00	
49	0	0				
50	0	0				
51	0	0				
52	0	0				
53	0	0				
54	0	0				
55	0	0				
56	0	0				
57	0	0				
58	0	0				
59	0	0				
60	0	0				
61	0	0				
62	0	0				
63	0	0				
64	0	0				
65	0	0				
66	0	0				
67	0	0				
68	0	0				
69	0	0				
70	0	0				
71	0	0				
72	0	0				
73	0	0				
74	0	0				
75	0	0				
76	0	0				
77	0	0				
78	0	0				
79	0	0				
80	0	0				

\$ 820.00

Tel: 6694 3197 Fax: 6694 3191

PAGE 1

[illegible]

\$

Date: