

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD			Ref: CC4/ASM19015006/Kpa3q2	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:RICHARD ANG		Date: 29-04-2020 Code: ASM		
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SCY 6968B	Veh. Inspected	SGP 6876H
	Policy No.	VPA/P1990614	Coverage (\$)	0.00
	Claim No.	S9M01XZ2	Excess (\$)	0.00
	Assign From		Assign Date	26/08/2019
2. Vehicle Particulars & Condition				
	Make & Model	SUBARU FORESTER (A)	c.c	1995
	Engine No.	HIDDEN	Year of Reg.	2015
	Chassis No.	JF1SJ5KC5FG059631	Colour	METALLIC PEARL WHITE
	Odometer	79879	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	225/60 R17	YOKOHAMA	5 mm
	L/H Front Tyre	225/60 R17	YOKOHAMA	5 mm
	R/H Rear Tyre	225/60 R17	YOKOHAMA	5 mm
	L/H Rear Tyre	225/60 R17	YOKOHAMA	5 mm
4.	Description of Damages			
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.			
	DAMAGES SEE DETAILS.			
5.	General Information			
	Accident Date	21/08/2019	Inspection Date	09/09/2019
	Survey held at	LAI HUAT (MENG KEE) MOTOR PTE LTD 160 SIN MING DRIVE #04-01/02 SIN MING AUTOCITY SINGAPORE 575722		
5a.	Remarks			
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b.	Estimate Days of Repair			
	ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days			