

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/1007/2019/NS
Date : 22-Aug-19

Vehicle NOT IN workshop. Please arrange for survey

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : MR.KENNETH GUO WEI QIANG
Address : 2 MARINE VISTA
#11-75
Singapore 449026
Telephone : HP +65 85331681
Type of Claim : Own Damage Claim
Policy No. : 2100485644-02
Vehicle No : **SLG 8579 R**
Model Code : Audi Q5 SPORT 2.0 TFSI QU
Model / Year : 17/10/2016
Engine No : CNC 175871
Chassis No : WAUZZZ8R0HA036438
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 21-Aug-19
Place of Accident : UPPER CHANGI ROAD NORTH

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLG 8579 R

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and reinstall rear parking aid and rear lid kick sensor. Check function.	S/N \$ 360.00 ✓	
2	To dismantle and renew rear bumper assy. To inspect rhs tail lamp panel. Re-organise rear crash management components. Reinstall all parts removed.	\$ 1,200.00 500	
3	To respray rear upper bumper, rear lower bumper, and both rear wheel arch covers. ✓ X	\$ 2,500.00 1100	
4	To carry out diagnostic check.	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES		: \$ 4,252.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLG 8579 R

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	REAR BUMPER <i>Rehd</i>	\$ 1,513.00	✓
2	REAR BUMPER FIXING PARTS <i>Men</i>	\$ 150.00	+
3	REAR BUMPER GUIDE SECTION - RH REAR <i>Men</i>	\$ 49.00	+
4	REAR BUMPER SPOILER <i>Reps</i>	\$ 788.00	+
5	REAR BUMPER CARRIER <i>Men</i>	\$ 598.00	+
6	REAR BUMPER BRACKET HOLDER - RH <i>Men</i>	\$ 195.00	+
7	REAR PARKING AID SENSOR <i>Men</i>	\$ 210.00	+
8	TAIL LIGHT - RH <i>Canhd</i>	\$ 273.00	✓
9	REAR SILENCER - RH <i>Men</i>	\$ 910.00	+
10	REAR SILENCER DUAL CLIP	\$ 49.00	+
11	REAR SILENCER BRACKET - LH / RH <i>Men</i>	2 \$ 104.00	+
12	REAR WHEEL HOUSING LINER - RH <i>Men</i>	\$ 246.00	+
13	REAR WHEEL HOUSING LINER ATTACHMENT PARTS <i>Men</i>	\$ 94.00	+
14	SUNDRIES	\$ 300.00	+
TOTAL SPARE PARTS		\$ 5,479.00	
TOTAL LABOUR CHARGES		\$ 4,252.00	
GRAND TOTAL		\$ 9,731.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Ling
Surveyed Date : 26/08/19
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 08 Days.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant