

ASS. REC. BY:

REF:

CS/C7219015062/Vqf302

Special Instruction:

Surveyor: MarcusASSIGNMENT (Office)From (Person): Chong Boon Sen of CTZ Date/Time: 26/08/2019

Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

OD (TP) / WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: SLC 5406Y Insured: SMJ 5412Eat Workshop m/s Jin Auto Services Pte Ltd Tel: 6289 8126of Blk 14 Defu Lane 10 #01-410/412Policy No: DMPCSN1917119000Claim No: SNM19D203961-SMJ5412E-CBS

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

Make of Veh: \_\_\_\_\_ D.O.A. 23/08/2019  
(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement: \_\_\_\_\_

Date/Time: 26/08/2019 04:53pm Person Contacted: Jouis Vehicle: IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SMJ 5412E X
	SLC 5406Y: NBA/INC10010523/Y D.O.A. 07/06/2016
09/01/19 @ 11.51am	confirmed with Jouis final Arg & 1714.43, 3 days.
	cred & 1006.10, 37%)
	no lump sum.

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

# ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLC5400Yat Workshop m/s J. n. Ave.

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_

Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 60k

IDAC Accident Rpt: \_\_\_\_\_

Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_

Consistent? : Yes or No

Est. Repairs: 3 days

Res.: Yes or No

Lum Sum: 131 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

939M

Vehicle: IN / OUT

Date: \_\_\_\_\_

Person Contacted: \_\_\_\_\_

Veh No: SLC5400YYr Regn: 51 16Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or CA /Make: Honda Vezelc.c. 1496Colour: Blue

A/C: Insured / Std / NI / NA

Sp. Reading: 44006

T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: RU1115843Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: NI / S/Rim / STD A/Rim orTyre Size: F: 215/60 R16

R: \_\_\_\_\_

BS DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or

Front

6

mm

Rear

6

mm

R/Bal.

R/Bal.

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

29/8/19

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop orRear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

LTA 3802No second hand parts using coffee price.

RECEIVED 10 SEP 2019

Date/Time, File Pass to?

☐ : Preli. Report  
☐ : Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: 3Resurvey No. of Trip: 1Survey Fee: 220

Transportation: \_\_\_\_\_

Add Fee:

☐ : Site Insp (\$ \_\_\_\_\_)  
☐ : Interview (\$ \_\_\_\_\_)  
☐ : Tech. Invs (\$ \_\_\_\_\_)  
☐ : Weekend (\$ \_\_\_\_\_)

) S + RS, SI

) Photos

) Others

TOTAL

Report Format: MER-TPLump Sum / I.B.I. (\$) 1714.43220

## ...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	26 Aug 2019 Sendback Est	26 Aug 2019 15:45 S\$2,720.53	26 Aug 2019 16:41 Assign				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b>									
Insured:	WEE KUAN HOE, ID: S9230586D								
Main Claimant:	NG ZI YANG, ID: S8535939H								
Vehicle Reg. No.:	SLC5406Y	Date of Loss:	23/08/2019 00:00 - :59 [39 Months and 5 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM19D203961- SMJ5412E-CBS	Policy/Cover Note No.:	DMPCSN19177119000						
Vehicle Reg. No. (Insured):	SMJ5412E	Policy No. (Claimant):							
		Excess:	S\$0.00						
Repairer:	Jin Auto Services Pte Ltd (Defu) Blk 14 Defu Lane 10, #01-410/412, 539195 Defu Lane - Tel: 6289 8126								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 04/09/2019]								
Driver/Custodian (Insured):	WEE KUAN HOE ( / Male) , NRIC: S9230586D Email:								
<b>ASSOCIATED MAIL RECEIVED</b>									
<a href="#">View All</a> <a href="#">Compose Case Mail</a>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b>									
<a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Shiau Chan (LKKAUTO)

---

**From:** jouis <jouis@jinauto.com.sg>  
**Sent:** Monday, 9 September 2019 11:51 AM  
**To:** Shiau Chan (LKKAUTO)  
**Subject:** RE: TP VEHICLE SLC 5406Y (DOA: 23/08/2019) - FINALISE

Dear Shiau Chan

Ok confirm

Thank you & Best Regards,  
Jouis Seow  
Jin Auto Services Pte Ltd  
Blk 14 #01-412 Defu Lane 10  
Singapore 539195.

Tel : (65) 62898126  
Fax : (65) 62870590  
Email : [jouis@jinauto.com.sg](mailto:jouis@jinauto.com.sg)

---

**From:** Shiau Chan (LKKAUTO) [mailto:[siewsc@lkkauto.com](mailto:siewsc@lkkauto.com)]  
**Sent:** Monday, 9 September 2019 10:57 AM  
**To:** [jouis@jinauto.com.sg](mailto:jouis@jinauto.com.sg)  
**Subject:** RE: TP VEHICLE SLC 5406Y (DOA: 23/08/2019) - FINALISE

Dear Jouis,

As per your requested.

Best Regards,

**Shiau Chan (Ms)** | Case Handler  
**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Shiau Chan (LKKAUTO)  
**Sent:** Friday, 6 September 2019 3:51 PM  
**To:** [jouis@jinauto.com.sg](mailto:jouis@jinauto.com.sg)  
**Subject:** TP VEHICLE SLC 5406Y (DOA: 23/08/2019) - FINALISE

Dear Jouis,

WITHOUT PREJUDICE

Offer final fig \$1,714.43 before GST and 3 repair days.

Kindly confirm.

Best Regards,

**Shiau Chan (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [sjewsc@lkkauto.com](mailto:sjewsc@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type: Singapore NRIC  
Owner ID: 939H

### Vehicle Details

Vehicle No.: SLC5406Y  
Vehicle to be Exported: No  
Intended Deregistration Date: 30 Aug 2019  
Vehicle Make: HONDA  
Vehicle Model: VEZEL 1.5X A  
Primary Colour: Blue  
Manufacturing Year: 2016  
Engine No.: L15B4035848  
Chassis No.: RU11115843  
Maximum Power Output: 96.0 kW (128 bhp)  
Open Market Value: \$20,115.00  
Original Registration Date: 18 May 2016  
First Registration Date: 18 May 2016  
Transfer Count: 0  
Actual ARF Paid: \$10,161.00

### Intended PARF Rebate Details

PARF Eligibility: Yes  
PARF Eligibility Expiry Date: 17 May 2026  
PARF Rebate Amount: \$7,620.00

### Intended COE Rebate Details

COE Expiry Date: 17 May 2026  
COE Category: A - Car up to 1600cc & 97kW (130bhp)  
COE Period(Years): 10  
QP Paid: \$46,009.00  
COE Rebate Amount: \$30,882.00  
**Total Rebate Amount: \$38,502.00**

The information contained herein is correct as at 30 Aug 2019

OK

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

F



AVIVA

## Post an Advertisement

Sell it yourself! Advertise it at just

**\$58 until it's SOLD!**

Post an Ad

Advertiser Login

Ways of Selling



Vezel S90 1.5 Momentum 2.0 Turbocharged At 250Bhp

Cheng Guan Enterprise

2016 Honda Vezel 1.5 Momentum 2.0 Turbocharged At 250Bhp

Auto Zoom Enterprise



Browse by Category

« Back ( 1 2 3 4 5 6 7 ) Next »

Sort by Date Posted

132 vehicles

Vezel

Advanced Search

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	V
Search Selection	Vezel	Any	Any	2016	Any	Any	



## Honda Vezel 1.5A X

\$65,800

\$8,970 /yr

10-Jun-2016

1,496 cc

66,000 km

100% Quality Deal! 1 Owner! Genuine Low Mileage! 100% Accident Free. Road Tax Till 06/2020. High Loan Available! Trade In Welcome! Cheapest In Town! STA Welcome! Call Now For Viewing And Test Drive.

Posted: 30-Aug-2019 Tags: 2016 Honda Vezel, 2016 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda



## Honda Vezel 1.5A X

\$64,500

\$8,430 /yr

13-Sep-2016

1,496 cc

53,000 km

1 Owner, Non-Private Hire Car! Call To Book For Appointment.

Posted: 29-Aug-2019 Tags: 2016 Honda Vezel, 2016 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda



## Honda Vezel 1.5A X

\$65,800

\$8,480 /yr

14-Sep-2016

1,496 cc

20,111 km

Confirm The Only Unit In Market! Genuine Low Mileage Done 20111km Only! Serviced At Autobacs With Proof. Non Private Hire/Leasing Car. Lady Owner, Used For Ferrying Kids. Totally Like New, See To Certify. 100% Accident Free. In House Loan With Low Rates. Call No

Lake View Credit Pte Ltd

Posted: 29-Aug-2019 Tags: 2016 Honda Vezel, 2016 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda



## Honda Vezel 1.5A X

\$58,503

\$8,360 /yr

03-Feb-2016

1,496 cc

-

1 Owner Up To Date, Car Is Almost New Condition, Low Depreciation, High Loan, Bank Loan, In House Loan Are All Available Now! Trade In Are Welcome Too! Call Us Now For A Viewing!

Posted: 29-Aug-2019 Tags: 2016 Honda Vezel, 2016 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda

Car Buying

Car Selling

Car Ownership

Buy

Car Aftermarket

On The Move

Lifestyle



## Honda Vezel 1.5A X

\$62,688

\$8,530 /yr

30-May-2016

1,496 cc

43,000 km

Single Owner, Extremely Under Utilised Unit. Comes In Beautiful White With Black Leather Upholstery. The Paintwork Is Almost Flawless With No Stone Chips. Consignment Unit. High Loan And Trade In Available.

Posted: 29-Aug-2019 Tags: 2016 Honda Vezel, 2016 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda

Compare

1a Vezel 1.5A X Honda

\$68,888

\$8,560 /yr

29-Nov-2016

1,496 cc

39,022 km

**Jin Auto Services Pte Ltd**  
**#01-410/412, 14 Defu Lane 10**  
**539195**

**Insurer Reference: Ntuc Income**  
**Repairer Reference: SLC 5406Y(HondaVezel)**  
**Date calculated: 26/08/2019 3:39 PM**

**Full Report**  
**Registration: SLC 5406Y**  
**Printed: 26/08/2019 3:40 PM**

**Summary Information**

<b>Claim</b>			
Location:	Singapore (SG)	Work Provider:	China Taiping Insurance (Singapore) Pte Ltd
Printed by:	JOUIS SEOW	Currency:	SGD
Claim Reference:	Ntuc Income	Date of Incident:	23/08/19
Estimated Repair Time:	8	Hire Car Start:	
Actual Repair Days:		Hire Car End:	

**Vehicle Details**

<b>Vehicle</b>	
Manufacturer:	HONDA
Model:	VEZEL RU1/5
Sub Model:	LX
Model Sheet Number:	35 VE 08
Registration:	SLC 5406Y
VIN number:	RU1-1115843
Odometer:	43840
<b>Model Specs</b>	
TWO COAT METALLIC	PREPARE OFF VEHICLE

*not allowed*  
*2 hr*  
*29/8/19*  
*try L/S.*  
*3 hr*


**Vehicle Condition**

**Vehicle Status**

Pre-Accident Damage:  
Date of Inspection:

**Damage Areas**

**All** ☐  
**Underbody** ☐



**Labour**

**Time Base 10 WU/h**

**Price = 42.00 SGD/h**



**Jin Auto Services Pte Ltd**  
**#01-410/412, 14 Defu Lane 10**  
**539195**

**Insurer Reference: Ntuc Income**  
**Repairer Reference: SLC 5406Y(HondaVezel)**  
**Date calculated: 26/08/2019 3:39 PM**

**Full Report**  
**Registration: SLC 5406Y**  
**Printed: 26/08/2019 3:40 PM**

**Labour Cost - Paint**

	Hrs	WU	Price SGD
Factor	42.00 SGD/h		
Time Paint		62.0	
Preparation Main Work Metal	2.50	25.0	105.00
Preparation Comp. Work Plastic	0.80	8.0	33.60
<b>Total</b>	10 WU/h	95.0	399.00

**Material Cost - Paint**

	Price SGD
New Part Painting - Plastic K1G/PUR	37.80
Repair Painting	60.83
Material-constant Metal Preparation	28.60
Material-constant Plastic	12.70
<b>Total</b>	139.93

**Spare Parts**

				prices as at 2015-06-01/01	Price SGD
Code	Description	Part Number	Supplier		
2583	REAR BUMPER	71501T8NT50	20 —	120	170.00
2587	L/R BUMPER CORNER	71507T7JH00ZZ	12 X		65.00
2588	R/R BUMPER CORNER	71502T7JH00ZZ	12 X		65.00
2711	REAR PANEL	66100T8NT00ZZ	R X		270.00
2931	BOOTLID/TAILGATE	68100T8PU10ZZ	20/21 —	530	580.00
2944	BOOT/TAILGATE SEAL	74440T7A003	2w1/ —	45	45.00
2973	REAR LOCK STRIKER	74813T5A003	fm X		25.00
2977	BOOT/TAILGATE LOCK	74800T7AJ02	2w1 —	53	55.00
3017	BADGE MODEL	75722T7A003	SVC —		28.00
3161	LWR REAR SCREEN SEAL	73226SZW000	2w1 —	16	16 0.00
3163	REAR SCREEN FIX SET	USE SINGLE PARTS	11 X		
3165	UPP R-SCREEN SEAL	SEE GUIDE NO. 3161	11 X		
3167	L/R WINDOW SEAL	73254T7JH01	2w1 —	11	38.00
3168	R/R WINDOW SEAL	73214T7JH01	2w1 —	11	0.00
3170	CHECK	91502S70003	X		0.00
3171	CHECK	91501S70003	X		0.00
3173	CHECK	91536SS0J01	X		0.00
3295	L/R REFLECTOR	33555T7AJ01	11 X		40.00
3296	R/R REFLECTOR	33505T7AJ01	11 X		40.00
1000	SEALANT	SEALANT	2w1 —		25.00
1002	End Panel Sealant	End Panel Seal	2w1 X		45.00
1003	Reverse Sensor	Reverse Sensor	2w1 —		200.00
					0.00
					1,691.00
					100.00

f: OEM Parts  
n: Non-OEM Parts  
u: Used parts

**Savings**

**Subtotal**

**Fixed Sundry Parts Price**

2-838

# Jin Auto Services Pte Ltd

Blk 14 Defu Lane 10 #01-410/412

Singapore 539195

Tel: 6289 8126 Fax: 6287 0590

Email: Jin@jinauto.com.sg

Company Reg. No: 200704370C GST Reg.No: 200704370C

TP INSURER:  
WEE KUAN HOE

China Taiping Insurance (Singapore) Pte. Ltd. (HQ)

Singapore

## PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	SLC5406Y
Policy No:		Date of Loss:	23/08/2019
Vehicle Reg. No.:	SLC5406Y	Driveable?	
Party At Fault:	UNKNOWN		
Driver (TP):	NG ZI YANG	Driver (Insured):	WEE KUAN HOE
Make/Model:	HONDA VEZEL, 1.5 (A)	Vehicle Reg. Date:	18/05/2016
Vehicle Colour:	BLUE		
Engine No:	L15B4035848	Chassis No:	RU11115843
Odometer:	1 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	5		
Description of Accident/Loss	1 STOPPED MY CAR SLC5406Y BEHIND TRAFFIC LIGHT JUNCTION, TRAFFIC LIGHT WAS RED AT THAT TIME. SHORTLY I FELT A STRONG IMPACT FROM BEHIND UPON CHECKING, SMJ5412E HAD BANG ONTO THE REAR PORTION OF MY CAR.		
Present Location:	JIN AUTO SERVICES PTE LTD (DEFU)		

COST OF CLAIMS	Amount
Parts	1,791.00
Miscellaneous Items	0.00
Labour	929.53
Paintwork Labour	0.00
Towing	0.00
<b>Gross Total (\$)</b>	<b>2,720.53</b>
<b>+ GST 7.00% (\$)</b>	<b>190.44</b>
<b>Nett Amount (\$)</b>	<b>2,910.97</b>

This claim is handled by: JOUIS SEOW

Generated using Merimen e-Claims Internet Estimation &amp; Adjusting System

**REPAIR DETAILS****Reference****Part Source:** MRM-SG      Version: 1.0 (Last Synchronised: 26 Aug 2019)**Parts:** M1-SUV      HONDA VEZEL 1.5 (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's      (Price-denominated Standard List)**Print Code:** Jin Auto Services Pte Ltd/SLC5406Y/26/08/2019 15:45**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*TOTAL PARTS	0.00	0.00	*1,791.00 F
Total Parts (S\$)						1,791.00

F=Franchise part.

Jin Auto Services Pte Ltd/SLC5406Y/26/08/2019 15:45. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

## Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

## Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	LABOUR CHARGE	New	163.80 390.60
2	TOTAL PAINT	New	377.63 538.93
Gross Labour Cost (S\$)			929.53

Jin Auto Services Pte Ltd/SLC5406Y/26/08/2019 15:45. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

&lt; END OF ESTIMATES &gt;

**Jin Auto Services Pte Ltd**  
**#01-410/412, 14 Defu Lane 10**  
**539195**

**Insurer Reference: Ntuc Income**  
**Repairer Reference: SLC 5406Y(HondaVezel)**  
**Date calculated: 05/09/2019 3:17 PM**

**Full Report**  
**Registration: SLC 5406Y**  
**Printed: 05/09/2019 3:17 PM**

Code	Description	WU	Price SGD
8111A5	RENEW REAR BUMPER INCLUDES: REMOVE AND REFIT REAR BUMPER, BUMPER CORNERS AND REQUIRED ATTACHED PARTS.	7.0	29.40
823100	RENEW TAILGATE INCLUDES: R + R TAILGATE, CONVERT ATTACHED PARTS, RENEW IF NECESSARY	32.0	134.40
<b>Labour Cost</b>		<b>Hrs</b>	<b>WU</b>
<b>Panel / Mechanical Labour</b>		<b>3.90</b>	<b>39.0</b>
<b>Total of Labour</b>			<b>163.80</b>

**Paint**

Paint Work		SYSTEM AZT		Time Basis 10 WU/h	
Code	Description - TWO COAT METALLIC	WU	Price SGD		
	REAR PANEL REPAIR PAINTING >50%	16.0			
	BOOTLID/TAILGATE REPAIR PAINTING >50%	30.0			

**Paint Material Per Part**

Code	Description	Price SGD
2711	REAR PANEL REPAIR PAINTING >50%	15.01
2931	BOOTLID/TAILGATE REPAIR PAINTING >50%	45.82

<b>Labour Cost - Paint</b>		<b>Hrs</b>	<b>WU</b>	<b>Price SGD</b>
Factor		42.00 SGD/h		
Time Paint			46.0	
Preparation Main Work Metal		2.50	25.0	105.00
<b>Total</b>		<b>10 WU/h</b>	<b>71.0</b>	<b>298.20</b>

<b>Material Cost - Paint</b>		<b>Price SGD</b>	
Repair Painting		60.83	
Material-constant Metal Preparation		28.60	
<b>Total</b>		<b>89.43</b>	

**Spare Parts**

prices as at 2015-06-01/01

**Jin Auto Services Pte Ltd**  
**#01-410/412, 14 Defu Lane 10**  
**539195**

Insurer Reference: Ntuc Income  
 Repairer Reference: SLC 5406Y(HondaVezel)  
 Date calculated: 05/09/2019 3:17 PM

Full Report  
 Registration: SLC 5406Y  
 Printed: 05/09/2019 3:17 PM

Code	Description	Part Number	Supplier	Price SGD
2583	REAR BUMPER	71501T8NT50		170.00
2931	BOOTLID/TAILGATE	68100T8PU10ZZ		530.00
2944	BOOT/TAILGATE SEAL	74440T7A003		45.00
2977	BOOT/TAILGATE LOCK	74800T7AJ02		55.00
3161	LWR REAR SCREEN SEAL	73226SZW000		16.00
3163	REAR SCREEN FIX SET	USE SINGLE PARTS		
3167	L/R WINDOW SEAL	73254T7JH01		11.00
3168	R/R WINDOW SEAL	73214T7JH01		11.00
3170	CHECK	91502S70003		0.00
3171	CHECK	91501S70003		0.00
3173	CHECK	91536SS0J01		0.00
1000	SEALANT	SEALANT		25.00
1003	Reverse Sensor	Reverse Sensor		200.00
f: OEM Parts	<b>Savings</b>			0.00
n: Non-OEM Parts	<b>Subtotal</b>			1,063.00
u: Used parts	<b>Fixed Sundry Parts Price</b>			100.00
	<b>Total</b>			1,163.00

**Final Calculation**

	SGD	SGD
<b>Parts</b>		
Fixed Sundry Parts Price	1,063.00	
<b>Total Parts</b>	100.00	1,163.00
<b>Labour Time Base 10 WU/h</b>		
Total 39.0 WU X 42.00 SGD/h	163.80	
<b>Total of Labour</b>		163.80
<b>Paint Work Time Base 10 WU/h</b>		
Labour Cost 71.0 WU X 42.00 SGD/h	298.20	
Material Cost	89.43	
<b>Total Paint Including Material</b>		387.63
<b>Repair Cost Excludes GST</b>		1,714.43
GST (+7.00%)		120.01
<b>Repair Cost Included GST</b>		1,834.44



柏维汽车零部件私人有限公司  
PARTWARE AUTO PTE LTD

10 Kaki Bukit Road 1, #01-21 KB Industrial Building S416175  
Company Registration No: 201540164H  
Email: admin@partwareauto.com  
Office: +(65) 6493 3228 Fax: +(65) 6493 3028

**TAX INVOICE**

GST Reg. No : 201540164H

Invoice No : AR201908-1128  
Invoice Date : 29 Aug 2019  
Page : Page 1 of 1  
Salesman : KENNY  
Term : 30 DAYS

AUTHORISED DEALER



**HONDA**

Customer A/C No: JAS  
JIN AUTO SERVICES PTE LTD

#01-412 BLK 14  
DEFU LANE 10

SINGAPORE539195  
TEL : 62898126 FAX : 62870590  
ATTN : ACCOUNTS

Deliver to:  
JIN AUTO SERVICES PTE LTD  
SLC5406Y=JIN BOSS

ATTN :

S/N	Part No	Description	Quantity	Unit Price	Amount
1	68100-T8P-U00ZZ	TAILGATE COMP	1 PCS	530.00	530.00
2	74800-T7A-J02	LOCK ASSY, TAILGATE	1 PCS	55.00	55.00
3	71501-T8N-T00	RR, BUMPER FACE	1 PCS	170.00	170.00
4	74440-T7A-003	W/STRIP, TAILGATE	1 PCS	45.00	45.00
5	73226-SZW-000	DAMPER, STD 5X5	2 PCS	8.00	16.00
6	73214-T7J-H01	RUBBER C,R.WINDSHIELD DAMPER	1 PCS	11.00	11.00
7	73254-T7J-H01	RUBBER C,L.WINDSHIELD DAMPER	1 PCS	11.00	11.00

Subtotal 838.00

GST 7% 58.66

Invoice Total SGD 896.66

Total Net Payments SGD 0.00

Amount Due SGD 896.66

- 1) GOODS SOLD ARE NOT REFUNDABLE.
- 2) OVERDUE AMOUNTS ARE SUBJECT TO INTEREST AT UOB'S PREVAILING LENDING RATE.

PARTWARE AUTO PTE LTD

GOODS RECEIVED IN GOOD ORDER & CONDITION.

CUSTOMER'S SIGN & STAMP

**LKK Auto Consultants**  
**#01-25 Paya Ubi Industrial Park, 51**  
**Ubi Avenue 1**  
**408933**

**Insurer Reference: Ntuc Income**  
**Repairer Reference: SLC 5406Y(HondaVezel)**  
**Date calculated: 06/09/2019 3:36 PM**  
**Summary Information**

**Full Report**  
**Registration: SLC 5406Y**  
**Printed: 06/09/2019 3:37 PM**

<b>Claim</b>			
Location:	Singapore (SG)	Work Provider:	China Taiping Insurance (Singapore) Pte Ltd
Printed by:	KK LAU	Currency:	SGD
Claim Reference:	Ntuc Income	Date of Incident:	23/08/19
Estimated Repair Time:	8	Hire Car Start:	
Actual Repair Days:		Hire Car End:	

### Vehicle Details


<b>Vehicle</b>	
Manufacturer:	HONDA
Model:	VEZEL RU1/5
Sub Model:	LX
Model Sheet Number:	35 VE 08
Registration:	SLC 5406Y
VIN number:	RU1-1115843
Odometer:	43840
<b>Model Specs</b>	
TWO COAT METALLIC	PREPARE OFF VEHICLE

### Vehicle Condition

**Vehicle Status**  
Pre-Accident Damage:  
Date of Inspection:

#### Damage Areas

**All** ☐  
**Underbody** ☐



### Labour

Time Base 10 WU/h

Price = 42.00 SGD/h



**LKK Auto Consultants**  
**#01-25 Paya Ubi Industrial Park, 51**  
**Ubi Avenue 1**  
**408933**

Insurer Reference: Ntuc Income  
 Repairer Reference: SLC 5406Y(HondaVezel)  
 Date calculated: 06/09/2019 3:36 PM

Full Report  
 Registration: SLC 5406Y  
 Printed: 06/09/2019 3:37 PM  
 WU Price SGD

Code	Description	WU	Price SGD
8111A5	RENEW REAR BUMPER INCLUDES: REMOVE AND REFIT REAR BUMPER, BUMPER CORNERS AND REQUIRED ATTACHED PARTS.	7.0	29.40
823100	RENEW TAILGATE INCLUDES: R + R TAILGATE, CONVERT ATTACHED PARTS, RENEW IF NECESSARY	32.0	134.40
<b>Labour Cost</b>		<b>Hrs</b>	<b>WU</b>
<b>Panel / Mechanical Labour</b>		<b>3.90</b>	<b>39.0</b>
<b>Total of Labour</b>			<b>163.80</b>

**Paint**

Paint Work	SYSTEM AZT	Time Basis 10 WU/h
Code	Description - TWO COAT METALLIC	WU Price SGD
	REAR PANEL REPAIR PAINTING >50%	16.0
	BOOTLID/TAILGATE REPAIR PAINTING >50%	30.0

**Paint Material Per Part**

Code	Description	Price SGD
2711	REAR PANEL REPAIR PAINTING >50%	15.01
2931	BOOTLID/TAILGATE REPAIR PAINTING >50%	45.82

Labour Cost - Paint	Hrs	WU	Price SGD
Factor	42.00 SGD/h		
Time Paint		46.0	
Preparation Main Work Metal	2.50	25.0	105.00
<b>Total</b>	<b>10 WU/h</b>	<b>7.10</b>	<b>71.0</b>

Material Cost - Paint	Price SGD
Repair Painting	60.83
Material-constant Metal Preparation	28.60
<b>Total</b>	<b>89.43</b>

**Spare Parts**

prices as at 2015-06-01/01

**LKK Auto Consultants**  
**#01-25 Paya Ubi Industrial Park, 51**  
**Ubi Avenue 1**  
**408933**

Insurer Reference: Ntuc Income  
 Repairer Reference: SLC 5406Y(HondaVezel)  
 Date calculated: 06/09/2019 3:36 PM

Full Report  
 Registration: SLC 5406Y  
 Printed: 06/09/2019 3:37 PM

Code	Description	Part Number	Supplier	Price SGD
2583	REAR BUMPER	71501T8NT50		170.00
2931	BOOTLID/TAILGATE	68100T8PU10ZZ		530.00
2944	BOOT/TAILGATE SEAL	74440T7A003		45.00
2977	BOOT/TAILGATE LOCK	74800T7AJ02		55.00
3161	LWR REAR SCREEN SEAL	73226SZW000		16.00
3163	REAR SCREEN FIX SET	USE SINGLE PARTS		
3167	L/R WINDOW SEAL	73254T7JH01		11.00
3168	R/R WINDOW SEAL	73214T7JH01		11.00
3170	CHECK	91502S70003		0.00
3171	CHECK	91501S70003		0.00
3173	CHECK	91536SS0J01		0.00
1000	SEALANT	SEALANT		25.00
1003	Reverse Sensor	Reverse Sensor		200.00
f: OEM Parts				0.00
n: Non-OEM Parts				1,063.00
u: Used parts				100.00
<b>Savings</b>				
<b>Subtotal</b>				1,063.00
<b>Fixed Sundry Parts Price</b>				100.00
<b>Total</b>				1,163.00

**Final Calculation**

	SGD	SGD
<b>Parts</b>	1,063.00	
Fixed Sundry Parts Price	100.00	
<b>Total Parts</b>		1,163.00
<b>Labour Time Base 10 WU/h</b>		
Total 39.0 WU X 42.00 SGD/h	163.80	
<b>Total of Labour</b>		163.80
<b>Paint Work Time Base 10 WU/h</b>		
Labour Cost 71.0 WU X 42.00 SGD/h	298.20	
Material Cost	89.43	
<b>Total Paint Including Material</b>		387.63
<b>Repair Cost Excludes GST</b>		1,714.43
GST (+7.00%)		120.01
<b>Repair Cost Included GST</b>		1,834.44

**LKK Auto Consultants**  
**#01-25 Paya Ubi Industrial Park, 51**  
**Ubi Avenue 1**  
**408933**

**Insurer Reference: Ntuc Income**  
**Repairer Reference: SLC 5406Y(HondaVezel)**  
**Date calculated: 06/09/2019 3:36 PM**

**Full Report**  
**Registration: SLC 5406Y**  
**Printed: 06/09/2019 3:37 PM**

**Comments**

\* - USER SUPPLIED DATA  
NN - NO MANUFACTURERS CODE EXISTS  
) - WU PARTIAL INCL IN OTHER POSITIONS

**Assessment Note**

---

**No assessment notes entered.**

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	26 Aug 2019 <a href="#">Sendback Est</a>	26 Aug 2019 15:45 <b>S\$2,720.53</b>	26 Aug 2019 16:41 <a href="#">Edit Adj Rpt</a>	<b>S\$1,714.43</b> <a href="#">Edit Estimates</a>	<b>S\$1,714.43</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b>									
Insured: <b>WEE KUAN HOE</b> , ID: S9230586D									
Main Claimant: <b>NG ZI YANG</b> , ID: S8535939H									
Vehicle Reg. No.: <b>SLC5406Y</b>		Date of Loss: 23/08/2019 00:00 - :59 [39 Months and 5 Days From LTA Reg Date (Man Yr)]							
Claim Type: <b>TP / SNM19D203961-SMJ5412E-CBS</b>		Policy/Cover Note No.: DMPCSN19177119000							
Vehicle Reg. No. (Insured): <b>SMJ5412E</b>		Policy No. (Claimant):							
		Excess: S\$0.00							
Repairer: <b>Jin Auto Services Pte Ltd (Defu)</b> Blk 14 Defu Lane 10, #01-410/412, 539195 Defu Lane - Tel: 6289 8126									
Handling Insurer: <b>China Taiping Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: 6389 6111 ... [Handled by <b>Chong Boon Sen</b> ]									
Adjuster: <b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>MARCUS CHUA</b> ] ... [Final Rpt due 04/09/2019]									
Driver/Custodian (Insured): <b>WEE KUAN HOE ( / Male )</b> , NRIC: S9230586D Email:									
<b>ASSOCIATED MAIL RECEIVED</b> <a href="#">View All</a> <a href="#">Compose Case Mail</a>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

**SLC5406Y (SNM19D203961-SMJ5412E-CBS)  
[SMJ5412E]**

**TP**

**NG ZI YANG**







































**Aug 23 2019 12:00AM**


**[WEE KUAN HOE]**

**Jin Auto Services Pte Ltd**

Upload Documents | Upload Photos | Compose New Letter

View View in Browser v

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Jin Auto Services Pte Ltd (Defu)	Thumbnail	Print
1	26/08/19 15:45	Repairer Estimates	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	09/09/19 13:52	Odometer Reading	 Load JPG	<input checked="" type="checkbox"/>
2	09/09/19 13:52	Chassis Number	 Load JPG	<input checked="" type="checkbox"/>
3	09/09/19 13:52	General View	 Load JPG	<input checked="" type="checkbox"/>
4	09/09/19 13:52	General View	 Load JPG	<input checked="" type="checkbox"/>
5	09/09/19 13:52	General View	 Load JPG	<input checked="" type="checkbox"/>
6	09/09/19 13:52	General View	 Load JPG	<input checked="" type="checkbox"/>
7	09/09/19 13:52	General View	 Load JPG	<input checked="" type="checkbox"/>
8	09/09/19 13:52	General View	 Load JPG	<input checked="" type="checkbox"/>
9	09/09/19 13:52	General View	 Load JPG	<input checked="" type="checkbox"/>
10	09/09/19 13:52	General View	 Load JPG	<input checked="" type="checkbox"/>
11	09/09/19 13:52	General View	 Load JPG	<input checked="" type="checkbox"/>
12	09/09/19 13:52	General View	 Load JPG	<input checked="" type="checkbox"/>
13	09/09/19 13:52	General View	 Load JPG	<input checked="" type="checkbox"/>
14	09/09/19 13:52	General View	 Load JPG	<input checked="" type="checkbox"/>
15	09/09/19 13:52	General View	 Load JPG	<input checked="" type="checkbox"/>
16	09/09/19 13:52	General View	 Load JPG	<input checked="" type="checkbox"/>
17	09/09/19 13:52	General View	 Load JPG	<input checked="" type="checkbox"/>
18	09/09/19 13:52	General View	 Load JPG	<input checked="" type="checkbox"/>
19	09/09/19 13:52	General View	 Load JPG	<input checked="" type="checkbox"/>
20	09/09/19 13:52	General View	 Load JPG	<input checked="" type="checkbox"/>
21	09/09/19 13:52	General View	 Load JPG	<input checked="" type="checkbox"/>
22	09/09/19 13:52	General View	 Load JPG	<input checked="" type="checkbox"/>
23	09/09/19 13:52	General View	 Load JPG	<input checked="" type="checkbox"/>
24	09/09/19 13:52	General View	 Load JPG	<input checked="" type="checkbox"/>
25	09/09/19 13:52	General View	 Load JPG	<input checked="" type="checkbox"/>
26	09/09/19 13:52	General View	 Load JPG	<input checked="" type="checkbox"/>
27	09/09/19 13:52	General View	 Load JPG	<input checked="" type="checkbox"/>
28	09/09/19 13:52	General View	 Load JPG	<input checked="" type="checkbox"/>
29	09/09/19 13:52	General View	 Load JPG	<input checked="" type="checkbox"/>
30	09/09/19 13:52	General View	 Load JPG	<input checked="" type="checkbox"/>
31	09/09/19 13:52	General View	 Load JPG	<input checked="" type="checkbox"/>
32	09/09/19 13:52	General View	 Load JPG	<input checked="" type="checkbox"/>
33	09/09/19 13:52	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
34	09/09/19 13:52	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
35	09/09/19 13:52	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
36	09/09/19 13:52	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Jin Auto Services Pte Ltd (Defu)	Thumbnail	Print
1	26/08/19 12:46	E-filed GIA report	 Load PDF	

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Jin Auto Services Pte Ltd (Defu)		Thumbnail	Print
2	26/08/19 15:42	audatex		 Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b>
<div></div>
<b>Show Remarks To:</b> <input type="checkbox"/> Repairer <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT119015062/UQF3E2

Date: 25/09/2019

## REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN19177119000
Claimant Vehicle No :	SLC5406Y	Insured Vehicle No :	SMJ5412E
Date of Loss:	23/08/2019	Nature of Claim:	TP
		Claim No:	SNM19D203961-SMJ5412E-CBS

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No:	SLC5406Y	Engine No:	L15B4035848
Make & Model:	HONDA VEZEL, 1.5 (A)	Chassis No:	RU11115843
Reg. Date:	18/05/2016 (Man. Year: 2016)	Odometer:	44006 km
Colour:	Blue		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,791.00	1,163.00	628.00	35.06
Miscellaneous Items	0.00	0.00	0.00	
Labour	929.53	551.43	378.10	40.68
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>2,720.53</b>	<b>1,714.43</b>	<b>1,006.10</b>	<b>36.98</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>190.44</b>	<b>120.01</b>	<b>70.43</b>	<b>36.98</b>
<b>Nett Amount (S\$)</b>	<b>2,910.97</b>	<b>1,834.44</b>	<b>1,076.53</b>	<b>36.98</b>

## INSPECTION

Date of Assignment:	26/08/2019	Present Location:	Jin Auto Services Pte Ltd (Defu)
Date Inspected:	29/08/2019	Inspected At:	Jin Auto Services Pte Ltd (Defu) Blk 14 Defu Lane 10, #01-410/412 Singapore 539195
Estimated Period of Repair:	3.0 days		

Adjuster: MARCUS CHUA

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

<b>Reference</b>		
<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 25 Sep 2019)
<b>Parts:</b>	M1-SUV	HONDA VEZEL 1.5 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLC5406Y)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TOTAL PARTS		1,791.00 F	*1,163.00 F
					<b>Total Parts (S\$)</b>	<b>1,791.00</b>
						<b>1,163.00</b>

F=Franchise part.

Report was unsubmitted during this print-out.



## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	LABOUR CHARGE	New	390.60	163.80
2	TOTAL PAINT	New	538.93	387.63
Gross Labour Cost (\$\$)			<b>929.53</b>	<b>551.43</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >