

Surveyor: MarcusASSIGNMENT (Office)From (Person): Pauline Tham of MSIG Date/Time: 26/08/2019

Estimated Cost: _____ Bill to: _____

OD / TH / WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: SJN 5582L Insured: SLD 9136Vat Workshop m/s Asia Motorsports Solution Pte Ltd Tel: 67453811of 37A EverittPolicy No: 28974559QMY Claim No: 604099

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 24/08/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement: _____

Date/Time: 26/08/2019 05:28pm Person Contacted: LOO Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate Inspection: 13 taxi Bukit Road 4 #01-05/53
	SLD 9136V: NA/INC19014936/r3 D.O.A.: 24/08/2019
	SJN 5582L: NA/INC19014936/r3 D.O.A.: 24/08/2019
28/8/19 @ 2.20pm	informed Pauline Tham, we are pending estimate from repairer.
10/9/19 @ 4.54pm	revised to Pauline Tham via Weimer.

(08/11/13) wef
ASS. REC. BY: *MARCUS*

REF:

MS161

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: *SJN5582L*
at Workshop m/s *ASIC*
of _____
Insured: _____
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: *30k*
IDAC Accident Rpt: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: *12* days Res.: Yes or No
Lum Sum: *20* % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: *SJN5582L* Yr Regn: *209*
Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or *CA*
Make: *Toyota PICNIC* c.c. *1998*
Colour: *Silver* A/C: Insured / Std / NI / NA
Sp. Reading: *244011* T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: *JTEGH23B900026348*
Gen. Cond: Good / Fair / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or
Brake: In order / Jammed / Leaked / Burnt or
Modi: Nil / S/Rim / STD A/Rim or
Tyre Size: F: *205/50R16*
R: _____
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or *Continental*
Front *6* mm Rear *6* mm
R/Bal. *6* mm L/Bal. *6* mm
D.O.A. *24/8/19* D.O.I. *27/8/19*
Survey held at _____
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Rear
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction
4 yrs 5 mths
4/13/873 *02 31-1-2024*

9/9/19 1/5 of 8000 conf. with AM leg (Red 8 2048.75, 53%)

RECEIVED 10 SEP 2019

10/9/2019

Date/Time, File Pass to? ☐ : Preli. Report
☐ : Final Report

1) Date/Time, File Return to?

2)

Days Of Repair: *12*

Resurvey No. of Trip: *1*

Survey Fee:

Transportation:

Add Fee: ☐ : Site Insp (\$ _____) S + RS _____
☐ : Interview (\$ _____) Photos
☐ : Tech. Invs (\$ _____) Others
☐ : Weekend (\$ _____)

Report Format: *MER-TP*

Lump Sum / I.B.I. (\$) *8000*

TOTAL

200
11
211

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Pauline Tham

Date: 10 Sep 2019

Preliminary Advice

Insured Vehicle No	: SLD9136U	Accident Date	: 24/08/2019
TP Vehicle No	: SJN5582L	Assignment Date	: 26/08/2019
Make	: TOYOTA PICNIC	Est. Duration of Repair	: 12.00
Date of Inspection	: 27/08/2019		
Inspection At	: ASIA MOTORSPORTS SOLUTION PTE LTD (HQ) 37A EVERITT SINGAPORE 428586		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	17,048.25
Revised Amount	:S\$	10,036.25
Check Items (Estimated)	:S\$	0.00
Total	:S\$	10,036.25
 Lump Sum Repair	 :S\$	 8,000.00

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	26 Aug 2019 13:38		26 Aug 2019 17:08 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:		KARUNAGARAN PRASATHAN, ID: S1269708B							
Main Claimant:		OPTIMAL SERVICES, Co. Reg. No.: 53306988B							
Vehicle Reg. No.:		SJN5582L	Date of Loss:	24/08/2019 04:00 - :59 [126 Months and 4 Days From LTA Reg Date (Man Yr)]					
Claim Type:		TP	Policy/Cover Note No.:	28974559QMY (Comprehensive) Coverage: 30/06/2019 - 29/06/2020					
Vehicle Reg. No. (Insured):		SLD9136U	Policy No. (Claimant):						
			Excess:						
Repairer:		Asia Motorsports Solution Pte Ltd (HQ) 37A Everitt, 428586 Joo Chiat - Tel:							
Handling Insurer:		MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Pauline Tham - 6594 2545]							
Adjuster:		LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 27/08/2019]							
Adj Asg. Remarks:		on WP. Liab: Dispute (NR) Agreed SJE (LKK Marcus) 6745 3811							
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Shiau Chan (LKKAuto)

From: Do-Not-Reply <do-not-reply@merimen.com>
Sent: Wednesday, 28 August 2019 2:20 PM
To: do-not-reply@merimen.com
Cc: SUR
Subject: TP VEHICLE SJN 5582L (YOUR POLICY NO. : 28974559QMY)

This mail is associated with :
***SJN5582L**
[SLD9136U]
TP
OPTIMAL SERVICES
Aug 24 2019 4:00AM
[KARUNAGARAN PRASATHAN]
Asia Motorsports Solution Pte Ltd

Dear Pauline,

Please be informed that we have inspected the vehicle SJN 5582L on 27/08/2019.

We are pending for estimate from repairer.

Thanks & Regards,

Shiau Chan (Ms)
LKK Auto Consultants Pte Ltd
Tel: 6256 3561

This is an auto-generated email. Do not reply to this email.

Sent by : SHIAU CHAN (LKK Auto Consultants Pte Ltd)



This email has been checked for viruses by AVG antivirus software.
www.avg.com



Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

Cheapest Almost New Citroen Berlingo 1.5 BLUEHD EA...



Cheapest In The Market! Almost
New Immediate Stock For
Registration! No Gimmick!
Net Link Partners StarAd



Browse by Category

« Back (1 2) Next »

Sort by Date Posted

20 results/page

29 vehicles

Toyota Picnic

Advanced Search

Submit

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Toyota Picnic		Any	Any	> 10 year(s) old	Any	Any	Any	Available
	Toyota Picnic	2.0A (New 10-yr COE)	\$57,888	\$5,780 /yr	07-Jul-2009	1,998 cc	124,000 km	MPV	Available
New Battery! 100% Loan Approval Rate! Good Condition On Both Interior And Exterior. Comes With 10 Years COE. Call Us Now To Book...									
Posted: 26-Aug-2019 Tags: 2009 Toyota Picnic, 2009 toyota picnic, Toyota Picnic, toyota picnic, Toyota, Picnic, picnic, Used Toyota									
	Toyota Picnic	2.0A (New 10-yr COE)	\$61,800	\$6,170 /yr	25-Aug-2009	1,998 cc	102,000 km	MPV	Available
100% Loan, Immediate Approval 5 Or 10 Years Renewal Available. Superb Well Maintained. Original Paint. Smooth Engine, Easy To Mai...									
Straits Euro Motors Pte Ltd									
Posted: 26-Aug-2019 Tags: 2009 Toyota Picnic, 2009 toyota picnic, Toyota Picnic, toyota picnic, Toyota, Picnic, picnic, Used Toyota									
	Toyota Picnic	2.0A (COE till 02/2024)	\$41,800	\$9,260 /yr	03-Mar-2009	1,998 cc	91,000 km	MPV	Available
Well Maintained, Super Low Genuine Mileage Done. Well Groomed Inside Out. No Repairs Needed. Comes With 6 Months Warranty By O...									
Posted: 25-Aug-2019 Tags: 2009 Toyota Picnic, 2009 toyota picnic, Toyota Picnic, toyota picnic, Toyota, Picnic, picnic, Used Toyota									
	Toyota Picnic	2.0A (COE till 05/2029)	\$61,500	\$6,340 /yr	07-May-2009	1,998 cc	128,005 km	MPV	Available
Borneo Motors Unit. Silver Colour. Inchcape Pre-Owned Certified Unit. One Owner With Low Mileage Done. Most Popular MPV In The Ma...									
Inchcape Pre-Owned									
Posted: 25-Aug-2019 Tags: 2009 Toyota Picnic, 2009 toyota picnic, Toyota Picnic, toyota picnic, Toyota, Picnic, picnic, Used Toyota									
	Is your COE expiring? Let us help you renew it! Getting your COE renewed is easy, fast and affordable. We'll help you renew your COE and get a loan for it. Get the cheapest loan in town and an approval in 2 days without effort! Enquire today.								
	Toyota Picnic	2.0A (COE till 02/2029)	\$55,800	\$5,870 /yr	27-Feb-2009	1,998 cc	105,000 km	MPV	Available
100% Accident Free With Low Mileage Done! Seats 7 Adult Comfortably With Spacious Booth Space & Full Rear Aircon Ventilation For Id...									
Creative Auto									
Posted: 24-Aug-2019 Tags: 2009 Toyota Picnic, 2009 toyota picnic, Toyota Picnic, toyota picnic, Toyota, Picnic, picnic, Used Toyota									
	Toyota Picnic	2.0A (COE till 07/2024)	\$37,800	\$7,740 /yr	15-Jul-2009	1,998 cc	188,317 km	MPV	Available
No Gimmicks, Priced \$37,800 Only! Picnic 2.0A With Rear Air-Con Of Top Tip Condition! Low Mileage Clocked Of 19000km Annually. Age...									
Lake View Credit Pte Ltd									
Posted: 24-Aug-2019 Tags: 2009 Toyota Picnic, 2009 toyota picnic, Toyota Picnic, toyota picnic, Toyota, Picnic, picnic, Used Toyota									
	Toyota Picnic	2.0A (COE till 04/2029)	\$56,800	\$5,870 /yr	02-Jul-2009	1,998 cc	-	MPV	Available
Low Interest Rate. COE Till April 2029. In House Financing Options Available. Buy With A Peace Of Mind. 100% Genuine Mileage. Immac...									
GOWheeler Pte Ltd									
Posted: 24-Aug-2019 Tags: 2009 Toyota Picnic, 2009 toyota picnic, Toyota Picnic, toyota picnic, Toyota, Picnic, picnic, Used Toyota									

Compare

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	988B
Vehicle Details	
Vehicle No.:	SJN5582L
Vehicle to be Exported:	No
Intended Deregistration Date:	27 Aug 2019
Vehicle Make:	TOYOTA
Vehicle Model:	PICNIC AUTO W/O ROOF RACK
Primary Colour:	Silver
Manufacturing Year:	2009
Engine No.:	1AZ5847970
Chassis No.:	JTEGH23B900026348
Maximum Power Output:	110.0 kW (147 bhp)
Open Market Value:	\$23,511.00
Original Registration Date:	20 Feb 2009
First Registration Date:	20 Feb 2009
Transfer Count:	2
Actual ARF Paid:	\$23,511.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	31 Jan 2024
COE Category:	B - Car (1601cc & above)
COE Period(Years):	5
PQP Paid:	\$15,668.00
COE Rebate Amount:	\$13,873.00
Total Rebate Amount:	\$13,873.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 27 Aug 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 26/08/2019 10:01
 Date Of Accident 24/08/2019 04:00
 Exact Location Of Accident WHAMPOA FLYOVER
 Country/State Of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SJN5582L
Insured/Policyholder
 Name Of Registered Owner OPTIMAL SERVICES
 Co Reg No 53306988B
 Email Address NOEMAIL
 Mobile Phone No
 Alternative Phone No OFFICE-97262447

Vehicle Particulars

Manufacturer TOYOTA
 Model PICNIC
 Exact Purpose for which vehicle was being used at time of accident GRAB
 Are you claiming under your own insurance policy for repair to your vehicle? NO
 If No, Please state action to be taken THIRD PARTY
 Vehicle Category PRIVATE HIRE

Insurance Company

Name of Insurance Company NTUC INCOME INSURANCE CO-OPERATIVE LTD
 Type Of Coverage THIRD PARTY
 Fleet Policy NO
 Policy Number 5098430404-01
 Cover Note Number

Driver

Name of Driver ATIF SHARJEEL
 NRIC No S7969073B
 Date Of Birth 16/04/1979
 Occupation OUTDOOR
 Date Of Driving Pass 14/06/2010
 Driving Experience 9 YEARS AND 2 MONTHS
 Gender MALE
 Mobile Number (LOCAL) +65-81331443
 Fax Number
 Contact Number
 EMail Address NOEMAIL

Address	BLK 658 HOUGANG AVE 8 #12-447
Postcode	530658
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
Insurance Company of Driver's Own Vehicle	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: UNKNOWN GENDER: FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of Intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLS REFER TO THE ATTACHED STATEMENT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLD9136U
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	DWISH DIVAKARAN
NRIC/Passport Number	S9238837I
Contact Number	98324294/96443465
Address	
Postcode	
Insurance Company / Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name ATIF SHARJEEL

Approximate Age

Injuries Sustain SLIGHT

Injured person in which vehicle? SJN5582L

Were seat belt YES

Was this injured conveyed to hospital by ambulance? NO

Address

Postcode

DETAILS OF INJURED PERSON 2

Name UNKNOWN(PASSENGER)

Approximate Age

Injuries Sustain SLIGHT

Injured person in which vehicle? SJN5582L

Were seat belt YES

Was this injured conveyed to hospital by ambulance? NO

Address

Postcode

Individual Statement

I WAS TRAVELLING FROM WHAMPDA TOWNS ASIA SQUARE TOWER 1 ON THE EXTREME RIGHT LANE INTXT OF MY VEH STOP AND I FOLLOW SUIT. SUDDENLY VEH B CAME FROM BEHIND AND HIT ONTO MY REAR PORTION OF MY VEH.

MS16 ASIS

N. F. Anthonys
 27/8/19 Take the Repair
 Page No. 1
 1/5 #8000 + 12 day.

VEHICLE NO SJN 5582L

TOYOTA PICNIC

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(\$\$)	SURVEYOR ADJUSTMENT
PARTS (LIST ITEMS)				
1	Tail Gate	Body m	1272.00	✓
1	Tail Gate Centre Badge	neu	45.50	✓
1	Tail Gate Toyota emblem	neu	72.00	✓
1	Tail Gate PICNIC emblem	neu	78.00	✓
1	Tail Gate Centre Garnish	Seal/cu	299.20 328.00	✓
1	Tail Gate inner Lock	DD/Gm	372.00	✓
1	Tail Gate Inner Trim Board	De/warped	325.10 488.00	✓
2	Tail Gate Dampers @ \$288.00	11	576.00	X
2	Rear Windscreen Moulding @ \$75.00	neu	118.00 150.00	✓
2	Tail Gate inner side garnish RH & LH	11	276.00	X
1	Tail Gate wiper motor	11	382.00	X
2	Tail Gate reflectors RH & LH @598	295.10 x 2 =	590.20 1196.00	✓
1	Tail Gate top spoiler	REFIX 11	0.00	X
2	Tail Lamps @ \$725.50	366.50 x 2 = 733.00	1451.00	✓
1	Rear Bumper	510.20 D.S	982.00	✓
2	Rear Bumper reflectors @ \$75.00	11	150.00	X
2	Rear Bumper Side Retainers @ \$90.00	42.50 x 2	85.00 180.00	✓
1	Rear Bumper tow cover	11	25.60 48.00	✓
1	Rear Boot Weatherstrip	7w1	285.10 287.50	✓
1	Rear End Panel Lock Catch	11	66.00	X
1	Rear End Panel	3.00 x 20	60.00 782.00	✓
1	Rear End Panel top garnish	7w1	274.00	✓
2	RHS & LHS Rear fender @782	11	1564.00	X
2	RHS & LHS Rear fender inner trim @352	De/cu	704.00	✓
2	RHS & LHS Rear fender 1/4 glass moulding	11	224.00	X
2	Rear seat belts @598	11	1196.00	X
1	Rear floor panel	crushed/Buc	1128.00	✓
1	Rear floor panel top board	warped	475.00	✓
1	Rear exhaust silencer assembly	11	652.00	X
1	Rear exhaust silencer assembly mountings	11	94.00	X
1	Rear reinforcement frame	lower	598.00	✓
			15891.00	
less 25%			3972.75	25%
			11918.25	
SPECIAL NETT ITEMS				
1	Rear Windscreen Sealant	neu	100.00	40
1	Reverse Sensor	neu	280.00	2005.00
2	RHS & LHS Rear fender 1/4 glass sealant	11	140.00	X
1	Child car seat	D.S	price to confirm*	X NPA
1 set	Rear Bumper Clips	neu	60.00	40
1 set	Rear End Panel Top Garnish Clips	11	60.00	X
1	Rear End Panel Sealant	neu	100.00	50
TOTAL PARTS			12658.25	

8825
 25%
 6506.25

330

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19015063/UQF3N2

Date: 12/09/2019

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	28974559QMY
Claimant Vehicle No :	SJN5582L	Insured Vehicle No :	SLD9136U
Date of Loss:	24/08/2019	Nature of Claim:	TP
		Claim No:	604099

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJN5582L	Engine No:	1AZ5847970
Make & Model:	TOYOTA PICNIC, 2.0 W/O ROOF RACK (A)	Chassis No:	JTEGH23B900026348
Reg. Date:	20/02/2009 (Man. Year: 2009)	Odometer:	244011 km
Colour:	Silver		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/50 R16	Rear Tyre Size:	205/50 R16
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	12,808.25	6,836.25	5,972.00	46.63
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,390.00	3,200.00	1,190.00	27.11
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	17,198.25	10,036.25	7,162.00	41.64
Approved Total (Overridden) (S\$)		8,000.00		
Nett Amount (S\$)	17,198.25	8,000.00	9,198.25	53.48

INSPECTION

Date of Assignment:	26/08/2019	
Date Inspected:	27/08/2019	Inspected At:
		15 Kaki Bukit Road #01-05/53
		Repairer: Asia Motorsports Solution Pte Ltd
		37A Everitt
		Singapore 428586
Estimated Period of Repair:	12.0 days	

Adjuster: MARCUS CHUA

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 12 Sep 2019)
Parts:	M1-MPV	TOYOTA PICNIC 2.0 W/O ROOF RACK (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJN5582L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAIL GATE	Badly Dented	1,272.00 FL	*1,272.00 FL
2	1		*TAIL GATE CENTRE BADGE	Necessary	45.50 FL	*45.50 FL
3	1		*TAIL GATE TOYOTA EMBLEM	Necessary	72.00 FL	*72.00 FL
4	1		*TAIL GATE PICNIC EMBLEM	Necessary	78.00 FL	*78.00 FL
5	1		*TAIL GATE CENTRE GARNISH	Bent/Cracked	328.00 FL	*299.20 FL
6	1		*TAIL GATE INNER LOCK	Dented/Jammed	372.00 FL	*372.00 FL
7	1		*TAIL GATE INNER TRIM BOARD	Deformed/Warped	488.00 FL	*325.10 FL
8	2		*TAIL GATE DAMPERS	Not Necessary	576.00 FL	*- FL
9	2		*REAR WINDSCREEN MOULDING	Necessary	150.00 FL	*118.00 FL
10	2		*TAIL GATE INNER SIDE GARNISH RH & LH	Not Necessary	276.00 FL	*- FL
11	1		*TAIL GATE WIPER MOTOR	Not Necessary	382.00 FL	*- FL
12	2		*TAIL GATE REFLECTORS RH & LH	Cracked	1,196.00 FL	*590.20 FL
13	1		*TAIL GATE TOP SPOILER (NPA)	Not Necessary	0.00 FL	*- FL
14	2		*TAIL LAMPS	Cracked	1,451.00 FL	*733.00 FL
15	1		*REAR BUMPER	Distorted	982.00 FL	*510.20 FL
16	2		*REAR BUMPER REFLECTORS	Not Necessary	150.00 FL	*- FL
17	2		*REAR BUMPER SIDE RETAINERS	Bent	180.00 FL	*85.00 FL
18	1		*REAR BUMPER TOW COVER N/S	Missing	48.00 FL	*25.60 FL
19	1		*REAR BOOT WEATHERSTRIP	Twisted	287.50 FL	*285.10 FL
20	1		*REAR END PANEL LOCK CATCH	Not Necessary	66.00 FL	*- FL
21	1		*REAR END PANEL	Badly Dented	782.00 FL	*685.10 FL
22	1		*REAR END PANEL TOP GARNISH	Twisted	274.00 FL	*274.00 FL
23	2		*RHS & LHS REAR FENDER	Repair	1,564.00 FL	*- FL
24	2		*RHS & LHS REAR FENDER INNER TRIM	Deformed/Cracked	704.00 FL	*704.00 FL
25	2		*RHS & LHS REAR FENDER 1/4 GLASS MOULDING	Not Necessary	224.00 FL	*- FL
26	2		*REAR SEAT BELTS	Not Necessary	1,196.00 FL	*- FL
27	1		*REAR FLOOR PANEL	Crumpled/Buckled	1,128.00 FL	*1,128.00 FL
28	1		*REAR FLOOR PANEL TOP BOARD	Warped	475.00 FL	*475.00 FL
29	1		*REAR EXHAUST SILENCER ASSEMBLY	Not Necessary	652.00 FL	*- FL
30	1		*REAR EXHAUST SILENCER ASSEMBLY MOUNTINGS	Not Necessary	94.00 FL	*- FL
31	1		*REAR REINFORCEMENT FRAME LOWER	Bent/Buckled	598.00 FL	*598.00 FL
32	1		*REAR WINDSCREEN SEALANT	Necessary	100.00 FS	*40.00 FS
33	1		*SET REVERSE SENSOR	Cracked	280.00 FS	*200.00 FS
34	2		*RHS & LHS REAR FENDER 1/4 GLASS SEALANT	Not Necessary	140.00 FS	*- FS
35	1		*CHILD CAR SEAT (NPA)	Distorted	0.00 FS	*- FS
36	1		*SET REAR BUMPER CLIPS	Necessary	60.00 FS	*40.00 FS
37	1		*SET REAR END PANEL TOP GARNISH CLIPS	Not Necessary	60.00 FS	*- FS
38	1		*REAR END PANEL SEALANT	Necessary	100.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) **16,831.00** **9,005.00**
 - List Item Discount on L Items 25.00/25.00% (\$\$) 4,022.75 2,168.75

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
					Total Parts (S\$)	12,808.25 6,836.25

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS;PANEL BEAT & RESHAPE THE AFFECTED AREAS AND REPLACE THE DAMAGED PARTS AND COMPONENTS	New	2,000.00	1,800.00
2	TO SUPPLY PAINT MATERIALS,EXPANDABLE ITEMS & PUTTY,RESPRAY PAINT ON PARTS REPLACED AND REPAIRED AREAS	New	1,000.00	1,000.00
3	TO REMOVE,REFIX WIRING SYSTEM AT ACCIDENT DAMAGED AREAS AND CHECK FOR PROPER FUNCTION	New	200.00	30.00
4	TO REMOVE/REFIX INNER TRIMS,FITTINGS,GARNISH ETC AT REAR COMPARTMENT SO AS TO FACILITATE REPAIRS AT REAR	New	300.00	80.00
5	TO REFIX REAR TAILGATE WINDSCREEN	New	140.00	120.00
6	TO REMOVE AND REFIX REAR FENDER 1/4 GLASS	New	160.00	0.00
7	TO REMOVE AND REPLACE REAR EXHAUST SILENCER ASSY	New	250.00	0.00
8	TO REMOVE AND REPLACE REVERSE SENSORS AND CHECK FOR PROPER FUNCTION	New	100.00	50.00
9	TO PERFORM ANTI-RUST TREATMENT ON AFFECTED AREAS	New	240.00	120.00
Gross Labour Cost (\$\$)			4,390.00	3,200.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >