



Mercedes-Benz

Finalization

Cycle & Carriage  
Industries Pte Limited  
Authorised Dealer  
Company No. 196400367W  
GST Reg No. MR-8500111-X

## ESTIMATE FOR SKM7686B\*RA

MSIG INSURANCE (S'PORE) PTE LTD

MOTOR CLAIM DEPARTMENT  
16 RAFFLES QUAY #24-01  
HONG LEONG BUILDING  
SINGAPORE 048581  
66431303

### Vehicle & Document Information

WIP No	35899
Reg No/Reg Date	SKM7686B*RA / 16/11/2012
Date In/Mileage	27/08/2019 / 64961
Chassis No	WDD2180592A033126
Engine No	27695230073341
Make/Model	MB/CLS 350 CGI (C218)
Colour/Trim	027 792 Palladium S/ 042 201 Black

Account No	Terms	Date/Time Printed	CSE	Operator	Qty	Unit Price	Disc%	Amount
WI000558	Credit	04/09/2019/ 09:59	CH	371 / Go Chee Han				
Description of Goods / Services					Qty	Unit Price	Disc%	Amount

7 REQUEST  
Customer Request  
M. BRINSON

POLICY NO/ACC DATE : VA1/GA033085 // 6-8-2019  
DRIVE IN/TP VEH NUMBER : 6-8-2019 // SFY7303C - MSIG  
DATE IN/DATE SURVEY: 27-8-2019 1430 // Rasul - LKK  
BY/AUTHORIZED ON : 21-8-2019 1103 // Katherine Wong - MSIG

- A BPILAB  
DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH.
- A BPIRES  
RESPRAY REAR BUMPER & TRUNK LID & END PANEL
- A BPILAB  
USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD. NETT
- A BPILAB  
CHECK REAR LIGHTING SYSTEM AND WATER TEST FOR ANY LEAKAGE. NETT
- X REAR AMG TRIM BUMPER
- X PARKING SENDER UNIT
- X GROMMET
- X MERCEDES STAR
- X CLS-350 TYPE DESIGNATION
- X AMG TYPE DESIGNATION

1920.00

1800.00

0.10

380.00

120.00

1.00 2467.44 00.00

2467.44

1.00 280.21 00.00

280.21

3.00 2.51 00.00

7.53

1.00 49.85 00.00

49.85

1.00 85.35 00.00

85.35

1.00 194.11 00.00

net 194.11

Confirmed & accepted by

7% GST on **Nett 7,304.49**  
**7304.49 511.31**

**Total Payable 7,815.80**

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.  
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center  
188 Pandan Loop  
Singapore 128378  
Tel: 6777 8388  
Fax: 6779 5383  
www.mercedes-benz.com.sg



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany