

Fong Mo

1, Kaki Bukit Ave 6, #01-45/27, Auto

Vehicle No. **99094**
 Make/Model **HYUNDAI ELANTRA**
 Year :
 Chassis No.

TPAIG.
 Jiale

PARTS LIST

- | | | |
|---|------|---|
| 1 | 1 pc | FRONT BUMPER <i>torn</i> |
| 2 | 1 pc | FRONT BUMPER FORD LAMP COVER <i>crushed</i> |
| 3 | 1 pc | FRONT BUMPER SIDE RETAINER <i>new</i> |
| 4 | 8 pc | FRONT BUMPER CLIP <i>new</i> |
| 5 | 1 pc | FRONT FENDER UNDERGARNISH <i>new</i> |
| 6 | 8 pc | FENDER UNDERGARNISH CLIP |
| 7 | 1 pc | FRONT HEAD LAMP <i>cut</i> |
| | 1 pc | Rim <i>new</i> |

L/S - \$1950

LABOUR CHARGE

TO KNOCK AND CHANGE PARTS
 TO SPRAY PAINT THE AFFECTED AREAR
 TUFF KOTE
 TO CHECK WIRING

475. +
 45. +
 68.5 +
 40. +
 1,756. =
 2,384.5 *
 2,384.5 x
 80. %
 1,907.6 *

2019

2

250. +
 250. +
 30. =
 530. *
 1,907.6 +
 530. =
 2,437.6 *
 2,437.6 x
 80. %
 1,950.08 *

0. 0

530

700.00 250
 \$ 600.00 250
 \$ 80.00 x
 \$ 80.00 30
 \$ 4,355.00

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature

Date:

FONG MOTORS

Adrian Ling
 L/S 26/08/19
 03 Pags.

total: 2437.60
 L/S: 1950