

Fong Motors

1, Kaki Bukit Ave 6, #01-45/27, Autobay, Singapore 417883

Vehicle No. 99094
 Make/Model HYUNDAI ELANTRA
 Year :
 Chassis No.

TPAIG.
 Jiale

DATE : 22/8/2019

KMH D841CMJ4533692

PARTS LIST

			Unit Price			
1	1 pc	FRONT BUMPER <i>torn</i>	\$ 968.00	\$	968.00 475	
2	1 pc	FRONT BUMPER FORD LAMP COVER <i>crushed</i>	\$ 45.00	\$	45.00	
3	1 pc	FRONT BUMPER SIDE RETAINER <i>new</i>	\$ 68.50	\$	68.50	
4	8 pc	FRONT BUMPER CLIP <i>new</i>	\$ 40.00	\$	40.00	
5	1 pc	FRONT FENDER UNDERGARNISH <i>new</i>	\$ 118.50	\$	118.50	
6	8 pc	FENDER UNDERGARNISH CLIP <i>new</i>	\$ 40.00	\$	40.00	
7	1 pc	FRONT HEAD LAMP <i>cut</i>	\$ 865.00	\$	1756	
	1 pc	Rim <i>new</i>	\$ 750.00	\$	750.00	SN
				\$	2,895.00	

2384.50

1907.60

LABOUR CHARGE

TO KNOCK AND CHANGE PARTS
 TO SPRAY PAINT THE AFFECTED AREAR
 TUFF KOTE
 TO CHECK WIRING

530

\$	700.00	250
\$	600.00	250
\$	80.00	x
\$	80.00	30
\$	4,355.00	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Sign: **FONG MOTORS**
 Date:

Adrian Ling
 L/S 26/08/19
 03899

total: 2487.60
 L/S: 1950