

ASS. REC. BY:

REF: CS/C1219015076/G9F32V

Special Instruction:

SUIVEUR

GQ

ASSIGNMENT (Office)

From (Person): Chong Boon Sen of CTI Date/Time: 27.8.19 11.26 PM

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLN 1836H Insured: _____at Workshop m/s STK Auto Pte Ltd Tel: 63860669of 8 Kaki Bukit Ave 4 #03-21Policy No: DMPASA 30227419000 Claim No: SVM 190203983001Sum Insured: _____ Excess: \$750.00Make of Veh: _____ D.O.A. 22.8.2019
(Client's Record)

CA / REV / REP. / REV 24 HRS

Date/Time: 27.8.19 1.55 PM Person Contacted: Linda H.O.D. Endorsement: _____Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	<u>SLN 1836H - X</u>
<u>28/8/19 @ 1.15 PM</u>	<u>revert to Boon Sen via Messenger.</u>
<u>29/8/19 @ 5.18 PM</u>	<u>2nd revert to Boon Sen via Messenger. (cost plus).</u>
<u>30/8/19 @ 10.13 AM</u>	<u>Boon Sen informed C/A via messenger. (cost plus).</u>
<u>29/8/19 @ 10.40 AM</u>	<u>informed Linda C/A to ex: \$750 by email.</u>

Surveyor

Gnl.

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

☒ OD / ☐ TP / ☐ WS / ☐ TP RES / ☐ OD RES / ☐ EVA / ☐ INV / ☐ MV

To Inspect Vehicle No: _____

at Workshop m/s STK

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: \$750

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \$82k

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / ☒ REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLN18364

Yr Regn: 25 Apr 2017

Type: ☒ M Car / ☐ M.Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or

Make: Tyota wish 1.8X c.c 1797

Colour: silver A/C: ☒ Insured / ☐ Std / ☐ NI / ☐ NA

Sp.Reading: 95262 T/Radio: ☒ Insured / ☐ Std / ☐ NI / ☐ NA

Eng/No: _____

C/No: 86E 206031963

Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ Burnt

Steering: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt or

Brake: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt or

Modi: ☒ Nil / ☐ S/Rim / ☐ STD A/Rim or

Tyre Size: F: 215/45 R17

R: 11

BS / ☒ DUN / ☐ EXNOVA / ☐ GY / ☐ FS / ☐ LIZA / ☐ MID / ☐ OHTSU / ☐ PIR / ☐ SUMI /

TOYO / YOKO or

Front

R/Bal. 6 mm

L/Bal. 6 mm

D.O.A. _____

Survey held at w/s

Des. of Damages: ☒ Fr / ☐ Rear / ☐ O/S / ☐ N/S / ☐ U/C / ☐ Rooftop or

Rear

R/Bal. 6 mm

L/Bal. 6 mm

D.O.I. 27-08-19

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

COE: \$56089

13/5 Finalized \$7727.4 with limbo
(Red \$10243.74, 57%)

RECEIVED 16 SEP 2019

Date/Time, File Pass to?

☐ : Preli. Report

1) 16/9 turnin

☐ : Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: 5

Resurvey No. of Trip: 1

Survey Fee: 220

Transportation: _____

Add Fee: ☐ : Site Insp (\$)

☐ : Interview (\$)

☐ : Tech. Invs (\$)

☐ : Weekend (\$)

) S + RS \$

) Photos

) Others

Report Format : MED-00

Lump Sum / I.B.I. (\$) 7727.40

TOTAL

220

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	27 Aug 2019		27 Aug 2019 13:26 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	HUANG JINHONG								
Vehicle Reg. No.:	SLB1836H	Date of Loss:	23/08/2019 00:00 - :59						
Claim Type:	OD / SNM19D203983C01	Policy/Cover Note No.:	DMPCSN30227419000 (Comprehensive)						
		Excess:	S\$750.00						
Repairer:	Stk Auto (s) Pte Ltd (HQ) 8 kaki bukit ave4, #03-21, 415875 Kaki Bukit - Tel:								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 05/09/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Shiau Chan (LKKAuto)

From: STK STK <stkautosg@gmail.com>
Sent: Friday, 13 September 2019 12:07 PM
To: SUR; Guo Qiang (LKKAuto)
Subject: Re: SLN1836H - Cost of repair Estimate
Attachments: SLN1836H ESTIMATE.pdf

Dear Guoqiang

As spoken we closed the part by part \$ 7727.40, 5 days repair.

Please refer to attachment.

Thank you

Yours sincerely

Tan Guohua

Chief Executive Officer

STK AUTO (S) PTE LTD | www.stkauto.com.sg

Mobile: (65) 9123 7949 | Tel: (65) 63860669

8 Kaki Bukit Ave 4 #03-21 Singapore 415875 @PREMIER



STK STK <stkautosg@gmail.com> 于 2019 年 8 月 29 日周四 下午 4:10 写道:

Dear In Charge office

Please refer to attached update cost of repair estimate.

Thank you

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Friday, 30 August 2019 10:43 AM
To: STK STK; SUR; Guo Qiang (LKKAUTO)
Subject: RE: SLN1836H - Cost of repair Estimate

Dear Linda,

Please be informed that the vehicle number should be SLN 1836H instead of SLB 1836H.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>
Sent: Friday, 30 August 2019 10:40 AM
To: STK STK <stkautosg@gmail.com>; SUR <sur@lkkauto.com>; Guo Qiang (LKKAUTO) <GuoQiang@lkkauto.com>
Subject: RE: SLN1836H - Cost of repair Estimate

Dear Linda,

As instructed by our client, please proceed to repair the insured vehicle **SLB 1836H (Excess \$750/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: STK STK <stkautosg@gmail.com>
Sent: Thursday, 29 August 2019 4:48 PM
To: SUR <sur@lkkauto.com>; Guo Qiang (LKKAUTO) <GuoQiang@lkkauto.com>
Subject: Re: SLN1836H - Cost of repair Estimate

Dear Guoqiang

Please refer to update estimate.

Thank you

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Friday, 30 August 2019 10:40 AM
To: STK STK; SUR; Guo Qiang (LKKAUTO)
Subject: RE: SLN1836H - Cost of repair Estimate
Attachments: SLN1836 EST-COST.pdf

Dear Linda,

As instructed by our client, please proceed to repair the insured vehicle **SLB 1836H (Excess \$750/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: STK STK <stkautosg@gmail.com>
Sent: Thursday, 29 August 2019 4:48 PM
To: SUR <sur@lkkauto.com>; Guo Qiang (LKKAUTO) <GuoQiang@lkkauto.com>
Subject: Re: SLN1836H - Cost of repair Estimate

Dear Guoqiang

Please refer to update estimate.

Thank you

Yours sincerely

Tan Guohua

Chief Executive Officer

STK AUTO (S) PTE LTD | www.stkauto.com.sg

Mobile: (65) 9123 7949 | Tel: (65) 63860669

Claim Audit

AUDIT TRAIL					
No.	On	Audit	Remarks	By	
1	27 Aug 2019 13:25	Cim Veh Model Changed	(201172) TOYOTA WISH 1.8 (A).	[I] Chong Boon Sen	
2	27 Aug 2019 13:25	Cim Created	Reg No: SLB1836H, Policy No: DMPC5N30227419000, Acct Date: 2019/08/23, Claim Ty pe: OD, Insurer: China Taiping Insurance (Singapore) Pte. Ltd, (HQ), Workshop: Stk Au to (s) Pte Ltd (HQ), Ins.Status => Incoming Claim	[I] Chong Boon Sen	
3	27 Aug 2019 13:26	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[I] Chong Boon Sen	
4	27 Aug 2019 13:26	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/09/05	[I] Chong Boon Sen	
5	27 Aug 2019 13:26	Adj Mandate Set	Approved:0.00,	[I] Chong Boon Sen	
6	27 Aug 2019 13:27	Assignment 1st Accessed		[A] LEE SU THING	
7	27 Aug 2019 16:54	Adj Adjuster Assigned	[None] -> XING GUO QIANG	[A] LEE SU THING	
8	28 Aug 2019 09:33	Cim Registration Modified	Reg No:SLB1836H->SLN1836H,	[I] Chong Boon Sen	
9	28 Aug 2019 13:11	Adj Rpt Initiated		[A] SHIAU CHAN	
10	28 Aug 2019 13:11	Cim Dtl Modified	Insured ID: -> S8165033J, Driver Name: -> HUANG JINHONG, Circumstances of Loss: -> 16,	[A] SHIAU CHAN	
11	28 Aug 2019 13:11	Cim Dtl Modified	JPJ Reg. Date: -> 2017/04/25,	[A] SHIAU CHAN	
12	28 Aug 2019 13:11	Cim Details Notified		[A] SHIAU CHAN	
13	28 Aug 2019 13:15	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2019/09/05	[A] SHIAU CHAN	
14	28 Aug 2019 13:15	Adj Mandate Request	Cur.Reg:10323.51:DAMAGES CONSISTENT, REPAIR COST ECONOMICAL, WE HAVE NOT AUTHORISE REPAIR.	[A] SHIAU CHAN	
15	29 Aug 2019 10:02	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/09/05, Mandate Remarks: Our authorisation will be s ubject to repair cost + 15%. Please assist to check with workshop & seek mandate upon confirmation, Thanks.	[I] Elaine Cheong	
16	29 Aug 2019 10:02	Adj Mandate Set	Maintained:Our authorisation will be subject to repair cost + 15%. Please assist to chec k with workshop & seek mandate upon confirmation, Thanks.	[I] Elaine Cheong	
17	29 Aug 2019 17:17	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2019/09/05	[A] SHIAU CHAN	
18	29 Aug 2019 17:18	Adj Mandate Request	Cur.Reg:6791.14:DAMAGES CONSISTENT, REPAIR COST ECONOMICAL, ESTIMATE OF C OST PLUS RE-UPLOADED WE HAVE NOT AUTHORISE REPAIR.	[A] SHIAU CHAN	
19	30 Aug 2019 10:13	Adj Next Rpt Changed	Cur Rpt:Final Rpt, Cur Due Date:2019/09/05, Mandate Remarks: Our authorisation will be subject to repair cost + 15%. Please assist to check with workshop & seek mandate upon confirmation, Thanks.	[I] Chong Boon Sen	
20	30 Aug 2019 10:13	Adj Mandate Set	Approved:6791.14:Our authorisation will be subject to repair cost + 15%, Please assist to check with workshop & seek mandate upon confirmation, Thanks.	[I] Chong Boon Sen	

Date From



Date To



Audit Type

None

Go

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Bill Type	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
-------------	-----------	-----------	----------	----------	---------------------	-------	-------	--------

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607196R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Chong Boon Sen

Date: 29 Aug 2019

Preliminary Advice

Vehicle No	: SLN1836H	Accident Date	: 23/08/2019
Make	: TOYOTA WISH	Policy No.	: DMPCSN30227419000
Assignment Date	: 27/08/2019	Excess	: S\$750.00
Date of Inspection	: 27/08/2019	Est. Duration of Repair	: 5.00
Inspection At	: STK AUTO (S) PTE LTD (HQ) 8 KAKI BUKIT AVE4, #03-21 SINGAPORE 415875		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	17,775.14
Revised Amount	:S\$	5,916.45
Check Items (Estimated)	:S\$	874.69
Total	:S\$	6,791.14

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	82,000.00
COE / PARF Rebate	:S\$	56,089.00
Salvage Value	:S\$	
Margin for Repair	:S\$	25,911.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Chong Boon Sen

Date: 28 Aug 2019

Preliminary Advice

Vehicle No	: SLN1836H	Accident Date	: 23/08/2019
Make	: TOYOTA WISH	Policy No.	: DMPCSN30227419000
Assignment Date	: 27/08/2019	Excess	: S\$750.00
Date of Inspection	: 27/08/2019	Est. Duration of Repair	: 5.00
Inspection At	: STK AUTO (S) PTE LTD (HQ) 8 KAKI BUKIT AVE4, #03-21 SINGAPORE 415875		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	28,303.92
Revised Amount	:S\$	8,866.03
Check Items (Estimated)	:S\$	1,457.48
Total	:S\$	10,323.51
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	82,000.00
COE / PARF Rebate	:S\$	56,089.00
Salvage Value	:S\$	
Margin for Repair	:S\$	25,911.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

[. > Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Owner ID Type:	Singapore NRIC
Owner ID:	033J
Vehicle No.:	SLN1836H
Vehicle to be Exported:	No
Intended Deregistration Date:	27 Aug 2019
Vehicle Make:	TOYOTA
Vehicle Model:	WISH 1.8X CVT ABS D/AIRBAG 2WD 5DR
Primary Colour:	Silver
Manufacturing Year:	2016
Engine No.:	2ZR1767145
Chassis No.:	ZGE206031963
Maximum Power Output:	105.0 kW (140 bhp)
Open Market Value:	\$19,628.00
Original Registration Date:	25 Apr 2017
First Registration Date:	25 Apr 2017
Transfer Count:	0
Actual ARF Paid:	\$19,628.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	24 Apr 2027
PARF Rebate Amount:	\$14,721.00
COE Expiry Date:	24 Apr 2027
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$54,501.00
COE Rebate Amount:	\$41,368.00
Total Rebate Amount:	\$56,089.00

The information contained herein is correct as at 27 Aug 2019

OK

▶ Wish Used Vehicle List (20 vehicles)

Car Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Company	Availability
Toyota Wish 1.8A X	\$85,000	\$10,150 /yr	04-Jan-2017	1,797 cc	-		Available
Well Maintained. Office No. - - Joanna - 91478239							
Toyota Wish 1.8A X	\$80,500	\$9,460 /yr	24-Jan-2017	1,797 cc	-	Prime Motor & Leasing	Available
Elegant Silver MPV, One Owner Only, Low Mileage Done, Low Maintenance Cost, Very Well Maintained, Easy Financing, Flexible In-House Loan Packages Available. Office No. - 64440088 Connie - 91130008 Pauline - 97810269 Andy - 91086443 Jordan - 91168032							
Toyota Wish 1.8A X	\$86,000	\$10,250 /yr	09-Feb-2017	1,797 cc	119,000 km	Prem Roy Motoring	Available
Cheapest In Town! Low Interest Rate! 100% Loan Available! Well Maintained, Reliable And Spacious MPV, Well Taken Care Of By 1 Previous Owner, Original Paintwork Since Day 1. In House Loan And Bank Loa... Office No. - 66028046 Zin - 90025579 PRM Admin - 98896985							
Toyota Wish 1.8A Elegance	\$81,500	\$9,540 /yr	22-Feb-2017	1,798 cc	39,300 km		Available
5 Years Warranty Till Feb 2022, 100,000 Km Free Servicing With Borneo Motors Package Deal Peace Of Mind For At Least 5 Years 39,800 Km Low Mileage 1 Careful Owner, No Other Drivers, Accident Free New ... Office No. - - Ronnie Sng - 96338713							
Toyota Wish 1.8A Elegance	\$84,000	\$9,760 /yr	27-Mar-2017	1,798 cc	20,500 km	Bavarian Marques Pte Ltd	Available
1 Careful And Meticulous Owner, Low Mileage Done, Original Sporty Orange On Mocha Brown Borneo Fitted Leather Seats, Comes With 5 Years Warranty With Borneo, Well Maintained And Timely Serviced With A... Office No. - 67178811 Jeremiah - 98807671 Shawn - 88188544 Qai - 88148478 Eugene - 81333924							
Toyota Wish 1.8A	\$86,800	\$10,130 /yr	28-Mar-2017	1,798 cc	33,509 km	Trillium Automobile Pte Ltd	Available
Borneo Motors Unit! 1 Owner! Full Agent Service History And 5 Years Warranty Till March 2022! STA Welcome! High Trade In And In House Financing Available! View Today! Office No. - 64632050 Nic - 91182220 Neo - 83694896 Sky - 91191186							
Toyota Wish 1.8A Elegance	\$82,600	\$9,540 /yr	06-Apr-2017	1,798 cc	46,000 km	Motorist Pte Ltd	Available
Still Under 5 Years Warranty And Fully Serviced By Agent Since Day 1. Always Parked Under Shelter. Beautiful Blue Unit With Paint Protective Coating Done Up On April 18 With 5 Years Warranty. High Loa... Office No. - 65896800 Eugene Yeo - 98307999 Kanthan - 90225037							
Toyota Wish 1.8A X	\$86,800	\$10,030 /yr	07-Apr-2017	1,797 cc	28,000 km	Heritage Auto Enterprise Pte Ltd	Available
Cheapest In Town! 1.98% Special Interest Rate! 100% Loan Available! Well Maintained, Reliable And Spacious MPV, Superbly Well Taken Care Of By 1 Previous Owner, Original Paintwork Since Day 1. In Hou... Office No. - 63926608 Terence Koh - 88008998							
Toyota Wish 1.8A X	\$82,800	\$9,540 /yr	19-Apr-2017	1,797 cc	23,000 km	Heritage Auto Enterprise Pte Ltd	Available
Cheapest In Town! 100% Loan Available! Well Maintained, Reliable And Spacious MPV, Superbly Well Taken Care Of By Previous Owner, Original Paintwork Since Day 1. In House Loan And Bank Loan Available!... Office No. - 63926608							

Terence Koh - 88008998

Toyota Wish 1.8A	\$83,800	\$9,590 /yr	08-May-2017	1,798 cc	33,283 km	Asia Carz Auto	Available
-------------------------	-----------------	--------------------	--------------------	-----------------	------------------	-----------------------	------------------

100% Loan Available. Bank Loan Or In House Loan. Highest Trade In Available. Price Negotiable. Free Leather Seats Colour Choice If Confirm.

Office No. - -

Jack - 85712226

Toyota Wish 1.8A	\$83,800	\$9,590 /yr	08-May-2017	1,798 cc	33,825 km	Asia Carz Auto	Available
-------------------------	-----------------	--------------------	--------------------	-----------------	------------------	-----------------------	------------------

100% Loan Available! Free New Colour Choice For The Leather If Confirm. Price Negotiable.

Office No. - -

Jack - 85712226

Toyota Wish 1.8A	\$87,800	\$9,980 /yr	14-Jun-2017	1,798 cc	39,000 km	Yong Lee Seng Motor	Available
-------------------------	-----------------	--------------------	--------------------	-----------------	------------------	----------------------------	------------------

Evaluated By Vicom, Free 6 Months Maintenance And 1 Grooming.

Office No. - 68440123

Raymond Tang - 96250045 | Richmond Tang - 96200045

Toyota Wish 1.8A Elegance	\$84,800	\$9,570 /yr	22-Jun-2017	1,798 cc	55,237 km	Classic Credit Pte Ltd	Available
----------------------------------	-----------------	--------------------	--------------------	-----------------	------------------	-------------------------------	------------------

Beautiful Condition. High Spec "Elegance" Edition. 1 Owner. 100% Accident Free. Under Agent Warranty. Must View. Up To 100% Flexible Loan. We Provide Lowest Interest Rate. Flexible Loan And High Trade...

Office No. - 68412076 / 68481203 / 68414849

Alex - 90847643 | Roland - 97479331 | Mr Chen - 90044461

Toyota Wish 1.8A Elegance	\$85,800	\$9,650 /yr	04-Jul-2017	1,798 cc	43,000 km	Creative Auto	Available
----------------------------------	-----------------	--------------------	--------------------	-----------------	------------------	----------------------	------------------

One Careful Ownership, Underutilized Unit With Only 43k Km Clocked, Neither Grab, Uber Nor Go-Jek Usage Vehicle, 5 Years Warranty From First Purchase Makes You Drive With A Peace Of Mind, Zero Mishap ...

Office No. - -

Tian Cheng - 88338380 | Alex Tan - 97556887 | Terence Leow - 90290899

Toyota Wish 1.8A	\$85,800	\$9,630 /yr	12-Jul-2017	1,798 cc	26,000 km	Kruise Auto	Available
-------------------------	-----------------	--------------------	--------------------	-----------------	------------------	--------------------	------------------

Maintained And Serviced By Borneo Motors, Still Under Agent Warranty! As Good As New! Evergreen And Reliable Toyota Wish MPV, Equipped With A 1.8L Dual VVT-i Engine Providing You Sufficient Power For ...

Office No. - 65471511

Elden - 96794694 | Colin - 96487189 | Des - 81867412

Toyota Wish 1.8A	\$85,000	\$9,500 /yr	20-Jul-2017	1,798 cc	36,000 km	Wheels Singapore Pte Ltd	Available
-------------------------	-----------------	--------------------	--------------------	-----------------	------------------	---------------------------------	------------------

Excellent And Original Condition. Beautiful Pearl White. Spotless And Accident Free. Exterior And Interior In Mint Condition. Well Maintained Interior And Exterior. Owner Selling Due To Under Usage. G...

Office No. - 66815662

Keene Ong - 91868133 | Benjamin - 83237600

Toyota Wish 1.8A X	\$85,800	\$9,440 /yr	29-Aug-2017	1,797 cc	19,332 km	Le Motor Enterprise	Available
---------------------------	-----------------	--------------------	--------------------	-----------------	------------------	----------------------------	------------------

Various Loan From Bank/In House/Balloon Scheme With Most Attractive And 100% Fast Approval Rates! 1 Owner Only! Extremely Low Mileage Done At 19332Km Only! As Good As Buying Brand New! Advance Super C...

Office No. - 64405131

Desmond Tan - 92721418 | Richard Wong - 97692303

Toyota Wish 1.8A Elegance	\$85,888	\$9,380 /yr	28-Sep-2017	1,798 cc	43,000 km	Cars 88 Pte Ltd	Available
----------------------------------	-----------------	--------------------	--------------------	-----------------	------------------	------------------------	------------------

Fully Serviced By Agent! Warranty Till 07/21. Super Well Maintained And Perfect Condition. Flexi- Loan Available, All Trade In Are Welcome. Hurry! Call Us Now For Viewing And Test Drive, The Popular A...

Office No. - -

Michael Tng - 87678797 | Barry Lee - 82828788

Toyota Wish 1.8A	\$90,800	\$9,710 /yr	21-Dec-2017	1,798 cc	18,514 km	Select By Performance Premium Selection	Available
-------------------------	-----------------	--------------------	--------------------	-----------------	------------------	--	------------------

Agent Warranty Till Dec 2022! Evergreen And Reliable Toyota Wish Mid Size MPV, Equipped With A 1.8L Dual VVT-i Engine Providing You Sufficient Power For Your Daily Drive, Yet Returning Good Fuel Effic...

Office No. - 65074866

Norven Ng - 91809129 | Amanda Ong - 97561414 | Fiona Neo - 98488890 | Han - 96644456

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	26/08/2019 17:17
Date Of Accident	23/08/2019 18:30
Exact Location Of Accident	PIE TWDS SERANGOON
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLN1836H
Insured/Policyholder	
Name Of Registered Owner	MR HUANG JINHONG
NRIC No	S8165033J
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-90221606
Alternative Phone No	OFFICE-90221606

Vehicle Particulars

Manufacturer	TOYOTA
Model	WISH
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMPCSN3022741900
Cover Note Number	-

Driver

Name of Driver	MR HUANG JINHONG
NRIC No	S8165033J
Date Of Birth	26/11/1981
Occupation	OUTDOOR
Date Of Driving Pass	14/04/2011
Driving Experience	8 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90221606
Fax Number	
Contact Number	OFFICE-90221606
Email Address	NOEMAIL

Address	BLK 752 WOODLANDS CIRCLE #09-526
Postcode	730752
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO STATEMENT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKX189H
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to rescind policy liability.
4. The use and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (a) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NIC/FIN No.:

Accident Sketch Plan

SKETCH PLAN

PIE Towards Serangan



A: SLN 18364

B: SKX 1894

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On the date and time, I was driving my car along PIE Towards Serangan. Suddenly the front vehicle (A: SKX 1894) coming to a stop. I followed suit. I could not stop in time and hit into the rear of vehicle B.

DECLARATION

(We declare the foregoing particulars are true in every respect)

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
Nec/IRIS No.:

Shiau Chan (LKKAuto)

From: STK STK <stkautosg@gmail.com>
Sent: Friday, 6 September 2019 3:57 PM
To: SUR; Guo Qiang (LKKAuto)
Subject: Re: SLN1836H - Cost of repair Estimate

Dear Guoqiang

Please finalize at part by part @ \$ 7819.70, 5 days repair.

Thank you

Yours sincerely



Tan Guohua

Chief Executive Officer

STK AUTO (S) PTE LTD | www.stkauto.com.sg

Mobile: (65) 9123 7949 | Tel: (65) 63860669

8 Kaki Bukit Ave 4 #03-21 Singapore 415875 @PREMIER



x

STK STK <stkautosg@gmail.com> 于 2019 年 8 月 29 日周四下午 4:10 写道:

Dear In Charge office

Please refer to attached update cost of repair estimate.

Thank you

Yours sincerely

PLEASE ARRANGE TO SURVEY VEHICLE AT
NO.8 KAKI BUKIT AVENUE 4
#03-21 PREMIER @ KAKI BUKIT GATE 2
SINGAPORE 415875

ve used
purpose



Date : 26/08/2019

STK AUTO (S) PTE LTD

DID : 63860669

Fax : 63860669

HP : 97519596

TP Vehicle Number :

To : CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

Attn : Motor Claim Department

Owner : HUANG JIN HONG
CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

Certificate Number : DMPCSN3022741900

Accident Date : 23/08/2019

Vehicle Number : SLN1836H

Make & Model : TOYOTA WISH

ESTIMATED REPAIR COST DETAILS

cost + 15%

Excess \$250

5 Days.
Lump sum repair
part by part
before part photos.
Enc Qial
82880282
27/8/19.
Not Authorize
Excess \$250

QTY	DESCRIPTION	REPAIR AMOUNT	SURVEYOR APP.
<u>List Item</u>			
1	FRONT BUMPER / De	\$ 62.80	628.00
1	FRONT BUMPER RETAINER RH = 5 Re.	\$ 95.70	
1	FRONT BUMPER RETAINER LH	\$ 95.70	
1	FRONT BUMPER BRACKET RH ?	\$ 65.80	
1	FRONT BUMPER BRACKET LH ?	\$ 65.80	
1	FRONT BUMPER FOG LAMP COVER RH = 4 Re.	\$ 95.80	
1	FRONT BUMPER FOG LAMP COVER LH	\$ 95.80	
1	FRONT BUMPER SPONGE - CFA	\$ 195.60	
1	FRONT BUMPER REINFORCEMENT - BT	\$ 395.60	
1	FRONT BUMPER LOWER GRILLE	\$ 195.60	
1	FRONT GRILLE - CFA	\$ 185.60	
1	BONNET LOGO - MC	\$ 95.60	
1	BONNET - Bul	\$ 850.20	
1	BONNET HINGE RH X	\$ 95.60	
1	BONNET HINGE LH X	\$ 95.60	
1	BONNET STAND X	\$ 55.90	
1	BONNET INNER RUBBER X	\$ 65.90	
1	BONNET LOCK LOWER - BT.	\$ 155.30	
1	BONNET LOCK CABLE X	\$ 95.60	
1	BONNET RUBBER X	\$ 135.60	
1	BONNET INSULATOR - Re.	\$ 394.70	7308.80 - 25% 6280.70
1	RH HEADLAMP - CFA	\$ 1,200.30	
1	RH HEADLAMP PANEL X repair	\$ 95.60	
1	LH HEADLAMP - CFA	\$ 1,200.30	
1	LH HEADLAMP PANEL X repair	\$ 95.60	
1	LH FRONT DOOR X repair	\$ 1,369.60	
1	LH FRONT DOOR HINGE UPPER X	\$ 95.60	
1	LH FRONT DOOR HINGE LOWER X	\$ 95.60	
Sub Total		\$ 7,583.90	
Discount 25% on Parts		\$ (1,895.98)	
		\$ 5,687.93	

PAGE : 1

PLEASE ARRANGE TO SURVEY VEHICLE AT
NO.8 KAKI BUKIT AVENUE 4
#03-21 PREMIER @ KAKI BUKIT GATE 2
SINGAPORE 415875



Date : 26/08/2019

STK AUTO (S) PTE LTD

DID : 63860669

Fax : 63860669

HP : 97519596

TP Vehicle Number :

To : CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

Attn : Motor Claim Department

Owner : HUANG JIN HONG

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

Certificate Number : DMPCSN3022741900

Accident Date :

23/08/2019

Vehicle Number : SLN1836H

Make & Model : TOYOTA WISH

ESTIMATED REPAIR COST DETAILS

QTY	DESCRIPTION	REPAIR AMOUNT	SURVEYOR APP.
<u>List Item</u>			
1	LH FRONT DOOR CHECKR X	\$ 135.70	
1	LH FRONT DOOR INNER TRIM BOARD X	\$ 904.79	
1	LH FRONT DOOR LOCK X	\$ 650.40	
1	RH FRONT DOOR HINGE UPPER X	\$ 95.60	
1	RH FRONT DOOR HINGE LOWER X	\$ 95.60	
1	RH FRONT DOOR CHECKER X	\$ 135.70	
1	RH FRONT FENDER - due X	\$ 1,380.60	
1	LH FRONT FENDER - repair X	\$ 1,380.60	
1	RH FRONT FENDER INNER SHIELD X	\$ 256.90	
1	LH FRONT FENDER INNER SHIELD X	\$ 256.90	
1	FRONT SUPPORT PANEL - repair X	\$ 1,803.60	
1	FRONT SUPPORT PANEL TOP GARNISH X	\$ 150.60	
1	AIR CON DUCT X	\$ 95.60	
1	AIR CON DUCT HOSE X	\$ 165.30	
1	INTAKE MAINFUL X	\$ 881.60	
1	AIR CON CONDENSER - cut	\$ 1,411.90	
1	AIR CON CONDENSER INTAKE PIPE X	\$ 400.70	
1	AIR CON CONDENSER DRY PIPE X	\$ 622.67	
1	AIR CON COMPRESSOR X	\$ 3,425.90	
1	AIR CON CONDENSER FAN BLADE X	\$ 169.70	
1	AIR CON CONDENSER FAN MOTOR X	\$ 422.70	
1	RADIATOR ?	\$ 1,811.70	
1	RADIATOR FAN BLADE X	\$ 144.67	
1	RADIATOR FAN MOTOR X	\$ 467.70	
1	RADIATOR HOSE X	\$ 55.70	
1	ALTERNATOR X	\$ 2,551.70	
1	ALTERNATOR BLET X	\$ 160.70	
1	ABW PUMP X	\$ 3,500.00	
	Sub Total	\$ 36,567.48	
	Discount 25% on Parts	\$ (9,141.87)	
		\$ 27,425.61	

23535.73
- 25%
19651.42

PAGE : 2

record
purpose

PLEASE ARRANGE TO SURVEY VEHICLE AT
NO.8 KAKI BUKIT AVENUE 4
#03-21 PREMIER @ KAKI BUKIT GATE 2
SINGAPORE 415875



Date : 26/08/2019

TP Vehicle Number :

To : CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD
Attn : Motor Claim Department

Owner : HUANG JIN HONG
CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

Certificate Number : DMPCSN3022741900 Accident Date :

Vehicle Number : SLN1836H

STK AUTO (S) PTE LTD

DID : 63860669

Fax : 63860669

HP : 97519596

STK Auto Consultants hence notify

the Rep. irer of the following:

- To resurvey before/after spray painting
- To display damaged parts) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Authenticated by Repairer

23/08/2019

Signature:

Date:

Make & Model : TOYOTA WISH

QTY	DESCRIPTION	REPAIR AMOUNT	SURVEYOR APP.
-----	-------------	---------------	---------------

Special Nett Item

10 RH FRONT FENDER INNER SHIELD CLIPS	=	\$50.00
10 LH FRONT FENDER INNER SHIELD CLIPS	=	\$50.00
10 FRONT SUPPORT PANEL TOP GARNISH CLIPS	=	\$50.00
10 RH HEADLAMP BRACKET CLIPS	X	\$100.00
10 LH HEADLAMP BRACKET CLIPS	X	\$100.00
1 FRONT BUMPER SENSOR RH	=	\$180.90
1 FRONT BUMPER SENSOR LH	=	\$180.90
1 FRONT NUMBER PLATE	-	\$55.00
1 FRONT NUMBER PLATE CASING	-	\$55.00
10 FRONT BUMPER CLIPS	-	\$50.00
1 FRONT WINDSCREEN SEALANT	X	\$50.00
SUB TOTAL :		\$921.80

Labour & Misc

TO CHECK ALL NECESSARY WIRINGS	\$	150.00
TO RUST PROOF ON AFFECTED AREAS	\$	100.00
TO REMOVE & REFIT AIR CON CONDENSER & TOP UP GAS	\$	150.00
TO CHECK AND RADIATOR PRESSURE TEST	\$	150.00
TO REMOVE & REFIX LH FRONT DOOR	\$	150.00
TO REMOVE & REFIX RH FRONT DOOR	\$	150.00
TO REMOVE & REFIX FRONT WINDSCREEN	\$	150.00
COMPONENTS TO FACILITATE REPAIRS	\$	100.00
LABOUR TO FACILITATE REPAIR	\$	1,200.00
LABOUR & SPRAY PAINTING	\$	1,200.00
Sub Total	\$	3,500.00

Sub Total \$ 37,535.34

7% GST \$ 2,627.47

Total \$ 40,162.81

30
60
50
50
X
X
X
X
500
1000

28303.92

PAGE : 3

STK AUTO (S) PTE LTD 8 KAKI BUKIT AVENUE 4 #03-21 SINGAPORE 415875 | Tel: 63860669 |

Company Registration No. : 201539883N

PLEASE ARRANGE TO SURVEY VEHICLE AT
NO.8 KAKI BUKIT AVENUE 4
#03-21 PREMIER @ KAKI BUKIT GATE 2
SINGAPORE 415875



STK AUTO (S) PTE LTD

DID : 63860669

Fax : 63860669

HP : 97519596

Date : 26/08/2019

TP Vehicle Number :

To : CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

Attn : Motor Claim Department

Owner : HUANG JIN HONG

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

Certificate Number : DMPCSN3022741900

Accident Date : 23/08/2019

Vehicle Number : SLN1836H

Make & Model : TOYOTA WISH

ESTIMATED REPAIR COST DETAILS

QTY	DESCRIPTION	REPAIR AMOUNT	SURVEYOR APP.
<u>List Item</u>			
1	FRONT BUMPER	\$ 280.00	OC-
1	FRONT BUMPER RETAINER RH	\$ 38.00	OC-
1	FRONT BUMPER RETAINER LH	\$ 38.00	OC-
1	FRONT BUMPER BRACKET RH	\$ 35.00	X SNN
1	FRONT BUMPER BRACKET LH	\$ 35.00	OC-
1	FRONT BUMPER FOG LAMP COVER RH	\$ 45.00	OC-
1	FRONT BUMPER FOG LAMP COVER LH	\$ 45.00	OC-
1	FRONT BUMPER SPONGE	\$ 95.00	OC-
1	FRONT BUMPER REINFORCEMENT	\$ 160.00	OC-
1	FRONT BUMPER LOWER GRILLE	\$ 95.60	X NN
1	FRONT GRILLE	\$ 160.00	OC-
1	BONNET LOGO	\$ 45.00	OC-
1	BONNET	\$ 350.00	OC-
40	BONNET HINGE RH	\$ 30.00	BT
40	BONNET HINGE LH	\$ 30.00	BT
1	BONNET STAND	\$ 25.00	OC-
1	BONNET INNER RUBBER	\$ 20.00	OC-
1	BONNET LOCK LOWER	\$ 55.00	OC-
1	BONNET LOCK CABLE	\$ 25.00	OC-
1	BONNET RUBBER	\$ 20.00	OC-
1	BONNET INSULATOR	\$ 200.00	OC-
1	RH HEADLAMP	\$ 400.00	OC-
1	RH HEADLAMP PANEL	\$ 65.00	BT
1	LH HEADLAMP	\$ 400.00	OC-
1	LH HEADLAMP PANEL	\$ 65.00	BT
1	LH FRONT DOOR	\$ 480.00	OC-
1	LH FRONT DOOR HINGE UPPER	\$ 35.00	OC-
1	LH FRONT DOOR HINGE LOWER	\$ 35.00	OC-
	Sub Total	\$ 3,328.60	
	Mark Up 15% on Parts	\$ 498.99	
		\$ 3,825.59	

PAGE : 1

PLEASE ARRANGE TO SURVEY VEHICLE AT
NO.8 KAKI BUKIT AVENUE 4
#03-21 PREMIER @ KAKI BUKIT GATE 2
SINGAPORE 415875



Date : 26/08/2019

STK AUTO (S) PTE LTD

DID : 63860669

Fax : 63860669

HP : 97519596

TP Vehicle Number :

To : CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

Attn : Motor Claim Department

Owner : HUANG JIN HONG

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

Certificate Number : DMPCSN3022741900

Accident Date :

23/08/2019

Vehicle Number : SLN1836H

Make & Model : TOYOTA WISH

ESTIMATED REPAIR COST DETAILS

QTY	DESCRIPTION	REPAIR AMOUNT	SURVEYOR APP.
<u>List Item</u>			
1	LH FRONT DOOR CHECKR	\$ 55.00	X
1	LH FRONT DOOR INNER TRIM BOARD	\$ 285.00	X
1	LH FRONT DOOR LOCK	\$ 150.00	X
1	RH FRONT DOOR HINGE UPPER	\$ 35.00	X
1	RH FRONT DOOR HINGE LOWER	\$ 35.00	X
1	RH FRONT DOOR CHECKER	\$ 55.00	X
1	RH FRONT FENDER	\$ 380.00	X
1	LH FRONT FENDER	\$ 380.00	X
1	RH FRONT FENDER INNER SHIELD	\$ 65.00	X
1	LH FRONT FENDER INNER SHIELD	\$ 65.00	X
1	FRONT SUPPORT PANEL	\$ 450.00	X
1	FRONT SUPPORT PANEL TOP GARNISH	\$ 55.00	X
1	AIR CON DUCT	\$ 45.00	X
1	AIR CON DUCT HOSE	\$ 45.00	X
1	INTAKE MAINFUL	\$ 280.00	X
1	AIR CON CONDENSER	\$ 380.00	X
1	AIR CON CONDENSER INTAKE PIPE	\$ 180.00	X
1	AIR CON CONDENSER DRY PIPE	\$ 280.00	X
1	AIR CON COMPRESSOR	\$ 1,800.00	X
1	AIR CON CONDENSER FAN BLADE	\$ 85.00	X
1	AIR CON CONDENSER FAN MOTOR	\$ 130.00	X
1	RADIATOR	\$ 500.00	X
1	RADIATOR FAN BLADE	\$ 65.00	X
1	RADIATOR FAN MOTOR	\$ 130.00	X
1	RADIATOR HOSE	\$ 25.00	X
1	ALTERNATOR	\$ 680.00	X
1	ALTERNATOR BELT	\$ 55.00	X
1	AWW PUMP	\$ 1,500.00	X
1	FRONT BRACE PANEL	\$ 95.00	X
	Sub Total	\$ 8,285.00	
	Mark Up 15% on Parts	\$ 1,242.75	
		\$ 9,527.75	

PAGE : 2

STK AUTO (S) PTE LTD @ KAKI BUKIT AVENUE 4 #03-21 SINGAPORE 415875 | Tel: 63860669 | Fax: 63860669

Company Registration No. : 201539863N

5607.4

4876

4706

+15%

PLEASE ARRANGE TO SURVEY VEHICLE AT
NO.8 KAKI BUKIT AVENUE 4
#03-21 PREMIER @ KAKI BUKIT GATE 2
SINGAPORE 415875



Date : 25/08/2019

TP Vehicle Number :

To : CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD
Attn : Motor Claim Department

Owner : HUANG JIN HONG
CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

Certificate Number : DMPCSN3022741900

Accident Date :

23/08/2019

Vehicle Number : SLN1836H

Make & Model : TOYOTA WISH

QTY	DESCRIPTION	REPAIR AMOUNT	SURVEYOR APP.
-----	-------------	---------------	---------------

Special Nett Item

10 RH FRONT FENDER INNER SHIELD CLIPS	20	\$50.00
10 LH FRONT FENDER INNER SHIELD CLIPS	20	\$50.00
10 FRONT SUPPORT PANEL TOP GARNISH CLIPS	20	\$50.00
10 RH HEADLAMP BRACKET CLIPS	X	\$100.00
10 LH HEADLAMP BRACKET CLIPS	X	\$100.00
1 FRONT BUMPER SENSOR RH	100	\$180.90
1 FRONT BUMPER SENSOR LH	100	\$180.90
1 FRONT NUMBER PLATE	20	\$55.00
1 FRONT NUMBER PLATE CASING	20	\$55.00
10 FRONT BUMPER CLIPS	30	\$50.00
1 FRONT WINDSCREEN SEALANT	X	\$50.00

SUB TOTAL :

\$821.80

Labour & Misc

TO CHECK ALL NECESSARY WIRINGS	\$	150.00
TO RUST PROOF ON AFFECTED AREAS	\$	100.00
TO REMOVE & REFIT AIR CON CONDENSER & TOP UP GAS	\$	150.00
TO CHECK AND RADIATOR PRESSURE TEST	\$	150.00
TO REMOVE & REFIX LH FRONT DOOR	\$	150.00
TO REMOVE & REFIX RH FRONT DOOR	\$	150.00
TO REMOVE & REFIX FRONT WINDSCREEN	\$	150.00
COMPONENTS TO FACILITATE REPAIRS	\$	100.00
LABOUR TO FACILITATE REPAIR	\$	1,200.00
LABOUR & SPRAY PAINTING	\$	1,200.00
Sub Total	\$	3,500.00

Sub Total \$ 17,775.14

7% GST \$ 1,244.26

Total \$ 19,019.40

Handwritten notes and signatures in the Surveyor App. column, including "NN" and "330".

PAGE : 3

STK AUTO (S) PTE LTD 8 KAKI BUKIT AVENUE 4 #03-21 SINGAPORE 415875 | Tel: 63980689

Company Registration No. : 201539883N

Handwritten calculation: 1777.4

Handwritten calculation: 17972.64

PLEASE ARRANGE TO SURVEY VEHICLE AT
NO.8 KAKI BUKIT AVENUE 4
#03-21 PREMIER @ KAKI BUKIT GATE 2
SINGAPORE 415875



STK AUTO (S) PTE LTD

DID : 63860869

Fax : 63860869

HP : 97118385

Date : 25/08/2019

TP Vehicle Number

To : CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

Attn : Motor Claim Department

Owner : HUANG JIN HONG

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

Certificate Number : OMPCSN3622741900

Accident Date

23/08/2019

Vehicle Number : SUN183BH

Make & Model : TOYOTA WISH

ESTIMATED REPAIR COST DETAILS

QTY	DESCRIPTION	REPAIR AMOUNT	SURVEYOR APP.
<u>List Item</u>			
1	LH FRONT DOOR CHECKR	\$ 55.00	X
1	LH FRONT DOOR INNER TRIM BOARD	\$ 285.00	X
1	LH FRONT DOOR LOCK	\$ 150.00	X
1	RH FRONT DOOR HINGE UPPER	\$ 35.00	X
1	RH FRONT DOOR HINGE LOWER	\$ 35.00	X
1	RH FRONT DOOR CHECKER	\$ 55.00	X
1	RH FRONT FENDER	\$ 380.00	X
1	LH FRONT FENDER	\$ 380.00	X
1	RH FRONT FENDER INNER SHIELD	\$ 65.00	X
1	LH FRONT FENDER INNER SHIELD	\$ 65.00	X
1	FRONT SUPPORT PANEL	\$ 450.00	X
1	FRONT SUPPORT PANEL TOP GARNISH	\$ 55.00	X
1	AIR CON DUCT	\$ 45.00	X
1	AIR CON DUCT HOSE	\$ 45.00	X
1	INTAKE MANIFUL	\$ 250.00	X
1	AIR CON CONDENSER	\$ 390.00	X
1	AIR CON CONDENSER INTAKE PIPE	\$ 180.00	X
1	AIR CON CONDENSER DRY PIPE	\$ 280.00	X
1	AIR CON COMPRESSOR	\$ 1,800.00	X
1	AIR CON CONDENSER FAN BLADE	\$ 55.00	X
1	AIR CON CONDENSER FAN MOTOR	\$ 170.00	X
1	RADIATOR	\$ 500.00	X
1	RADIATOR FAN BLADE	\$ 65.00	X
1	RADIATOR FAN MOTOR	\$ 130.00	X
1	RADIATOR HOSE	\$ 25.00	X
1	ALTERNATOR	\$ 680.00	X
1	ALTERNATOR BELT	\$ 65.00	X
1	AWW PUMP	\$ 1,500.00	X
1	FRONT BRACE PANEL	\$ 95.00	X
	Sub Total	\$ 8,285.00	
	Mark Up 15% on Parts	\$ 1,242.75	
		\$ 9,527.75	

PAGE : 2

PLEASE ARRANGE TO SURVEY VEHICLE AT
NO.8 KAKI BUKIT AVENUE 4
#03-21 PREMIER @ KAKI BUKIT GATE 2
SINGAPORE 415875



STK AUTO (S) PTE LTD

DID : 63860669

Fax : 63440869

HP : 97518846

Date : 26/08/2019

TP Vehicle Number :

To : CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

Attn : Motor Claim Department

Owner : HUANG JIN HONG

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

Certificate Number : DMPCSN3022741900

Accident Date : 23/08/2019

Vehicle Number : SLN1636H

Make & Model : TOYOTA WISH

Emo Ap
UK 30/8/19.

ESTIMATED REPAIR COST DETAILS

QTY	DESCRIPTION	REPAIR AMOUNT	SURVEYOR APP.
<u>List Item</u>			
1	FRONT BUMPER	\$ 280.00	<i>OK</i>
1	FRONT BUMPER RETAINER RH	\$ 38.00	<i>OK</i>
1	FRONT BUMPER RETAINER LH	\$ 38.00	<i>OK</i>
1	FRONT BUMPER BRACKET RH	\$ 38.00	<i>OK</i>
1	FRONT BUMPER BRACKET LH	\$ 38.00	<i>OK</i>
1	FRONT BUMPER FOG LAMP COVER RH	\$ 45.00	<i>OK</i>
1	FRONT BUMPER FOG LAMP COVER LH	\$ 45.00	<i>OK</i>
1	FRONT BUMPER SPONGE	\$ 35.00	<i>OK</i>
1	FRONT BUMPER REINFORCEMENT	\$ 115.00	<i>OK</i>
1	FRONT BUMPER LOWER GRILLE	\$ 95.00	<i>OK</i>
1	FRONT GRILLE	\$ 100.00	<i>OK</i>
1	BONNET LOGO	\$ 45.00	<i>OK</i>
1	BONNET	\$ 150.00	<i>OK</i>
1	BONNET HINGE RH	\$ 30.00	<i>OK</i>
1	BONNET HINGE LH	\$ 30.00	<i>OK</i>
1	BONNET STAY	\$ 15.00	<i>OK</i>
1	BONNET INNER RUBBER	\$ 10.00	<i>OK</i>
1	BONNET LOCK LOWER	\$ 15.00	<i>OK</i>
1	BONNET LOCK CABLE	\$ 15.00	<i>OK</i>
1	BONNET RUBBER	\$ 10.00	<i>OK</i>
1	BONNET INSULATOR	\$ 20.00	<i>OK</i>
1	RH HEADLAMP	\$ 450.00	<i>OK</i>
1	RH HEADLAMP PANEL	\$ 15.00	<i>OK</i>
1	LH HEADLAMP	\$ 450.00	<i>OK</i>
1	LH HEADLAMP PANEL	\$ 15.00	<i>OK</i>
1	LH FRONT DOOR	\$ 45.00	<i>OK</i>
1	LH FRONT DOOR HINGE UPPER	\$ 35.00	<i>OK</i>
1	LH FRONT DOOR HINGE LOWER	\$ 35.00	<i>OK</i>
	Sub Total	\$ 3,235.00	
	Mark Up 15% on Parts	\$ 485.25	
		\$ 3,720.25	

PAGE : 1

PLEASE ARRANGE TO SURVEY VEHICLE AT
NO.8 KAKI BUKIT AVENUE 4
#03-21 PREMIER @ KAKI BUKIT GATE 2
SINGAPORE 415875



Date : 26/08/2019

STK AUTO (S) PTE LTD

DID : 63860669

Fax : 63860669

HP : 97519386

TP Vehicle Number :

To : CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

Attn : Motor Claim Department

Owner : HUANG JIN HONG

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

Certificate Number : DMPCSN3022741900

Accident Date :

23/08/2019

Vehicle Number : SLN1836H

Make & Model : TOYOTA WISH

ESTIMATED REPAIR COST DETAILS

QTY	DESCRIPTION	REPAIR AMOUNT	SURVEYOR APP.
<u>List Item</u>			
1	LH FRONT DOOR CHECKR	\$ 55.00	
1	LH FRONT DOOR INNER TRIM BOARD	\$ 285.00	
1	LH FRONT DOOR LOCK	\$ 150.00	
1	RH FRONT DOOR HINGE UPPER	\$ 35.00	
1	RH FRONT DOOR HINGE LOWER	\$ 35.00	
1	RH FRONT DOOR CHECKER	\$ 55.00	
1	RH FRONT FENDER	\$ 380.00	
1	LH FRONT FENDER	\$ 380.00	
1	RH FRONT FENDER INNER SHIELD	\$ 65.00	
1	LH FRONT FENDER INNER SHIELD	\$ 65.00	
1	FRONT SUPPORT PANEL	\$ 450.00	
1	FRONT SUPPORT PANEL TOP GARNISH	\$ 55.00	
1	AIR CON DUCT	\$ 45.00	
1	AIR CON DUCT HOSE	\$ 45.00	
1	INTAKE MAINFUL	\$ 280.00	
1	AIR CON CONDENSER	\$ 380.00	
1	AIR CON CONDENSER INTAKE PIPE	\$ 180.00	
1	AIR CON CONDENSER DRY PIPE	\$ 280.00	
1	AIR CON COMPRESSOR	\$ 1,800.00	
1	AIR CON CONDENSER FAN BLADE	\$ 85.00	
1	AIR CON CONDENSER FAN MOTOR	\$ 130.00	
1	RADIATOR	\$ 500.00	
1	RADIATOR FAN BLADE	\$ 65.00	
1	RADIATOR FAN MOTOR	\$ 130.00	
1	RADIATOR HOSE	\$ 25.00	
1	ALTERNATOR	\$ 680.00	
1	ALTERNATOR BLET	\$ 55.00	
1	AWP PUMP	\$ 1,500.00	
1	FRONT BRACE PANEL	\$ 95.00	
	Sub Total	\$ 8,285.00	
	Mark Up 15% on Parts	\$ 1,242.75	
		\$ 9,527.75	

PAGE : 2

PLEASE ARRANGE TO SURVEY VEHICLE AT
NO.8 KAKI BUKIT AVENUE 4
#03-21 PREMIER @ KAKI BUKIT GATE 2
SINGAPORE 416875



STK AUTO (S) PTE LTD
DID : 63560869
Fm : 63560869
Hf : 63560869

STK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" base
- No illegal modification(s) is allowed
- Supplementary detail(s) must be resurveyed and is subject to final approval from Insurance Company

Date : 25/03/2019

TP Vehicle Number :

To : CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD
Attn : Motor Claim Department

Owner : HUANG JIN HONG
CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

Acknowledged by Repairer
Signature :

Certificate Number : DMPCBN3022741900

Accident Date : 23/03/2019

Vehicle Number : SUH1636H

Make & Model : TOYOTA WISH

QTY	DESCRIPTION	REPAIR AMOUNT	SURVEYOR APP.
-----	-------------	---------------	---------------

Special Net Item

10 RH FRONT FENDER INNER SHIELD CLIPS	\$50.00	
10 LH FRONT FENDER INNER SHIELD CLIPS	\$50.00	
10 FRONT SUPPORT PANEL TOP GARNISH CLIPS	\$50.00	
10 RH HEADLAMP BRACKET CLIPS	\$100.00	
10 LH HEADLAMP BRACKET CLIPS	\$100.00	
1 FRONT BUMPER SENSOR RH	\$180.00	
1 FRONT BUMPER SENSOR LH	\$180.00	
1 FRONT NUMBER PLATE	\$55.00	
1 FRONT NUMBER PLATE CASING	\$55.00	
10 FRONT BUMPER LAMPS	\$5.00	
1 FRONT WINDSCREEN SEALANT	\$50.00	
SUB TOTAL :	\$650.00	

Labour & Notes

TO CHECK ALL NECESSARY WIRINGS	\$	50.00	
TO RUST PROOF ON AFFECTED AREAS	\$	50.00	
TO REMOVE & REPAIR AIR CON CONDENSER & TOP UP GAS	\$	150.00	
TO CHECK AND RADIATOR PRESSURE TEST	\$	50.00	
TO REMOVE & REPAIR LH FRONT DOOR	\$	150.00	
TO REMOVE & REPAIR RH FRONT DOOR	\$	150.00	
TO REMOVE & REPAIR FRONT WINDSCREEN	\$	100.00	
COMPONENTS TO FACILITATE REPAIRS	\$	100.00	
LABOUR TO FACILITATE REPAIR	\$	1,200.00	
LABOUR & SPRAY PAINTING	\$	2,500.00	
Sub Total	\$	3,300.00	
Sub Total	\$	3,300.00	
7% GST	\$	231.00	
Total	\$	3,531.00	

PAGE : 3

PLEASE ARRANGE TO SURVEY VEHICLE AT
NO.8 KAKI BUKIT AVENUE 4
#03-21 PREMIER @ KAKI BUKIT GATE 2
SINGAPORE 415875



Date : 26/08/2019

STK AUTO (S) PTE LTD

DID : 63860669

Fax : 63860669

HP : 97519596

TP Vehicle Number :

To : CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

Attn : Motor Claim Department

Owner : HUANG JIN HONG

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

Certificate NDMPCSN3022741900

Accident Date : 23/08/2019

Vehicle Num SLN1836H

Make & Mod TOYOTA WISH

ESTIMATED REPAIR COST DETAILS

S/N	QTY	DESCRIPTION	REPAIR AMOUNT	SURVEYOR
		<u>List Item</u>		
1 1		FRONT BUMPER	\$ 280.00	\$ 280.00
2 1		FRONT BUMPER RETAINER RH	\$ 38.00	\$ 38.00
3 1		FRONT BUMPER RETAINER LH	\$ 38.00	\$ 38.00
4 1		FRONT BUMPER BRACKET RH	\$ 35.00	
5 1		FRONT BUMPER BRACKET LH	\$ 35.00	
6 1		FRONT BUMPER FOG LAMP COVER RH	\$ 45.00	\$ 45.00
7 1		FRONT BUMPER FOG LAMP COVER LH	\$ 45.00	\$ 45.00
8 1		FRONT BUMPER SPONGE	\$ 95.00	\$ 95.00
9 1		FRONT BUMPER REINFORCEMENT	\$ 180.00	\$ 180.00
10 1		FRONT BUMPER LOWER GRILLE	\$ 95.60	
11 1		FRONT GRILLE	\$ 160.00	\$ 160.00
12 1		BONNET LOGO	\$ 45.00	\$ 45.00
13 1		BONNET	\$ 350.00	\$ 350.00
14 1		BONNET HINGE RH	\$ 40.00	\$ 40.00
15 1		BONNET HINGE LH	\$ 40.00	\$ 40.00
16 1		BONNET STAND	\$ 25.00	
17 1		BONNET INNER RUBBER	\$ 20.00	
18 1		BONNET LOCK LOWER	\$ 55.00	\$ 55.00
19 1		BONNET LOCK CABLE	\$ 25.00	
20 1		BONNET RUBBER	\$ 20.00	
21 1		BONNET INSULATOR	\$ 200.00	\$ 200.00
22 1		RH HEADLAMP	\$ 400.00	\$ 400.00
23 1		RH HEADLAMP PANEL	\$ 65.00	\$ 65.00
24 1		LH HEADLAMP	\$ 400.00	\$ 400.00
25 1		LH HEADLAMP PANEL	\$ 65.00	\$ 65.00
26 1		LH FRONT DOOR	\$ 480.00	
27 1		LH FRONT DOOR HINGE UPPER	\$ 35.00	
28 1		LH FRONT DOOR HINGE LOWER	\$ 35.00	
		Sub Total	\$ 3,346.60	2541
		Mark Up 15% on Parts	\$ 836.65	381.15
			\$ 4,183.25	2922.15
			PAGE :	1

PLEASE ARRANGE TO SURVEY VEHICLE AT
NO.8 KAKI BUKIT AVENUE 4
#03-21 PREMIER @ KAKI BUKIT GATE 2
SINGAPORE 415875



Date : 26/08/2019

TP Vehicle Number :

To : CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

Attn : Motor Claim Department

STK AUTO (S) PTE LTD

DID : 63860669

Fax : 63860669

HP : 97519596

Owner : HUANG JIN HONG
CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

Certificate NDMPCSN3022741900

Accident Date : 23/08/2019

Vehicle Nun:SLN1836H

Make & Mod:TOYOTA WISH

ESTIMATED REPAIR COST DETAILS

QTY	DESCRIPTION	REPAIR AMOUNT	SURVEYOR APP.
<u>List Item</u>			
29	1 LH FRONT DOOR CHECKR	\$ 55.00	
30	1 LH FRONT DOOR INNER TRIM BOARD	\$ 285.00	
31	1 LH FRONT DOOR LOCK	\$ 150.00	
32	1 RH FRONT DOOR HINGE UPPER	\$ 35.00	
33	1 RH FRONT DOOR HINGE LOWER	\$ 35.00	
34	1 RH FRONT DOOR CHECKER	\$ 55.00	
35	1 RH FRONT FENDER	\$ 380.00	\$ 380.00
36	1 LH FORNT FENDER	\$ 380.00	\$ 380.00
37	1 RH FRONT FENDER INNER SHIELD	\$ 65.00	
38	1 LH FRONT FENDER INNER SHIELD	\$ 65.00	
39	1 FRONT SUPPORT PANEL	\$ 500.00	\$ 500.00
40	1 FRONT SUPPORT PANEL TOP GARNISH	\$ 55.00	
41	1 AIR CON DUCT	\$ 45.00	
42	1 AIR CON DUCT HOSE	\$ 45.00	
43	1 INTAKE MAINFUL	\$ 280.00	
44	1 AIR CON CONDENSER	\$ 380.00	\$ 380.00
45	1 AIR CON CONDENSER INTAKE PIPE	\$ 180.00	
46	1 AIR CON CONDENSER DRY PIPE	\$ 280.00	
47	1 AIR CON COMPRESSOR	\$ 1,800.00	
48	1 AIR CON CONDENSER FAN BLADE	\$ 85.00	
49	1 AIR CON CONDENSER FAN MOTOR	\$ 130.00	
50	1 RADIATOR	\$ 600.00	\$ 600.00
51	1 RADIATOR FAN BLADE	\$ 65.00	
52	1 RADIATOR FAN MOTOR	\$ 130.00	
53	1 RADIATOR HOSE	\$ 25.00	
54	1 ALTERNATOR	\$ 680.00	
55	1 ALTERNATOR BLET	\$ 55.00	
56	1 ABW PUMP	\$ 1,500.00	
57	1 FROTN BRACE PANEL	\$ 95.00	\$ 95.00
	Sub Total	\$ 8,435.00	\$ 2,335.00
	Mark Up 15% on Parts	\$ 1,265.25	\$ 350.25
		\$ 9,700.25	\$ 2,685.25
	PAGE :	2	

PLEASE ARRANGE TO SURVEY VEHICLE AT
NO.8 KAKI BUKIT AVENUE 4
#03-21 PREMIER @ KAKI BUKIT GATE 2
SINGAPORE 415875



Date : 28/08/2019

TP Vehicle Number :

STK AUTO (S) PTE LTD

DID : 63860669

Fax : 63860669

HP : 97519596

To : CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD
Attn : Motor Claim Department

Owner : HUANG JIN HONG
CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

Certificate NDMPCSN3022741900

Accident Date : 23/08/2019

Vehicle Num SLN1836H

Make & Mod TOYOTA WISH

S/N	QTY	DESCRIPTION	REPAIR AMOUNT	SURVEYOR
Special Nett Item				
1	10	RH FRONT FENDER INNER SHIELD CLIPS	\$50.00	\$ 20.00
2	10	LH FRONT FENDER INNER SHIELD CLIPS	\$50.00	\$ 20.00
3	10	FRONT SUPPORT PANEL TOP GARNISH CLIPS	\$50.00	\$ 20.00
4	10	RH HEADLAMP BRACKET CLIPS	\$100.00	
5	10	LH HEADLAMP BRACKET CLIPS	\$100.00	
6	1	FRONT BUMPER SENSOR RH	\$180.90	\$ 100.00
7	1	FRONT BUMPER SENSOR LH	\$180.90	\$ 100.00
8	1	FRONT NUMBER PLATE	\$55.00	\$ 20.00
9	1	FRONT NUMBER PLATE CASING	\$55.00	\$ 20.00
10	10	FRONT BUMPER CLIPS	\$50.00	
11	1	FRONT WINDSCREEN SEALANT	\$50.00	
SUB TOTAL :			\$921.80	\$ 300.00
S/N Labour & Misc				
	1	TO CHECK ALL NECESSARY WIRINGS	\$ 150.00	\$ 30.00
	2	TO RUST PROOF ON AFFECTED AREAS	\$ 100.00	\$ 60.00
	3	TO REMOVE & REFIT AIR CON CONDENSER & TOP UP	\$ 150.00	\$ 50.00
	4	TO CHECK AND RADIATOR PRESSURE TEST	\$ 150.00	\$ 50.00
	5	TO REMOVE & REFIX LH FRONT DOOR	\$ 150.00	
	6	TO REMOVE & REFIX RH FRONT DOOR	\$ 150.00	
	7	TO REMOVE & REFIX FRONT WINDSCREEN	\$ 150.00	
	8	COMPONENTS TO FACILITATE REPAIRS	\$ 100.00	
	9	LABOUR TO FACILITATE REPAIR	\$ 1,200.00	\$ 600.00
	10	LABOUR & SPRAY PAINTING	\$ 1,200.00	\$ 1,000.00
		Sub Total	\$ 3,500.00	\$ 1,790.00
		Sub Total	\$ 18,305.30	\$ 7,727.40
		7% GST	\$ 1,281.37	\$ 540.92
		Total	\$ 19,586.67	\$ 8,268.32
			PAGE :	3

STK AUTO (S) PTE LTD # KAKI BUKIT AVENUE 4 #03-21 SINGAPORE 415875 | Tel: 63860669 |

Company Registration No. : 201539883N

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	27 Aug 2019		27 Aug 2019 13:26 Edit Adj Rpt	\$7,727.40 Edit Estimates	\$7,727.40 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	HUANG JINHONG, ID: S81650331								
Vehicle Reg. No.:	SLN1836H	Date of Loss:	23/08/2019 00:00 - :59 [27 Months and 29 Days From LTA Reg Date (Man Yr)]						
Claim Type:	OD / SNM19D203983C01	Policy/Cover Note No.:	DMPCSN30227419000 (Comprehensive)						
		Excess:	\$750.00						
Repairer:	Stk Auto (s) Pte Ltd (HQ) 8 kaki bukit ave4, #03-21, 415875 Kaki Bukit - Tel:								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 05/09/2019]								
Driver/Custodian:	HUANG JINHONG (/ Male) , NRIC: S81650331 Email:								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- CHINA_TAIPING (30/08/2019): Alert - Adj Mandate Approved (\$6791.14) - SLN1836H - Claim Handler: Chong Boon ... - CHINA_TAIPING (29/08/2019): Alert - Adj Mandate Maintained - SLN1836H - Claim Handler: Chong Boon Sen									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLN1836H (SNM19D203983C01)

OD

Aug 23 2019 12:00AM

[HUANG JINHONG]

Stk Auto (s) Pte Ltd

[Upload Documents](#) |
 [Upload Photos](#) |
 [Compose New Letter](#)
View [View in Browser](#)

Assessment Reports			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	28/08/19 13:15	Adjuster Immediate Advice	 Load HTM	☐
2	29/08/19 17:17	Adjuster Immediate Advice	 Load HTM	☐
Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	28/08/19 13:05	General View	 Load JPG	☒
2	28/08/19 13:05	General View	 Load JPG	☒
3	28/08/19 13:05	General View	 Load JPG	☒
4	28/08/19 13:05	General View	 Load JPG	☒
5	28/08/19 13:05	General View	 Load JPG	☒
6	28/08/19 13:05	General View	 Load JPG	☒
7	28/08/19 13:05	General View	 Load JPG	☒
8	28/08/19 13:05	General View	 Load JPG	☒
9	28/08/19 13:05	General View	 Load JPG	☒
10	28/08/19 13:05	General View	 Load JPG	☒
11	28/08/19 13:05	General View	 Load JPG	☒
12	28/08/19 13:05	General View	 Load JPG	☒
13	28/08/19 13:05	General View	 Load JPG	☒
14	28/08/19 13:05	General View	 Load JPG	☒
15	28/08/19 13:05	General View	 Load JPG	☒
16	28/08/19 13:05	General View	 Load JPG	☒
17	28/08/19 13:05	General View	 Load JPG	☒
18	28/08/19 13:05	General View	 Load JPG	☒
19	28/08/19 13:05	General View	 Load JPG	☒
20	28/08/19 13:05	General View	 Load JPG	☒
21	28/08/19 13:05	General View	 Load JPG	☒
22	28/08/19 13:05	General View	 Load JPG	☒
23	28/08/19 13:05	General View	 Load JPG	☒
24	28/08/19 13:05	General View	 Load JPG	☒
25	28/08/19 13:05	General View	 Load JPG	☒
26	28/08/19 13:05	General View	 Load JPG	☒
27	28/08/19 13:05	General View	 Load JPG	☒
28	28/08/19 13:05	General View	 Load JPG	☒
29	28/08/19 13:05	General View	 Load JPG	☒
30	28/08/19 13:05	General View	 Load JPG	☒
31	28/08/19 13:05	General View	 Load JPG	☒
32	28/08/19 13:05	General View	 Load JPG	☒
33	28/08/19 13:05	General View	 Load JPG	☒
34	28/08/19 13:05	General View	 Load JPG	☒
35	28/08/19 13:05	General View	 Load JPG	☒
36	28/08/19 13:05	General View	 Load JPG	☒
37	28/08/19 13:05	General View	 Load JPG	☒
38	28/08/19 13:05	General View	 Load JPG	☒
39	28/08/19 13:05	General View	 Load JPG	☒
40	28/08/19 13:05	General View	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
41	28/08/19 13:05	General View		☒
42	28/08/19 13:05	General View		☒
43	28/08/19 13:05	Odometer Reading		☒
44	13/09/19 17:32	Dismantled Parts		☒
45	13/09/19 17:32	Dismantled Parts		☒
46	13/09/19 17:32	Dismantled Parts		☒
47	13/09/19 17:32	Dismantled Parts		☒
48	13/09/19 17:32	Dismantled Parts		☒
49	13/09/19 17:32	Dismantled Parts		☒
50	13/09/19 17:32	Dismantled Parts		☒
51	13/09/19 17:32	Dismantled Parts		☒
52	13/09/19 17:32	Dismantled Parts		☒
53	13/09/19 17:32	Dismantled Parts		☒
54	13/09/19 17:32	Dismantled Parts		☒
55	13/09/19 17:32	Dismantled Parts		☒
56	13/09/19 17:32	Dismantled Parts		☒
57	13/09/19 17:32	Dismantled Parts		☒
58	13/09/19 17:32	Dismantled Parts		☒
59	13/09/19 17:32	Dismantled Parts		☒
60	13/09/19 17:32	Dismantled Parts		☒
61	13/09/19 17:32	Dismantled Parts		☒
62	13/09/19 17:32	Dismantled Parts		☒
63	13/09/19 17:32	Dismantled Parts		☒
64	13/09/19 17:32	Dismantled Parts		☒
65	13/09/19 17:32	Dismantled Parts		☒
66	13/09/19 17:32	Dismantled Parts		☒
67	13/09/19 17:32	Dismantled Parts		☒
68	13/09/19 17:32	Dismantled Parts		☒
69	13/09/19 17:32	Dismantled Parts		☒
70	13/09/19 17:32	Dismantled Parts		☒
71	13/09/19 17:32	Dismantled Parts		☒
72	13/09/19 17:32	Dismantled Parts		☒
73	13/09/19 17:32	Dismantled Parts		☒
74	13/09/19 17:32	Dismantled Parts		☒
75	13/09/19 17:32	Dismantled Parts		☒
76	13/09/19 17:32	Dismantled Parts		☒
77	13/09/19 17:32	Dismantled Parts		☒
78	13/09/19 17:32	Dismantled Parts		☒
79	13/09/19 17:32	Dismantled Parts		☒
80	13/09/19 17:32	Dismantled Parts		☒
81	13/09/19 17:33	Reinspection Photo		☒
82	13/09/19 17:33	Reinspection Photo		☒
83	13/09/19 17:33	Reinspection Photo		☒
84	13/09/19 17:33	Reinspection Photo		☒
85	13/09/19 17:33	Reinspection Photo		☒
86	13/09/19 17:33	Reinspection Photo		☒
87	13/09/19 17:33	After Repair Photo		☒
88	13/09/19 17:33	After Repair Photo		☒
Documentation			1 per page	☒
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	27/08/19 13:26	OD ESTIMATE		☒
2	27/08/19 14:33	COE PARF REBATE FORM		☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	28/08/19 13:04	ESTIMATE		☒
2	29/08/19 17:15	ESTIMATE-COST PLUS		☒

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer			
Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co Reg No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CTI19015076/GQF3E2

Date: 18/09/2019

REFERENCE

Insured/Claimant: HUANG JINHONG Policy No: DMPCSN30227419000

Date of Loss: 23/08/2019 Nature of Claim: OD Claim No: SNM19D203983C01

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLN1836H

Make & Model: TOYOTA WISH, 1.8 (A)

Engine No: 2ZR1767145

Reg. Date: 25/04/2017 (Man. Year: 2016)

Chassis No: ZGE206031963

Colour: Silver

Odometer: 95262 km

Engine Capacity: 1797 cc

Market Value/New Car Price: S\$82,000.00

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/45Z R17

Rear Tyre Size: 215/45Z R17

Front Left Side: Michelin 6 mm

Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm

Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,470.64	5,937.40	8,533.24	58.97
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,500.00	1,790.00	1,710.00	48.86
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	17,970.64	7,727.40	10,243.24	57.00
- Excess (S\$)	750.00	750.00	0.00	0.00
(S\$)	17,220.64	6,977.40	10,243.24	59.48
+ GST 7.00/7.00% (S\$)	1,205.44	488.42	717.02	59.48
Nett Amount (S\$)	18,426.08	7,465.82	10,960.26	59.48

INSPECTION

Date of Assignment: 27/08/2019

Date Inspected: 27/08/2019 Inspected At: Stk Auto (s) Pte Ltd (HQ)
8 kaki bukit ave4, #03-21
Singapore 415875

Estimated Period of Repair: 5.0 days

Adjuster: XING GUO QIANG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 18 Sep 2019)
Parts:	M1-MPV	TOYOTA WISH 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLN1836H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	280.00 F	*280.00 F
2	1		*FRONT BUMPER RETAINER RH	Deformed	38.00 F	*38.00 F
3	1		*FRONT BUMPER RETAINER LH	Deformed	38.00 F	*38.00 F
4	1		*FRONT BUMPER BRACKET RH	Not Necessary	35.00 F	*- F
5	1		*FRONT BUMPER BRACKET LH	Not Necessary	35.00 F	*- F
6	1		*FRONT BUMPER FOG LAMP COVER RH	Deformed	45.00 F	*45.00 F
7	1		*FRONT BUMPER FOG LAMP COVER LH	Deformed	45.00 F	*45.00 F
8	1		*FRONT BUMPER SPONGE	Cracked	95.00 F	*95.00 F
9	1		*FRONT BUMPER REINFORCEMENT	Bent	180.00 F	*180.00 F
10	1		*FRONT BUMPER LOWER GRILLE	Not Necessary	95.60 F	*- F
11	1		*FRONT GRILLE	Cracked	160.00 F	*160.00 F
12	1		*BONNET LOGO	Necessary	45.00 F	*45.00 F
13	1		*BONNET	Buckled	350.00 F	*350.00 F
14	1		*BONNET HINGE RH	Bent	40.00 F	*40.00 F
15	1		*BONNET HINGE LH	Bent	40.00 F	*40.00 F
16	1		*BONNET STAND	Not Necessary	25.00 F	*- F
17	1		*BONNET INNER RUBBER	Not Necessary	20.00 F	*- F
18	1		*BONNET LOCK LOWER	Bent	55.00 F	*55.00 F
19	1		*BONNET LOCK CABLE	Not Necessary	25.00 F	*- F
20	1		*BONNET RUBBER	Not Necessary	20.00 F	*- F
21	1		*BONNET INSULATOR	Deformed	200.00 F	*200.00 F
22	1		*RH HEADLAMP	Cracked	400.00 F	*400.00 F
23	1		*RH HEADLAMP PANEL	Bent	65.00 F	*65.00 F
24	1		*LH HEADLAMP	Cracked	400.00 F	*400.00 F
25	1		*LH HEADLAMP PANEL	Bent	65.00 F	*65.00 F
26	1		*LH FRONT DOOR	Repair	480.00 F	*- F
27	1		*LH FRONT DOOR HINGE UPPER	Not Necessary	35.00 F	*- F
28	1		*LH FRONT DOOR HINGE LOWER	Not Necessary	35.00 F	*- F
29	1		*LH FRONT DOOR CHECKER	Not Necessary	55.00 F	*- F
30	1		*LH FRONT DOOR INNER TRIM BOARD	Not Necessary	285.00 F	*- F
31	1		*LH FRONT DOOR LOCK	Not Necessary	150.00 F	*- F
32	1		*RH FRONT DOOR HINGE UPPER	Not Necessary	35.00 F	*- F
33	1		*RH FRONT DOOR HINGE LOWER	Not Necessary	35.00 F	*- F
34	1		*RH FRONT DOOR CHECKER	Not Necessary	55.00 F	*- F
35	1		*RH FRONT FENDER	Buckled	380.00 F	*380.00 F
36	1		*LH FRONT FENDER	Bent	380.00 F	*380.00 F
37	1		*RH FRONT FENDER INNER SHIELD	Not Necessary	65.00 F	*- F
38	1		*LH FRONT FENDER INNER SHIELD	Not Necessary	65.00 F	*- F
39	1		*FRONT SUPPORT PANEL	Bent	500.00 F	*500.00 F
40	1		*FRONT SUPPORT PANEL TOP GARNISH	Not Necessary	55.00 F	*- F
41	1		*AIR CON DUCT	Not Necessary	45.00 F	*- F
42	1		*AIR CON DUCT HOSE	Not Necessary	45.00 F	*- F
43	1		*INTAKE MAINFUL	Not Necessary	280.00 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
44	1		*AIR CON CONDENSER	Cut	380.00 F	*380.00 F
45	1		*AIR CON CONDENSER INTAKE PIPE	Not Necessary	180.00 F	*- F
46	1		*AIR CON CONDENSER DRY PIPE	Not Necessary	280.00 F	*- F
47	1		*AIR CON COMPRESSOR	Not Necessary	1,800.00 F	*- F
48	1		*AIR CON CONDENSER FAN BLADE	Not Necessary	85.00 F	*- F
49	1		*AIR CON CONDENSER FAN MOTOR	Not Necessary	130.00 F	*- F
50	1		*RADIATOR	Bent	600.00 F	*600.00 F
51	1		*RADIATOR FAN BLADE	Not Necessary	65.00 F	*- F
52	1		*RADIATOR FAN MOTOR	Not Necessary	130.00 F	*- F
53	1		*RADIATOR HOSE	Not Necessary	25.00 F	*- F
54	1		*ALTERNATOR	Not Necessary	680.00 F	*- F
55	1		*ALTERNATOR BLET	Not Necessary	55.00 F	*- F
56	1		*ABW PUMP	Not Necessary	1,500.00 F	*- F
57	1		*FRONT BRACE PANEL	Bent	95.00 F	*95.00 F
58	10		*RH FRONT FENDER INNER SHIELD CLIPS	Necessary	50.00 FS	*20.00 FS
59	10		*LH FRONT FENDER INNER SHIELD CLIPS	Necessary	50.00 FS	*20.00 FS
60	10		*FRONT SUPPORT PANEL TOP GARNISH CLIPS	Necessary	50.00 FS	*20.00 FS
61	10		*RH HEADLAMP BRACKET CLIPS	Not Necessary	100.00 FS	*- FS
62	10		*LH HEADLAMP BRACKET CLIPS	Not Necessary	100.00 FS	*- FS
63	1		*FRONT BUMPER SENSOR RH	Damaged	180.90 FS	*100.00 FS
64	1		*FRONT BUMPER SENSOR LH	Damaged	180.90 FS	*100.00 FS
65	1		*FRONT NUMBER PLATE	Scratched	55.00 FS	*20.00 FS
66	1		*FRONT NUMBER PLATE CASING	Scratched	55.00 FS	*20.00 FS
67	10		*FRONT BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
68	1		*FRONT WINDSCREEN SEALANT	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett.

Sub Total (\$\$)	12,703.40	5,206.00
+ Margin on L,N Items 15.00/15.00% (\$\$)	1,767.24	731.40
Total Parts (\$\$)	14,470.64	5,937.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK ALL NECESSARY WIRINGS	New	150.00	30.00
2	TO RUST PROOF ON AFFECTED AREAS	New	100.00	60.00
3	TO REMOVE & REFIT AIR CON CONDENSER & TOP UP GAS	New	150.00	50.00
4	TO CHECK AND RADIATOR PRESSURE TEST	New	150.00	50.00
5	TO REMOVE & REFIX LH FRONT DOOR	New	150.00	0.00
6	TO REMOVE & REFIX RH FRONT DOOR	New	150.00	0.00
7	TO REMOVE & REFIX FRONT WINDSCREEN	New	150.00	0.00
8	COMPONENTS TO FACILITATE REPAIRS	New	100.00	0.00
9	LABOUR TO FACILITATE REPAIR	New	1,200.00	600.00
10	LABOUR & SPRAY PAINTING	New	1,200.00	1,000.00
Gross Labour Cost (\$\$)			3,500.00	1,790.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >