# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: **EQ Insurance Company Ltd** From: LKK Auto Consultants Pte Ltd

5 Maxwell Road,#17-00 Tower Block

51 Ubi Ave 1 #01-25 MND Complex Paya Ubi Industrial Park Singapore 069110 Singapore 408933

Attn: JANET TAN Date: 28 Aug 2019

# **Preliminary Advice**

Insured Vehicle No : YM8903C

TP Vehicle No : SLL9482C Accident Date : 22/08/2019 Make : HONDA GRACE HYBRID Assignment Date : 27/08/2019 : 27/08/2019 Date of Inspection Est. Duration of Repair : 20 days

Inspection At : ComfortDelGro Engineering Pte Ltd (Braddell)

205 Braddell Road Singapore 579701

## Point of Impact / General Description of Damages

The vehicle sustained impact / damages ...front and rear.... portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	19,084.16
Revised Amount	:S\$	15,590.64
Check Items (Estimated)	:S\$	1,905.52
Total	:S\$	17,496.16

Lump Sum Repair :S\$

#### **Total Loss Consideration**

New for Old Value :S\$ Pre-Accident Value :S\$ COE / PARF Rebate :S\$ Salvage Value :S\$ Margin for Repair :S\$

### Remarks

(	)	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
(	)	The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

(X) Other comments: We have not authorized repairs.