

Kg

Tel: 63837168 / 63837466 Fax:62815767

ComfortDelgro Engineering Pte Ltd
 205 Braddell Road S (579701)
 Tel: 63837168 / 63837466 Fax:62815767

Finalization Form

Bill To : EQ Vehicle Number : SLL9482C
 Attn to : LKK - Kenneth Type Of Claim : TP

A. Spare parts	<u>\$ 12,626.50</u>	F. Total Parts	<u>\$ 10,642.32</u>
B. Supplementary	<u>\$ 201.40</u>	G. Total Labour	<u>\$ 5,680.00</u>
C. Nett Price	<u>\$ -</u>	H. Total Repair	<u>\$ 16,322.32</u>
D. Supp Nett Price	<u>\$ -</u>	I. Excess	<u> </u>
E. S/Nett	<u>\$ 380.00</u>	P/P Total	<u>16,322.32</u>

Total Spare Parts Price		\$ 12,827.90
Cost plus / List Down	20%	2,565.58
Total		10,262.32

Total Nett Price		\$ -
Nett Price Less		\$ -
Total		-

Lump Sum Less 20% \$ 3,264.46

Lump Sum Rounding \$ 13,057.86

Total Finalized \$ 13,000.00

If we DO NOT receive your reply within 2 weeks, we shall treat the above finalized amount as confirmed & co

Remarks : Please confirm and revert by Fax or Email

Date In : _____	Total Repair Day _____
Date Survey : _____	LOU/ Day _____
Date Out : _____	Total LOU _____
Sat/Sun/Ph. : _____	Rental/Day _____
Authorized Repair Day <u>20</u>	Total Rental _____

Submitted By / Date :

Confirmed By / Date :

Andrew / 20.09.2019

Spark Car Care
ComfortDelGro Engineering Pte Ltd
 205 Braddell Road S (579701)
 Tel: 63837168 / 63837466 Fax: 62844284, 62815767

Spare Parts

Vehicle No : SLL9482C Case Owner : Andrew

Make & Model : HONDA GRACE HYBRID Year Manufacture : 2016

Chassis No : GM41104666 Engine No : 0

Sales Order : _____ Supplier : _____

Order By : _____ Type of Claim : TP

S/N	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Disposition B Surveyor
1	Front number plate	1				\$ 45.00	
2	Front bumper	1		\$ 921.00			
3	Front bumper side retainer LH	1					
4	Front bumper side retainer RH	1		\$ 14.10			
5	Front bumper clips	10		\$ 39.00			
6	Radiator grille	1		\$ 86.90			
7	Radiator grille outer moulding	1		\$ 208.60			
8	Radiator grille chrome moulding lower	1		\$ 125.00			
9	Radiator grille emblem logo H	1		\$ 27.40			
10	Radiator grille bracket	1		\$ 16.70			
11	Headlamp LH	1		\$ 1,383.20			
12	Headlamp RH	1		\$ 1,383.20			
13	Headlamp lower bracket LH	1					
14	Headlamp lower bracket RH	1		\$ 27.50			
15	Front bumper sponge	1					
16	Front bumper reinforcement	1		\$ 236.40			
17	Bonnet	1		\$ 688.00			
18	Bonnet hinge LH	1		\$ 31.70			
19	Bonnet hinge RH	1		\$ 31.70			
20	Bonnet lock	1		\$ 87.40			
21	Bonnet lock cable	1					
22	LH front fender	1					
23	RH front fender	1		\$ 270.60			
24	LH front fender emblem HYBRID	1		\$ 58.00			
25	RH front fender emblem HYBRID	1		\$ 58.00			
26	Front support panel top garnish	1		\$ 32.30			
27	Front support panel top garnish clips	10		\$ 39.00			
28	Front support panel	1		\$ 455.00			
29	Front support top panel LH	1					
30	Front support top panel RH	1					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Spark Car Care
ComfortDelGro Engineering Pte Ltd
 205 Braddell Road S (579701)
 Tel: 63837168 / 63837466 Fax: 62844284, 62815767

Spare Parts

Vehicle No : SLL9482C Case Owner : Andrew

Make & Model : HONDA GRACE HYBRID Year Manufacture : 2016

Chassis No : GM41104666 Engine No : 0

Sales Order : 0 Supplier : 0

Order By : 0 Type of Claim : TP

S/N	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Disposition B Surveyor
31	Rear number plate with casing	1				\$ 45.00	
32	Rear bumper	1		\$ 937.00			
33	Rear bumper reflector LH	1					
34	Rear bumper reflector RH	1					
35	Rear bumper side retainer LH	1		\$ 13.90			
36	Rear bumper side retainer RH	1		\$ 13.90			
37	Rear bumper clips	10		\$ 39.00			
38	Bootlid	1		\$ 675.50			
39	Bootlid spoiler	1		\$ 400.00			
40	Bootlid chrome moulding	1		\$ 165.00			
41	Bootlid chrome moulding clips	4		\$ 29.50			
42	Bootlid emblem GRACE	1		\$ 45.00			
43	Bootlid emblem HYBRID	1		\$ 58.00			
44	Bootlid emblem logo H	1		\$ 24.70			
45	Bootlid lock	1		\$ 90.30			
46	Bootlid weatherstrip	1		\$ 71.60			
47	Bootlid hinge LH	1		\$ 68.50			
48	Bootlid hinge RH	1		\$ 68.50			
49	Bootlid inner trim	1					
50	Bootlid lamp LH	1		\$ 306.70			
51	Bootlid lamp RH	1		\$ 306.70			
52	Taillamp LH	1		\$ 381.70			
53	Taillamp RH	1		\$ 381.70			
54	Taillamp side clips (blue)	2		\$ 10.60			
55	Taillamp panel LH	1		\$ 98.00			
56	Taillamp panel RH	1		\$ 98.00			
57	Rear windscreen glass moulding upper	1		\$ 28.20			
58	Rear windscreen glass moulding lower	1		\$ 28.20			
59	Rear windscreen glass moulding LH	1		\$ 26.00			
60	Rear windscreen glass moulding RH	1		\$ 26.00			

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Spark Car Care
ComfortDelGro Engineering Pte Ltd
 205 Braddell Road S (579701)
 Tel: 63837168 / 63837466 Fax: 62844284, 62815767

Spare Parts

Vehicle No : SLL9482C Case Owner : Andrew

Make & Model : HONDA GRACE HYBRU Year Manufacture : 2016

Chassis No : GM41104666 Engine No : 0

Sales Order : 0 Supplier : 0

Order By : 0 Type of Claim : TP

S/N	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Disposition B Surveyor
61	Sealant	1			<i>nu</i>	\$ 40.00	—
62	Inner seal	1			<i>nu</i>	\$ 30.00	—
63	Rear end panel	1	<i>nu</i>	\$ 395.00	—		
64	Rear end panel top garnish	1	<i>nu</i>	\$ 86.40	—		
65	LH rear fender	1	<i>nu</i>	\$ 1,109.40	—		
66	LH rear fender inner trim	1					
67	Rear cargo tools tray	1	<i>nu</i>	\$ 168.50	—		
68	Rear cargo top cover	1	<i>CM</i>	\$ 254.30	—		
69	Rear floor undercover	1					
70	Rear end panel buzzer	1					
71	Reverse sensor	1			<i>short</i>	\$ 220.00	—
72	0	0					
73	0	0					
74	0	0					
75	0	0					
76	0	0					
77	0	0					
78	0	0					
79	0	0					
80	0	0					
81	0	0					
82	0	0					
83	0	0					
84	0	0					
85	0	0					
86	0	0					
87	0	0					
88	0	0					
89	0	0					
90	0	0					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Spark Car Care

ComfortDelGro Engineering Pte Ltd

205 Braddell Road S (579701)

Tel: 63837168 / 63837466 Fax: 62844284, 62815767

Supplementary 1

Vehicle No : <u>SLL9482C</u>	Case Owner : <u>Andrew</u>
Make & Model : <u>HONDA GRACE HYBRID</u>	Year Manufacture : <u>2016</u>
Chassis No : <u>GM41104666</u>	Engine No : <u>0</u>
Sales Order : <u>0</u>	Supplier : <u>0</u>
Order By : _____	Type of Claim : <u>TP</u>

S/No	Part Description	QTY	Cost Price	List Price	Nett Item	S/N	Disposition By Surveyor
1	Bootlid license plate lamp LH	1	CM	\$ 28.00			—
2	Bootlid license plate lamp RH	1	CM	\$ 28.00			—
3	LH rear fender air vent	1	hw	\$ 28.50			—
4	Bootlid opening switch	1	shot	\$ 108.20			—
5	Bonnet stopper	1	251	\$ 8.70			—
6	0	0					
7	0	0					
8	0	0					
9	0	0					
10	0	0					
11	0	0					
12	0	0					
13	0	0					
14	0	0					
15	0	0					
16	0	0					
17	0	0					
18	0	0					
19	0	0					
20	0	0					
21	0	0					
22	0	0					
23	0	0					
24	0	0					
25	0	0					
26	0	0					
27	0	0					
28	0	0					
29	0	0					
30	0	0					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Spark Car Care

Spark Car Care
ComfortDelGro Engineering Pte Ltd
 205 Braddell Road S (579701)
 Tel: 63837168 / 63837466 Fax:62844284,62815767

Labour

Vehicle No. : SLL9482C Case Owner : Andrew
 Make & Model : IONDA GRACE HYBRID Year of Manufacture : 2016

S/No	Labour Description	Estimated Price	Adjusted Price
1	To remove and refit rear windscreen to facilitate repair	\$120.00	\$ 120.00
2	To remove and refit cushions and upholstery to facilitate repairs	\$280.00	\$ 180.00
3	To transfer bootlid parts and mechanisms to new bootlid	\$250.00	\$ 80.00
4	To remove, reinstall Hybrid Electronic Module connection and to reset and synchronization the electronic system	\$550.00	
5	Labor charges to repair, panel beat RH rear fender, rear floor panel, cut, weld rear end panel, LH rear fender and replaced damaged parts on front and rear damaged parts	\$2,880.00	\$ 2,400.00
6	To check wiring functions	\$120.00	\$ 60.00
	To install reverse sensor	\$120.00	\$ 80.00
7	To putty and spray paint front bumper, LH front fender, RH front fender, bonnet, front support panel, rear bumper, bootlid, LH rear fender, RH rear fender, rear end panel, rear cargo floor panel and affected areas	\$3,000.00	\$ 2,500.00
8	To apply rust proofing on replaced and repaired panels	\$300.00	\$ 180.00
9	To remove and refit fuel tank to facilitate repair	\$150.00	\$ 80.00

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.

48	1	*Bootlid lamp RH	20.00	0.00	CM	*306.70 FL	✓
49	1	*Taillamp LH	20.00	0.00	Bu	*381.70 FL	✓
50	1	*Taillamp RH	20.00	0.00	Bu	*381.70 FL	✓
51	1	*Taillamp side clips	20.00	0.00	Bu	*10.60 FL	✓
52	1	*Taillamp panel LH	20.00	0.00	Bu	*98.00 FL	✓
53	1	*Taillamp panel RH	20.00	0.00	Bu	*98.00 FL	✓
54	1	*Rear windscreen glass moulding upper	20.00	0.00	Bu	*28.20 FL	✓
55	1	*Rear windscreen glass moulding lower	20.00	0.00	Bu	*28.20 FL	✓
56	1	*Rear windscreen glass moulding LH	20.00	0.00	Bu	*26.00 FL	✓
57	1	*Rear windscreen glass moulding RH	20.00	0.00	Bu	*26.00 FL	✓
58	1	*Sealant	0	0.00	Bu	*40.00 FS	✓
59	1	*Inner seal	0	0.00	Bu	*30.00 FS	✓
60	1	*Rear end panel	20.00	0.00	Bu	*395.00 FL	✓
61	1	*Rear end panel top garnish	20.00	0.00	Bu	*86.40 FL	✓
62	1	*LH rear fender	20.00	0.00	Bu	*1,109.40 FL	✓
63	1	*LH rear fender inner trim	20.00	0.00	Bu	*265.00 FL	✓
64	1	*Rear cargo tools tray	20.00	0.00	Bu	*188.50 FL	✓
65	1	*Rear cargo top cover	20.00	0.00	Bu	*254.30 FL	✓
66	1	*Rear floor undercover	20.00	0.00	Bu	*135.00 FL	✓
67	1	*Rear end panel buzzer	20.00	0.00	Bu	*85.00 FL	✓
68	1	*Rear antenna control	20.00	0.00	Bu	*60.00 FL	✓
69	1	*Reverse sensor	20.00	0.00	Bu	*220.00 FS	✓
F=Franchise part. S=SpcNett. L=ListItemDisc.			Sub Total (\$\$)			14,047.70	
			- List Item Discount on L Items (\$\$)			2,733.54	
			Total Parts (\$\$)			11,314.16	

ComfortDelGro Engineering Pte Ltd/SLL9482C/27/08/2019 10:22. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Bootlid license plate lamp LH	-	\$28
Bootlid license plate lamp RH	-	\$28
LH rear fender air vent	-	\$28.50
Bootlid opening switch	-	\$108.20
Bonnet stopper	-	\$2.70

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 27-Aug-2019)
 Parts: 143 HONDA GRACE HYBRID 1.5 (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: ComfortDelGro Engineering Pte Ltd/SLL9482C/27/08/2019 10:22
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*Front number plate with casing	CM 0	0.00	*45.00 FS
2	1		*Front bumper	Bu 20.00	0.00	*921.00 FL
3	1		*Front bumper side retainer LH	Sm 20.00	0.00	*14.10 FL
4	1		*Front bumper side retainer RH	Sm 20.00	0.00	*14.10 FL
5	1		*Front bumper clips	Ca 20.00	0.00	*39.00 FL
6	1		*Radiator grille	Ca 20.00	0.00	*86.90 FL
7	1		*Radiator grille outer moulding	Ca 20.00	0.00	*208.60 FL
8	1		*Radiator grille chrome moulding lower	Ca 20.00	0.00	*125.00 FL
9	1		*Radiator grille emblem logo	Ca 20.00	0.00	*27.40 FL
10	1		*Radiator grille bracket	Ca 20.00	0.00	*16.70 FL
11	1		*Headlamp LH	Ca 20.00	0.00	*1,383.20 FL
12	1		*Headlamp RH	Ca 20.00	0.00	*1,383.20 FL
13	1		*Headlamp lower bracket LH	R 20.00	0.00	*27.50 FL
14	1		*Headlamp lower bracket RH	R 20.00	0.00	*27.50 FL
15	1		*Front bumper reinforcement	Bu 20.00	0.00	*236.40 FL
16	1		*Bonnet	Bu 20.00	0.00	*688.00 FL
17	1		*Bonnet hinge LH	D/H 20.00	0.00	*31.70 FL
18	1		*Bonnet hinge RH	D/H 20.00	0.00	*31.70 FL
19	1		*Bonnet lock	R 20.00	0.00	*87.40 FL
20	1		*Bonnet lock cable	Ca 20.00	0.00	*39.70 FL
21	1		*LH front fender	R 20.00	0.00	*270.60 FL
22	1		*RH front fender	Bu 20.00	0.00	*270.60 FL
23	1		*LH front fender emblem HYBRID	Ca 20.00	0.00	*58.00 FL
24	1		*RH front fender emblem HYBRID	Ca 20.00	0.00	*58.00 FL
25	1		*Front support top garnish	Ca 20.00	0.00	*32.30 FL
26	1		*Front support top garnish clips	Ca 20.00	0.00	*39.00 FL
27	1		*Front support panel	Bu 20.00	0.00	*455.00 FL
28	1		*Rear number plate with casing	Ca 0	0.00	*45.00 FS
29	1		*Rear bumper	R 20.00	0.00	*937.00 FL
30	1		*Rear bumper reflector LH	Bu 20.00	0.00	*30.00 FL
31	1		*Rear bumper reflector RH	Sm 20.00	0.00	*30.00 FL
32	1		*Rear bumper side retainer LH	D/H 20.00	0.00	*13.90 FL
33	1		*Rear bumper side retainer RH	Ca 20.00	0.00	*13.90 FL
34	1		*Rear bumper clips	Ca 20.00	0.00	*39.00 FL
35	1		*Bootlid	R 20.00	0.00	*675.50 FL
36	1		*Bootlid spoiler	D/H 20.00	0.00	*38.60 FL
37	1		*Bootlid chrome moulding	Bu 20.00	0.00	*165.00 FL
38	1		*Bootlid chrome moulding clips	Ca 20.00	0.00	*29.50 FL
39	1		*Bootlid emblem GRACE	Ca 20.00	0.00	*45.00 FL
40	1		*Bootlid emblem HYBRID	Ca 20.00	0.00	*58.00 FL
41	1		*Bootlid emblem logo H	Ca 20.00	0.00	*24.70 FL
42	1		*Bootlid lock	Ca 20.00	0.00	*90.30 FL
43	1		*Bootlid weatherstrip	D/H 20.00	0.00	*71.60 FL
44	1		*Bootlid hinge LH	B 20.00	0.00	*68.50 FL
45	1		*Bootlid hinge RH	R 20.00	0.00	*68.50 FL
46	1		*Bootlid inner trim	Ca 20.00	0.00	*99.70 FL
47	1		*Bootlid lamp LH	CM 20.00	0.00	*306.70 FL

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	To remove and refit rear windscreen to facilitate repair	New	120.00
2	To remove and refit cushions and upholstery to facilitate repairs	New	280.00
3	To transfer bootlid parts and mechanisms to new bootlid	New	250.00
4	To remove, re-install Hybrid Electronic Module connection and to reset and synchronization the electronic system	New	650.00
5	Labor charges to repair, panel beat RH rear fender, rear floor panel, cut, weld rear end panel, LH rear fender and replaced damaged parts on front and rear damaged parts	New	2,880.00
6	To check wiring functions	New	120.00
7	To install reverse sensor	New	120.00
8	To putty and spray paint front bumper, LH front fender, RH front fender, bonnet, front support panel, rear bumper, bootlid, LH rear fender, RH rear fender, rear end panel, rear cargo floor panel and affected areas	New	3,000.00
9	To apply rust proofing on replaced and repaired panels	New	300.00
10	To remove and refit fuel tank to facilitate repair	New	150.00
Gross Labour Cost (\$\$)			7,770.00

ComfortDelGro Engineering Pte Ltd/SLL9482C/27/08/2019 10:22. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)
205 Braddell Road
Singapore 579701
Tel: 63837168 /63837118 Fax: 62815767/65462533 Email: denisteo@cdge.com.sg

TP INSURER: EQ Insurance Company Ltd (HQ)
TAN TECK HUA

Singapore

Claimant Insurer: Tokio Marine Insurance Singapore Ltd

PARTICULARS OF CLAIM

Claim Type:	Third Party	Ref. No:	
Policy No:		Date of Loss:	22/08/2019
Vehicle Reg. No.:	SLL9482C	Driveable?	
Party At Fault:	UNKNOWN		
Driver (TP):	NG WEE BENG		
Make/Model:	HONDA GRACE HYBRID, 1.5 (A)	Vehicle Reg. Date:	16/03/2017
Vehicle Colour:	Metallic White		
Engine No:	LEB5254679	Chassis No:	GM41104666
Odometer:	174104 KM		
Paint Type:			
List Item Discount:	20.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	20 ✓		
Description of Accident/Loss	REFER TO REPORT ATTACHED		
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (BRADDELL)		

*Not Withheld
Running B4 paint*

COST OF CLAIMS	AMOUNT
Parts	11,314.16
Miscellaneous Items	0.00
Labour	7,770.00
Paint/Mobile Labour	0.00
Towing	0.00
Gross Total (\$\$)	19,084.16
+ GST 7.00% (\$\$)	1,335.89
Nett Amount (\$\$)	20,420.05

This claim is handled by: ANDREW CORNELIUS GOH CHENG CHUAN

Generated using Merimen e-Claims Internet Estimation & Adjusting System