

48	1	*Bootlid lamp RH	20.00	0.00	CM	*306.70 FL	
49	1	*Taillamp LH	20.00	0.00	R2	*381.70 FL	
50	1	*Taillamp RH	20.00	0.00	R2	*381.70 FL	
51	1	*Taillamp side clips	20.00	0.00	M	*10.60 FL	
52	1	*Taillamp panel LH	20.00	0.00	R2	*98.00 FL	
53	1	*Taillamp panel RH	20.00	0.00	R2	*98.00 FL	
54	1	*Rear windscreen glass moulding upper	20.00	0.00	R2	*28.20 FL	
55	1	*Rear windscreen glass moulding lower	20.00	0.00	R2	*28.20 FL	
56	1	*Rear windscreen glass moulding LH	20.00	0.00	R2	*26.00 FL	
57	1	*Rear windscreen glass moulding RH	20.00	0.00	R2	*26.00 FL	
58	1	*Sealant	0	0.00	M	*40.00 FS	
59	1	*Inner seal	0	0.00	M	*30.00 FS	
60	1	*Rear end panel	20.00	0.00	R2	*395.00 FL	
61	1	*Rear end panel top garnish	20.00	0.00	R2	*86.40 FL	
62	1	*LH rear fender	20.00	0.00	R2	*1,109.40 FL	
63	1	*LH rear fender inner trim	20.00	0.00	R2	*265.00 FL	
64	1	*Rear cargo tools tray	20.00	0.00	R2	*168.50 FL	
65	1	*Rear cargo top cover	20.00	0.00	R2	*254.30 FL	
66	1	*Rear floor undercover	20.00	0.00	R2	*135.00 FL	
67	1	*Rear end panel buzzer	20.00	0.00	R2	*85.00 FL	
68	1	*Rear antenna control	20.00	0.00	R2	*60.00 FL	
69	1	*Reverse sensor	0	0.00	R2	*220.00 FS	

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	14,047.70
- List Item Discount on L Items (\$\$)	2,733.54
Total Parts (\$\$)	11,314.16

ComfortDelGro Engineering Pte Ltd/SL19482C/27/08/2019 10:22. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Bootlid license plate lamp LH	-	\$28
Bootlid license plate lamp RH	-	\$28
LH rear fender air vent	-	\$28.50
Bootlid opening switch	-	\$108.20
Bonnet stopper	-	\$2.70

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 27-Aug-2019)
 Parts: 143 HONDA GRACE HYBRID 1.5 (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: ComfortDelGro Engineering Pte Ltd/SLL9482C/27/08/2019 10:22

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*Front number plate with casing	CM	0.00	*45.00 FS
2	1		*Front bumper	Bu	20.00	*921.00 FL
3	1		*Front bumper side retainer LH	Sn	20.00	*14.10 FL
4	1		*Front bumper side retainer RH	Rn	20.00	*14.10 FL
5	1		*Front bumper clips	Cl	20.00	*39.00 FL
6	1		*Radiator grille	Gr	20.00	*86.90 FL
7	1		*Radiator grille outer moulding	Mo	20.00	*208.60 FL
8	1		*Radiator grille chrome moulding lower	CM	20.00	*125.00 FL
9	1		*Radiator grille emblem logo	Em	20.00	*27.40 FL
10	1		*Radiator grille bracket	Br	20.00	*16.70 FL
11	1		*Headlamp LH	mg CM	20.00	*1,383.20 FL
12	1		*Headlamp RH	CM	20.00	*1,383.20 FL
13	1		*Headlamp lower bracket LH	R	20.00	*27.50 FL
14	1		*Headlamp lower bracket RH	CM	20.00	*27.50 FL
15	1		*Front bumper reinforcement	Bu	20.00	*236.40 FL
16	1		*Bonnet	Bu	20.00	*688.00 FL
17	1		*Bonnet hinge LH	D.I	20.00	*31.70 FL
18	1		*Bonnet hinge RH	D.I	20.00	*31.70 FL
19	1		*Bonnet lock	R	20.00	*87.40 FL
20	1		*Bonnet lock cable	R	20.00	*39.70 FL
21	1		*LH front fender	R	20.00	*270.60 FL
22	1		*RH front fender	Bu	20.00	*270.60 FL
23	1		*LH front fender emblem HYBRID	Em	20.00	*58.00 FL
24	1		*RH front fender emblem HYBRID	Em	20.00	*58.00 FL
25	1		*Front support top garnish	CM	20.00	*32.30 FL
26	1		*Front support top garnish clips	Cl	20.00	*39.00 FL
27	1		*Front support panel	Bu	20.00	*455.00 FL
28	1		*Rear number plate with casing	CM	0.00	*45.00 FS
29	1		*Rear bumper	R	20.00	*937.00 FL
30	1		*Rear bumper reflector LH	Rn	20.00	*30.00 FL
31	1		*Rear bumper reflector RH	Rn	20.00	*30.00 FL
32	1		*Rear bumper side retainer LH	D.I	20.00	*13.90 FL
33	1		*Rear bumper side retainer RH	CM	20.00	*13.90 FL
34	1		*Rear bumper clips	Cl	20.00	*39.00 FL
35	1		*Bootlid	R	20.00	*675.50 FL
36	1		*Bootlid spoiler	CM	20.00	*200.38 FL
37	1		*Bootlid chrome moulding	Mo	20.00	*165.00 FL
38	1		*Bootlid chrome moulding clips	Cl	20.00	*29.50 FL
39	1		*Bootlid emblem GRACE	Em	20.00	*45.00 FL
40	1		*Bootlid emblem HYBRID	Em	20.00	*58.00 FL
41	1		*Bootlid emblem logo H	Em	20.00	*24.70 FL
42	1		*Bootlid lock	CM	20.00	*30.30 FL
43	1		*Bootlid weatherstrip	D.I	20.00	*71.60 FL
44	1		*Bootlid hinge LH	Cl	20.00	*68.50 FL
45	1		*Bootlid hinge RH	R	20.00	*68.50 FL
46	1		*Bootlid inner trim	CM	20.00	*99.70 FL
47	1		*Bootlid lamp LH	CM	20.00	*306.70 FL

Handwritten marks and notes on the right side of the table, including 'SVC' and 'X' marks, indicating service status or specific actions for certain items.

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	To remove and refit rear windscreen to facilitate repair	New	120.00
2	To remove and refit cushions and upholstery to facilitate repairs	New	280.00
3	To transfer bootlid parts and mechanisms to new bootlid	New	250.00
4	To remove, reinstall Hybrid Electronic Module connection and to reset and synchronization the electronic system	New	650.00
5	Labor charges to repair, panel beat RH rear fender, rear floor panel, cut, weld rear end panel, LH rear fender and replaced damaged parts on front and rear damaged parts	New	2,880.00
6	To check wiring functions	New	120.00
7	To install reverse sensor	New	120.00
8	To putty and spray paint front bumper, LH front fender, RH front fender, bonnet, front support panel, rear bumper, bootlid, LH rear fender, RH rear fender, rear end panel, rear cargo floor panel and affected areas	New	3,000.00
9	To apply rust proofing on replaced and repaired panels	New	300.00
10	To remove and refit fuel tank to facilitate repair	New	150.00
Gross Labour Cost (\$\$)			7,770.00

ComfortDelGro Engineering Pte Ltd/SL9482C/27/08/2019 10:22. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)
205 Braddell Road
Singapore 579701
Tel: 63837168 /63837118 Fax: 62815767/65462533 Email: denisteo@cdge.com.sg

TP INSURER: EQ Insurance Company Ltd (HQ)
TAN TECK HUA

Singapore

Claimant Insurer: Tokio Marine Insurance Singapore Ltd

PARTICULARS OF CLAIM

Claim Type:	Third Party	Ref. No:	
Policy No:		Date of Loss:	22/08/2019
Vehicle Reg. No.:	SLL9482C	Driveable?	
Party At Fault:	UNKNOWN		
Driver (TP):	NG WEE BENG		
Make/Model:	HONDA GRACE HYBRID, 1.5 (A)	Vehicle Reg. Date:	16/03/2017
Vehicle Colour:	Metallic White		
Engine No:	LEB5254679	Chassis No:	GM41104666
Odometer:	174104 KM		
Paint Type:			
List Item Discount:	20.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	20 ✓		
Description of Accident/Loss	REFER TO REPORT ATTACHED		
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (BRADDELL)		

*Not with work
Missing B4 paint*

Parts	11,314.16
Miscellaneous Items	0.00
Labour	7,770.00
Paint Work/Labour	0.00
Towing	0.00
Gross Total (S\$)	19,084.16
+ GST 7.00% (S\$)	1,335.89
Nett Amount (S\$)	20,420.05

This claim is handled by: ANDREW CORNELIUS GOH CHENG CHUAN

19,257.60#

Generated using Merimen e-Claims Internet Estimation & Adjusting System