

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

TO	: ERGO	DATE	: 23-Aug-19
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT	:		
<u>VEHICLE DETAILS</u>			
VEHICLE NO	: GBF2740D		
MODEL	: TOYOTA HIACE		
CHASSIS NO			
<u>ACCIDENT DETAILS</u>		DATE	: 22-Aug-19
		TIME	: 14:18HRS
THIRD PARTY REQUESTOR / CONTACT		:	JACK LI

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	TAILGATE <i>Dented</i>	1	\$ 2,115.00	\$ 2,115.00
2	TAILGATE LOGO <i>Nec</i>	1	\$ 68.00	\$ 68.00
3	TAILGATE HIACE EMBLEM <i>Nec</i>	1	\$ 50.00	\$ 50.00
4	TAILGATE WEATHERSTRIP <i>Nec</i>	1	\$ 380.00	\$ 380.00
5	TAILGATE INNER LOCK <i>Dmgd</i>	1	\$ 270.00	\$ 270.00
6	TAILGATE LOWER LOCK <i>Nec</i>	1	\$ 116.30	\$ 116.30
7	TAILGATE WINDSCREEN <i>Shattered</i>	1	\$ 890.00	\$ 890.00
8	TAILGATE WINDSCREEN MOULDING <i>Nec</i>	1	\$ 190.00	\$ 190.00
9	REAR BUMPER <i>Dmgd</i>	1	\$ 580.00	\$ 580.00
10	REAR BUMPER STEP PANEL <i>Best</i>	1	\$ 410.00	\$ 410.00
11	REAR BUMPER SIDE RETAINER <i>Nec</i>	2	\$ 78.60	\$ 157.20
12	NUMBER PLATE GARNISH <i>Cracked</i>	1	\$ 190.00	\$ 190.00
13	TAIL LAMP LH <i>Cracked</i>	1	\$ 355.30	\$ 355.30
14	TAILLAMP LOWER GARNISH LH <i>Nec</i>	1	\$ 122.20	\$ 122.20
15	TAILLAMP LOWER GARNISH RETAINER LH <i>Nec</i>	1	\$ 45.00	\$ 45.00
16	REAR END PANEL (OUTER) <i>Dented</i>	1	\$ 590.30	\$ 590.30

TOTAL PRICE \$ 6,529.30
LESS 25% \$ 1,632.33

5301.80

3876.35

SUB TOTAL PRICE \$ 4,896.98

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR NUMBER PLATE <i>Not New</i>	1	\$ 50.00	\$ 50.00
2	TAILGATE WINDSCREEN SEALANT <i>New</i>	1	\$ 60.00	\$ 60.00
3	TAILGATE STICKER <i>New</i>	1	\$ 380.00	\$ 380.00
4	REAR BUMPER CLIP (SET) <i>New</i>	1	\$ 20.00	\$ 20.00
5	STICKER 70KM/H <i>New</i>	1	\$ 50.00	\$ 50.00
6	TAIL LAMP CLIP (SET) <i>New</i>	1	\$ 20.00	\$ 20.00
7	REAR END PANEL (OUTER) SEALANT <i>New</i>	1	\$ 60.00	\$ 60.00
8	REVERSE SENSOR <i>Damaged</i>	1	\$ 220.00	\$ 220.00

545 TOTAL \$ 860.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

1	PANEL BEATING AND REPLACE PARTS	\$ 1,400.00	800
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,400.00	600
3	TUFF COAT	\$ 150.00	60.
4	WIRNING, BULB CHECKING	\$ 80.00	30
5	REMOVE AND REFIX TAILGATE WINDSCREEN	\$ 160.00	120
6	TRANSFER TAILGATE MECHAISM	\$ 120.00	80.
7	REMOVE AND REFIX REAR REVERSE SENSOR	\$ 80.00	50

TOTAL \$3,390.00 1746

ESTIMATE REPORT

TOTAL PARTS COST : \$ 5,756.98

TOTAL LABOUR COST \$ 3,390.00

TOTAL REPAIR COST \$ 9,146.98

APPROVED DETAILS

SURVEYOR

CONTACT NO

LKKA Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

FAX :

Adrian Lim.

2/S 26/08/15

06 Days

total: 6261.35

4/S: SK