

12/03/2017

ASS. REC. BY:

REF:

CS/C7219015088/Krf302

Special Instruction:

Surveyor: Kenneth

ASSIGNMENT (Office)

From (Person): Irene Tang Hui Ping of C71

Date/Time: 27.8.19 14.13p.m

Estimated Cost: Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No: SJF 5709 G

Insured: GV 2175 S

at Workshop m/s: Yee Auto Service.

Tel: 6457 5768 / 6457 2625

of 160 Sin Ming Drive #02-17

Policy No: DMCVSH300071901

Claim No: SNM191203978C02

Sum Insured:

Excess:

Make of Veh:

D.O.A. 25.8.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 27.8.19 3pm.m

Person Contacted: Mr Tan

Vehicle: IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	GV 2175S: NA/C7219015026/24 D.O.A. 25/08/2019
	SJF 5709G: NA/C7219015026/24 D.O.A. 25/08/2019
18/9	Call 830001 email
27/8/19	@ 234pm LS \$3000 confirmed with Winnie (Red 8182.42, 7390)

ASS. REC. BY:

REF: C72 /

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s Yec Auto

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 05 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: 5/23 Person Contacted: _____

Vehicle: IN / OUT

Veh No: SJF 57096 Yr Regn: 06, 08Type: M / Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toy VIA E c.c. 1800Colour: N. Blue A/C: Insured / Std / NI / NASp. Reading: 144710 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: NR0531149305062012Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModl: Nil / S/Rlm / STD / A/Rlm orTyre Size: F: 185 / 60 R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 9 mmL/Bal. 9 mmD.O.A. 25/8/19

Survey held at

Rear

R/Bal. 9 mmL/Bal. 9 mmD.O.I. 27/8/19Des. of Damages: Frt Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

1 / File pass to

RECEIVED 27 SEP 2019

Date/Time, File Pass to?

☐ : Prell. Report☐ : Final Report

1)

Date/Time, File Return to?

2) 27/9 - typistDays Of Repair: 5Resurvey No. of Trip: 1

Survey Fee:

Transportation:

S + RS. \$

Fees

Others

TOTAL

220

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

Report Format:

Lump Sum / I.B.I. (\$

MERIMEN

3000/-

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	26 Aug 2019		27 Aug 2019 14:13 Edit Adj Rpt				Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	
Main Claimant:	LIM MENG HAR
Vehicle Reg. No.:	SJF5709G
Claim Type:	TP / SNM19D203978C02
Vehicle Reg. No. (Insured):	GV2175S
Date of Loss:	25/08/2019 13:00 - :59
Policy/Cover Note No.:	DMCVSN30000719011
Policy No. (Claimant):	
Excess:	S\$0.00
Repairer:	Yee Auto Service (HQ) 160 Sin Ming Drive #02-17 Sin Ming Autocity, 575722 Sin Ming - Tel: 64575768
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 05/09/2019]
Adj Asg. Remarks:	PLEASE SURVEY AND REVERT

[View All](#)
[Compose Case Mail](#)

ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	(Not Notified)		27 Aug 2019 14:13 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:									
Main Claimant:		LIM MENG HAR							
Vehicle Reg. No.:		SJF5709G	Date of Loss:	25/08/2019 13:00 - :59					
Claim Type:		TP	Policy/Cover Note No.:						
Vehicle Reg. No. (Insured):		GV2175S	Policy No. (Claimant):						
		Excess:	S\$0.00						
Repairer:		Yee Auto Service (HQ) 160 Sin Ming Drive #02-17 Sin Ming Autocity, 575722 Sin Ming - Tel: 64575768							
Handling Insurer:		China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]							
Adjuster:		LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 05/09/2019]							
Adj Asg. Remarks:		PLEASE SURVEY AND REVERT							
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Nivitha (LKK Auto)

From: Irene Tay <irene.tay@sg.cntaiping.com>
Sent: Tuesday, 27 August 2019 12:54 PM
To: assignments; kkrishna@singnet.com.sg
Cc: Asher Sng (LKK Auto)
Subject: CTP REF NO. SNM19D203978C02 CTP VEH : GV2175S KK REF NO. SJR5709G
Attachments: GIA-SJR 5709G.PDF

Dear Sir/Mdm (LKK),

We refer to the above matter and email below.

Please assist to get your surveyor to liaise with Mr Chan from M/s Yee Auto Services to conduct PRS.

Thank You.

Regards,

Irene Tay
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #15-00 Springleaf Tower Singapore 079909
DID: (65) 63896192 | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: kkrishna [mailto:kkrishna@singnet.com.sg]
Sent: Tuesday, 27 August, 2019 12:45 PM
To: Irene Tay <irene.tay@sg.cntaiping.com>
Subject: Re: CTP REF NO. SNM19D203978C02 CTP VEH : GV2175S KK REF NO. SJR5709G

Dear Madam

We attached herewith our client's GIA report.

Regards

Daphne on behalf of K. Krishna & Partners

On 27-Aug-19 12:41 PM, Irene Tay wrote:

Dear Sir,

Please forward to us your client's GIA report.

Thank You.

Regards,

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Thank you.

Regards,

Irene Tay
Executive
Claims Department (Motor Division)

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #16-00 Springleaf Tower Singapore 079909
Direct (65) 6389 6192
Fax (65) 62247478/62247175
Email: claimsdept@sg.cntaiping.com
www.sg.cntaiping.com



Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.



YEE AUTO PTE LTD

160 Sin Ming Drive #02-17/#07-12 Sin Ming AutoCity Singapore 575722

Tel: 6457 5768 Fax: 6252 8459 Mobile: 9687 4031

Email: yeeautopte ltd@gmail.com

Registration No.: 201719251W GST No: 201719251W

M/S : China Taiping Insurance (Singapore) Pte Ltd

3 Anson Road

#16-00 Springleaf Tower

Singapore 079909

ATTN: Motor Claim Department

Your Ref No: -

Claim Type: Third Party

Accident Date: 25/08/2019

TP Veh Reg No: GV2175S

Estimate No: ES1900065

Date: 27 Aug 2019

Policy No:

Veh Reg No: SJF5709G

Make/Model: TOYOTA VIOS E AUTO

Chassis No: MR053HY9305062012

Engine No: 1NZX736435

Reg. Date: 03/06/2008

Estimate Repair Cost to Vehicle No :SJF5709G

Description	U/Price	Quantity	List Price	Amount
			<u>SS</u>	<u>SS</u>
Net Price				
1 REAR NUMBER PLATE	50.00	1 PC	50.00	X
2 REVERSE SENSORS	300.00	1 PC	300.00	200.00
			350.00	350.00
Spare Parts				
3 BOOT EMBLEM 'LOGO'	53.00	1 PC	53.00	✓
4 BOOT EMBLEM 'VIOS'	36.90	1 PC	36.90	✓
5 BOOT HINGE - LH	100.00	1 PC	100.00	X
6 BOOT HINGE - RH	100.00	1 PC	100.00	X
7 BOOT LOCK	185.10	1 PC	185.10	X
8 BOOT OUTER GARNISH	251.40	1 PC	251.40	X
9 BOOT TOP LOCK	90.95	1 PC	90.95	X
10 BOOT LID	656.95	1 PC	656.95	✓
11 BOOT LID WEATHERSTRIP	165.62	1 PC	165.62	X
12 EXHAUST MUFFLER	538.10	1 PC	538.10	X
13 REAR BODY PANEL	503.30	1 PC	503.30	✓
14 REAR BODY PANEL TOP GARNISH	200.76	1 PC	200.76	✓
15 REAR BUMPER	529.50	1 PC	529.50	✓
16 REAR BUMPER CLIPS	6.00	1 PCS	6.00	✓
17 REAR BUMPER REFLECTOR - LH	162.50	1 PC	162.50	✓
18 REAR BUMPER REFLECTOR - RH	162.50	1 PC	162.50	X
19 REAR BUMPER SIDE RETAINER - LH	78.05	1 PC	78.05	✓
20 REAR BUMPER SIDE RETAINER - RH	78.05	1 PC	78.05	X
21 REAR FENDER INNER TRIM - LH	369.50	1 PC	369.50	X
22 REAR FENDER INNER TRIM - RH	369.50	1 PC	369.50	X
23 REAR NUMBER PLATE LAMP - LH	103.90	1 PC	103.90	X
24 REAR NUMBER PLATE LAMP - RH	103.90	1 PC	103.90	X
25 REAR SPARE TYRE SPONGE	288.00	1 PC	288.00	X
26 REAR TOOL BOX	138.00	1 PC	138.00	✓
27 REAR WHEEL PANEL COVER	235.10	1 PC	235.10	X
28 SPARE WHEEL PANEL	499.50	1 PC	499.50	X
29 TAIL LAMP LH	297.62	1 PC	297.62	✓
30 TAIL LAMP RH	297.62	1 PC	297.62	X
31 TAIL LAMP PANEL - LH	138.00	1 PC	138.00	X
32 TAIL LAMP PANEL - RH	138.00	1 PC	138.00	X
33 REAR BODY GARNISH CLIP	10.00	1 PCS	10.00	X
34 REAR BOOT EMBLEM 'E'	35.10	1 PC	35.10	✓
35 REAR PARKING CAMERA	300.00	1 PC	300.00	X

Not Authorized

61 Day @ 3000.

*Repair After Paint
5 days*

251



YEE AUTO PTE LTD

160 Sin Ming Drive #02-17/#07-12 Sin Ming AutoCity Singapore 575722

Tel: 6457 5768 Fax: 6252 8459 Mobile: 9687 4031

Email: yeeautopte ltd@gmail.com

Registration No.: 201719251W GST No: 201719251W

M/S : China Taiping Insurance (Singapore) Pte Ltd
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

ATTN: Motor Claim Department
Your Ref No: -
Claim Type: Third Party
Accident Date: 25/08/2019
TP Veh Reg No: GV2175S

Estimate No: ES1900065
Date: 27 Aug 2019
Policy No:
Veh Reg No: SJF5709G
Make/Model: TOYOTA VIOS E AUTO
Chassis No: MR053HY9305062012
Engine No: 1NZX736435
Reg. Date: 03/06/2008

Estimate Repair Cost to Vehicle No :SJF5709G

Description	U/Price	Quantity	List Price	Amount
			<u>SS</u>	<u>SS</u>
			7,222.42	7,222.42
Labour				
36 TO DISMANTLE & REPLACE DAMAGED PARTS, PANEL BEAT WHERE NECESSARY.	1,700.00	1 JOB	1,700.00	700
37 TO PUTTY, APPLY PRIMER & SPRAY-PAINT ON THE AFFECTED PORTION.	1,500.00	1 JOB	1,500.00	800
38 TO APPLY RUST-PROOFING ON REPAIRED, REPLACED PANEL.	150.00	1 JOB	150.00	60
39 TO REMOVE/RENEW EXHAUST MUFFLER.	100.00	1 JOB	100.00	X
40 TO CHECK WIRING FUNCTIONS.	40.00	1 JOB	40.00	20
41 TOWING FEE	120.00	1 JOB (Bill)	120.00	X
			3,610.00	3,610.00
			Total	SS 11,182.42
			Add GST @ 7%	782.77
			Total Amount Payable	SS 11,965.19

TOTAL: SINGAPORE DOLLAR ELEVEN THOUSAND NINE HUNDRED SIXTY FIVE AND CENTS NINETEEN ONLY

For Yee Auto Pte Ltd

AUTHORISED SIGNATURE

LIK Auto Consultants hence notify the Repairer of the following:

- To resurvey before spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:
Signature:
Date:

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI19015088/KVF3N2

Date: 02/10/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN30000719011	
Claimant Vehicle No :	SJF5709G	Insured Vehicle No :	GV2175S	
Date of Loss:	25/08/2019	Nature of Claim:	TP	Claim No: SNM19D203978C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJF5709G	Engine No:	1NZX736435
Make & Model:	TOYOTA VIOS, 1.5 (A)	Chassis No:	MR053HY9305062012
Reg. Date:	03/06/2008 (Man. Year: 2008)	Odometer:	144710 km
Colour:	Metallic Grey		
Engine Capacity:	1497 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60R15	Rear Tyre Size:	185/60R15
Front Left Side:	Linglong 9 mm	Rear Left Side:	Linglong 9 mm
Front Right Side:	Linglong 9 mm	Rear Right Side:	Linglong 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	7,572.42	2,223.26	5,349.16	70.64
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,610.00	1,580.00	2,030.00	56.23
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	11,182.42	3,803.26	7,379.16	65.99
Approved Total (Overridden) (\$\$)		3,000.00		
(\$\$)	11,182.42	3,000.00	8,182.42	73.17
+ GST 7.00/7.00% (\$\$)	782.77	210.00	572.77	73.17
Nett Amount (\$\$)	11,965.19	3,210.00	8,755.19	73.17

INSPECTION

Date of Assignment:	27/08/2019	
Date Inspected:	27/08/2019 Inspected At:	Yee Auto Service (HQ) 160 Sin Ming Drive #02-17 Sin Ming Autocity Singapore 575722
Estimated Period of Repair:	5.0 days	

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 02 Oct 2019)
Parts: 143	TOYOTA VIOS 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SJF5709G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOT EMBLEM LOGO	Necessary	53.00 F	*53.00 FL
2	1		*BOOT EMBLEM VIOS	Necessary	36.90 F	*36.90 FL
3	1		*BOOT HINGE-LH	Repair	100.00 F	*- FL
4	1		*BOOT HINGE-RH	Repair	100.00 F	*- FL
5	1		*BOOT LOCK	Repair	185.10 F	*- FL
6	1		*BOOT OUTER GARNISH	Serviceable	251.40 F	*- FL
7	1		*BOOT TOP LOCK	Repair	90.95 F	*- FL
8	1		*BOOT LID	Buckled	656.95 F	*656.95 FL
9	1		*BOOT LID WEATHERSTRIP	Serviceable	165.62 F	*- FL
10	1		*EXHAUST MUFFLER	Repair	538.10 F	*- FL
11	1		*REAR BODY PANEL	Bent	503.30 F	*503.30 FL
12	1		*REAR BODY PANEL TOP GARNISH	Distorted	200.76 F	*200.76 FL
13	1		*REAR BUMPER	Bent	529.50 F	*529.50 FL
14	1		*REAR BUMPER CLIPS	Necessary	6.00 F	*6.00 FL
15	1		*REAR BUMPER REFLECTOR-LH	Cracked	162.50 F	*162.50 FL
16	1		*REAR BUMPER REFLECTOR-RH	Serviceable	162.50 F	*- FL
17	1		*REAR BUMPER SIDE RETAINER-LH	Distorted	78.05 F	*78.05 FL
18	1		*REAR BUMPER SIDE RETAINER-RH	Serviceable	78.05 F	*- FL
19	1		*REAR FENDER INNER TRIM-LH	Serviceable	369.50 F	*- FL
20	1		*REAR FENDER INNER TRIM-RH	Serviceable	369.50 F	*- FL
21	1		*REAR NUMBER PLATE LAMP-LH	Serviceable	103.90 F	*- FL
22	1		*REAR NUMBER PLATE LAMP-RH	Serviceable	103.90 F	*- FL
23	1		*REAR SPARE TYRE SPONGE	Serviceable	288.00 F	*- FL
24	1		*REAR TOOL BOX	Cracked	138.00 F	*138.00 FL
25	1		*REAR WHEEL PANEL COVER	Serviceable	235.10 F	*- FL
26	1		*SPARE WHEEL PANEL	Repair	499.50 F	*- FL
27	1		*TAIL LAMP LH	Cracked	297.62 F	*297.62 FL
28	1		*TAIL LAMP RH	Serviceable	297.62 F	*- FL
29	1		*TAILLAMP PANEL-LH	Repair	138.00 F	*- FL
30	1		*TAILLAMP PANEL-RH	Repair	138.00 F	*- FL
31	1		*REAR BODY GARNISH CLIP	Not Necessary	10.00 F	*- FL
32	1		*REAR BOOT EMBLEM E	Necessary	35.10 F	*35.10 FL
33	1		*REAR PARKING CAMERA	Serviceable	300.00 F	*- FL
34	1		*REAR NUMBER PLATE	Serviceable	50.00 FS	*- FS
35	1		*REVERSE SENSORS	Dented	300.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	7,572.42	2,897.68
- List Item Discount on L Items 0.00/25.00% (\$\$)	0.00	674.42
Total Parts (\$\$)	7,572.42	2,223.26

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE & REPLACE DAMAGED PARTS.PANEL BEAT WHERE NECESSARY	New	1,700.00	700.00
2	TO PUTTY,APPLY PRIMER & SPRAY-PAINT ON THE AFFECTED PORTION	New	1,500.00	800.00
3	TO APPLY RUST-PROOFING ON REPAIRED,REPLACED PANEL	New	150.00	60.00
4	TO REMOVE/RENEW EXHAUST MUFFLER	New	100.00	0.00
5	TO CHECK WIRING FUNCTIONS	New	40.00	20.00
6	TOWING FEE	New	120.00	0.00
Gross Labour Cost (\$\$)			3,610.00	1,580.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >