

Your Ref : C10003837/KY

Date: 24<sup>th</sup> September 2019

Our Ref : CS/AGI19015091/Pvd3s2

**M/s Auto & General Insurance (Singapore) Pte Ltd**  
(Budget Direct Insurance)  
190 Clemenceau Avenue #03-01  
Singapore Shopping Centre  
Singapore 239924  
(The Motor Claims Department)

Dear Sirs/Madam,

**AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE SGX 938K  
ACCIDENT ON 24/08/2019**

Instruction was received to inspect the vehicle Reg. No. SGX 938K. The inspection was conducted on 27/08/2019 at the premises of SME Motor Pte Ltd, 1 Kaki Bukit Ave 6 #02-15 (Autobay @ Kaki Bukit) Singapore 417883.

The following vehicle information was recorded:

Registration Number	: SGX 938K
Make/Model	: Toyota Camry
Year of Registration	: 2007
Body Colour	: Silver
Chassis Number	: ACV403117788
Engine Capacity	: 2362 cc
Speedometer Reading	: Damaged

The vehicle sustained damages at the front portion. (Details see photographs enclosed)


In view of this, we are of the opinion that it would be **uneconomical** to proceed with the repairs due to extensive repair cost and recommend it to be written off as **"Total Loss"**.

Market Value	S\$	20,000.00(est)
Less: LTA Reimbursement Value (RV)	(S\$	15,044.00)
Nett Liability	S\$	4,956.00

Vehicle Inspected By:



SHERWIN BEH SWEE YANG  
Technical Investigator



K.K.LAU  
MSc(Eng M), B Eng(Hons), Peng(UK),  
MASME(USA), B Bus(Aust), MBA(UK),  
IEng(UK), MIIE(mech), MinstAEA, MFIEA,  
MIRTE, MIMI, MSAE, MCIARD, AM, NIJAAR(USA),  
AM CATARI(CAN), M.MATA(USA), M.MdATA(USA),  
Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.