

AKA

P

VEHICLE NO SJC 2567J

TOYOTA ESTIMA ACES

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(\$\$)	SURVEYOR'S ADJUSTMENT
PARTS (LIST ITEMS)				
1	Front Bumper 1255.10	Def/ Torn	1744.00	==
1	Front Bumper Side Retainer LHS 75.50	Def	97.00	==
1	LHS Front Fender 758.10	Def	980.00	==
1	LHS Front Fender inner splash shield	Torn	242.00	==
1	LHS Head Lamp	17	2187.00	X
2	RHS & LHS Fog lamp	17	0.00	X
1	LHS Front door	17	572.00	X
1	LHS Front door lower moulding	17	112.00	X
1	LHS Front door upper moulding	17	98.00	X
2	LHS Front door hinges @49.20	17	98.40	X
1	Front Shock Absorber 115	502	455.00	X
1	Front Shock Absorber Mounting 115	17	193.00	X
1	Front Lower Arm 115	Def	278.00	==
1	Front Knuckle Arm 115	Def	492.00	==
1	Front Wheel Bearing 115	Def	198.00	==
			7746.40	
502 less 25%			1936.50	25%
			5809.90	
SPECIAL NETT ITEMS				
1	LHS Front sports rim	10/Def	980.00	502
1set	Front bumper clips	11	50.00	✓
1set	LHS Front fender inner shield clips	11	80.00	X
Total Parts			6919.90	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Not Authorized
LKK
2/5 3200
4/27

Wheghe Akhup

2-3285-7
502
P-1647-85
SN-550-00
L-1050-00
3247-85

VEHICLE NO SJC 2567J TOYOTA ESTIMA

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)	SURVEYOR'S ADJUSTMENT
	LABOUR		
1	To remove the affected parts & fittings to commence repairs; replace damaged parts and components	1000.00 —	400
2	To supply paint materials, expandable items & putty, respray paint on parts replaced	750.00 —	400
3	To remove, refix wiring system at accident damaged areas and check for proper function and focus headlamp beam	120.00 —	20
4	To remove and replace LHS front undercarriage parts (suspension system)	300.00 —	120
5	To conduct full computerised wheel alignment test	120.00 —	80
6	To perform anti-rust treatment on affected areas	150.00 —	30
	Labour Total :	2440.00	
	TOTAL (PARTS & LABOUR):	9359.90	1050

NOTE: The parts listed in this preliminary estimate will be checked for damage after the vehicle is disassembled (dismantle). Additional damaged parts (if any) will be submitted as supplementary parts