

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHA 4875R

DATE 26/8/2019 17:23

MAKE :

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Bumper			\$ 553.00
	Rear Bumper Clip 10 pcs			\$ 22.00
	Per Fender (RM) x repair			
	Per Door (RM) x repair			
	Per Rocker Panel (RM) x repair			
	SUB TOTAL			\$ 575.00
	LESS 20%			\$ 115.00
	DISCOUNTED TOTAL			\$ 460.00
	Per Door Logo			
	Labour Charge			
	Panel Beating			\$ 400.00
	Spray Painting Charge			\$ 300.00
	Wiring Charge			\$ 50.00
	Remove/Refix Reverse Sensor			\$ 80.00
	TOTAL LABOUR			\$ 830.00
	ESTIMATE TOTAL			\$ 1,290.00

1/Calvin 11/11/19

27/8/19 1130

2 Day

4/5

After Repair plb

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.