

/32, REC. BY:

REF:

ALG CC3/AIG 19015104/AT-P312

myrimy

ASSIGNMENT

From:

Date:

27/8/2019

Estimated Cost:

Veh No:

SLK 2700A

Yr Regn:

2016 Dec

Type: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

☒ OD / ☐ IP / ☐ WS / ☐ TP RES / ☐ OD RES / ☐ EVA / ☐ INV / ☐ MV

To inspect Vehicle No:

SLK 2700A

at Workshop m/s

premium

of

55 ubi Road 1

Insured:

Policy No.

2100495355

Claims No.

98462472285

Sum Insured:

Excess:

88A \$3.300

(Client's Record)

Make of Veh:

10-300m (weihing)

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

88K

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

04/88 days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / ☒ REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Make:

Audi A3 Sedan

C.C.

999.

Colour

Red.

A/C:

Insured / Std / NI / NA

Sp. Reading

40328

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

WAN228V7H1018600

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 205/55R16

R: 205/55R16

☒ BS / ☐ DUN / ☐ EXNOVA / ☐ GY / ☐ FS / ☐ LIZA / ☐ MIC / ☐ OHTSU / ☐ PIR / ☐ SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

06

mm

R/Bal.

06

mm

L/Bal.

06

mm

L/Bal.

06

mm

D.O.A.

D.O.I.

27/08/19

Survey held at

Premium

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Front N/S.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

OD ALG.

SLK 2700A - CC3/AIG 19014734/dh3

b.0A - 21/03/2019

28/8@9:13- Revert via manmeh

28/8@10:39-mandate approval by victor koh

28/8@10:45- email to premium authorise repair excess \$3300/-

Part by Part \$9,286.96 (Red: 16,953.04; 64%)

Date/Time, File Pass to?



Preli. Report

1) 28/2 Typist



Final Report

Date/Time, File Return to?

2)

Days Of Repair:

4

Resurvey No. of Trip:

1

Add Fee:



Site Insp (\$)



Interview (\$)



Tech. Invs (\$)



Week end %

Survey Fee:

Transportation:

S + RS. \$

Photos

Others

TOTAL

200

11

211

Report Format:

Long Sum / L.B. /

9,286.96
OD

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #08-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 28 Aug 2019

Preliminary Advice

Vehicle No	: SLK2700A	Accident Date	: 21/08/2019
Make	: AUDI A3	Policy No.	: 2100495355
Assignment Date	: 27/08/2019	Excess	: S\$0.00
Date of Inspection	: 27/08/2019	Est. Duration of Repair	: 4.00
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (UBI) 55 UBI ROAD 1 SINGAPORE 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	26,240.00
Revised Amount	:S\$	10,539.00
Check Items (Estimated)	:S\$	695.00
	:S\$	11,234.00

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	88,000.00
COE / PARF Rebate	:S\$	48,702.00
Salvage Value	:S\$	
Margin for Repair	:S\$	39,298.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

View Received Message

This mail is associated with :

***SLK2700A (9846247228SG)**

OD

Aug 21 2019 7:00PM

[TAN KIN LIANG]

Premium Automobiles Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on 28/08/2019 10:39 AM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$10539.00) - SLK2700A - Claim Handler: Mithoo Singh, Aashweenjeet Kaur

Approved:10539.00:Re-inspection to be done for damage check and supplementary items / labour.

DOCUMENTS SUMMARY

There are no documents.

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Wednesday, 28 August 2019 10:45 AM
To: claims@premiumauto.com.sg; Admin A; Admin-D (LKKAuto); SUR
Subject: RE: OD CLAIM FOR SLK 2700 A ON 21/8/2019

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle **SLK 2700 A (Excess \$ S\$3,300.00 /-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claims <claims@premiumauto.com.sg>
Sent: Tuesday, 27 August 2019 1:54 PM
To: Admin A <admin-a@lkkauto.com>; Admin-D (LKKAuto) <admin-d@lkkauto.com>; SUR <sur@lkkauto.com>
Cc: claims@premiumauto.com.sg
Subject: RE: OD CLAIM FOR SLK 2700 A ON 21/8/2019

Dear All,

Above mention vehicle already survey today by surveyor Adrian. Please assist on the approval. Thank you

Thank you.

Best Regards,
Ezuwan Huzaini
Claims Advisor

Premium Automobiles Pte Ltd (Reg No 199902271W)
55 Ubi Road 1 Road Singapore 408699
p. +65 6388 2323 d. +65 6768 9911 f. +65 6841 1183
e. claims@premiumauto.com.sg w. www.audi.com.sg
Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	833D
Vehicle Details	
Vehicle No.:	SLK2700A
Vehicle to be Exported:	No
Intended Deregistration Date:	28 Aug 2019
Vehicle Make:	AUDI
Vehicle Model:	A3 SEDAN 1.0 TFSI S TRONIC (LED)
Primary Colour:	Red
Manufacturing Year:	2016
Engine No.:	CHZ146426
Chassis No.:	WAUZZZ8V7H1018600
Maximum Power Output:	85.0 kW (113 bhp)
Open Market Value:	\$24,582.00
Original Registration Date:	23 Dec 2016
First Registration Date:	23 Dec 2016
Transfer Count:	0
Actual ARF Paid:	\$16,415.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	22 Dec 2026
PARF Rebate Amount:	\$12,311.00
Intended COE Rebate Details	
COE Expiry Date:	22 Dec 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$49,751.00
COE Rebate Amount:	\$36,391.00
Total Rebate Amount:	\$48,702.00

The information contained herein is correct as at 28 Aug 2019

OK



AUTOPLUS PRIVATE VEHICLE

Policy No. : 2100495355-02
Period of Insurance : 23 Dec 2018 to 22 Dec 2019

Issued Date : 04 Dec 2018

ABOUT THE POLICYHOLDER

Name of Policyholder : TAN KIN LIANG
Address : 662 BUFFALO ROAD
14-19
SINGAPORE 210662
Occupation/Nature of Business : Self Employed/Freelancer

ABOUT THE VEHICLE

Registration No. : SLK2700A
Chassis No. : WAUZZZ8V7H1018600
Seating Capacity : 5
Make/Model : AUDI A3 Sedan 1.0 TFSI S tronic
Hire Purchase Company/Employer's Loan : United Overseas Bank Limited
Engine Capacity/Tonnage : 999.00 CC
Engine No. : CHZ146426
Body Type : Sedan
First Year of Registration : 2016

ABOUT THE COVER

Sum Insured : Market Value
Driver Restriction : NA
Off Peak Car : No
Insuring with COE/PAFF : Yes

Person or Classes of Persons Entitled to Drive :

- a) The Policyholder
b) Any other person who is driving on the Policyholder's order or with his/her permission.
This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition

Limitation as to use :

Use only for social, domestic and pleasure purposes and for the Policyholder's business.
This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Other Key Policy Benefits :

Act of God, Dealer (First 3 years from original registration) + AIG Authorised Workshops, Waiver of Excess, PA to Authorised Driver / Unnamed Passengers- \$10000, PA Insured- \$50000, Key Replacement Cover- \$800, Strike, Riots and Civil Commotions, Loss of Use 1500cc - 1600cc Optional, In-Car Camera Excess Waiver, New For Old (36 months)

EXCESS

Section 1
Fire - \$0 Own Damage - \$600 Theft - \$0 Flood Cover - \$0

Section 2
Property Damage - \$0

Windscreen : \$100

Named Driver
TAN KIN LIANG - \$600 (Own Damage)

PREMIUM

Premium	:	\$	2,047.57
GST (7%)	:	\$	143.33
Total	:	\$	2,190.90

Your Premium includes the following discount(s):
Loyalty Discount - 5.00%, No Claim Discount - 20%

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 65049

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/1009/2019/NS
Date	:	23-Aug-19

Vehicle NOT IN workshop. Please arrange for survey

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Mr. Tan Kin Liang
Address	:	Blk 662 Buffalo Road #14-19 Singapore 210662
Telephone	:	HP +65 91905912
Type of Claim	:	Own Damage Claims
Policy No.	:	2100495355-02
Vehicle No	:	SLK 2700 A
Model Code	:	Audi A3 Sedan 1.0 TFSI 8V
Model / Year	:	Dec-16
Engine No	:	CHZ 146426
Chassis No	:	WAUZZZ8V7H1018600
Mileage	:	
Date In	:	
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	16-Aug-19
Place of Accident	:	Double Bay Residences Lvl 4 Visitor Carpark

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLK 2700 A

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N \$ 360.00	✓
2	To remove and reinstall aircond condenser, additional radiator, radiator. Check electrical fans and control unit. Pressurise cooling system. To carry out vacuum and regas.	S/N \$ 1,200.00	✗
3	To dismantle and renew front bumper, lhs front fender, and lhs headlight. To repair bonnet and lhs front fender top support. Renew front lock carrier and align to position. Re-organise crash management components. Reinstall all parts removed.	\$ 5,250.00	1250 ✓
4	To respray front bumper, lhs front fender, bonnet and lhs front fender top support.	\$ 3,500.00	1100 ✓
5	To carry out diagnostic checks.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 10,502.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLK 2700 A

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARK
1	FRONT BUMPER <i>deformed</i>	\$ 1,830.00	✓ 1464
2	FRONT BUMPER FIXING PART <i>new</i>	\$ 170.00	+
3	FRONT BUMPER GUIDE SECTION - LH <i>crushed</i>	\$ 35.00	? 27.52
4	FRONT BUMPER GRILLE - CENTRE <i>new</i>	\$ 146.00	+
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>new</i>	\$ 488.00	+
6	FRONT BUMPER CLOSING ELEMENT - LH <i>new</i>	\$ 270.00	+
7	FRONT BUMPER COVER TRIM - LH <i>new</i>	\$ 148.00	+
8	FRONT BUMPER WHEEL HOUSING LINER ADAPTER - LH <i>new</i>	\$ 34.00	+
9	RADIATOR GRILLE <i>not new</i>	\$ 1,301.00	+
10	RADIATOR GRILLE CLOSING ELEMENT <i>new</i>	\$ 174.00	+
11	FRONT BUMPER AIR GUIDE GRILLE	\$ 171.00	+
12	AIRCON STICKER <i>new</i>	NEC \$ 7.00	+
13	CAUTION SIGN <i>new</i>	NEC \$ 13.00	+
14	FRONT BUMPER SIDE REINFORCEMENT <i>new</i>	\$ 660.00	+
15	FRONT BUMPER FOAM FILLER PIECE <i>new</i>	\$ 172.00	?
16	FRONT BUMPER COVER - LH / RH <i>new</i>	2 \$ 222.00	+
17	SIGNAL HORN - LH HIGH TONE <i>new</i>	\$ 182.00	+
18	FENDER - LH <i>Dented</i>	\$ 778.00	✓ 622
19	FENDER ATTACHMENT PARTS <i>not new</i>	\$ 65.00	? X
20	FENDER REAR BRACKET - LH <i>new</i>	\$ 25.00	<i>new</i>
SUB TOTAL SPARE PARTS		\$ 6,891.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLK 2700 A

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	Remarks
21	FENDER CENTRE BRACKET - LH <i>new</i>	\$ 35.00	<i>7x</i>
22	FENDER BRACE <i>Bent.</i>	\$ 88.00	<i>69.84</i>
23	WHEEL HOUSING LINER SEAL - LH <i>new</i>	\$ 31.00	<i>+</i>
24	WHEEL HOUSING LINER - LH <i>new</i>	\$ 158.00	<i>+</i>
25	WHEEL HOUSING LINER ATTACHMENT PARTS <i>new</i>	\$ 81.00	<i>+</i>
26	LED HEADLIGHT - LH <i>cracked</i>	\$ 5,029.00	<i>4023.20</i>
27	LIGHT CONTROL SYSTEM CONTROL UNIT <i>new</i>	\$ 508.00	<i>+</i>
28	MAIN LIGHT ELECTRONICS POWER MODULE <i>new</i>	\$ 693.00	<i>+</i>
29	LED WITH HEAT SINK - LH <i>new</i>	\$ 666.00	<i>+</i>
30	HEADLIGHT HOSE - LH <i>new</i>	\$ 36.00	<i>+</i>
31	HEADLIGHT WASHER LIFT CYLINDER <i>new</i>	\$ 128.00	<i>+</i>
32	LIFT CYLINDER HOSE <i>new</i>	\$ 61.00	<i>+</i>
33	WASH WATER RESERVOIR <i>deformed.</i>	\$ 186.00	<i>148.40</i>
34	STRAINER <i>new</i>	\$ 19.00	<i>+</i>
35	WASH WATER RESERVOIR END CAP <i>new</i>	\$ 19.00	<i>+</i>
36	COOLANT RADIATOR LOCK CARRIER <i>new</i>	\$ 663.00	<i>+</i>
37	READY MIX COOLANT <i>new</i>	4 \$ 84.00	<i>+</i>
38	RADIATOR AIR GUIDE <i>new</i>	\$ 22.00	<i>+</i>
39	FRONT NO. PLATE <i>new</i>	S/N \$ 40.00	<i>+</i>
40	SUNDRIES <i>new</i>	\$ 300.00	<i>30</i>
TOTAL SPARE PARTS		:	\$ 15,738.00
TOTAL LABOUR CHARGES		:	\$ 10,502.00
GRAND TOTAL		:	\$ 26,240.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : *Adrian King*
Surveyed Date : *27/08/19*
Authorised Date :
Excess Cost :
Liability :
Remarks : *Not Authorised, 04 Days.*

LKKA 1001

the Repairer of

- To ensure before repair is completed
- To display damaged parts during repair
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be requested and is subject to final approval from insurance Company

Acknowledged by Repairer
Signature:
Date:

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 65049

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/1009/2019/NS
Date	:	23-Aug-19

Vehicle NOT IN workshop. Please arrange for survey

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Hi Adrian

4 days - ok - jb - 26 Dec 19

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Mr. Tan Kin Liang
Address	:	Blk 662 Buffalo Road #14-19 Singapore 210662
Telephone	:	HP +65 91905912
Type of Claim	:	Own Damage Claims
Policy No.	:	2100495355-02
Vehicle No	:	SLK 2700 A
Model Code	:	Audi A3 Sedan 1.0 TFSI 8V
Model / Year	:	Dec-16
Engine No	:	CHZ 146426
Chassis No	:	WAUZZZ8V7H1018600
Mileage	:	
Date In	:	
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	16-Aug-19
Place of Accident	:	Double Bay Residences Lvl 4 Visitor Carpark

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLK 2700 A

S/N	Nature of Jobs		Estimated Charges		Surveyor's Recommendation
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N	\$ 360.00	\$	360.00
2	To remove and reinstall aircond condenser, additional radiator, radiator. Check electrical fans and control unit. Pressurise cooling system. To carry out vacuum and regas.	S/N	\$ 1,200.00		
3	To dismantle and renew front bumper, lhs front fender, and lhs headlight. To repair bonnet and lhs front fender top support. Renew front lock carrier and align to position. Re-organise crash management components. Reinstall all parts removed.		\$ 5,250.00	\$	1,250.00
4	To respray front bumper, lhs front fender, bonnet and lhs front fender top support.		\$ 3,500.00	\$	1,100.00
5	To carry out diagnostic checks.	S/N	\$ 192.00	\$	192.00
	TOTAL LABOUR CHARGES	:	\$ 10,502.00	\$	2,902.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLK 2700 A

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARK
1	FRONT BUMPER	\$ 1,830.00	\$ 1,464.00
2	FRONT BUMPER FIXING PART	\$ 170.00	
3	FRONT BUMPER GUIDE SECTION - lh	\$ 35.00	\$ 27.52
4	FRONT BUMPER GRILLE - CENTRE	\$ 146.00	
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	\$ 488.00	
6	FRONT BUMPER CLOSING ELEMENT - LH	\$ 270.00	
7	FRONT BUMPER COVER TRIM - LH	\$ 148.00	
8	FRONT BUMPER WHEEL HOUSING LINER ADAPTER - LH	\$ 34.00	
9	RADIATOR GRILLE	\$ 1,301.00	
10	RADIATOR GRILLE CLOSING ELEMENT	\$ 174.00	
11	FRONT BUMPER AIR GUIDE GRILLE	\$ 171.00	
12	AIRCON STICKER	NEC \$ 7.00	
13	CAUTION SIGN	NEC \$ 13.00	
14	FRONT BUMPER SIDE REINFORCEMENT	\$ 660.00	
15	FRONT BUMPER FOAM FILLER PIECE	\$ 172.00	
16	FRONT BUMPER COVER - LH / RH	2 \$ 222.00	
17	SIGNAL HORN - LH HIGH TONE	\$ 182.00	
18	FENDER - LH	\$ 778.00	\$ 622.00
19	FENDER ATTACHMENT PARTS	\$ 65.00	
20	FENDER REAR BRACKET - LH	\$ 25.00	
	SUB TOTAL SPARE PARTS	\$ 6,891.00	\$ 2,113.52

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLK 2700 A

S/N	Parts Description		Damage Pa S/NETT
		<i>c/f</i>	
21	FENDER CENTRE BRACKET - LH	\$	35.00
22	FENDER BRACE	\$	88.00
23	WHEEL HOUSING LINER SEAL - LH	\$	31.00
24	WHEEL HOUSING LINER - LH	\$	158.00
25	WHEEL HOUSING LINER ATTACHMENT PARTS	\$	81.00
26	LED HEADLIGHT - LH	\$	5,029.00
27	LIGHT CONTROL SYSTEM CONTROL UNIT	\$	508.00
28	MAIN LIGHT ELECTRONICS POWER MODULE	\$	693.00
29	LED WITH HEAT SINK - LH	\$	666.00
30	HEADLIGHT HOSE - LH	\$	36.00
31	HEADLIGHT WASHER LIFT CYLINDER	\$	128.00
32	LIFT CYLINDER HOSE	\$	61.00
33	WASH WATER RESERVOIR	\$	186.00
34	STRAINER	\$	19.00
35	WASH WATER RESERVOIR END CAP	\$	19.00
36	COOLANT RADIATOR LOCK CARRIER	\$	663.00
37	READY MIX COOLANT	4 \$	84.00
38	RADIATOR AIR GUIDE	\$	22.00
39	FRONT NO. PLATE	S/N \$	40.00
40	SUNDRIES	\$	300.00
	TOTAL SPARE PARTS	:	\$ 15,738.00
	TOTAL LABOUR CHARGES	:	\$ 10,502.00
	GRAND TOTAL	:	\$ 26,240.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Costs & Prices

Remarks

\$ 2,113.52

\$ 69.84

\$ 4,023.20

\$ 148.40

\$ 30.00

\$ 6,384.96

\$ 2,902.00

\$ 9,286.96

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Yr Ref: SLK 2700 A

Norah Khai
6768 9911
6841 1183
Nora.khai@premiumauto.com.sg
Body & Paint Dept
PA/OD/1009/2019/NH

20th February 2020

from
Telephone +65-
Telefax +65-
Email
Our department
Our Ref
Your Ref
Date

Dear Sir,

RE: INSURANCE CLAIM FOR SLK 2700 A, Audi A3 SEDAN 1.0 TFSI.

With reference to the above-mentioned vehicle, no. **SLK 2700 A**, claimant, **Mr. Tan Kin Liang**, please find the related document per attached.

1. A copy of the Original invoice no. 85014862 – S\$ 6,406.05.
2. A copy of the Discharge Voucher duly signed by client.

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai
Claims Dept

Encl
AIG – SLK 2700 A

total pages

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6336 2323
Telefax (65) 684 11183

Premium Automobiles Pte Ltd



Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6836 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Main Telephone 6388 2223
Main Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408699
Main Telephone 6388 2323
Main Telefax 6841 1183

Customer Service
Service Appointment 6366 2323
24-hour Breakdown Service 9828 1233
Email customer.care@premiumauto.com.sg

INS TAX INVOICE

Page 1 14:44

Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120		Invoice No: 85014862	Account: A0006 (T 0)		
		Date : 19/02/2020	AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120		
		Order : SLK2700A			
		Term : 30			
Regn No: SLK2700A (V 31839)		Regn Date: 23/12/2016	Mileage: 44057 WIP No.: 65049		
Model: A3 SEDAN 1.0 TFSI 8VMANG		Chassis: WAUZZZ8V7H1018600	Engine: CHZ 146426 Dept: U		
You have been assisted by :- UB-Tony Foong (33)					
		Details	Qty	Unit Price	Amount
Q	EXC	M: 8888 Insurance Excess/Liability	-3300.00	1.00	-3,300.00
S	BODYWORK	M: TO REMOVE,CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS,HORNS,OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	360.00	1.00	360.00
S	BODYWORK	M: TO DISMANTLE AND RENEW FRONT BUMPER,LHS FRONT FENDER AND LHS HEADLIGHT.TO REPAIR BONNET AND LHS FRONT FENDER TOP SUPPORT. RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION.REORGANISE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	1250.00	1.00	1,250.00
S	BODYWORK	M: TO RESPRAY FRONT BUMPER AND LHS FRONT FENDER	1100.00	1.00	1,100.00
S	BODYWORK	M: TO CARRY OUT DIAGNOSTIC CHECK	192.00	1.00	192.00
X	A8V5807065R GRU	(A)(SK)COVER 28/8/19	Less 020%	1.00	1830.00
X	A8V5821105A	FENDER(LAST)	Less 020%	1.00	777.50
X	AN 0161857	POP-RIVET	Less 020%	5.00	3.00
X	A8V0941773D	HEADLIGHT	Less 020%	1.00	5029.00
X	A5Q0955453R	WATER RES. AP	Less 020%	1.00	185.50
X	AN 0161857	POP-RIVET	Less 020%	3.00	3.00
X	A443955465	GASKET AP	Less 020%	1.00	3.10
X	A431955465A	GASKET AP	Less 020%	1.00	7.40
X	AN 91022001	NUT AP	Less 020%	2.00	1.50
X	A8V0821135A	SUPPORT BORROW WAREH	Less 020%	1.00	87.30
X	A8V5807183	GUIDE BORROW WAREHOU	Less 020%	1.00	34.40
Parts 6,384.96			Sub-Total		5,986.9
Labour 0.00					
Sublet 2,902.00			7% GST		419.0
Menus 0.00					
Lubricant 0.00			Grand Total		6,406.0



Received by

For & on behalf of
Premium Automobiles Pte Ltd

Premium Automobiles

Telefax

to AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Motor Claims Dept
Yr Ref: SLK 2700 A

Norah Khai
6768 9828
6841 1183

Body Repair

PA/OD/1009/2019/EH
6 September 2019

from
Telephone +65-
Telefax +65-
Mobile +65-
Our department
Your Claim Ref
Our Ref
Date

1 total pages

RE: CLAIM – OWNER'S SATISFACTION/DISCHARGE VOUCHER

Make & Model : Audi A3 SEDAN 1.0 TFSI 8V
Vehicle Chassis No. : WAUZZZ8V7H1018600
Vehicle Regn No. : SLK 2700 A
Vehicle Mileage : 40506 KM
Vehicle Owner : Mr. Tan Kin Liang
Certificate No : 2100495355-02
Own Damage Excess : \$ 3,531.00 (Inclusive GST)
Accident Date : 21 August 2019
Place : Double Bay Residences LVL 4 Visitor CP
Repair Cost : S\$ 6406.05
WIP No. : 65049
Repairer's Name : Premium Automobiles Pte Ltd

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Road 1
Singapore 408699
Telephone (65) 6366 2323
Telefax (65) 6841 1183

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer's charges that are claimable under the policy will be deemed in full and final settlement of my claim.

Owner / Insured Signature : 
Time : 6/9
Date : 18/5/19

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est. Submitted	Adj. Assigned	Adj. Rpt	Adj. Submitted	Ins. Auth'd	Status
Main	28 Aug 2019		27 Aug 2019 16:29 Edit Adj Rpt	\$9,286.96 Edit Estimates	\$9,286.96 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured: TAN KIN LIANG , ID: S1566833D, Tel: +6591905912	
Vehicle Reg. No.: SLK2700A	Date of Loss: 21/08/2019 19:00 - :59 [31 Months and 29 Days From LTA Reg Date (Man Yr)]
Claim Type: OD / 9846247228SG	Policy/Cover Note No.: 2100495355 (Comprehensive)
	Excess: \$3,300.00
Repairer: Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911	
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Mithoo Singh, Aashweenjeet Kaur] Aashweenjeetkaur.Mithoosingh@aig.com	
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 05/09/2019]	
Driver/Custodian: TAN HONG HEOK (22 / Male) , NRIC: S9707588C, Tel: +6596694328 Email: hongheok@gmail.com	

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

- AIG_SG (28/08/2019): Alert - Adj Mandate Approved (\$10539.00) - SLK2700A - Claim Handler: Mithoo Sin...
- AIG_SG (28/08/2019): SLK2700A / OD / 21/08/2019 / Coverage & Excess update

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLK2700A (9846247228SG)

OD

Aug 21 2019 7:00PM

[TAN KIN LIANG]

Premium Automobiles Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser		
Video															1 per page			☒		
No	Finalized On	Premium Automobiles Pte Ltd (UBI)												Thumbnail			Print			
1	22/08/19 11:43	Video - Accident [Linked Accident Report Documents]												1			Load MP4			
Assessment Reports															1 per page			☒		
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)												Thumbnail			Print			
1	28/08/19 09:12	Adjuster Immediate Advice												1			Load HTM			
Photos/Images															3 per page			☒		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)												Thumbnail			Print			
1	27/08/19 17:41	General View												1			Load JPG			
2	27/08/19 17:41	General View												1			Load JPG			
3	27/08/19 17:41	General View												1			Load JPG			
4	27/08/19 17:41	General View												1			Load JPG			
5	27/08/19 17:41	General View												1			Load JPG			
6	27/08/19 17:41	General View												1			Load JPG			
7	27/08/19 17:41	General View												1			Load JPG			
8	27/08/19 17:41	General View												1			Load JPG			
9	27/08/19 17:41	General View												1			Load JPG			
10	27/08/19 17:41	General View												1			Load JPG			
11	27/08/19 17:41	General View												1			Load JPG			
12	27/08/19 17:41	General View												1			Load JPG			
13	27/08/19 17:41	General View												1			Load JPG			
14	27/08/19 17:41	General View												1			Load JPG			
15	27/08/19 17:41	General View												1			Load JPG			
16	22/01/20 13:18	Reinspection Photo												1			Load JPG			
17	22/01/20 13:18	Reinspection Photo												1			Load JPG			
18	22/01/20 13:18	Reinspection Photo												1			Load JPG			
19	22/01/20 13:18	Reinspection Photo												1			Load JPG			
20	22/01/20 13:18	Reinspection Photo												1			Load JPG			
21	22/01/20 13:18	Reinspection Photo												1			Load JPG			
Documentation															1 per page			☒		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)												Thumbnail			Print			
1	27/08/19 17:40	ESTIMATE												1			Load PDF			
2	27/08/19 17:40	Certificate of Insurance												1			Load PDF			
3	27/08/19 17:40	Driver's Driving License												1			Load PDF			
4	27/08/19 17:40	Singapore Accident Statement												1			Load PDF			
5	05/03/20 09:04	WORKSHOP INVOICE												1			Load PDF			
6	05/03/20 09:04	DISCHARGE VOUCHER												1			Load PDF			

Linked Accident Report Documents

										View		View in Browser ▼	
Video										1 per page ▼		☒	
No	Finalized On	Premium Automobiles Pte Ltd (UBI)									Thumbnail	Print	

Video			1 per page ▼	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	22/08/19 11:43	Video - Accident	 Load MP4	☒
Assessment Reports			1 per page ▼	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	04/09/19 02:29	Accident Statement	 Load HTM	☒
Photos/Images			3 per page ▼	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	22/08/19 11:29	Accident Photo	 Load JPG	☒
2	22/08/19 11:29	Accident Photo	 Load JPG	☒
3	22/08/19 11:29	Accident Photo	 Load JPG	☒
4	22/08/19 11:29	Accident Photo	 Load JPG	☒
5	22/08/19 11:29	Accident Photo	 Load JPG	☒
6	22/08/19 11:29	Accident Photo	 Load JPG	☒
7	22/08/19 11:29	Accident Photo	 Load JPG	☒
8	22/08/19 11:29	Accident Photo	 Load JPG	☒
9	22/08/19 11:29	Accident Photo	 Load JPG	☒
10	22/08/19 11:29	Accident Photo	 Load JPG	☒
11	22/08/19 11:29	Accident Photo	 Load JPG	☒
12	22/08/19 11:29	Accident Photo	 Load JPG	☒
13	22/08/19 11:29	Accident Photo	 Load JPG	☒
14	22/08/19 11:29	Accident Photo	 Load JPG	☒
15	22/08/19 11:29	Accident Photo	 Load JPG	☒
16	22/08/19 11:29	Accident Photo	 Load JPG	☒
17	22/08/19 11:29	Accident Photo	 Load JPG	☒
18	22/08/19 11:29	Accident Photo	 Load JPG	☒
19	22/08/19 11:29	Accident Photo	 Load JPG	☒
20	22/08/19 11:29	Accident Photo	 Load JPG	☒
21	22/08/19 11:29	Accident Photo	 Load JPG	☒
22	22/08/19 11:29	Accident Photo	 Load JPG	☒
Documentation			1 per page ▼	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	22/08/19 11:33	Sketch Plan	 Load JPG	☒
2	22/08/19 11:33	Sketch Plan #2	 Load JPG	☒
3	22/08/19 11:33	Sketch Plan #3	 Load JPG	☒
4	22/08/19 11:33	Sketch Plan #4	 Load JPG	☒
5	22/08/19 11:33	Sketch Plan #5	 Load JPG	☒
6	22/08/19 11:33	Sketch Plan #6	 Load JPG	☒

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #08-16
Singapore 079120

Our File No: CC3/AIG19015104/ATF3N2

Date: 05/03/2020

REFERENCE

Insured/Claimant:	TAN KIN LIANG	Policy No:	2100495355	
Date of Loss:	21/08/2019	Nature of Claim:	OD	Claim No: 9846247228SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLK2700A	Engine No:	CHZ146426
Make & Model:	AUDI A3, 999cc SEDAN TFSI (A)	Chassis No:	WAUZZZ8V7H1018600
Reg. Date:	23/12/2016 (Man. Year: 2016)	Odometer:	40328 km
Colour:	Red		
Engine Capacity:	999 cc		
Market Value/New Car Price:	S\$88,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55R16	Rear Tyre Size:	205/55R16
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,738.00	6,384.96	9,353.04	59.43
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,502.00	2,902.00	7,600.00	72.37
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	26,240.00	9,286.96	16,953.04	64.61
- Excess (S\$)	3,300.00	3,300.00	0.00	0.00
(S\$)	22,940.00	5,986.96	16,953.04	73.90
+ GST 7.00/7.00% (S\$)	1,605.80	419.09	1,186.71	73.90
Nett Amount (S\$)	24,545.80	6,406.05	18,139.75	73.90

INSPECTION

Date of Assignment:	27/08/2019		Premium Automobiles Pte Ltd (UBI)
Date Inspected:	27/08/2019	Inspected At:	55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	4.0 days		

Adjuster: ADRIAN LING

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,830.00 FS	*1,464.00 FS
2	1		*FRONT BUMPER FIXING PART	Not Necessary	170.00 FS	*- FS
3	1		*FRONT BUMPER GUIDE SECTION-LH	Cracked	35.00 FS	*27.52 FS
4	1		*FRONT BUMPER GRILLE-CENTRE	Not Necessary	146.00 FS	*- FS
5	1		*FRONT BUMPER CLOSING ELEMENT-LOWER CENTRE	Not Necessary	488.00 FS	*- FS
6	1		*FRONT BUMPER CLOSING ELEMENT-LH	Not Necessary	270.00 FS	*- FS
7	1		*FRONT BUMPER COVER TRIM-LH	Not Necessary	148.00 FS	*- FS
8	1		*FRONT BUMPER WHEEL HOUSING LINER ADAPTER-LH	Not Necessary	34.00 FS	*- FS
9	1		*RADIATOR GRILLE	Not Necessary	1,301.00 FS	*- FS
10	1		*RADIATOR GRILLE CLOSING ELEMENT	Not Necessary	174.00 FS	*- FS
11	1		*FRONT BUMPER AIR GUIDE GRILLE	Not Necessary	171.00 FS	*- FS
12	1		*AIRCON STICKER	Not Necessary	7.00 FS	*- FS
13	1		*CAUTION SIGN	Not Necessary	13.00 FS	*- FS
14	1		*FRONT BUMPER SIDE REINFORCEMENT	Not Necessary	660.00 FS	*- FS
15	1		*FRONT BUMPER FOAM FILLER PIECE	Not Necessary	172.00 FS	*- FS
16	2		*FRONT BUMPER COVER-LH/RH	Not Necessary	222.00 FS	*- FS
17	1		*SIGNAL HORN-LH HIGH TONE	Not Necessary	182.00 FS	*- FS
18	1		*FENDER-LH	Dented	778.00 FS	*622.00 FS
19	1		*FENDER ATTACHMENT PARTS	Not Necessary	65.00 FS	*- FS
20	1		*FENDER REAR BRACKET-LH	Not Necessary	25.00 FS	*- FS
21	1		*FENDER CENTRE BRACKET-LH	Not Necessary	35.00 FS	*- FS
22	1		*FENDER BRACE	Bent	88.00 FS	*69.84 FS
23	1		*WHEEL HOUSING LINER SEAL-LH	Not Necessary	31.00 FS	*- FS
24	1		*WHEEL HOUSING LINER-LH	Not Necessary	158.00 FS	*- FS
25	1		*WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	81.00 FS	*- FS
26	1		*LED HEADLIGHT-LH	Cracked	5,029.00 FS	*4,023.20 FS
27	1		*LIGHT CONTROL SYSTEM CONTROL UNIT	Not Necessary	508.00 FS	*- FS
28	1		*MAIN LIGHT ELECTRONICS POWER MODULE	Not Necessary	693.00 FS	*- FS
29	1		*LED WITH HEAT SINK-LH	Not Necessary	666.00 FS	*- FS
30	1		*HEADLIGHT HOSE-LH	Not Necessary	36.00 FS	*- FS
31	1		*HEADLIGHT WASHER LIFT CYLINDER	Not Necessary	128.00 FS	*- FS
32	1		*LIFT CYLINDER HOSE	Not Necessary	61.00 FS	*- FS
33	1		*WASH WATER RESERVOIR	Deformed	186.00 FS	*148.40 FS
34	1		*STRAINER	Not Necessary	19.00 FS	*- FS
35	1		*WASH WATER RESERVOIR END CAP	Not Necessary	19.00 FS	*- FS
36	1		*COOLANT RADIATOR LOCK CARRIER	Not Necessary	663.00 FS	*- FS
37	4		*READY MIX COOLANT	Not Necessary	84.00 FS	*- FS
38	1		*RADIATOR AIR GUIDE	Not Necessary	22.00 FS	*- FS
39	1		*FRONT NO PLATE	Not Necessary	40.00 FS	*- FS
40	1		*SUNDRIES	Necessary	300.00 FS	*30.00 FS

F=Franchise part. S=SpcNett.

Total Parts (\$)	15,738.00	6,384.96
-------------------------	------------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE,CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS,HORNS,OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	360.00
2	TO REMOVE AND REINSTALL AIRCOND CONDENSER,ADDITIONAL RADIATOR,RADIATOR,CHECK ELECTRICAL FANS AND CONTROL UNIT.PRESSURISE COOLING SYSTEM.TO CARRY OUT VACUUM AND REGAS	New	1,200.00	0.00
3	TO DISMANTLE AND RENEW FRONT BUMPER,LHS FRONT FENDER,AND LHS HEADLIGHT.TO REPAIR BONNET AND LHS FRONT FENDER TOP SUPPORT.RENEW FRONT LOCK CARRIER AND LIGN TO POSITION.RE-ORGANISE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	5,250.00	1,250.00
4	TO RESPRAY FRONT BUMPER,LHS FRONT FENDER,BONNET AND LHS FRONT FENDER TOP SUPPORT	New	3,500.00	1,100.00
5	TO CARRY OUT DIAGNOSTIC CHECKS	New	192.00	192.00
Gross Labour Cost (S\$)			10,502.00	2,902.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #08-16
Singapore 079120

Our File No: CC3/AIG19015104/ATF3N2

Date: 05/03/2020

REFERENCE

Insured/Claimant: TAN KIN LIANG Policy No: 2100495355
Date of Loss: 21/08/2019 Nature of Claim: OD Claim No: 9846247228SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLK2700A Engine No: CHZ146426
Make & Model: AUDI A3, 999cc SEDAN TFSI (A) Chassis No: WAUZZZ8V7H1018600
Reg. Date: 23/12/2016 (Man. Year: 2016) Odometer: 40328 km
Colour: Red
Engine Capacity: 999 cc
Market Value/New Car Price: S\$88,000.00
Sum Insured (\$\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55R16 Rear Tyre Size: 205/55R16
Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,738.00	6,384.96	9,353.04	59.43
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,502.00	2,902.00	7,600.00	72.37
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	26,240.00	9,286.96	16,953.04	64.61
- Excess (\$\$)	3,300.00	3,300.00	0.00	0.00
(\$\$)	22,940.00	5,986.96	16,953.04	73.90
+ GST 7.00/7.00% (\$\$)	1,605.80	419.09	1,186.71	73.90
Nett Amount (\$\$)	24,545.80	6,406.05	18,139.75	73.90

INSPECTION

Date of Assignment: 27/08/2019
Date Inspected: 27/08/2019 Inspected At: Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699
Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,830.00 FS	*1,464.00 FS
2	1		*FRONT BUMPER FIXING PART	Not Necessary	170.00 FS	*- FS
3	1		*FRONT BUMPER GUIDE SECTION-LH	Cracked	35.00 FS	*27.52 FS
4	1		*FRONT BUMPER GRILLE-CENTRE	Not Necessary	146.00 FS	*- FS
5	1		*FRONT BUMPER CLOSING ELEMENT-LOWER CENTRE	Not Necessary	488.00 FS	*- FS
6	1		*FRONT BUMPER CLOSING ELEMENT-LH	Not Necessary	270.00 FS	*- FS
7	1		*FRONT BUMPER COVER TRIM-LH	Not Necessary	148.00 FS	*- FS
8	1		*FRONT BUMPER WHEEL HOUSING LINER ADAPTER-LH	Not Necessary	34.00 FS	*- FS
9	1		*RADIATOR GRILLE	Not Necessary	1,301.00 FS	*- FS
10	1		*RADIATOR GRILLE CLOSING ELEMENT	Not Necessary	174.00 FS	*- FS
11	1		*FRONT BUMPER AIR GUIDE GRILLE	Not Necessary	171.00 FS	*- FS
12	1		*AIRCON STICKER	Not Necessary	7.00 FS	*- FS
13	1		*CAUTION SIGN	Not Necessary	13.00 FS	*- FS
14	1		*FRONT BUMPER SIDE REINFORCEMENT	Not Necessary	660.00 FS	*- FS
15	1		*FRONT BUMPER FOAM FILLER PIECE	Not Necessary	172.00 FS	*- FS
16	2		*FRONT BUMPER COVER-LH/RH	Not Necessary	222.00 FS	*- FS
17	1		*SIGNAL HORN-LH HIGH TONE	Not Necessary	182.00 FS	*- FS
18	1		*FENDER-LH	Dented	778.00 FS	*622.00 FS
19	1		*FENDER ATTACHMENT PARTS	Not Necessary	65.00 FS	*- FS
20	1		*FENDER REAR BRACKET-LH	Not Necessary	25.00 FS	*- FS
21	1		*FENDER CENTRE BRACKET-LH	Not Necessary	35.00 FS	*- FS
22	1		*FENDER BRACE	Bent	88.00 FS	*69.84 FS
23	1		*WHEEL HOUSING LINER SEAL-LH	Not Necessary	31.00 FS	*- FS
24	1		*WHEEL HOUSING LINER-LH	Not Necessary	158.00 FS	*- FS
25	1		*WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	81.00 FS	*- FS
26	1		*LED HEADLIGHT-LH	Cracked	5,029.00 FS	*4,023.20 FS
27	1		*LIGHT CONTROL SYSTEM CONTROL UNIT	Not Necessary	508.00 FS	*- FS
28	1		*MAIN LIGHT ELECTRONICS POWER MODULE	Not Necessary	693.00 FS	*- FS
29	1		*LED WITH HEAT SINK-LH	Not Necessary	666.00 FS	*- FS
30	1		*HEADLIGHT HOSE-LH	Not Necessary	36.00 FS	*- FS
31	1		*HEADLIGHT WASHER LIFT CYLINDER	Not Necessary	128.00 FS	*- FS
32	1		*LIFT CYLINDER HOSE	Not Necessary	61.00 FS	*- FS
33	1		*WASH WATER RESERVOIR	Deformed	186.00 FS	*148.40 FS
34	1		*STRAINER	Not Necessary	19.00 FS	*- FS
35	1		*WASH WATER RESERVOIR END CAP	Not Necessary	19.00 FS	*- FS
36	1		*COOLANT RADIATOR LOCK CARRIER	Not Necessary	663.00 FS	*- FS
37	4		*READY MIX COOLANT	Not Necessary	84.00 FS	*- FS
38	1		*RADIATOR AIR GUIDE	Not Necessary	22.00 FS	*- FS
39	1		*FRONT NO PLATE	Not Necessary	40.00 FS	*- FS
40	1		*SUNDRIES	Necessary	300.00 FS	*30.00 FS

F=Franchise part. S=SpcNett.

Total Parts (\$)	15,738.00	6,384.96
-------------------------	------------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE,CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS,HORNS,OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	360.00
2	TO REMOVE AND REINSTALL AIRCOND CONDENSER,ADDITIONAL RADIATOR,RADIATOR,CHECK ELECTRICAL FANS AND CONTROL UNIT.PRESSURISE COOLING SYSTEM.TO CARRY OUT VACUUM AND REGAS	New	1,200.00	0.00
3	TO DISMANTLE AND RENEW FRONT BUMPER,LHS FRONT FENDER,AND LHS HEADLIGHT.TO REPAIR BONNET AND LHS FRONT FENDER TOP SUPPORT.RENEW FRONT LOCK CARRIER AND LIGN TO POSITION.RE-ORGANISE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	5,250.00	1,250.00
4	TO RESPRAY FRONT BUMPER,LHS FRONT FENDER,BONNET AND LHS FRONT FENDER TOP SUPPORT	New	3,500.00	1,100.00
5	TO CARRY OUT DIAGNOSTIC CHECKS	New	192.00	192.00
Gross Labour Cost (\$\$)			10,502.00	2,902.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >