

Accident Photo



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	26/11/2018 17:35
Date Of Accident	23/11/2018 23:00
Exact Location Of Accident	UPP CHANGI RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SBR567M
Insured/Policyholder	
Name Of Registered Owner	HO KIAN TIONG
NRIC No	S8813979H
Email Address	JULIANHKT@GMAIL.COM
Mobile Phone No	(LOCAL) +65-97660767
Alternative Phone No	OFFICE-97660767

Vehicle Particulars

Manufacturer	TOYOTA
Model	HARRIER-2.0 (A)
Exact Purpose for which vehicle was being used at time of accident	NORMAL USAGE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	P2139049
Cover Note Number	

Driver

Name of Driver	HO ZHI XUAN
NRIC No	S8813979H
Date Of Birth	18/04/1988
Occupation	INDOOR
Date Of Driving Pass	15/07/2009
Driving Experience	9 YEARS AND 4 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-83834533
Fax Number	
Contact Number	
EMail Address	ZHIXUAN.HO@GMAIL.COM

Address	26 JALAN ANGIN LAUT
Postcode	489217
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER AS ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJS6237B
Vehicle Make/Model/Colour	MAZDA
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	VANESSA KOH
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies
5. Any false reporting may be referred to the Police for investigation
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid
8. Consent under the Personal Data Protection Act (PDPA)
I understand, acknowledge, agree and consent that:
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may be permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information"), and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
(ii) investigating the accident and/or my claims;
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' law yers/law firms, may be permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law yers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan

Upper Changi Rd

SJS 6237B

SBR ~~567~~ M

567

Accident Sketch Plan

Describe Circumstances of the Accident


It was very late at night, I skid and put the car in ~~to~~ front of me
at Upper Changi Rd.

Declaration

We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date &
Time

 26 NOV 2018 4pm
Driver's Signature (if driver is not the policyholder) / Date
& Time


Witnessed by Reporting Centre
Personnel


Undertaking Letter

UNDERTAKING

I, HO Zhi Xuan (NRIC No. S883979H), hereby confirm that the Singapore Accident Statement lodged by me on 26 NOV 2018 at 4PM hours pertaining to the accident involving motor car Reg. No: SBR567M, in which I was the driver are true and accurate to the best of my knowledge, information and belief.

I acknowledge that my insurers are not liable under the contract of insurance if there is a breach of policy terms and conditions.

In the event that an unrelated/unreported third party property or injury claim arises or there is evidence emerges that there is a breach of policy terms and conditions, I irrevocably undertake to absolve my insurer from all liability under the contract of insurance and I undertake to re-pay any sums paid by my insurers pursuant to the contract of insurance upon receipt of written demand by my insurers.

Signature : 
Name of Insured / Driver : HO Zhi Xuan
Nric No. : S883979H
Date : 26 NOV 2018

Signature : _____
Name of Policyholder : _____
Nric No. : _____
Date : _____

IC

YOU ARE LICENCED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(S)

Class	Vehicle Description	Valid Date
Class 3A	Motor cars without clutch pedals (Auto) <= 3000kg with <= 7 passengers, exclusive of the driver, and other motor vehicles without clutch pedals <= 2500kg	15 Jul 2009

NP 4284

Licence No. S8813979H

3109747

S8813979H

29-04-2009

29 JALAN ABBIN LAUT
SINGAPORE 489217

MRIC No: S8813979H Date: 22/01/2011 No: 6681884

REPUBLIC OF SINGAPORE DRIVING LICENCE

Licence Number: S8813979H

Name: HO ZHI XUAN

Birth Date: 18 Apr 1988

Issue Date: 15 Jul 2009

001762086A

REPUBLIC OF SINGAPORE

IDENTITY CARD NO. S8813979H

HO ZHI XUAN

何正萱

CHINESE

18-04-1988

SINGAPORE

AXA INSURANCE PTE LTD
 8 Shenton Way, #24-01
 AXA Tower, Singapore 068811
 Customer Service Centre #B1-01
 Tel (65) 63387288 Fax (65) 63382522
 Website: www.axa.com.sg
 GST Registration Number: 199903512M
 customer.service@axa.com.sg



CERTIFICATE OF INSURANCE

Motor Vehicle (Third-Party Risk and Compensation) Act, (Chapter 159) Motor Vehicles (Third-Party Risk and Compensation) Rules, 1960 Road Transport Act, 1997 (Malaysia) Motor Vehicles (Third-Party Risk) Rules, 1959 (Malaysia)		
CERTIFICATE NO.:	VPA/P2139049	Account No.: 14885
Coverage:	Comprehensive (SmartDrive Toyota Prestige)	
Sum Insured:	Market Value At The Time Of Loss	
Name of Policyholder:	HO KIAN TIONG	
Vehicle Registration No.:	SBR567M	
Period of Insurance:	From 21/06/2018 To 20/06/2019 (Both Dates Inclusive)	
PERSONS OR CLASSES OF PERSONS ENTITLED TO DRIVE* (a) The Policyholder The Policyholder may also drive a Motor Car not belonging to or not hired under a hire purchase agreement or otherwise to him or his employer or in payment. (b) Any other person who is driving on the Policyholder's order or with his permission. Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.		
LIMITATIONS AS TO USE* Law only for social, domestic and pleasure purposes and for the Policyholder's business. The policy does not cover - use for hire or reward, racing, pace-making, reliability trial, speedtesting, the carriage of goods other than samples or connection with any trade or business or use for any purpose in connection with motor trades or when the Motor Car, whether stationary, in use or otherwise, is in or on, a racing track, circuit, route, course or any other roads by whatever name called that are typically used for racing, pace-making or such similar purposes.		
Basic Own Damage Excess : SGD 500.00 An Additional Excess is applicable as follows: SGD 1,000.00 for Young or Inexperienced Driver. Young or Inexperienced Driver is defined as any driver who is aged below 21 years old and/or less than one year of driving experience. (Please refer to your policy on the terms & conditions. Limitations rendered imperative by Section 8 of the Motor Vehicles (Third-Party Risk and Compensation) Act, (Chapter 159) and Section 88 of the Road Transport Act, 1997 (Malaysia), are not to be included under these headings).		
I/We hereby certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risk and Compensation) Act, (Chapter 159) and Part IV of the Road Transport Act, 1997 (Malaysia).		

AXA INSURANCE PTE LTD

Authorized Signature

Issued by - SGOAGPH on 27/06/2018

IMPORTANT

Policyholders are warned that on the sale of a motor vehicle they must surrender the Certificate of Insurance and the Policy to the insurance company. If the Certificate of Insurance has been lost or destroyed a Statutory Declaration to the effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third-Party Risk and Compensation) Act, (Chapter 159). The Premium Waiver Clause requires the premium to be paid in full within a specific period, failing which there would be no liability under the policy, general certificate, covernote and endorsement etc.

Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo




Accident Photo




Accident Photo




Accident Photo



TP VEH




TP VEH



TP VEH



TP VEH



Constant Appraiser Services

Qualified Automobile Accident Damage Appraisers/Loss Adjusters

Blk 2 Rivervale Link, #09-02 Singapore 545040

Tel/Fax: 6886 1106 Mobile: 9007 5234

Email: constant_as@yahoo.com.sg

RCB No. 53138015K

Automobile Inspection Report

To: Faithful Chauffer Services c/o Blk 3C Woodlands Road 391C/G Yew Tee Industrial Estate Singapore 677966		Date : 03/01/2019	Reference No : CAS/19-01/007
<u>General Information</u>			
Registration No.	: SJS 6237B		
Accident Date	: 23/11/2018		
<u>Particulars of Damaged Vehicle</u>			
Colour	: White	Make & Model	: Mazda 2
Engine Capacity	: 1498 cc	Pre-Accident Condition	: Good
Mileage (KM)	: 266468	Engine No.	: ZY535741
Chassis No.	: JM0DE10Y190134358	Steering	: In Order
Registration Date	: 26/08/2009	Brake	: In Order
<u>Tyre Condition</u>			
	Size	Make	Balance
R/H Front Tyre	205/45R16	KUMHO	90%
L/H Front Tyre	205/45R16	KUMHO	90%
R/H Rear Tyre	205/45R16	KUMHO	90%
L/H Rear Tyre	205/45R16	KUMHO	90%
<u>Inspection</u>			
Repairer	: Toh Painting & Services Pte Ltd Blk 3C Woodlands Road, 391C/G Yew Tee Industrial Estate, Singapore 677966		
<u>Adjustment And Recommendation Cost Of Repair</u>			
Repairer's Estimate	: \$10,252.03		
Revised Amount	: \$6,600.00		
Less Excess	: -		
Nett Total	: \$6,600.00		
<u>Remarks</u>			
(A) Survey was done on 27/11/2018			
(B) Re-survey was done on 29/11/2018			
(C) Re-survey after repair was done on 03/12/2018			
(D) The survey was conducted entirely on WITHOUT PREJUDICE basis.			
(E) We have NOT given any instruction to authorize the repair of the vehicle.			

NOTE: The revised estimate was made from a visual inspection. Should there be any discrepancy or unseen damage/item in this survey, kindly notified the company within 7 (seven) days from the date hereof. Otherwise, the revised amount shall be deem to be valid.

Constant Appraiser Services

Vehicle No : SJS 6237B

Our ref : CAS/19-01/007

Adjustment On Repair Costs And Replacement Of Parts:

S/No	Qty	Descriptions	Assessed Condition	Estimate by Workshop (\$)	Revised Amount (\$)
<u>PARTS REPLACEMENT - LIST ITEMS</u>					
1	1pc	Tailgate	Dented/Buckled	911.10	911.10 ✓
2	1pc	Tailgate lock	Bent/Jammed	202.10	202.10 ✓
3	1pc	Tailgate lock catch	Bent	24.50	24.50 X NAI
4	1pc	Tailgate outer opening switch	Broken	177.20	177.20 ✓
5	1pc	Tailgate weatherstrip	Distorted	160.50	160.50 ✓
6	1pc	Tailgate emblem logo	Necessary	58.20	58.20 ✓
7	1pc	Tailgate emblem Mazda 2	Necessary	55.50	55.50 ✓
8	1pc	Tailgate glass moulding	Necessary	97.20	97.20 ✓
9	1pc	Tailgate wiper motor	Dented/Jammed	193.30	193.30 X NAI
10	2pcs	Tailgate rubber stopper @ \$10.80	Necessary	21.60	21.60 X NAI
11	1pc	Tailgate inner handle	Serviceable	14.20	-
12	2pcs	Tailgate damper @ \$89.90	Bent/Jammed	179.80	179.80 X NAI
13	2pcs	Tailgate hinge @ \$76.20	Repair	152.40	-
14	2pcs	Taillamp @ \$728.00	Broken	1,456.00	1,456.00 X NAI
15	2pcs	Taillamp panel @ \$145.60	Dented	291.20	291.20 X NAI
16	2pcs	Taillamp lower bracket @ \$78.30	Broken	156.60	156.60 X NAI
17	1pc	Rear bumper	Dented/Broken	850.80	850.80 ✓
18	2pcs	Rear bumper retainer @ \$25.90	Broken	51.80	51.80 ✓
19	1pc	Rear bumper reinforcement	Dented/Bent	456.93	456.93 X NAI
20	2pcs	Rear bumper under bracket @ \$5.10	Broken	10.20	10.20 X NAI
21	1pc	Rear licence plate lamp @ \$53.10	Broken	106.20	106.20 X NAI
22	1pc	Rear end panel	Dented/Warped	380.20	380.20 X R
23	1pc	Rear end panel garnish	Deformed	73.30	73.30 X NAI
24	1pc	Rear compartment top board	Serviceable	296.60	-
25	2pcs	Rear fender inner trim @ \$359.00	Deformed/Broken	718.00	718.00 X NAI
26	1pc	Exhaust pipe	Repair	651.20	-
27	2pcs	Exhaust pipe mounting @ \$33.30	Serviceable	66.60	-
28	1pc	Rear fender air vent LH	Broken	46.80	46.80 X NAI
				7,860.03	6,679.03
		Less 20% 2564.49 - 20% 2051.52		(1,572.00)	(1,335.80)
		Sub total		6,288.03	5,343.23

Constant Appraiser Services

Vehicle No : SJS 6237B

Our ref : CAS/19-01/007


S/No	Qty	Descriptions	Assessed Condition	Est.mate by Workshop (\$)	Revised Amount (\$)
<u>PARTS REPLACEMENT - SPECIAL NETT ITEMS</u>					
1	1pc	Tailgate glass sealant	Necessary	100.00	80.00 40%
2	1set	Rear end panel garnish clip	Necessary	22.00	22.00 X 100%
3	2sets	Rear fender inner trim clip @ \$34.00	Necessary	68.00	68.00 X 100%
4	1set	Reverse sensor	Broken	250.00	220.00 X 88%
5	1pc	Rear licence plate	Cracked	45.00	45.00 X 100%
6	1pc	Exhaust chrome pipe	Serviceable	165.00	-
7	1set	Tailgate inner trim clip	Necessary	24.00	24.00
<u>LABOUR & MISC. CHARGES</u>			Sub total 64	6,962.03	5,802.23
1		Repair & replace rear damaged parts		1,400.00	1,100.00 80%
2		Spray paint affected area		1,200.00	900.00 75%
3		Remove & refix tailgate glass		140.00	120.00
4		Remove & refix tailgate mechanism		100.00	70.00 50%
5		Remove & refix exhaust pipe	Not Necessary	100.00	-
6		Remove & refix rear trim board & garnish		100.00	80.00 30%
7		Check rear wiring system		50.00	20.00
8		Remove & renew reverse sensor		80.00	60.00 20%
9		Spray anti rust on affected area		120.00	60.00 30%
Grand total				10,252.03	8,212.23
Recommended cost of lump sum repair (To its pre-accident condition)					6,600.00

Adjustment/Recommendations

We have thoroughly inspected each and every item on the estimate against the physical damage found on the vehicle and we have listed the breakdown of our finding and our recommendation.

The repairer has agreed to undertake the job at a lump sum of **\$6,600.00** on a contractual basis. Under normal circumstances, the repair period would be about **6 (Six)** working days.

Yours faithfully,
Constant Appraiser Services


Lim Yong Tian (Sebastian)
Licensed Appraiser
Adv. Dip. In Mechanical Engineering (AUS)
MSAAA

P-2051-52
N-64
L-1479
3585-52

L/S-2868-41
= 2850

5 repair days



Your Ref: 19.26222 PD-O

Date: 02nd September 2019

Our Ref: CS1/LAW19015112/Eyd3s2

M/s AXA Insurance Pte Ltd
c/o Seah Ong & Partners LLP
36 Robinson Road
#12-03 City House
Singapore 068877

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SJS 6237B
INSURED VEHICLE: SBR 567M ACCIDENT DATE: 23/11/2018**

We thank you for your instruction on 25/08/2019.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SJS 6237B from M/s Constant Appraiser Services.
- b) Final Repair Bill of SJS 6237B from M/s Toh Painting & Services Pte Ltd.
- c) Singapore Accident Statement of Vehicles SJS 6237B and SBR 567M.
- d) Damaged vehicle photographs of SJS 6237B.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SJS 6237B
Make & Model	: Mazda 2
Year of Registration	: 2009
Chassis Number	: JM0DE10Y190134358
Engine Capacity	: 1498 cc

2. We recommend that the repairs of the entire damage require about 5 (Five) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJS 6237B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	TAILGATE	DENTED / BUCKLED	911.10	911.10
1	TAILGATE LOCK	BENT / JAMMED	202.10	202.10
1	TAILGATE LOCK CATCH	NOT NECESSARY	24.50	-
1	TAILGATE OUTER OPENING SWITCH	BROKEN	177.20	177.20
1	TAILGATE WEATHERSTRIP	DISTORTED	160.50	160.50
1	TAILGATE EMBLEM LOGO	NECESSARY	58.20	58.20
1	TAILGATE EMBLEM MAZDA 2	NECESSARY	55.50	55.50
1	TAILGATE GLASS MOULDING	NECESSARY	97.20	97.20
1	TAILGATE WIPER MOTOR	NOT NECESSARY	193.30	-
2	TAILGATE RUBBER STOPPER @ \$10.80	NOT NECESSARY	21.60	-
1	TAILGATE INNER HANDLE	SERVICEABLE	14.20	-
2	TAILGATE DAMPER @ \$89.90	NOT NECESSARY	179.80	-
2	TAILGATE HINGE @ \$76.20	TO REPAIR SEE LABOUR	152.40	-
2	TAILLAMP @ \$728.00	NOT NECESSARY	1,456.00	-
2	TAILLAMP PANEL @ \$145.60	NOT NECESSARY	291.20	-
2	TAILLAMP LOWER BRACKET @ \$78.30	NOT NECESSARY	156.60	-
1	REAR BUMPER	DENTED / BROKEN	850.80	850.80
2	REAR BUMPER RETAINER @ \$25.90	BROKEN	51.80	51.80
1	REAR BUMPER REINFORCEMENT	NOT NECESSARY	456.93	-
2	REAR BUMPER UNDER BRACKET @ \$5.10	NOT NECESSARY	10.20	-
1	REAR LICENCE PLATE LAMP @ \$53.10	NOT NECESSARY	106.20	-
1	REAR END PANEL	TO REPAIR SEE LABOUR	380.20	-
1	REAR END PANEL GARNISH	NOT NECESSARY	73.30	-
1	REAR COMPARTMENT TOP BOARD	SERVICEABLE	296.60	-
2	REAR FENDER INNER TRIM @ \$359.00	NOT NECESSARY	718.00	-
1	EXHAUST PIPE	TO REPAIR SEE LABOUR	651.20	-
2	EXHAUST PIPE MOUNTING @ \$33.30	SERVICEABLE	66.60	-
1	REAR FENDER AIR VENT LH	NOT NECESSARY	46.80	-
	LESS 20% DISCOUNT		-1,572.00	-512.88
			6,288.03	2,051.52



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>SPECIAL NETT ITEMS</u>			
1	TAILGATE GLASS SEALANT (SN)	NECESSARY	100.00	40.00
1	SET REAR END PANEL GARNISH (SN)	NOT NECESSARY	22.00	-
2	REAR FENDER INNER TRIM CLIP @ \$34.00 (SN)	NOT NECESSARY	68.00	-
1	SET REVERSE SENSOR (SN)	NOT NECESSARY	250.00	-
1	REAR LICENCE PLATE (SN)	NOT NECESSARY	45.00	-
1	EXHAUST CHROME PIPE (SN)	SERVICEABLE	165.00	-
1	SET TAILGATE INNER TRIM CLIP (SN)	NECESSARY	24.00	24.00
			674.00	64.00
	<u>LABOUR</u>			
	REPAIR & REPLACE REAR DAMAGED PARTS. INCLUSIVE OF THE REPAIR OF TAILGATE HINGE, REAR END PANEL AND EXHAUST PIPE.		1,400.00	600.00
	SPRAY PAINT AFFECTED AREA.		1,200.00	600.00
	REMOVE & REFIX TAILGATE GLASS.		140.00	120.00
	REMOVE & REFIX TAILGATE MECHANISM.		100.00	50.00
	REMOVE & REFIX EXHAUST PIPE.	NOT NECESSARY	100.00	-
	REMOVE & REFIX REAR TRIM BOARD & GARNISH.		100.00	30.00
	CHECK REAR WIRING SYSTEM.		50.00	20.00
	REMOVE & RENEW REVERSE SENSOR.		80.00	20.00
	SPRAY ANTI RUST ON AFFECTED AREA.		120.00	30.00
			3,290.00	1,470.00
	GRAND TOTAL		10,252.03	3,585.52
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,850.00

Report Ref No. CS1/LAW19015112/Eyd3s2

CHEN TSUE YEE

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.