



Case Details

Case Reference Number : TAX/08/19/2084
 Type of Repair : Accident Repair
 Vehicle Registration Number : SHC4070K

Company Type : SMRT Taxis Pte Ltd
 Estimation ID : EST-8196-ID
 Assigned By : Taxi Claims Manager Team

Insurance Company Name : AIG Asia Pacific Insurance Pte Ltd
 Accident Date and Time : 23/08/2019 06:50 AM
 Vehicle Age(In Months) : 66

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

BOM Type	Costing Type	Portion	Material Number	SMRT Recommendation							Surveyor Approval			
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			MIRROR ASSY,RH	1	1,307.10	1,307.10	25.00	980.32	Replace	0	0.00	Not Give	X NAI
One Time Key In	Main			DOOR FRT/RH	1	894.40	894.40	25.00	670.80	Replace	1	670.80	Replace	/ DO
One Time Key In	Main			STICKER DECAL SMRT (DOOR)	1	60.00	60.00	0.00	60.00	Replace	1	60.00	Replace	/ APC
One Time Key In	Main			HINGE LOWER RHF, DOOR	1	90.10	90.10	25.00	67.57	Replace	0	0.00	Not Give	X NAI
One Time Key In	Main			HINGE UPPER RHF, DOOR	1	80.50	80.50	25.00	60.38	Replace	0	0.00	Not Give	X NAI
One Time Key In	Main			DOOR RR/RH	1	954.50	954.50	25.00	715.88	Replace	0	0.00	Not Give	X NAI
One Time Key In	Main			MOULDING BODY, RH	1	673.60	673.60	25.00	505.20	Replace	0	0.00	Not Give	X NAI
One Time Key In	Main			PIXEL STICKER	2	60.00	120.00	0.00	120.00	Replace	0	0	Not Give	X NAI
One Time Key In	Main			DOOR LOCK FRT/RH	1	575.80	575.80	25.00	431.85	Replace	0	0.00	Not Give	X NAI

Total Spare Part Cost 4,329.23

Surveyor Total 730.80

Lump Sum Discount (%) 0.00

Lump Sum Dis (%) 20.00

Final Spare Part Cost 4,329.23

Final Sur Total 584.64

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			CHECK ASSY, FR DOOR,	1	150.30	150.30	25.00	112.73	Replace	0	0.00	Not Give ▾	X N/A
One Time Key In	Main			FENDER RR/RH	1	766.80	766.80	25.00	575.10	Replace	0	0.00	Not Give ▾	X N/A
One Time Key In	Main			SMRT LOGO	1	7.80	7.80	0.00	7.80	Replace	0	0	Not Give ▾	X N/A
One Time Key In	Main			STICKER DECAL 65558888	1	21.60	21.60	0.00	21.60	Replace	0	0	Not Give ▾	X N/A
Total Spare Part Cost									4,329.23	Surveyor Total		730.80		
Lump Sum Discount (%)									0.00	Lump Sum Dis (%)		20.00		
Final Spare Part Cost									4,329.23	Final Sur Total		584.64		

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR RH PORTION	507.00	200.00	
Total:			507.00	200.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	RESPRAY MIRROR COVER RH	180.00	0.00	
2	Main	TO RESPRAY FRONT DOOR RH	378.00	200.00	
3	Main	TO RESPRAY REAR DOOR RH	378.00	0.00	
4	Main	TO RESPRAY ROCKER PANEL MOULDING	180.00	0.00	
5	Main	TO RESPRAY REAR FENDER RH	378.00	0.00	
Total:			1,494.00	200.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
Total:			536.00	60.00	

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO WASH AND VACUUM	60.00	0.00	
2	Main	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	20.00	AK
3	Main	TO REPLACE SUNDRY PARTS	100.00	20.00	AK
4	Main	TO TRANSFER DOOR MECHANISM	120.00	20.00	AK
5	Main	TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	0.00	
6	Main	TOWING CHARGE	56.00	0.00	
Total:			536.00	60.00	

Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	4,329.23	584.64
Total Labour Cost	507.00	200.00
Total Spray Painting	1,494.00	200.00
Other	536.00	60.00
Overall Total	6,866.23	1,190.80
Lump Sum Repair Option		
Lump Sum Total	6,850.00	1,200.00
Surveyor Approved Amount		1,200.00
No of Repair Days*	5	2
Remarks	-	L/S repair, take after spray. Finalize sent to stevechen@lkkauto.com
Surveyor Name		STEVE CHEN
Signature		
Survey Date	26/08/2019	

**LKK Auto Consultants hence notify
the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: