

Section A - Accident Details

Registration Number	SHC4070K
Case Reference Number	TAX/08/19/2084
Registration Date	7/2/2014
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	RIDUAN BIN RAHIM
Type of Accident	Open Door Case
Accident Date and Time	23/8/2019 2:50 PM
Accident Reported Date and Time	23/8/2019 5:12 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	Yes
Towed Back Date and Time	23/8/2019 3:02 PM
Replacement Vehicle issued?	No
Job Card Number	24102992
Special Instruction to ARC, if any	TOWED
Prepared Date and Time	24/8/2019 8:57 AM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$507.00	\$200.00
Total Spray Cost	\$1,494.00	\$200.00
Total Spare Part Cost	\$3,463.38	\$584.64
Total Other Cost	\$536.00	\$100.00
TOTAL COST	\$6,000.38	\$1,084.64
Lump Sum Total	\$6,000.00	\$1,100.00 (L/S)
Number of Repair Days	5.0	2.0
Prepared / Adjusted By	Ang Bang Kien	STEVE CHEN (LKK) / AIG
ARC / Surveyor Sign Off Date	26/08/2019 3:38 PM	26/08/2019 3:02 PM
Signature		
Remarks	L/S repair, take after spray. Finalize sent to stevechen@lkkauto.com	

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-1909-0294	Invoice Number	
Quotation Date	18.09.2019	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR RH PORTION	\$507.00	\$200.00
Total Labour	\$507.00	\$200.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
RESpray MIRROR COVER RH	\$180.00	\$0.00
TO RESPRAY FRONT DOOR RH	\$378.00	\$200.00
TO RESPRAY REAR DOOR RH	\$378.00	\$0.00
TO RESPRAY ROCKER PANEL MOULDING	\$180.00	\$0.00
TO RESPRAY REAR FENDER RH	\$378.00	\$0.00
Total Spray Painting & Panel Beating	\$1,494.00	\$200.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO WASH AND VACUUM	\$60.00	\$0.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00
TO REPLACE SUNDRY PARTS	\$100.00	\$20.00
TO TRANSFER DOOR MECHANISM	\$120.00	\$20.00
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	\$0.00
TOWING CHARGE	\$56.00	\$40.00
Total Other Costs	\$536.00	\$100.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		87910-47330	MIRROR ASSY,RH	0.00	\$1,307.10	0.00	\$0.00	Replace	Not Given X
		67001-47070	DOOR FRT/RH	1.00	\$894.40	25.00	\$670.80	Replace	Replace ✓
			STICKER DECAL SMRT (DOOR)	1.00	\$60.00	0.00	\$60.00	Replace	Replace ✓
		68730-12120	HINGE LOWER RHF, DOOR	0.00	\$90.10	0.00	\$0.00	Replace	Not Given X
		68710-12151	HINGE UPPER RHF, DOOR	0.00	\$80.50	0.00	\$0.00	Replace	Not Given X
		67003-47080	DOOR RR/RH	0.00	\$954.50	0.00	\$0.00	Replace	Not Given X
		75851-47900	MOULDING BODY, RH	0.00	\$673.60	0.00	\$0.00	Replace	Not Given X
			PIXEL STICKER	0.00	\$60.00	0.00	\$0.00	Replace	Not Given X
		69030-47070	DOOR LOCK FRT/RH	0.00	\$575.80	0.00	\$0.00	Replace	Not Given X
		68610-47021	CHECK ASSY, FR DOOR,	0.00	\$150.30	0.00	\$0.00	Replace	Not Given X
		61604-47090	FENDER RR/RH	0.00	\$766.80	0.00	\$0.00	Replace	Not Given X



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number: 03655592
Estimator Telephone Number: 68662623
Accident Reporting Number: 88662672

Date Generated: 18/08/2018

User ID: PehSuan

			SMRT LOGO	0.00	\$7.80	0.00	\$0.00	Replace	Not Given X
			STICKER DECAL 65558888	0.00	\$21.60	0.00	\$0.00	Replace	Not Given X
Total					\$5,642.50		\$730.80		
Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

730.80
- 206
584.64
+ 200.00
+ 300.00

1084.64
L/S \$1100/-



Case Details

Case Reference Number : TAX/08/19/2084
 Type of Repair : Accident Repair
 Vehicle Registration Number : SHC4070K

Company Type : SMRT Taxis Pte Ltd
 Estimation ID : EST-8196-ID
 Assigned By : Taxi Claims Manager Team

Insurance Company Name : AIG Asia Pacific Insurance Pte Ltd
 Accident Date and Time : 23/08/2019 06:50 AM
 Vehicle Age(In Months) : 66

Documents / Photographs

View Documents / Photographs

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

BOM Type	Costing Type	Portion	Material Number	SMRT Recommendation				Surveyor Approval						
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			MIRROR ASSY,RH	1	1,307.10	1,307.10	25.00	980.32	Replace	0	0.00	Not Give	X NM
One Time Key In	Main			DOOR FRT/RH	1	894.40	894.40	25.00	670.80	Replace	1	670.80	Replace	/ DO
One Time Key In	Main			STICKER DECAL SMRT (DOOR)	1	60.00	60.00	0.00	60.00	Replace	1	60.00	Replace	/ MC
One Time Key In	Main			HINGE LOWER RHF, DOOR	1	90.10	90.10	25.00	67.57	Replace	0	0.00	Not Give	X NM
One Time Key In	Main			HINGE UPPER RHF, DOOR	1	80.50	80.50	25.00	60.38	Replace	0	0.00	Not Give	X NM
One Time Key In	Main			DOOR RR/RH	1	954.50	954.50	25.00	715.88	Replace	0	0.00	Not Give	X NM
One Time Key In	Main			MOULDING BODY, RH	1	673.60	673.60	25.00	505.20	Replace	0	0.00	Not Give	X NM
One Time Key In	Main			PIXEL STICKER	2	60.00	120.00	0.00	120.00	Replace	0	0	Not Give	X NM
One Time Key In	Main			DOOR LOCK FRT/RH	1	575.80	575.80	25.00	431.85	Replace	0	0.00	Not Give	X NM

Total Spare Part Cost 4,329.23

Surveyor Total 730.80

Lump Sum Discount (%) 0.00

Lump Sum Dis (%) 20.00

Final Spare Part Cost 4,329.23

Final Sur Total 584.64

SMRT Recommendation										Surveyor Approval				
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			CHECK ASSY, FR DOOR,	1	150.30	150.30	25.00	112.73	Replace	0	0.00	Not Give	X JAI
One Time Key In	Main			FENDER RR/RH	1	766.80	766.80	25.00	575.10	Replace	0	0.00	Not Give	X JAI
One Time Key In	Main			SMRT LOGO	1	7.80	7.80	0.00	7.80	Replace	0	0	Not Give	X JAI
One Time Key In	Main			STICKER DECAL 65558888	1	21.60	21.60	0.00	21.60	Replace	0	0	Not Give	X JAI
Total Spare Part Cost									4,329.23	Surveyor Total 730.80				
Lump Sum Discount (%)									0.00	Lump Sum Dis (%) 20.00				
Final Spare Part Cost									4,329.23	Final Sur Total 584.64				

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR RH PORTION	507.00	200.00	
Total:			507.00	200.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	RESPRAY MIRROR COVER RH	180.00	0.00	
2	Main	TO RESPRAY FRONT DOOR RH	378.00	200.00	
3	Main	TO RESPRAY REAR DOOR RH	378.00	0.00	
4	Main	TO RESPRAY ROCKER PANEL MOULDING	180.00	0.00	
5	Main	TO RESPRAY REAR FENDER RH	378.00	0.00	
Total:			1,494.00	200.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
Total:			536.00	60.00	

8/26/2019

https://vacswb.smr.com.sg/Estimation.aspx

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO WASH AND VACUUM	60.00	0.00	
2	Main	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	20.00	AKC
3	Main	TO REPLACE SUNDRY PARTS	100.00	20.00	AKC
4	Main	TO TRANSFER DOOR MECHANISM	120.00	20.00	AKC
5	Main	TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	0.00	
6	Main	TOWING CHARGE	56.00	200 40	
Total:			536.00	50.00 100	

Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	4,329.23	584.64
Total Labour Cost	507.00	200.00
Total Spray Painting	1,494.00	200.00
Other	536.00	60.00
Overall Total	6,866.23	1,190.80
Lump Sum Repair Option		☒
Lump Sum Total	6,850.00	1,200.00
Surveyor Approved Amount		1,200.00
No of Repair Days*	5	2
Remarks		L/S repair, take after spray. Finalize sent to stevechen@lkkauto.com
Surveyor Name		STEVE CHEN
Signature		
Survey Date	28/08/2019	

https://vacswb.smr.com.sg/Estimation.aspx

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: