



新福德車廠私人有限公司

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com Website: www.nhtmotor.com

Tel: 6747 9241 Fax: 6741 7276

UEN: 201718370K

26/08/2019

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

TP China.

Vic.

Accident date: 21/08/2019

Estimated repair cost for vehicle no: SKB2392P BMW X3 3.0 A '11

CHASSIS: WBAWX52040LK44357

S/n	Qty	Items	U/price	Amount
1	1	Front L/H Fender <i>Dented</i>		\$808.10 ✓
2	1	Front L/H Fender Protector <i>cut</i>		\$180.00 ✓
3	1	Front L/H Fender Cowling <i>3 new</i>		\$268.10 +
4	8	Front L/H Fender Cowling Clip <i>new</i>	\$6.50	\$52.00 +
5	1	Front L/H Door <i>Repair</i>		\$1,457.60 +
6	1	Front L/H Door Protector <i>cut</i>		\$335.70 ✓
7	1	Front L/H Door Side Mirror Assy <i>new</i>		\$1,705.50 +
8	1	Front L/H Tyre <i>new</i>		\$580.00 +
9	1	Front L/H Rim <i>cut</i>		\$1,218.00 <i>850/50</i>
10	1	Front L/H Lower Arm <i>2</i>		\$321.00 +
11	1	Front L/H Knuckle Arm <i>1P</i>		\$507.00 +
12	1	Front L/H Knuckle Arm Bearing <i>new</i>		\$484.00 +
13	1	Front L/H Shock Absorber		\$1,452.70 +

Subtotal :- \$9,369.70

1323.80

1257.61

S.W 850

Labour charges

To remove & refit front L/H undercarriage	\$380.00 X
To check wheel alignment computer	\$150.00 80
To reset computer	\$200.00 X
To check wiring	\$100.00 X
Tuff kote	\$150.00 X
Panel beating	\$800.00 300
Spray painting	\$1,000.00 400

Subtotal :- \$2,780.00

Total:- \$12,149.70

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____

total: 2887.61
4/8: 23K.
03 Days

2.3K