

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel: 6366 2323 Fax: 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP:65271

## Telefax

**Estimate** : Accident Repairs  
**Workshop** : Ubi Road 1  
**Contact No** : 6366 2323  
**Fax No** : 6841 1183  
**Reference** : PA/OD/10145/2019/NS  
**Date** : 26-Aug-19

**Vehicle IN workshop. Please arrange for survey**

### AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

**Attn: Mr. Adrian Ling - Motor Claims Dept**

**Tel: 6841 0055 - Fax: 6256 4315**

**Owner's Name** : Ms Hsiao Chia Mae  
**Address** : 45 Toh Tuck Road  
#04-17  
Singapore 596720  
**Telephone** : HP +65 83665630  
**Type of Claim** : Own Damage Claim  
**Policy No.** : 1700059447  
**Vehicle No** : **SLS 9488 A**  
**Model Code** : Audi A3 Sportsback 1.0 TF  
**Model / Year** : Oct-17  
**Engine No** : CHZ 551135  
**Chassis No** : WAUZZZ8V4JA032783  
**Mileage** :  
**Date In** :  
**Estimated By** : Johnny Boo / Allan Wu  
**Accident Date** : 23-Aug-19  
**Place of Accident** : Junction Padang Jeringan And Kallang Road

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

## Telefax

### Estimated Labour Charges for Accident Vehicle SLS 9488 A

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N \$ 360.00 ✓	
2	To remove and reinstall aircond condenser, additional radiator, radiator. Check electrical fans and control unit. Pressurise cooling system. To carry out vacuum and regas.	S/N \$ 1,200.00 ?	
3	To dismantle lhs front door panel trim. To remove and reinstall lhs wing mirror assy.	S/N \$ 300.00 X	
4	To dismantle and renew front bumper, lhs front fender, bonnet and lhs headlight. Renew front lock carrier and align to position. Re-organise crash management components. Reinstall all parts removed.	\$ <del>5,250.00</del> 1500	
5	To respray front bumper, lhs front fender, bonnet and lhs front door. X	\$ 3,700.00 1650	
6	To carry out diagnostic checks.	S/N \$ 192.00 ✓	
	<b>TOTAL LABOUR CHARGES</b>	<b>: \$ <u>11,002.00</u></b>	

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

Telefax

## Material List for Accident Vehicle Regn No. SLS 9488 A

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER <i>de -</i>	\$ 1,698.00	
2	FRONT BUMPER FIXING PARTS <i>?</i>	\$ 170.00	
3	FRONT BUMPER GUIDE SECTION - LH <i>?</i>	\$ 35.00	
4	FRONT BUMPER GRILLE - CENTRE <i>X</i>	\$ 146.00	
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>X</i>	\$ 270.00	
6	FRONT BUMPER CLOSING ELEMENT - LH <i>?</i>	\$ 270.00	
7	RADIATOR GRILLE <i>scr -</i>	\$ 1,301.00	
8	RADIATOR GRILLE CLOSING ELEMENT <i>?</i>	\$ 174.00	
9	FRONT BUMPER AIR GUIDE GRILLE - LH <i>?</i>	\$ 171.00	
10	FRONT BUMPER SIDE REINFORCEMENT <i>?</i>	\$ 660.00	
11	FRONT BUMPER FOAM FILLER PIECE <i>?</i>	\$ 172.00	
12	FRONT BUMPER COVER <i>?</i>	\$ 111.00	
13	AIRCON STICKER <i>scr -</i>	NEC \$ 7.00	
14	CAUTION SIGN <i>scr -</i>	NEC \$ 13.00	
15	FENDER - LH <i>buc -</i>	\$ 778.00	
16	POP RIVET <i>scr -</i>	NEC \$ 24.00	
17	FENDER ATTACHMENT PARTS <i>?</i>	\$ 65.00	
18	FENDER BRACKET - LH INNER / OUTER <i>?</i>	2 \$ 68.00	
19	FENDER SEAL STRIP - LH <i>?</i>	\$ 31.00	
20	FENDER BRACE <i>?</i>	\$ 88.00	
<b>SUB TOTAL SPARE PARTS</b>		<b>\$ 6,252.00</b>	

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

Telefax

## Material List for Accident Vehicle Regn No. SLS 9488 A

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
21	FENDER CLOSING ELEMENT - LH ?	\$	56.00
22	WHEEL HOUSING LINER - LH ?	\$	158.00
23	WHEEL HOUSING LINER ATTACHMENT PARTS ?	\$	52.00
24	BONNET <i>repair</i>	\$	2,501.00
25	BONNET ATTACHMENT PARTS X	\$	149.00
26	BONNET CATCH HOOK X	\$	81.00
27	BONNET EDGE PROTECTION - FRONT X	NEC \$	25.00
28	BONNET STRIKER - LH / RH X	2 \$	200.00
29	WATER BOX ADAPTER SEAL - LH X	\$	12.00
30	BONNET CATCH HOOK X	\$	58.00
31	LID LOCK WITH MICRO SWITCH X	2 \$	367.00
32	CONNECTOR HOUSING BRACKET X	2 \$	11.00
33	FENDER BOWDEN CABLE - CENTRE X	\$	53.00
34	FENDER LID LOCK CABLE X	\$	67.00
35	ENGINE BONNET SOUND ABSORBER X	\$	201.00
36	PLENUM CHAMBER COVER X	\$	164.00
37	PLENUM CHAMBER TOP COVER X	\$	15.00
38	SIGNAL HORN - LH HIGH TONE ?	\$	182.00
39	LED HEADLIGHT <i>be</i>	\$	5,029.00
40	LIGHT CONTROL SYSTEM CONTROL UNIT ?	\$	508.00
<b>SUB TOTAL SPARE PARTS</b>		<b>\$</b>	<b>9,889.00</b>

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

Telefax

## Material List for Accident Vehicle Regn No. SLS 9488 A

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
41	MAIN LIGHT ELECTRONIS POWER MODULE ?	\$	693.00
42	LED WITH HEAT SINK - LH ?	\$	666.00
43	HEADLIGHT HOSE - LH ?	\$	36.00
44	HEADLIGHT WASHER LIFT CYLINDER ?	\$	128.00
45	LIFT CYLINDER HOSE ?	\$	61.00
46	WASH WATER PUMP ?	\$	147.00
47	WASH WATER RESERVOIR ?	\$	186.00
48	WASH WATER STRAINER ?	\$	19.00
49	WASH WATER END CAP ? X	\$	19.00
50	WINDSCREEN WASHER SYSTEM PUMP ?	\$	118.00
51	COOLANT RADIATOR LOCK CARRIER ?	\$	663.00
52	READY MIX COOLANT ?	4 \$	84.00
53	RADIATOR AIR GUIDE - LH ?	\$	22.00
54	RADIATOR AIR GUIDE - UPPER CENTRE ?	\$	11.00
55	WINDOW SLOT SEAL WITH TRIM STRIP - LH FRONT X	\$	247.00
56	ROOF MOLDING - LH X	\$	537.00
57	FRONT NO PLATE M /	S/N \$	40.00
58	SUNDRIES ?	\$	400.00
TOTAL SPARE PARTS		:	\$ 20,218.00
TOTAL LABOUR CHARGES		:	\$ 11,002.00
GRAND TOTAL		:	\$ 31,220.00

All charges are not inclusive of GST.

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel: 6366 2323 Fax: 6841 1183

## Telefax

Name : Pasu - Hp 90010068  
Surveyed Date : 7 days  
Authorised Date :  
Excess Cost : 27/08/17 @ 1545  
Liability :  
Remarks : EXCESS: TBC

REPAIR  
Resu before paint

**Please Note** : This estimate is based on visual inspection of the affected vehicle.  
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.  
For inspection of vehicle, please refer to Ms Norah Khai at  
Tel:6768 9828 for appointment.

Yours faithfully,  
Premium Automobiles Pte Ltd

Johnny Boo  
Body Repair Manager

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

Allan Wu  
Claims Consultant