


Premium Automobiles Pte Ltd



Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6836 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Main Telephone 6388 2223
Main Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408699
Main Telephone 6388 2323
Main Telefax 6841 1183

Customer Service
Service Appointment 6366 2323
24-hour Breakdown Service 9828 1233
Email customer.care@premiumauto.com.sg

C

INS TAX INVOICE

Page 1 11:10

Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice No: 85014339	Account: A0006 (T 0)
	Date : 10/10/2019	AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
	Order : SLS9488A	
	Term : 30	

Regn No: SLS9488A (V 35438) **Regn Date:** 11/10/2017 **Mileage:** 34215 **WIP No.:** 65271

Model: A3 SPORTSBACK 1.0 TFSI 8VFANG **Chassis:** WAUZZZ8V4JA032783 **Engine:** CHZ 551135 **Dept:** U

You have been assisted by :- UB-Tony Foong (33)

		Details	Qty	Unit Price	Amount
S	SUBLET	M: TO SUPPLY VEHICLE NUMBER PLATE	40.00	1.00	40.00
Q	EXC	M: 8888 Insurance Excess/Liability	-600.00	1.00	-600.00
S	BODYWORK	M: TO REMOVE,CHECK AND REINSTALL FRONT WIRE HARNESSE FOR HEADLIGHTS,HORNS,OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	360.00	1.00	360.00
S	BODYWORK	M: TO DISMANTLE AND RENEW FRONT BUMPER,LHS FRONT FENDER AND LHS HEADLIGHT.REPAIR BONNET. REALIGN LOCK CARRIER TO POSITION.REORGANISE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	1500.00	1.00	1,500.00
S	BODYWORK	M: TO RESPRAY FRONT BUMPER,LHS FRONT FENDER AND BONNET.	1650.00	1.00	1,650.00
S	BODYWORK	M: TO CARRY OUT DIAGNOSTIC CHECK	192.00	1.00	192.00
X	A8V3853651AA3FZ	GRILLE	Less 020%	1.00	1301.00
X	A8V0941773D	HEADLIGHT	Less 020%	1.00	5029.00
X	A8V0821105L	FENDER(LAST)	Less 020%	1.00	777.50
X	A8V0807550A	(SK)FOAM INSER (SHAR	Less 020%	1.00	172.00
X	A8V0807065R GRU	COVER(LAST)	Less 020%	1.00	1698.00
X	A8V3807319	PLATE(LAST) AP	Less 020%	1.00	270.00
X	A8V3807183B	GUIDE AP	Less 020%	1.00	34.40
X	A8V0821091C	PLATE AP	Less 020%	1.00	55.30
X	A431955465A	GASKET AP	Less 020%	1.00	6.90
X	A8K0010520A	PLATE	Less 020%	1.00	12.20
X	A8V0010515A	STICKER	Less 020%	1.00	6.40
X	A8V3853949	(SK)PLATE(SHARE) AP	Less 020%	1.00	173.50
X	A5Q0955453R	WATER RES.AP	Less 020%	1.00	185.50
X	AN 0161857	POP-RIVET	Less 020%	8.00	3.00

Parts 7,796.56
Labour 0.00
Sublet 3,742.00
Menus 0.00
Lubricant 0.00

Sub-Total 10,938.56

7% GST 765.70

Grand Total 11,704.26



Received by

For & on behalf of
Premium Automobiles Pte Ltd

Premium Automobiles

Telefax

to **AIG Asia Pacific Insurance Pte Ltd**
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Motor Claims Dept
Yr Ref: SLS 9488 A

Norah Khai
6768 9828
6841 1183

Body Repair

PA/OD/1015/2019/EH
5 September 2019

from
Telephone +65-
Telefax +65-
Mobile +65-
Our department
Your Claim Ref
Our Ref
Date

1 total pages


RE: CLAIM – OWNER’S SATISFACTION/DISCHARGE VOUCHER

Make & Model : Audi A3 SPORTSBACK 1.0 TFSI
Vehicle Chassis No. : WAUZZZ8V4JA032783
Vehicle Regn No. : **SLS 9488 A**
Vehicle Mileage : **34215** KM
Vehicle Owner : Ms. Hsiao Chia Mae
Certificate No : 1700059447
Own Damage Excess : \$ 642.00 (Inclusive GST)
Accident Date : 23 August 2019
Place : Junction Padang Jeringan and Kallang Rd
Repair Cost : S\$ **11,704.26**
WIP No. : 65271
Repairer’s Name : Premium Automobiles Pte Ltd

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Road 1
Singapore 408699
Telephone (65) 6366 2323
Telefax (65) 6841 1183

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer’s charges that are claimable under the policy will be deemed in full and final settlement of my claim.

Owner / Insured Signature : 
Time : 5/9/2019 7pm-
Date : 5/9/19