

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: FOO AI NGOH

Date: 18 Sep 2019

Preliminary Advice

Vehicle No	: SKU9165H	Accident Date	: 07/12/2018
Make	: MITSUBISHI LANCER EX	Policy No.	: 28603908QMY
Assignment Date	: 28/08/2019	Excess	: S\$3,000.00
Date of Inspection	: 28/08/2019	Est. Duration of Repair	: 5 days
Inspection At	: Falcon-Air Auto Services Pte Ltd (Tampines) Blk 9006 #01-200 Tampines St 93 Singapore		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front o/s portion, front windscreen broken and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	4,646.17
Revised Amount	:S\$	4,384.17
Check Items (Estimated)	:S\$	0.00
Total	:S\$	4,384.17

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	56,000.00 (Estimated On Dec 2018)
COE / PARF Rebate	:S\$	45,960.00 (Estimated On Dec 2018)
Salvage Value	:S\$	
Margin for Repair	:S\$	10,040.00

Remarks

(X) The vehicle is economical for repair.

() The above survey was conducted on a 'without prejudice' basis.