

ASS. REC. BY:

REF: CS / MSG 19015138 / USF301

Special Instruction:

Surveyor: MARCUS

ASSIGNMENT (Office)

From (Person): FOO AI NGOH

of MSG

Date/Time: 28.8.19 10.38am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKU 9165H

Insured:

at Workshop m/s Falcon - Air Auto

Tel: 67897997

of BIC 9006 #01-200 Tampine St 93

Policy No: 28603908QMY

Claim No: 578894

Sum Insured:

Excess: \$3000.00

Make of Veh:

D.O.A. 7.12.2019

(Client's Record)

CA / (REV) / REP. / REV 24 HRS

Date/Time: 28.8.2019

Person Contacted: Joel

H.O.D. Endorsement:

Vehicle (IN) OUT

Date/Time	Action/Instruction (✓) Estimate
	SKU 9165H - C1 / TP / 1900788 / NC
	DOA - 07/12/2019
28/08/19	@ 16:06 pm revised IA to Foo AI: Ngoh via merimer
28/08/19	@ 16:10 pm mandate requested authorize repair to Foo AI: Ngoh via merimer.
02/09/19	@ 16:13 pm mandate approved by Eng Huey N. via merimer.

08/11/13) wel

ASS. REC. BY: *MARCUS*

REF:

CS/789190/0100/0243

MS16/

ASSIGNMENT

From:

Date:

Estimated Cost:

00 / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SKU 9165H

at Workshop m/s

False Air Temp

of

Insured:

Policy No:

Claims No:

Sum Insured:

Excess: *3000*

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

☒	☒
N/S	O/S
☐	☐

Bal. or Market Value:

56 now *50k*

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

5 days Res.: Yes or No

Lum Sum:

131 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No: *SKU 9165H* Yr Regn: *21/8/15*

Type: *M.Cat* / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or *CA* /

Make:

mit Lander EX

c.c *1590*

Colour

Grey

A/C: Insured / Std / NI / NA

Sp. Reading

52061

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JMYSRCY / AFU 005160

Gen. Cond: *Good* / Fair / Poor / Burnt

Steering: *In order* / Jammed / Leaked / Burnt or

Brake: *In order* / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: *205/60 R16*

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

6 mm

L/Bal.

6 mm

D.O.A.

7/12/18

Rear

R/Bal.

6 mm

L/Bal.

6 mm

D.O.I.

28/8/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

LP O/S & LP wheel screen broken

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

227 7500 During 20A 7-12-18 by 9th.

During inspection of vehicle seat interior have rain water?

17/9/18 confirmed fault by 438K.17 m.t. Jal
(4262.00 Red - 6%)

18/9/2019

RECEIVED 04 OCT 2019

Date/Time, File Pres to?

04/10/19

1) *TPA*

Date/Time, File Return to?

2)

☐

: Preli. Report

☒

: Final Report

Days Of Repair:

5

Resurvey No. of Trip:

1

Survey Fee:

190

Transportation:

Add Fee:

☐

: Site Insp (\$

) S + RS. \$

☐

: Interview (\$

) Photos

☐

: Tech. Invs (\$

) Others

☐

: Weekend (\$

)

Report Format:

Lump Sum / I.B.I: (\$ *4.384.17 p/p*)

TOTAL

161

TOTAL

			
--	--	--	--

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Inv Auth'd	Status
Main	14 Dec 2018 Sendback Est	27 Aug 2019 11:02 S\$4,646.17	28 Aug 2019 10:38 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured:	YEO SOK BUAY, ID: S1585826E								
Vehicle Reg. No.:	SKU9165H	Date of Loss:	07/12/2018 00:00 - :59 [39 Months and 16 Days From LTA Reg Date (Man Yr)]						
Claim Type:	OD / 578894	Policy/Cover Note No.:	28603908QMY (Comprehensive) Coverage: 21/08/2018 - 20/08/2019						
		Excess:	S\$3,000.00						
Repairer:	Falcon-Air Auto Services Pte Ltd (Tampines) Blk 9006 #01-200 Tampines St 93, Tampines - Tel: 67897997								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by FOO AI NGOH - 6643 1318]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 29/08/2019]								
Driver/Custodian:	BRANDON HAN WEI DING (23 / Male), NRIC: S9544092D, Tel: +6591732900 Email: katherine_yeo@sg.msig-asia.com								
Adj Asg. Remarks:	Car in, pls arrange survey by today. Survey & revert. Please contact us ASAP if you cannot attend this assignment. Please revert. Need to seek approval from HOS/HOD as this is staff's claim								
ASSOCIATED MAIL RECEIVED									
There are no mail for this case.									
ALL ASSOCIATED TASKS									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Note: Vehicle impounded by Traffic Police since Dec 2018.
 Recently towed out and driver's seat found
 found seat interior found wet with
 & due to rain water.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 826E

Vehicle Details

Vehicle No.: SKU9165H
Vehicle to be Exported: No
Intended Deregistration Date: 28 Aug 2019
Vehicle Make: MITSUBISHI
Vehicle Model: LANCER EX 1.6 AT LED TAIL LAMP
Primary Colour: Grey
Manufacturing Year: 2015
Engine No.: 4A92CA1221
Chassis No.: JMYSRCY1AFU005160
Maximum Power Output: 86.0 kW (115 bhp)
Open Market Value: \$11,318.00
Original Registration Date: 21 Aug 2015
First Registration Date: 21 Aug 2015
Transfer Count: 0
Actual ARF Paid: \$11,318.00 *5659*

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 20 Aug 2025
PARF Rebate Amount: \$8,488.00

Intended COE Rebate Details

COE Expiry Date: 20 Aug 2025
COE Category: A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$56,209.00
COE Rebate Amount: \$33,604.00
Total Rebate Amount: \$42,092.00

The information contained herein is correct as at 28 Aug 2019

OK

Don: 07/10/18
PARF = 8488
COE = 8P x 621 miles
= 56209 x $\frac{10}{120}$
= 37472.67
LTA = PARF + COE
= 45960.67
SLTA = 45960

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	826E
Vehicle Details	
Vehicle No.:	SKU9165H
Vehicle to be Exported:	No
Intended Deregistration Date:	28 Aug 2019
Vehicle Make:	MITSUBISHI
Vehicle Model:	LANCER EX 1.6 AT LED TAIL LAMP
Primary Colour:	Grey
Manufacturing Year:	2015
Engine No.:	4A92CA1221
Chassis No.:	JMYSRCY1AFU005160
Maximum Power Output:	86.0 kW (115 bhp)
Open Market Value:	\$11,318.00
Original Registration Date:	21 Aug 2015
First Registration Date:	21 Aug 2015
Transfer Count:	0
Actual ARF Paid:	\$11,318.00 5659
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	20 Aug 2025
PARF Rebate Amount:	\$8,488.00
Intended COE Rebate Details	
COE Expiry Date:	20 Aug 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$56,209.00
COE Rebate Amount:	\$33,604.00
Total Rebate Amount:	\$42,092.00

The information contained herein is correct as at 28 Aug 2019

OK



Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad Advertiser Login Ways of Selling

2013 Opel GTC 1.4 Pano At \$52k



0 Accident, 18" Rims, Low
Mileage
Direct Owner StarAd

- Free VICOM evaluation
- Free grooming and 8 months maintenance
- In-house workshop ensures quality service
- Member of SYTA and hire purchase association
- 100% deposit refund for unapproved loan

YONG LEE SENG MOTOR PTE LTD

Browse by Category

Sort by Date Posted 20 results/page

2 vehicles

Mitsubishi Lancer ex

Advanced Search Submit

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Mitsubishi Lancer ex		Any	Any	2015	Any	Any	Any	Available
	Mitsubishi Lancer EX 1.6A		\$53,800	\$7,670 /yr	13-Nov-2015	1,590 cc	53,260 km	Sedan	Available
	1 Owner, Assured Its Non-Private Hire/Leasing Car! Amazing Low Mileage Clocked Of 14500km Annually! Fully Serviced At C&C With 5 Y...								PREMIUM AD
	Lake View Credit Pte Ltd								
	Posted: 25-Aug-2019 Tags: 2015 Mitsubishi Lancer, 2015 mitsubishi lancer, Mitsubishi Lancer, mitsubishi lancer, Mitsubishi, Lancer, lancer, Used Mitsubishi								
	Mitsubishi Lancer EX 1.6A		\$52,000	\$7,350 /yr	30-Nov-2015	1,590 cc	28,678 km	Sedan	Available
	5 Years Warranty By C&C Service And Maintenance By Agent. Very Low Mileage And Hardly Use. Call Bobby For Viewing And Scheduled...								
	Prime Motor & Leasing								
	Posted: 05-Aug-2019 Tags: 2015 Mitsubishi Lancer, 2015 mitsubishi lancer, Mitsubishi Lancer, mitsubishi lancer, Mitsubishi, Lancer, lancer, Used Mitsubishi								

Save this search criteria, to get email alerts whenever a match is found.

Make Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

For old advertisements, view Expired ads

20 results/page

Home New Cars Used Cars Sell My Car Directory Products Insurance Article Forum Resources

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. Find buy used Mitsubishi Lancer ex, Mitsubishi Lancer ex Singapore, used Mitsubishi Lancer ex Singapore, used Mitsubishi Lancer ex, used vehicles Singapore or even buy used Mitsubishi Lancer ex Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarMart.com

About Us Careers Contact Us Sitemap Terms of Service Privacy Policy Personal Data Protection Statement
©2004-2019 sgCarMart. All rights reserved.

Compare

SKU 9165H OD (MSIG) DOA - 07/12/2018

Shirley Hiew (LKK Auto)

Mon 2/9/2019 5:51 PM

To: JOEL <joel@falconair.com.sg>

Cc: SUR <sur@lkkauto.com>

Dear Joel,

As instructed by our client, please proceed to repair the insured vehicle **SKU 9165H** (Excess \$ 3,000/-).

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte LtdPhone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

View Received Message

This mail is associated with :

SKU9165H (578894)

OD

Dec 7 2018 12:00AM

[YEO SDK BUAY]

Falcon-Air Auto Services Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From MSIG Insurance (Singapore) Pte. Ltd. (MSIG_SG), sent on 04/10/2019 11:43 AM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$4384.17) - SKU9165H - Claim Handler: FOO AI NGOH

Approved:4384.17:check items of \$770 to be verified

DOCUMENTS SUMMARY

There are no documents.

View Received Message

This mail is associated with :

SKU9165H (578894)

OD

Dec 7 2018 12:00AM

[YEO SOK BUAY]

Falcon-Air Auto Services Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From MSIG Insurance (Singapore) Pte. Ltd. (MSIG_SG), sent on 02/09/2019 16:13 PM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (\$3652.67) - SKU9165H - Claim Handler: FOO AI NGOH

Approved:3652.67;check items of \$770 to be verified

DOCUMENTS SUMMARY

There are no documents.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: FOO AI NGOH

Date: 18 Sep 2019

Preliminary Advice

Vehicle No	: SKU9165H	Accident Date	: 07/12/2018
Make	: MITSUBISHI LANCER EX	Policy No.	: 28603908QMY
Assignment Date	: 28/08/2019	Excess	: S\$3,000.00
Date of Inspection	: 28/08/2019	Est. Duration of Repair	: 5 days
Inspection At	: Falcon-Air Auto Services Pte Ltd (Tampines) Blk 9006 #01-200 Tampines St 93 Singapore		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front o/s portion, front windscreen broken and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	4,646.17
Revised Amount	:S\$	4,384.17
Check Items (Estimated)	:S\$	0.00
Total	:S\$	4,384.17

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	56,000.00 (Estimated On Dec 2018)
COE / PARF Rebate	:S\$	45,960.00 (Estimated On Dec 2018)
Salvage Value	:S\$	
Margin for Repair	:S\$	10,040.00

Remarks

- (X) The vehicle is economical for repair.
- () The above survey was conducted on a 'without prejudice' basis.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: FOO AI NGOH

Date: 28 Aug 2019

Preliminary Advice

Vehicle No	: SKU9165H	Accident Date	: 07/12/2018
Make	: MITSUBISHI LANCER EX	Policy No.	: 28603908QMY
Assignment Date	: 28/08/2019	Excess	: S\$3,000.00
Date of Inspection	: 28/08/2019	Est. Duration of Repair	: 5 days
Inspection At	: Falcon-Air Auto Services Pte Ltd (Tampines) Blk 9006 #01-200 Tampines St 93 Singapore		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front o/s portion, front windscreen broken and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	4,646.17
Revised Amount	:S\$	3,652.67
Check Items (Estimated)	:S\$	770.00
Total	:S\$	4,422.67

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	56,000.00 (Estimated on Dec 2018)
COE / PARF Rebate	:S\$	45,960.00 (Estimated on Dec 2018)
Salvage Value	:S\$	
Margin for Repair	:S\$	10,040.00

Remarks

(X) The vehicle is economical for repair.

() The above survey was conducted on a 'without prejudice' basis.

(X) Remarks : Vehicle impounded by Traffic Police since December 2018. Recently towed out and driver's seat interior found wet due to rain water.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	14/12/2018 16:38
Date Of Accident	07/12/2018 20:30
Exact Location Of Accident	ALONG ROAD 1 PETIR ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKU9165H
Insured/Policyholder	
Name Of Registered Owner	YEO SOK BUAY
NRIC No	S1585826E
Email Address	KATHERINE_YEO@SG.MSIG-ASIA.COM
Mobile Phone No	(LOCAL) +65-96163440
Alternative Phone No	Others-96163440

Vehicle Particulars

Manufacturer	MITSUBISHI
Model	LANCER EX-1.6 LED TAIL LAMP (A)
Exact Purpose for which vehicle was being used at time of accident	personal use
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	REPORTING ONLY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	28603908
Cover Note Number	

Driver

Name of Driver	BRANDON HAN WEI DING
NRIC No	S9544092D
Date Of Birth	17/11/1995
Occupation	INDOOR
Date Of Driving Pass	01/01/2013
Driving Experience	5 YEARS AND 11 MONTHS

Gender	MALE
Mobile Number	(LOCAL) +65-91732900
Fax Number	
Contact Number	
Email Address	KATHERINE_YEO@SG.MSIG-ASIA.COM
Address	99A CASHEW ROAD #13-04 CASHEW HEIGHTS
Postcode	679670
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	CHILDREN
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLIDED INTO PEDESTRIAN
Weather Conditions	RAINING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	YES
Was any other material or property damaged?	NO
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	10 UBI AVENUE 3
Police Station Address	ROAD: 10 UBI AVENUE 3 , POSTCODE: 408865 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

see attached police report

Attachment(s)

Are accident photos available for attachment?	NOT AVAILABLE DUE TO CIRCUMSTANCES OF ACCIDENT
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. The Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance company.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Roadside Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copying of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)
9. I understand, acknowledge, agree and consent that:
 - (a) my insurer, my workshop and the General Insurance Association of Singapore ("GIA") may be permitted to collect, use, disclose and/or process my personal data/personal information set out in this Form and any other personal information provided by me or generated by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurers who have insured vehicle(s) involved in this accident (all insurers) who have insured vehicle(s) involved in this accident that be referred to as the "Insurers", the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/body (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claim;
 - (ii) investigating the accident and/or my claim;
 - (iii) dealing and/or dealing with my enquiries or responding to my enquiries by me;
 - (iv) administering my claims (including the sending of correspondence, statements, invoices, reports or notices to me, which could involve the issue of certain personal data about me to being about delivery of the same as well as on the external cover of envelopes used such as my name); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
 - (b) I hereby (the "Purposes")
 - (c) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may be permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (d) my Personal Information may also be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms) which may be filed outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan



Sketch Plan #2

Describe Circumstances of the Accident

Please refer to Police Report as attached.

Have notified msc via email on 8/15/15 1pm.

Declaration

I/We declare the foregoing particulars are true in every respect.


Policyholder's Signature / Date &
Time


Driver's Signature (If driver is not the policyholder) / Date
& Time


Witnessed by Reporting Centre
Personnel

Police report

IMPORTANT NOTE: Please submit the completed Addendum form to the same Authorised Reporting Centre with whom you submitted the Original Report.

ADDENDUM

(A) PARTICULARS OF PERSON MAKING THE AMENDMENTS:

Original Report No : MSJ18161354 Vehicle Registration No: SKH9165H
Name (as shown in NRIC) : YEO SCK BUAY NRIC/FIN/Passport No : S1585826E
(*Vehicle Driver / Vehicle Owner) (*) Please delete as appropriate
Address : 99A CASHOW ROAD # 13-04 Singapore (679670)
Contact (Tel) : _____ Mobile No.: 91732900
Email Address : _____
Date of Accident : 07/12/2018 Time of Accident : 20:30
Place of Accident : ALONG ROAD 3 PETIR ROAD
Insurance Company: MSIG

(B) ADDITIONAL INFORMATION / AMENDMENTS:

I have made a report on the above mentioned accident and would like to include additional information or make the following amendments:

CLAIMING REPAIR OF VEHICLE UNDER MY OWN INSURANCE
POLICY

Policyholder / Driver's Signature
Date: 27/08/2019

Reporting Centre Personnel's Signature
Name: SURETE UBANA
NRIC/FIN No.: _____
Date: 27/8/2019



**SINGAPORE
POLICE FORCE**



T/20181208/2007

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 40865
Tel No: 65470000

1 of 3
Report No. T/20181208/2007

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 08/12/2018 01:06		Vide Report No.:		Station Diary No.:	
Informant's Particulars					
Name of Informant: BRANDON HAN WEI DING			Address: APT BLK 99 CASHEW ROAD #13-04 CASHEW HEIGHTS SINGAPORE 679570		
ID Type / ID No.: NRIC NO / S9544092D			Contact No.: Home/Office: Mobile: 91732900		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 23	Date of Birth: 17/11/1995	Type of Informant: Driver		
Race: Chinese			Language: English		Institution / School Name:
Occupation: National Service Full Time			Driving Licence Information: Class: 3A Date of Expiry:		

General Information of the Accident				
Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 07/12/2018 20:30	Type of Location:
Location: Along Road 1 PETIR ROAD				
Weather: Heavy rain		Road Surface: Wet		Road Speed Limit:
Traffic Flow: One Way		Traffic Control: Traffic Light - Working		Traffic Volume: Heavy
Type of Collision: Moving Vehicle Against - Pedestrian				Anyone conveyed by ambulance: Yes

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SKU9165H	Car	MITSUBISHI	LANCER EX 1.8 AT LED TAIL LAMP	Grey		0

Details of Person Involved	
Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA

Police report



**SINGAPORE
POLICE FORCE**



T/20161208/2007

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

2 of 3
Report No. T/20161208/2007

CONTINUATION OF REPORT

Driver			
Name	BRANDON HAN WEI DING	ID No.	S9544092D
Related Vehicle	NIL	Contact No.	91732900
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3A Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

ON THE ABOVE MENTIONED DATE AND TIME,

I WAS DRIVING THE VEHICLE SKU9165H, ALONG PETIR ROAD ON THE EXTREME LEFT LANE. AS THE BUS INFRONT OF ME STOPPED AT THE BUS STOP, I CHANGED TO THE 2ND LANE TO OVERTAKE THE BUS. I SIGNALLED AND HANGED BACK ONTO THE LEFT LANE WHEN I SAW THAT THE BUS WAS STILL STATIONARY AFTER I OVERTOOK IT. I SIGNALLED AND STARTED CHANGING ONTO THE LEFT LANE. BEFORE I COULD STRAIGHTEN MY VEHICLE AFTER CHANGING INTO THE LEFT LANE, I REALISED THAT I HAD KNOCKED DOWN A PEDESTRIAN WHO WAS JAY-WALKING. THE MOMENT I HIT THE PEDESTRIAN, I APPLIED E-BRAKE BUT DUE TO THE RAIN AND WET ROAD, MY VEHICLE SKIDDED FORWARD A BIT.

I DID NOT SEE THE PEDESTRIAN PRIOR TO THE COLLISION. I GOT OFF MY VEHICLE AND CALLED THE POLICE. THE PEDESTRIAN WAS CONVEYED BY THE AMBULANCE SHORTLY AFTER.

Police report



SINGAPORE
POLICE FORCE



T/20181208/2007

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

3 of 3

Report No. T/20181208/2007

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording This Report:

TP /
ZENG ZI CONG

Signature Of Interpreter:

Not applicable

Officer In Charge Of Case:

TP / GIT /
Sr Staff Sgt RAZIZ BIN TAHAR
Contact No.: 65476200

Authentication Stamp
SP168

Signature Of Informant:

Date/Time:

08/12/2018 01:06

Classification Of Case:



SINGAPORE
POLICE FORCE

Signature:

Falcon-Air Auto Services Pte Ltd
#01-06/07/13, #05-17 Sin Ming Auto
Care, 176 Sin Ming Drive
575721

Insurer Reference: TP/SKU9165H/MSIG(OD)
 Repairer Reference: TP/SKU9165H/MSIG(OD)
 Date calculated: 27/08/2019 10:27 AM
Summary Information

Full Report
 Registration: SKU9165H
 Printed: 27/08/2019 10:29 AM

Claim

Location:	Singapore (SG)	Work Provider:	MSIG Insurance (Singapore) Pte Ltd
Printed by:	Falcon-Air 5	Currency:	SGD
Claim Reference:	TP/SKU9165H/MSIG(OD)	Date of Incident:	07/12/18
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details**Vehicle**

Manufacturer: MITSUBISHI
 Model: LANCER (CY,CX)
 Sub Model: EX COMFORT CVT
 Model Sheet Number: 32 39 38
 Registration: SKU9165H

VIN number:

Odometer:

Model Specs

4-DOOR SALOON PREPARE OFF VEHICLE CLEAR COAT HARD TWO COAT PEARL/MICA

*Not Affected
 LK
 the photo before? only.
 excess \$3000
 sdg. 28/8/19*

Labour

Code	Description	Time Base 10 WU/h	Price = 50.00 SGD/h	
			WU	Price SGD
NO NUMBER	PREPARATION TIME		2.0	10.00
514110 00	R + R FRONT BUMPER		8.0	40.00
514121 00)	RENEW FRONT BUMPER		10.0	50.00
	INCLUDES: R + R NECESSARY ATTACHED PARTS			
541011 10)	R + R RIGHT HEADLAMP UNIT		1.0	5.00
425110 00	R + R BONNET		4.0	20.00
425111 10)	RENEW BONNET		2.0	10.00
	(REMOVED)			
	INCLUDES: R + R ATTACHED PARTS,			
	ALIGN BONNET			
NO NUMBER	ADJUST HEADLAMPS		2.0	10.00
423121 10	RENEW WINDSCREEN		32.0	160.00
	INCLUDE: R + R NECESSARY PARTS			
NO NUMBER	R + R REAR CENTRE CONSOLE		3.0	15.00
523111 10)	RENEW INSTRUMENT PANEL CPL		14.0	70.00
	(INSTRUMENT PANEL REMOVED)			
	INCLUDES: R + R INSTRUMENT PANEL PAD			
NO NUMBER	R + R INSTRUMENT PANEL CPL		14.0	70.00
371010 10	R + R STEERING WHEEL		4.0	20.00
0340	FRT BUMPER REINF REPAIR		15.0*	75.00

/ou

Falcon-Air Auto Services Pte Ltd
#01-06/07/13, #05-17 Sin Ming Auto
Care, 176 Sin Ming Drive
575721

Insurer Reference: TP/SKU9165H/MSIG(OD)
 Repairer Reference: TP/SKU9165H/MSIG(OD)
 Date calculated: 27/08/2019 10:27 AM

Full Report
 Registration: SKU9165H
 Printed: 27/08/2019 10:29 AM

Labour Cost	Hrs	WU	
Panel / Mechanical Labour	11.10	111.0	555.00
Total of Labour			555.00

Paint

Paint Work	SYSTEM A2T	Time Basis 10 WU/h
Code	Description - TWO COAT PEARL/MICA	WU Price SGD
	BONNET NEW PART PAINTING	24.0
	FRONT BUMPER COVER NEW PART PAINT K1G/P	29.0
	FRT BUMPER REINF SURFACE PAINT	4.0
	FRT BUMPER SUPPORT SURFACE PAINT	4.0
	CTR BUMPER BRACKET SURFACE PAINT	4.0
	L/F WING SURFACE PAINT	6.0
	R/F WING SURFACE PAINT	6.0

Paint Material Per Part

Code	Description	Price SGD
0471	BONNET NEW PART PAINTING	76.88
0283	FRONT BUMPER COVER NEW PART PAINT K1G/P	118.80
0340	FRT BUMPER REINF SURFACE PAINT	2.49
0341	FRT BUMPER SUPPORT SURFACE PAINT	2.49
0345	CTR BUMPER BRACKET SURFACE PAINT	2.49
0741	L/F WING SURFACE PAINT	10.21
0742	R/F WING SURFACE PAINT	10.21

Labour Cost - Paint	Hrs	WU	Price SGD
Factor	50.00 SGD/h		
Time Paint		77.0	
Preparation Main Work Metal	2.50	25.0	125.00
Preparation Comp. Work Plastic	0.80	8.0	40.00
Total	10 WU/h	11.00	550.00

Material Cost - Paint	Price SGD
New Part Painting	76.88
New Part Painting - Plastic K1G/FUR	118.80
Surface-Blend Paint	27.89
Material-constant Metal Preparation	28.60
Material-constant Plastic	12.70
Total	264.87

Falcon-Air Auto Services Pte Ltd
#01-06/07/13, #05-17 Sin Ming Auto
Care, 176 Sin Ming Drive
575721

Insurer Reference: TP/SKU9165H/MSIG(OD)
 Repairer Reference: TP/SKU9165H/MSIG(OD)
 Date calculated: 27/08/2019 10:27 AM

Full Report
 Registration: SKU9165H
 Printed: 27/08/2019 10:29 AM

Spare Parts

				prices as at 2015-06-01	
Code	Description	Part Number	Supplier	Price SGD	
0283	FRONT BUMPER COVER	6400D159		Re/ FD 350.00	✓
0288	R/F BUMPER BRACKET	6400A852		1cc 10.00	✓
0313	LWR RADIATOR GRILLE	6400A827		n1 55.00	X
0352	R/LOWER AIR GRILLE	7450A224		n1 20.00	X
0356	R/F BUMPER BRACKET	6400F550		n1 10.00	✓
0471	BONNET	5900A209		n2 360.00	✓
0562	R/F HEADLAMP CPL	8301B408		holder 350.00	✓
1227	SPACER PART	MR520530		n5 0.00	X
1228	SPACER	MR957780		n5 0.00	X
1393	COWL PANEL COVER	7405A057		du7 68.00	✓
1401	WINDSCREEN	6102A124		du7 600.00	✓
1411	BONDING KIT	Z2156737		n5 0.00	X
1413	FRT SCREEN MNTG KIT	USE SINGLE PARTS			
1423	UPP WINDSCREEN MLDG	6107A013		n1 50.00	✓
1454	R/F WIPER ARM	8250A233		du7 80.00	✓
1464	R/F WIPER COVER	MB881494		n13 10.00	✓
4331	INSTRUMENT PANEL	8000A062XA		700.00	✓
4942	R/UPP A-PILLAR TRIM	7211A160HA		du7 90.00	✓
1006	FRT BUMPER SEAL	FRT BUMPER SEAL		Turn 20.00	✓
f: OEM Parts				Savings	0.00
n: Non-OEM Parts				Subtotal	2,773.00
u: Used parts				Addition(+10.00%)	277.30
				Total	3,050.30

Extras

Code	Description	Price SGD
1000	w/screen sealant w/screensealant	n1 40.00*✓
1001	ERP BRKT ERP BRKT	n1 26.00*10
1002	RH WIPER BLADE RH WIPER BLADE	n13 40.00*20
1003	BONNETINSULATOR CLIP INSULATOR CLIP	n1 40.00*X
1004	FRT BUMPER CLIP FRT BUMPER CLIP	n1 40.00*✓
1005	FRT BUMPER RIVET FRT BUMPER RIVET	Reps 40.00*X
Total Extras		226.00

Falcon-Air Auto Services Pte Ltd
#01-06/07/13, #05-17 Sin Ming Auto
Care, 176 Sin Ming Drive
575721

Insurer Reference: TP/SKU9165H/MSIG(OD)
 Repairer Reference: TP/SKU9165H/MSIG(OD)
 Date calculated: 27/08/2019 10:27 AM

Full Report
Registration: SKU9165H
Printed: 27/08/2019 10:29 AM

Final Calculation

	SGD	SGD
Parts	2,773.00	
Addition(+10.00%)	277.30	
Total Parts		3,050.30
Labour Time Base 10 WU/h		
Total 111.0 WU X 50.00 SGD/h	555.00	
Total of Labour		555.00
Total Of Extras		226.00
Paint Work Time Base 10 WU/h		
Labour Cost 110.0 WU X 50.00 SGD/h	550.00	
Material Cost	264.87	
Total Paint Including Material		814.87
Repair Cost Excludes GST		4,646.17
GST (+7.0%)		325.23
Repair Cost Included GST		4,971.40

Comments

* - USER SUPPLIED DATA
 NN - NO MANUFACTURERS CODE EXISTS
) - WU PARTIAL INCL IN OTHER POSITIONS

Assessment Note

No assessment notes entered.

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Falcon-Air Auto Services Pte Ltd
#01-06/07/13, #05-17 Sin Ming Auto
Care, 176 Sin Ming Drive
575721

Insurer Reference: TP/SKU9165H/MSIG(OD)
Repairer Reference: TP/SKU9165H/MSIG(OD)
Date calculated: 16/09/2019 2:13 PM
Summary Information

Full Report
Registration: SKU9165H
Printed: 16/09/2019 2:13 PM

Claim			
Location:	Singapore (SG)	Work Provider:	MSIG Insurance
Printed by:	Falcon-Air 5	Currency:	(Singapore) Pte Ltd
Claim Reference:	TP/SKU9165H/MSIG(OD)	Date of Incident:	SGD
Estimated Repair Time:		Hire Car Start:	07/12/18
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle	
Manufacturer:	MITSUBISHI
Model:	LANCER (CY,CX)
Sub Model:	EX COMFORT CVT
Model Sheet Number:	32 39 38
Registration:	SKU9165H
VIN number:	
Odometer:	
Model Specs	
4-DOOR SALOON	PREPARE OFF VEHICLE
	CLEAR COAT HARD
	TWO COAT PEARL/MICA

Labour

Code	Description	Time Base 10 WU/h	Price = 50.00 SGD/h	
			WU	Price SGD
NO NUMBER	PREPARATION TIME			
514110 00	R + R FRONT BUMPER		2.0	10.00
514121 00)	RENEW FRONT BUMPER		8.0	40.00
	INCLUDES: R + R NECESSARY ATTACHED PARTS		10.0	50.00
541011 10)	R + R RIGHT HEADLAMP UNIT			
425110 00	R + R BONNET		1.0	5.00
425111 10)	RENEW BONNET		4.0	20.00
	(REMOVED)		2.0	10.00
	INCLUDES: R + R ATTACHED PARTS,			
	ALIGN BONNET			
NO NUMBER	ADJUST HEADLAMPS		2.0	10.00
423121 10	RENEW WINDSCREEN		32.0	160.00
	INCLUDE: R + R NECESSARY PARTS			
NO NUMBER	R + R REAR CENTRE CONSOLE		3.0	15.00
523111 10)	RENEW INSTRUMENT PANEL CPL		14.0	70.00
	(INSTRUMENT PANEL REMOVED)			
	INCLUDES: R + R INSTRUMENT PANEL PAD			
NO NUMBER	R + R INSTRUMENT PANEL CPL		14.0	70.00
371010 10	R + R STEERING WHEEL		4.0	20.00
0340	FRT BUMPER REINF REPAIR		10.0*	50.00

Falcon-Air Auto Services Pte Ltd
#01-06/07/13, #05-17 Sin Ming Auto
Care, 176 Sin Ming Drive
575721

Insurer Reference: TP/SKU9165H/MSIG(OD)
 Repairer Reference: TP/SKU9165H/MSIG(OD)
 Date calculated: 16/09/2019 2:13 PM

Labour Cost
 Panel / Mechanical Labour

Total of Labour

Full Report
 Registration: SKU9165H
 Printed: 16/09/2019 2:13 PM

Hrs	WU	
10.60	106.0	530.00
		530.00

Paint

Paint Work

SYSTEM AZT

Time Basis 10 WU/h

Code	Description - TWO COAT PEARL/MICA	WU	Price SGD
	BONNET NEW PART PAINTING	24.0	
	FRONT BUMPER COVER NEW PART PAINT K1G/P	29.0	
	FRT BUMPER REINF SURFACE PAINT	4.0	
	FRT BUMPER SUPPORT SURFACE PAINT	4.0	
	CTR BUMPER BRACKET SURFACE PAINT	4.0	
	L/F WING SURFACE PAINT	6.0	
	R/F WING SURFACE PAINT	6.0	

Paint Material Per Part

Code	Description	Price SGD
0471	BONNET NEW PART PAINTING	
0283	FRONT BUMPER COVER NEW PART PAINT K1G/P	76.88
0340	FRT BUMPER REINF SURFACE PAINT	118.80
0341	FRT BUMPER SUPPORT SURFACE PAINT	2.49
0345	CTR BUMPER BRACKET SURFACE PAINT	2.49
0741	L/F WING SURFACE PAINT	2.49
0742	R/F WING SURFACE PAINT	10.21
		10.21

Labour Cost - Paint

Factor	Hrs	WU	Price SGD
Time Paint			
Preparation Main Work Metal	2.50	25.0	125.00
Preparation Comp. Work Plastic	0.80	8.0	40.00
Total	10 WU/h	11.00	110.0

Material Cost - Paint

	Price SGD
New Part Painting	76.88
New Part Painting - Plastic K1G/PUR	118.80
Surface-/Blend Paint	27.89
Material-constant Metal Preparation	28.60
Material-constant Plastic	12.70
Total	264.87

Falcon-Air Auto Services Pte Ltd
#01-06/07/13, #05-17 Sin Ming Auto
Care, 176 Sin Ming Drive
575721

Insurer Reference: TP/SKU9165H/MSIG(OD)
 Repairer Reference: TP/SKU9165H/MSIG(OD)
 Date calculated: 16/09/2019 2:13 PM

Full Report
 Registration: SKU9165H
 Printed: 16/09/2019 2:13 PM

Spare Parts

Code	Description	Part Number	Supplier	prices as at 2015-06-01 Price SGD
0283	FRONT BUMPER COVER	6400D159		350.00
0288	R/F BUMPER BRACKET	6400A852		10.00
0356	R/F BUMPER BRACKET	6400F550		10.00
0471	BONNET	5900A209		360.00
0562	R/F HEADLAMP CPL	8301B408		350.00
1227	SPACER PART	MR520530		0.00
1228	SPACER	MR957780		0.00
1393	COWL PANEL COVER	7405A057		68.00
1401	WINDSCREEN	6102A124		600.00
1411	BONDING KIT	Z2156737		0.00
1413	FRT SCREEN MNTG KIT	USE SINGLE PARTS		
1423	UPP WINDSCREEN MLDG	6107A013		50.00
1454	R/F WIPER ARM	8250A233		55.00
1464	R/F WIPER COVER	MB881494		10.00
4331	INSTRUMENT PANEL	8000A062XA		700.00
4942	R/UPP A-PILLAR TRIM	7210A160HA		80.00
1006	FRT BUMPER SEAL	FRT BUMPER SEAL		20.00
f: OEM Parts	Savings			0.00
n: Non-OEM Parts	Subtotal			2,663.00
u: Used parts	Addition(+10.00%)			266.30
	Total			2,929.30

Extras

Code	Description	Price SGD
1000	w/screen sealant w/screensealant	40.00*
1001	ERP BRKT ERP BRKT	10.00*
1002	RH WIPER BLADE RH WIPER BLADE	20.00*
1004	FRT BUMPER CLIP FRT BUMPER CLIP	40.00*
	Total Extras	110.00

Falcon-Air Auto Services Pte Ltd
#01-06/07/13, #05-17 Sin Ming Auto
Care, 176 Sin Ming Drive
575721

Insurer Reference: TP/SKU9165H/MSIG(OD)
Repairer Reference: TP/SKU9165H/MSIG(OD)
Date calculated: 16/09/2019 2:13 PM

Full Report
Registration: SKU9165H
Printed: 16/09/2019 2:13 PM

Final Calculation

	SGD	SGD
Parts		
Addition(+10.00%)	2,663.00	
Total Parts	266.30	2,929.30
Labour Time Base 10 WU/h		
Total 106.0 WU X 50.00 SGD/h		
Total of Labour	530.00	530.00
Total Of Extras		110.00
Paint Work Time Base 10 WU/h		
Labour Cost 110.0 WU X 50.00 SGD/h		
Material Cost	550.00	
Total Paint Including Material	264.87	814.87
Repair Cost Excludes GST		4,384.17
GST (+7.0%)		306.89
Repair Cost Included GST		4,691.06

Comments

* - USER SUPPLIED DATA
NN - NO MANUFACTURERS CODE EXISTS
) - WU PARTIAL INCL IN OTHER POSITIONS

Assessment Note

No assessment notes entered.

Falcon-Air Auto Services Pte Ltd
#01-06/07/13, #05-17 Sin Ming Auto
Care, 176 Sin Ming Drive
575721

Insurer Reference: TP/SKU9165H/MSIG(OD)
Repairer Reference: TP/SKU9165H/MSIG(OD)
Date calculated: 27/08/2019 10:27 AM
Summary Information

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before after work is painted
- To display damaged parts in during resurvey
- Paint process must be subject to confirmation
- That only survey is on a "Without Prejudice" basis
- No actual measurement is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurers Company

Acknowledged by Repairer

Signature:

Date:

Full Report

Registration: SKU9165H

Printed: 27/08/2019 10:29 AM

Claim

Location:	Singapore (SG)	Work Provider:	MSIG Insurance (Singapore) Pte Ltd
Printed by:	Falcon-Air 5	Currency:	SGD
Claim Reference:	TP/SKU9165H/MSIG(OD)	Date of Incident:	07/12/18
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle

Manufacturer: MITSUBISHI
 Model: LANCER (CY,CX)
 Sub Model: EX COMFORT CVT
 Model Sheet Number: 32 39 38
 Registration: SKU9165H
 VIN number:
 Odometer:

Model Specs

4-DOOR SALOON PREPARE OFF VEHICLE CLEAR COAT HARD TWO COAT PEARL/MICA

*not Affiliated
 LKK
 the photo before? only.
 EXCESS \$3000
 Sdy. 28/8/19*

Labour

Code	Description	Time Base 10 WU/h	Price = 50.00 SGD/h	
			WU	Price SGD
NO NUMBER	PREPARATION TIME		2.0	10.00
514110 00	R + R FRONT BUMPER		8.0	40.00
514121 00)	RENEW FRONT BUMPER		10.0	50.00
	INCLUDES: R + R NECESSARY ATTACHED PARTS			
541011 10)	R + R RIGHT HEADLAMP UNIT		1.0	5.00
425110 00	R + R BONNET		4.0	20.00
425111 10)	RENEW BONNET		2.0	10.00
	(REMOVED)			
	INCLUDES: R + R ATTACHED PARTS, ALIGN BONNET			
NO NUMBER	ADJUST HEADLAMPS		2.0	10.00
423121 10	RENEW WINDSCREEN		32.0	160.00
	INCLUDE: R + R NECESSARY PARTS			
NO NUMBER	R + R REAR CENTRE CONSOLE		3.0	15.00
523111 10)	RENEW INSTRUMENT PANEL CPL		14.0	70.00
	(INSTRUMENT PANEL REMOVED)			
	INCLUDES: R + R INSTRUMENT PANEL PAD			
NO NUMBER	R + R INSTRUMENT PANEL CPL		14.0	70.00
371010 10	R + R STEERING WHEEL		4.0	20.00
0340	FRT BUMPER REINF REPAIR		15.0*	75.00

50 / 104

Falcon-Air Auto Services Pte Ltd
#01-06/07/13, #05-17 Sin Ming Auto
Care, 176 Sin Ming Drive
575721

Insurer Reference: TP/SKU9165H/MSIG(OD)
 Repairer Reference: TP/SKU9165H/MSIG(OD)
 Date calculated: 27/08/2019 10:27 AM

Full Report
 Registration: SKU9165H
 Printed: 27/08/2019 10:29 AM

Labour Cost	Hrs	WU	
Panel / Mechanical Labour	11.10	111.0	555.00
Total of Labour			555.00

Paint

Paint Work	SYSTEM AZT	Time Basis 10 WU/h
Code	Description - TWO COAT PEARL/MICA	WU Price SGD
	BONNET NEW PART PAINTING	24.0
	FRONT BUMPER COVER NEW PART PAINT K1G/P	29.0
	FRT BUMPER REINF SURFACE PAINT	4.0
	FRT BUMPER SUPPORT SURFACE PAINT	4.0
	CTR BUMPER BRACKET SURFACE PAINT	4.0
	L/F WING SURFACE PAINT	6.0
	R/F WING SURFACE PAINT	6.0

Paint Material Per Part

Code	Description	Price SGD
0471	BONNET NEW PART PAINTING	76.88
0283	FRONT BUMPER COVER NEW PART PAINT K1G/P	118.80
0340	FRT BUMPER REINF SURFACE PAINT	2.49
0341	FRT BUMPER SUPPORT SURFACE PAINT	2.49
0345	CTR BUMPER BRACKET SURFACE PAINT	2.49
0741	L/F WING SURFACE PAINT	10.21
0742	R/F WING SURFACE PAINT	10.21

Labour Cost - Paint	Hrs	WU	Price SGD
Factor	50.00 SGD/h		
Time Paint		77.0	
Preparation Main Work Metal	2.50	25.0	125.00
Preparation Comp. Work Plastic	0.80	8.0	40.00
Total	10 WU/h	11.00	110.0

Material Cost - Paint	Price SGD
New Part Painting	76.88
New Part Painting - Plastic K1G/PUR	118.80
Surface-/Blend Paint	27.89
Material-constant Metal Preparation	28.60
Material-constant Plastic	12.70
Total	264.87

Falcon-Air Auto Services Pte Ltd
#01-06/07/13, #05-17 Sin Ming Auto
Care, 176 Sin Ming Drive
575721

Insurer Reference: TP/SKU9165H/MSIG(OD)
 Repairer Reference: TP/SKU9165H/MSIG(OD)
 Date calculated: 27/08/2019 10:27 AM

Full Report
 Registration: SKU9165H
 Printed: 27/08/2019 10:29 AM

Spare Parts

				prices as at 2015-06-01	
Code	Description	Part Number	Supplier	Price SGD	
0283	✓ FRONT BUMPER COVER	6400D159		26/ 350.00	✓
0288	✓ R/F BUMPER BRACKET	6400A852		10.00	✓
0313	LWR RADIATOR GRILLE	6400A827		55.00	X
0352	R/LOWER AIR GRILLE	7450A224		20.00	X
0356	✓ R/F BUMPER BRACKET	6400F550		10.00	✓
0471	✓ BONNET	5900A209		360.00	✓
0562	✓ R/F HEADLAMP CPL	8301B408		350.00	✓
1227	SPACER PART	MR520530		0.00	X
1228	SPACER	MR957780		0.00	X
1393	✓ COWL PANEL COVER	7405A057		68.00	✓
1401	✓ WINDSCREEN	6102A124		600.00	✓
1411	BONDING KIT	Z2156737		0.00	X
1413	FRT SCREEN MNTG KIT	USE SINGLE PARTS			X
1423	✓ UPP WINDSCREEN MLDG	6107A013		50.00	✓
1454	R/F WIPER ARM	8250A233	SR	80.00	✓
1464	✓ R/F WIPER COVER	MB881494		10.00	✓
4331	✓ INSTRUMENT PANEL	8000A062XA		700.00	✓
4942	✓ R/UPP A-PILLAR TRIM	7210A160HA	80	90.00	✓
1006	✓ FRT BUMPER SEAL	FRT BUMPER SEAL		20.00	✓
f: OEM Parts				Savings	0.00
n: Non-OEM Parts				Subtotal	2,773.00
u: Used parts				Addition(+10.00%)	277.30
				Total	3,050.30

Extras

Code	Description	Price SGD
1000	w/screen sealant w/screensealant	40.00*
1001	ERP BRKT ERP BRKT	26.00*10
1002	RH WIPER BLADE RH WIPER BLADE	40.00*20
1003	BONNETINSULATOR CLIP INSULATOR CLIP	40.00*X
1004	FRT BUMPER CLIP FRT BUMPER CLIP	40.00*
1005	FRTBUMPER RIVET FRTBUMPER RIVET	40.00*X
Total Extras		226.00

Falcon-Air Auto Services Pte Ltd
#01-06/07/13, #05-17 Sin Ming Auto
Care, 176 Sin Ming Drive
575721

Insurer Reference: TP/SKU9165H/MSIG(OD)
Repairer Reference: TP/SKU9165H/MSIG(OD)
Date calculated: 27/08/2019 10:27 AM

Full Report
Registration: SKU9165H
Printed: 27/08/2019 10:29 AM

Final Calculation

	SGD	SGD
Parts	2,773.00	
Addition(+10.00%)	277.30	
Total Parts		3,050.30
Labour Time Base 10 WU/h		
Total 111.0 WU X 50.00 SGD/h	555.00	
Total of Labour		555.00
Total Of Extras		226.00
Paint Work Time Base 10 WU/h		
Labour Cost 110.0 WU X 50.00 SGD/h	550.00	
Material Cost	264.87	
Total Paint Including Material		814.87
Repair Cost Excludes GST		4,646.17
GST (+7.0%)		325.23
Repair Cost Included GST		4,971.40

Comments

* - USER SUPPLIED DATA
NN - NO MANUFACTURERS CODE EXISTS
) - WU PARTIAL INCL IN OTHER POSITIONS

Assessment Note

No assessment notes entered.

LKK Auto Consultants
#01-25 Paya Ubi Industrial Park, 51
Ubi Avenue 1
408933

Insurer Reference: TP/SKU9165H/MSIG(OD)
Repairer Reference: TP/SKU9165H/MSIG(OD)
Date calculated: 18/09/2019 10:52 AM

Full Report
Registration: SKU9165H
Printed: 18/09/2019 10:52 AM

Summary Information

Claim

Location:	Singapore (SG)	Work Provider:	MSIG Insurance (Singapore) Pte Ltd
Printed by:	KK LAU	Currency:	SGD
Claim Reference:	TP/SKU9165H/MSIG(OD)	Date of Incident:	07/12/18
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle

Manufacturer: MITSUBISHI
Model: LANCER (CY,CX)
Sub Model: EX COMFORT CVT
Model Sheet Number: 32 39 38
Registration: SKU9165H
VIN number:
Odometer:

Model Specs

4-DOOR SALOON	PREPARE OFF VEHICLE	CLEAR COAT HARD	TWO COAT PEARL/MICA
---------------	---------------------	-----------------	---------------------


Vehicle Condition

Vehicle Status

Pre-Accident Damage:
Date of Inspection:

Damage Areas

All ☐
Underbody ☐



Labour

Time Base 10 WU/h

Price = 50.00 SGD/h

LKK Auto Consultants
#01-25 Paya Ubi Industrial Park, 51
Ubi Avenue 1
408933

Insurer Reference: TP/SKU9165H/MSIG(OD)
 Repairer Reference: TP/SKU9165H/MSIG(OD)
 Date calculated: 18/09/2019 10:52 AM

Full Report
 Registration: SKU9165H
 Printed: 18/09/2019 10:52 AM

Code	Description	WU	Price SGD
NO NUMBER	PREPARATION TIME	2.0	10.00
514110 00	R + R FRONT BUMPER	8.0	40.00
514121 00)	RENEW FRONT BUMPER	10.0	50.00
	INCLUDES: R + R NECESSARY ATTACHED PARTS		
541011 10)	R + R RIGHT HEADLAMP UNIT	1.0	5.00
425110 00	R + R BONNET	4.0	20.00
425111 10)	RENEW BONNET	2.0	10.00
	(REMOVED)		
	INCLUDES: R + R ATTACHED PARTS,		
	ALIGN BONNET		
NO NUMBER	ADJUST HEADLAMPS	2.0	10.00
423121 10	RENEW WINDSCREEN	32.0	160.00
	INCLUDE: R + R NECESSARY PARTS		
NO NUMBER	R + R REAR CENTRE CONSOLE	3.0	15.00
523111 10)	RENEW INSTRUMENT PANEL CPL	14.0	70.00
	(INSTRUMENT PANEL REMOVED)		
	INCLUDES: R + R INSTRUMENT PANEL PAD		
NO NUMBER	R + R INSTRUMENT PANEL CPL	14.0	70.00
371010 10	R + R STEERING WHEEL	4.0	20.00
0340	FRT BUMPER REINF REPAIR	10.0*	50.00
Labour Cost		Hrs	WU
Panel / Mechanical Labour		10.60	106.0
Total of Labour			530.00

Paint

Paint Work	SYSTEM AZT	Time Basis 10 WU/h
Code	Description - TWO COAT PEARL/MICA	WU Price SGD
	BONNET NEW PART PAINTING	24.0
	FRONT BUMPER COVER NEW PART PAINT K1G/P	29.0
	FRT BUMPER REINF SURFACE PAINT	4.0
	FRT BUMPER SUPPORT SURFACE PAINT	4.0
	CTR BUMPER BRACKET SURFACE PAINT	4.0
	L/F WING SURFACE PAINT	6.0
	R/F WING SURFACE PAINT	6.0

Paint Material Per Part

Code	Description	Price SGD
0471	BONNET NEW PART PAINTING	76.88
0283	FRONT BUMPER COVER NEW PART PAINT K1G/P	118.80
0340	FRT BUMPER REINF SURFACE PAINT	2.45
0341	FRT BUMPER SUPPORT SURFACE PAINT	2.45

LKK Auto Consultants
#01-25 Paya Ubi Industrial Park, 51
Ubi Avenue 1
408933

Insurer Reference: TP/SKU9165H/MSIG(OD)
 Repairer Reference: TP/SKU9165H/MSIG(OD)
 Date calculated: 18/09/2019 10:52 AM
 Paint Material Per Part

Full Report
 Registration: SKU9165H
 Printed: 18/09/2019 10:52 AM

Code	Description	Price SGD
0345	CTR BUMPER BRACKET SURFACE PAINT	2.49
0741	L/F WING SURFACE PAINT	10.21
0742	R/F WING SURFACE PAINT	10.21

Labour Cost - Paint

	Hrs	WU	Price SGD
Factor	50.00 SGD/h		
Time Paint		77.0	
Preparation Main Work Metal	2.50	25.0	125.00
Preparation Comp. Work Plastic	0.80	8.0	40.00
Total	10 WU/h	11.00	550.00

Material Cost - Paint

	Price SGD
New Part Painting	76.88
New Part Painting - Plastic K1G/PUR	118.80
Surface-/Blend Paint	27.89
Material-constant Metal Preparation	28.60
Material-constant Plastic	12.70
Total	264.87

Spare Parts

Code	Description	Part Number	Supplier	prices as at 2015-06-01	Price SGD
0283	FRONT BUMPER COVER	6400D159			350.00
0288	R/F BUMPER BRACKET	6400A852			10.00
0356	R/F BUMPER BRACKET	6400F550			10.00
0471	BONNET	5900A209			360.00
0562	R/F HEADLAMP CPL	8301B408			350.00
1227	SPACER PART	MR520530			0.00
1228	SPACER	MR957780			0.00
1393	COWL PANEL COVER	7405A057			68.00
1401	WINDSCREEN	6102A124			600.00
1411	BONDING KIT	Z2156737			0.00
1413	FRT SCREEN MNTG KIT	USE SINGLE PARTS			
1423	UPP WINDSCREEN MLDG	6107A013			50.00
1454	R/F WIPER ARM	8250A233			55.00
1464	R/F WIPER COVER	MB881494			10.00
4331	INSTRUMENT PANEL	8000A062XA			700.00
4942	R/UPP A-PILLAR TRIM	7210A160HA			80.00
1006	FRT BUMPER SEAL	FRT BUMPER SEAL			20.00

f: OEM Parts

n: Non-OEM Parts

u: Used parts

Audatex System Using Manufacturer Times

LKK Auto Consultants
#01-25 Paya Ubi Industrial Park, 51
Ubi Avenue 1
408933

Insurer Reference: TP/SKU9165H/MSIG(OD)
 Repairer Reference: TP/SKU9165H/MSIG(OD)
 Date calculated: 18/09/2019 10:52 AM

Full Report
 Registration: SKU9165H
 Printed: 18/09/2019 10:52 AM

Savings	0.00
Subtotal	2,663.00
Addition(+10.00%)	266.30
Total	2,929.30

Extras

Code	Description	Price SGD
1000	w/screen sealant w/screensealant	40.00*
1004	FRT BUMPER CLIP FRT BUMPER CLIP	40.00*
1007	ERP BRKT	10.00*
1008	RH WIPER BLADE	20.00*
Total Extras		110.00

Final Calculation

	SGD	SGD
Parts	2,663.00	
Addition(+10.00%)	266.30	
Total Parts		2,929.30
Labour Time Base 10 WU/h		
Total 106.0 WU X 50.00 SGD/h	530.00	
Total of Labour		530.00
Total Of Extras		110.00
Paint Work Time Base 10 WU/h		
Labour Cost 110.0 WU X 50.00 SGD/h	550.00	
Material Cost	264.87	
Total Paint Including Material		814.87
Repair Cost Excludes GST		4,384.17
GST (+7.0%)		306.89
Repair Cost Included GST		4,691.06

Comments

* - USER SUPPLIED DATA
 NN - NO MANUFACTURERS CODE EXISTS
) - WU PARTIAL INCL IN OTHER POSITIONS

LKK Auto Consultants
#01-25 Paya Ubi Industrial Park, 51
Ubi Avenue 1
408933

Insurer Reference: TP/SKU9165H/MSIG(OD)
Repairer Reference: TP/SKU9165H/MSIG(OD)
Date calculated: 18/09/2019 10:52 AM

Full Report
Registration: SKU9165H
Printed: 18/09/2019 10:52 AM

Assessment Note

No assessment notes entered.



合興汽車玻璃私人有限公司

HE XING AUTO GLASS PTE LTD

MAIN OFFICE: No. 76 DUNLOP STREET, SINGAPORE 209403

CAR WINDSCREEN DIV. No 26 CUFF RD. S 200736

TEL: 6296 3113 FAX: 6296 3002

A/C: 8291 1886 FAX: 6291 7717

Co. Reg. No: 200310936C GST Reg. No: 20-0310936-C

TAX INVOICE

M/S FALCON-AIR AUTOSERVICES PTE LTD 1142

REGISTRATION: M0500000000000000

801-200 SINGAPORE 529840

MITSUBISHI LANCER 2000CC

594

TEXT

NET 618142.70

GST 8.10%

GST 50.00

GST 50.00

GST 50.00

GST 50.00

Part No	Description	Location	Qty	Unit Price	Amount
				SIN	SIN
1	WMT 6102A486	WINDGLASS SET	1	600.00	600.00
2	WMT 6102A013	WINDGLASS SET	1	500.00	500.00
TOTAL QUANTITY			2	TOTAL	SIN 650.00
				ADD GST 8.10%	45.50
				GRAND TOTAL	SIN 695.50

Print: SENG 30/08/2019 10:53:19 AM

SALESMAN: SENG

This document is computer generated. No signature required.

GOODS SOLD ARE NOT RETURNABLE

E & O E

GOODS RECEIVED BY



© 2007 The McGraw-Hill Companies. All rights reserved. Reproduction or translation of this work without written permission of McGraw-Hill is prohibited. Printed in the United States of America. 0-07-070000-0

TAX INVOICE AR201909-04987

DATE 10/09/2019

CUSTOMER ID : FALCOD-2

VEH REG. NO. SKU9165H

TERMS	30 days
-------	---------

PO NO. _____

PAGE NO. Page 1 of 1

CURR.	SGD
-------	-----

1 J7210A160HA
CY4A CY2

SUB-TOTAL	80.00
-----------	-------

ADD GST 7.00 %	\$ 60
----------------	-------

EAOE

TOTAL AMOUNT	SGD	85.60
--------------	-----	-------

2] 10/09/2019 5:45:14PM

[E] 10/09/2019 5:42:51PM

Goods Sold are not refundable for Cash

Interest Rate of 1.5% per month will be imposed on OverDue Account(s)

AF Auto Pte. Ltd.

ales Executive NIN



This is computer generated document.
No signature is required.

Goods Received in Good Order

Signature / C/ Stamp / Date

ORIGINAL



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 LBI ROAD 1 #01-121 SINGAPORE 438710
TEL: 67453833 FAX: 67454442, 67450818 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672

TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@paciflo.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

FALCON AIR AUTO SERVICES PTE LTD

BLK 9006 #01-200

TAMPINES ST93

SINGAPORE 528839

ATTN: JEREMY



Wiper blade: NWS (Nippon Wiper Blade), Tilipac / Made in Korea

Fuchs / Made in Germany

Spark plug: Nippon Denso, NGK / Made in Japan

TAX INVOICE AR201908-12973

DATE 28/08/2019

CUSTOMER ID FALCOID-2

VEH REG NO SKU9165H

TERMS 30 days

PO NO

PAGE NO Page 1 of 1

CURR SGD

B44
T279

SQ STOCKID

118000A062XA

CY2 CY4

DESCRIPTION

DASHBOARD

SKLAW

QTY

U/PRICE

AMOUNT

PA

1

700.00

700.00

PU4-G1-05

SUB-TOTAL 700.00

ADD GST 7.00 % 49.00

E & O E

TOTAL AMOUNT SGD 749.00

[P] 28/08/2019 15:14:57

[E] 28/08/2019 3:03:59PM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte Ltd

Sales Executive: NIN



* 1 8 2 0 1 9 0 8 - 1 2 9 7 3 *

This is computer generated document.

No signature is required.

ORIGINAL

Goods Received in Good Order

Signature / Co Stamp / Date



日美汽車私人有限公司

JAE AUTO PTE LTD

BLK 3018 UBI ROAD 1 #01-121 SINGAPORE 408711
TEL: 67453833 FAX: 67454442, 67450616 (Rochum)

WAREHOUSE:

48A SUNGAI KADUT AVE SINGAPORE 729672
TEL: 6385 1255 FAX: 6385 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M



Subaru (Stock #111111)

Subaru (Stock #111111)

Subaru (Stock #111111)

Subaru (Stock #111111)

Wiper blade: NWH (Import) Wiper blade: NWH (Made in Korea)

Excess (Made in Germany)

Spark plug: NGK (Import) NGK (Made in Japan)

FALCON AIR AUTO SERVICES PTE LTD

BLK 9006 #01-200

TAMPINES ST93

SINGAPORE 528839

ATTN: JEREMY

TAX INVOICE AR201908-12917

DATE 28/08/2019

CUSTOMER ID FALCOD-2

VEH REG. NO. SKU9165H

TERMS 30 days

PO NO.

PAGE NO. Page 1 of 2

CURR. SGD

SO STOCK ID	DESCRIPTION	SkLec	QTY	U/PRICE	AMOUNT
1 J15900A209 CY2A,CY4A	BONNET	CC OCH1-B-07A	1	360.00	360.00
2 J16400D158 CY2A,CY4A	FACE,FR BUMPER (6400B913)	CC OCH1-D-03D	1	350.00	350.00
3 J16400E550 CY2 CY4	FR BUMPER SIDE BRACKET RH	CC OCH1-A-02B5	1	10.00	10.00
4 J18301C342/8301A912 CY2A,CY1A NEW	HEADLAMP ASSY RH	CC OCH1-B-05C	1	350.00	350.00
5 J16400A852 CY2 CY4	FR BUMPER INR BRACKET RH	CC OCH1-A-01B3	1	10.00	10.00
6 J15902A021 CY2 CY4	BONNET RUBBER FR	CC OCH1-A-11	1	20.00	20.00
7 J17405A057 CY2 CY4	GARNISH,FR DECK	CC OCH1-E-01B	1	68.00	68.00

CONTINUE NEXT PAGE

[P] 28/08/2019 14:30:05

Goods Sold are not refundable for Cash

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

ORIGINAL

[E] 28/08/2019 2:20:09PM



日美汽車私人有限公司 JAE AUTO PTE LTD

BLK 3018 UBI ROAD #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450816 (Account)

WAREHOUSE

48A SUNGEI KADUT AVE SINGAPORE 729072
TEL: 6365 1255 FAX: 6365 2580

Email: geninfo@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M



Wiper blade: NWS (Japan Super Wiper), Wiper 1 Made in Korea
Farm 1 Made in Germany
Spoke plug: Aspin Denso, NGK, Warts in Japan

FALCON AIR AUTO SERVICES PTE LTD
BLK 9006 #01-200
TAMPINES ST.93

SINGAPORE 528839

ATTN: JEREMY

TAX INVOICE AR201908-12917
DATE 28/08/2019
CUSTOMER ID FALCOD-2
VEH REG NO SKU9165H
TERMS 30 days
PO NO
PAGE NO Page 2 of 2
CURR SGD

B44
T236

NO STOCKID	DESCRIPTION	StkLoc	QTY	UPRICE	AMOUNT
✓ J1MB881494	COVER WINDSHIELD WIPER ARM	CC	1	10.00	10.00
A03A CS2 CS3 CY2 CY4		CC11-A-03D2			

SUB-TOTAL 1,178.00
ADD GST 7.00 % 82.46

E & O E TOTAL AMOUNT SGD 1,260.46

[P] 28/08/2019 14:30:05

[E] 28/08/2019 2:20:09PM

Goods Sold are not refundable for Cash

Interest Rate of 1.5% per month will be imposed on OverDue Account(s)

JAE Auto Pte. Ltd.

Sales Executive: NTN



This is computer generated document.
No signature is required.

ORIGINAL

Goods Received in Good Order

Signature / Co Stamp / Date



日美汽車私人有限公司

JAE AUTO PTE LTD

88, 3018 UBI ROAD (#01-121) SINGAPORE 408710

TEL: 67453633 FAX: 67454442 67450010 (Account)

WAREHOUSE:

50, JALAN LAMBUKAT #01-05/06 CARROS CENTRE

SINGAPORE 737869 TEL: 63625226 FAX: 63626927

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M



Best Deal: 6471 0001 1010 0000



Best Deal: 6400 0001

Best Deal: 6400 0001

Best Deal: 6417 0001



Best Deal: 6417 0001

Best Deal: 6417 0001

Best Deal: 6417 0001

Best Deal: 6417 0001

Wiper blade: M&M (Japan) wiper blade, Super 1 (Japan) & Korea
Kia (Made in Germany)

Spark plug: Japan (M&M) 1025, 1025, 1025, 1025

wiper 9/10

55 /



DATE: 2000/01/01

DATE: 2000/01/01

THE COMPANY: JAE AUTO PTE LTD

SIGNATURE: [Signature]

[Signature]

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	14 Dec 2018 Sendback Est	27 Aug 2019 11:02 S\$4,646.17	28 Aug 2019 10:38 Edit Adj Rpt	S\$4,384.17 Edit Estimates	S\$4,384.17 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured: YEO SOK BUAY , ID: 51585826E									
Vehicle Reg. No.: SKU9165H		Date of Loss: 07/12/2018 00:00 - :59 [39 Months and 16 Days From LTA Reg Date (Man Yr)]							
Claim Type: OD / 578894		Policy/Cover Note No.: 28603908QMY (Comprehensive) Coverage: 21/08/2018 - 20/08/2019 Excess: S\$3,000.00							
Repairer: Falcon-Air Auto Services Pte Ltd (Tampines) Blk 9006 #01-200 Tampines St 93, Tampines - Tel: 67897997									
Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Pang Xiu Shi - 6594 2586]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 27/09/2019]									
Driver/Custodian: BRANDON HAN WEI DING (23 / Male) , NRIC: S9544092D, Tel: +6591732900 Email: katherine_yeo@sg.msig-asia.com									
Adj Asg. Remarks: Car in, pls arrange survey by today. Survey & revert. Please contact us ASAP if you cannot attend this assignment. Please revert. Need to seek approval from HOS/HOD as this is staff's claim									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- MSIG_SG (04/10/2019): Alert - Adj Mandate Approved (S\$4384.17) - SKU9165H - Claim Handler: FOO AI NGOH - MSIG_SG (02/09/2019): Alert - Adj Mandate Approved (S\$3652.67) - SKU9165H - Claim Handler: FOO AI NGOH									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SKU9165H (578894)
OD
Dec 7 2018 12:00AM
[YEO SOK BUAY]
Falcon-Air Auto Services Pte Ltd

[Upload Documents](#) |
 [Upload Photos](#) |
 [Compose New Letter](#)

View [View in Browser](#)

Assessment Reports				1 per page	☒
No	Finalized On	Falcon-Air Auto Services Pte Ltd (Tampines)		Thumbnail	Print
1	27/08/19 11:02	Repairer Estimates		Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	28/08/19 16:06	Adjuster Immediate Advice		Load HTM	
2	18/09/19 11:17	Adjuster Immediate Advice		Load HTM	
Photos/Images				3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	28/08/19 16:51	Odometer Reading		Load JPG	☒
2	28/08/19 16:51	Chassis Number		Load JPG	☒
3	28/08/19 16:52	General View		Load JPG	☒
4	28/08/19 16:52	General View		Load JPG	☒
5	28/08/19 16:52	General View		Load JPG	☒
6	28/08/19 16:52	General View		Load JPG	☒
7	28/08/19 16:52	General View		Load JPG	☒
8	28/08/19 16:52	General View		Load JPG	☒
9	28/08/19 16:52	General View		Load JPG	☒
10	28/08/19 16:52	General View		Load JPG	☒
11	28/08/19 16:52	General View		Load JPG	☒
12	28/08/19 16:52	General View		Load JPG	☒
13	28/08/19 16:52	General View		Load JPG	☒
14	28/08/19 16:52	General View		Load JPG	☒
15	28/08/19 16:52	General View		Load JPG	☒
16	28/08/19 16:52	General View		Load JPG	☒
17	28/08/19 16:52	General View		Load JPG	☒
18	28/08/19 16:52	General View		Load JPG	☒
19	28/08/19 16:52	General View		Load JPG	☒
20	28/08/19 16:52	General View		Load JPG	☒
21	28/08/19 16:52	General View		Load JPG	☒
22	28/08/19 16:52	General View		Load JPG	☒
23	28/08/19 16:52	General View		Load JPG	☒
24	28/08/19 16:52	General View		Load JPG	☒
25	28/08/19 16:52	General View		Load JPG	☒
26	28/08/19 16:52	General View		Load JPG	☒
27	28/08/19 16:52	General View		Load JPG	☒
28	28/08/19 16:52	General View		Load JPG	☒
29	28/08/19 16:52	General View		Load JPG	☒
30	28/08/19 16:52	General View		Load JPG	☒
31	28/08/19 16:52	General View		Load JPG	☒
32	28/08/19 16:52	General View		Load JPG	☒
33	28/08/19 16:52	General View		Load JPG	☒
34	28/08/19 16:52	General View		Load JPG	☒
35	28/08/19 16:52	General View		Load JPG	☒
36	28/08/19 16:52	General View		Load JPG	☒
37	28/08/19 16:52	General View		Load JPG	☒
38	28/08/19 16:52	General View		Load JPG	☒
39	28/08/19 16:52	General View		Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	Falcon-Air Auto Services Pte Ltd (Tampines)	Thumbnail	Print
				☒
40	28/08/19 16:52	General View	 Load JPG	☒
41	28/08/19 16:52	General View	 Load JPG	☒
42	28/08/19 16:52	General View	 Load JPG	☒
43	28/08/19 16:52	General View	 Load JPG	☒
44	28/08/19 16:52	General View	 Load JPG	☒
45	28/08/19 16:52	General View	 Load JPG	☒
46	28/08/19 16:52	General View	 Load JPG	☒
47	28/08/19 16:52	General View	 Load JPG	☒
48	28/08/19 16:52	General View	 Load JPG	☒
49	28/08/19 16:52	General View	 Load JPG	☒
50	28/08/19 16:52	General View	 Load JPG	☒
51	28/08/19 16:52	General View	 Load JPG	☒
52	28/08/19 16:52	General View	 Load JPG	☒
53	28/08/19 16:52	General View	 Load JPG	☒
54	28/08/19 16:52	General View	 Load JPG	☒
55	28/08/19 16:52	General View	 Load JPG	☒
56	28/08/19 16:52	General View	 Load JPG	☒
57	28/08/19 16:52	General View	 Load JPG	☒
58	28/08/19 16:52	General View	 Load JPG	☒
59	28/08/19 16:52	General View	 Load JPG	☒
60	28/08/19 16:52	General View	 Load JPG	☒
61	28/08/19 16:52	General View	 Load JPG	☒
62	28/08/19 16:52	General View	 Load JPG	☒
63	28/08/19 16:52	General View	 Load JPG	☒
64	28/08/19 16:52	General View	 Load JPG	☒
65	28/08/19 16:52	General View	 Load JPG	☒
66	28/08/19 16:52	General View	 Load JPG	☒
67	28/08/19 16:52	General View	 Load JPG	☒
68	28/08/19 16:52	General View	 Load JPG	☒
69	28/08/19 16:52	General View	 Load JPG	☒
70	28/08/19 16:52	General View	 Load JPG	☒
71	28/08/19 16:52	General View	 Load JPG	☒
72	28/08/19 16:52	General View	 Load JPG	☒
73	28/08/19 16:52	General View	 Load JPG	☒
74	28/08/19 16:52	General View	 Load JPG	☒
75	28/08/19 16:52	General View	 Load JPG	☒
76	28/08/19 16:52	General View	 Load JPG	☒
77	28/08/19 16:52	General View	 Load JPG	☒
78	28/08/19 16:52	General View	 Load JPG	☒
79	28/08/19 16:52	General View	 Load JPG	☒
80	02/09/19 17:02	Reinspection Photo	 Load JPG	☒
81	02/09/19 17:02	Reinspection Photo	 Load JPG	☒
82	02/09/19 17:02	Reinspection Photo	 Load JPG	☒
83	02/09/19 17:02	Reinspection Photo	 Load JPG	☒
84	02/09/19 17:02	Reinspection Photo	 Load JPG	☒
85	02/09/19 17:02	Reinspection Photo	 Load JPG	☒
86	02/09/19 17:02	Reinspection Photo	 Load JPG	☒
87	02/09/19 17:02	Reinspection Photo	 Load JPG	☒
88	02/09/19 17:02	Reinspection Photo	 Load JPG	☒
89	02/09/19 17:02	Reinspection Photo	 Load JPG	☒
90	02/09/19 17:02	Reinspection Photo	 Load JPG	☒
91	02/09/19 17:02	Reinspection Photo	 Load JPG	☒
92	02/09/19 17:02	Reinspection Photo	 Load JPG	☒
93	02/09/19 17:02	Reinspection Photo	 Load JPG	☒
94	02/09/19 17:02	Reinspection Photo	 Load JPG	☒

Assessment Reports				1 per page	☒
No	Finalized On			Thumbnail	Print
95	02/09/19 17:02	Falcon-Air Auto Services Pte Ltd (Tampines)			
		Reinspection Photo		Load JPG	☒
96	02/09/19 17:02	Reinspection Photo		Load JPG	☒
97	02/09/19 17:02	Reinspection Photo		Load JPG	☒
98	02/09/19 17:02	Reinspection Photo		Load JPG	☒
99	02/09/19 17:02	Reinspection Photo		Load JPG	☒
Documentation				1 per page	☒
No	Finalized On			Thumbnail	Print
		MSIG Insurance (Singapore) Pte. Ltd. (HQ)			
1	18/12/18 13:53	OI'S DRIVER DRIVING LICENCE From: TP BI - Reg. No: PEDESTRIAN, Claimant: NA		Load PDF	
2	18/12/18 13:53	Police Report of OI From: TP BI - Reg. No: PEDESTRIAN, Claimant: NA		Load PDF	
3	18/12/18 13:53	police report given through our customer service From: TP BI - Reg. No: PEDESTRIAN, Claimant: NA		Load TXT	
		Falcon-Air Auto Services Pte Ltd (Tampines)			
1	27/08/19 10:50	GIA REPORT		Load PDF	
2	27/08/19 11:01	AUDATEX		Load PDF	
		LKK Auto Consultants Pte Ltd (HQ)			
1	28/08/19 16:12	ESTIMATE.pdf		Load PDF	
2	18/09/19 11:06	ESTIMATE MARKED.pdf		Load PDF	
3	18/09/19 11:06	SKU 9165H - AUDATEX.pdf		Load PDF	
4	16/10/19 11:26	Parts Invoice		Load PDF	

Linked Accident Report Documents

Assessment Reports				1 per page	☒
No	Finalized On			Thumbnail	Print
		MSIG Insurance (Singapore) Pte. Ltd. (HQ)			
1	14/12/18 16:47	Accident Statement		Load HTM	
2	27/08/19 12:25	Addendum Sheet		Load JPG	☒
3	27/08/19 12:25	Accident Statement Addm. #1		Load HTM	
Documentation				1 per page	☒
No	Finalized On			Thumbnail	Print
		MSIG Insurance (Singapore) Pte. Ltd. (HQ)			
1	14/12/18 16:46	Sketch Plan		Load TIF	
2	14/12/18 16:46	Sketch Plan #2		Load TIF	
3	14/12/18 16:47	Police report		Load TIF	
4	14/12/18 16:47	Police report		Load TIF	
5	14/12/18 16:47	Police report		Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Repairer ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way, #21-01 SGX Centre 2
Singapore 068807

Our File No: CS/MSG19015138/USF3E2

Date: 16/10/2019

REFERENCE

Insured/Claimant:	YEO SOK BUAY	Policy No:	28603908QMY	Claim No:	578894
Date of Loss:	07/12/2018	Nature of Claim:	OD		

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKU9165H	Engine No:	4A92CA1221
Make & Model:	MITSUBISHI LANCER EX, 1.6 Led Tail Lamp (A)	Chassis No:	JMYSRCY1AFU005160
Reg. Date:	21/08/2015 (Man. Year: 2015)	Odometer:	52061 km
Colour:	Grey		
Engine Capacity:	1590 cc		
Market Value/New Car Price:	S\$56,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,050.30	2,929.30	121.00	3.97
Miscellaneous Items	226.00	110.00	116.00	51.33
Labour	555.00	530.00	25.00	4.50
Paintwork Labour	814.87	814.87	0.00	0.00
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,646.17	4,384.17	262.00	5.64
- Excess (S\$)	3,500.00	3,000.00	500.00	14.29
(S\$)	1,146.17	1,384.17	-238.00	-20.76
+ GST 7.00/7.00% (S\$)	80.23	96.89	-16.66	-20.77
Nett Amount (S\$)	1,226.40	1,481.06	-254.66	-20.76

INSPECTION

Date of Assignment:	28/08/2019 Present Location:	Falcon-Air Auto Services Pte Ltd (Tampines)
Date Inspected:	28/08/2019 Inspected At:	BLK 9006 TAMPINES ST 93 #01-200 SINGAPORE 528840
Estimated Period of Repair:	5.0 days	

Adjuster: MARCUS CHUA

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 16 Oct 2019)
Parts:	143	mitsubishi LANCER EX 1.6 Led Tail Lamp (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKU9165H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1	NA	*BONDING KIT (NPA)	No such part	0.00 FL	*- F
2	1	NA	*BONNET (WCP)	Dented	360.00 FL	*360.00 F
3	1	NA	*COWL PANEL COVER (WCP)	Cut	68.00 FL	*68.00 F
4	1	NA	*FRONT BUMPER COVER (WCP)	Deformed / Dented	350.00 FL	*350.00 F
5	1	NA	*FRT BUMPER SEAL (WCP)	Torn	20.00 FL	*20.00 F
6	1	NA	*FRT SCREEN MNTG KIT (NPA)	Not Necessary	0.00 FL	*- F
7	1	NA	*INSTRUMENT PANEL (WCP)	Deformed / Cut	700.00 FL	*700.00 F
8	1	NA	*LWR RADIATOR GRILLE (WCP)	Not Necessary	55.00 FL	*- F
9	1	NA	*R/F BUMPER BRACKET (WCP)	Necessary	10.00 FL	*10.00 F
10	1	NA	*R/F BUMPER BRACKET (WCP)	Necessary	10.00 FL	*10.00 F
11	1	NA	*R/F HEADLAMP CPL (WCP)	Holder Cracked	350.00 FL	*350.00 F
12	1	NA	*R/F WIPER ARM (WCP)	Broken	80.00 FL	*55.00 F
13	1	NA	*R/F WIPER COVER (WCP)	Missing	10.00 FL	*10.00 F
14	1	NA	*R/LOWER AIR GRILLE (WCP)	Not Necessary	20.00 FL	*- F
15	1	NA	*R/UPP A-PILLAR TRIM (WCP)	Cut	90.00 FL	*80.00 F
16	1	NA	*SPACER (NPA)	No such part	0.00 FL	*- F
17	1	NA	*SPACER PART (NPA)	No such part	0.00 FL	*- F
18	1	NA	*UPP WINDSCREEN MLDG (WCP)	Necessary	50.00 FL	*50.00 F
19	1	NA	*WINDSCREEN (WCP)	Broken	600.00 FL	*600.00 F

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	2,773.00	2,663.00
- List Item Discount on L Items -10.00/0.00% (\$\$)	-277.30	0.00
+ Margin on L,N Items 0.00/10.00% (\$\$)	0.00	266.30
Total Parts (\$\$)	3,050.30	2,929.30

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	BONNET INSULATOR (NOT NECESSARY)	40.00	0.00
2	1	ERP BRACKET (NECESSARY)	26.00	10.00
3	1	FRT BUMPER CLIP (NECESSARY)	40.00	40.00
4	1	FRT BUMPER RIVET (REPEATED)	40.00	0.00
5	1	RH WIPER BLADE (MISSING)	40.00	20.00
6	1	W/SCREEN SEALANT (NECESSARY)	40.00	40.00
Sub Total (\$\$)			226.00	110.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Paintwork Labour				
1	TOTAL PAINT LABOUR	New	550.00	550.00
2	TOTAL PAINT MATERIALS	New	264.87	264.87
Labour Items				
3	Total Panel/Mechanical Labour	New	555.00	530.00
Gross Labour Cost (\$\$)			1,369.87	1,344.87

Report was unsubmitted during this print-out.

< END OF ESTIMATES >