

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: Sompo Insurance Singapore Pte. Ltd.
50 Raffles Place
#05-01/06, Singapore Land Tower
Singapore 048623

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Ruth Chua Gek Tiang

Date: 03 Sep 2019

Preliminary Advice

Insured Vehicle No : SKX6113L
TP Vehicle No : SLD9833R Accident Date : 25/08/2019
Make : MERCEDES-BENZ GLA180 URBAN (R18 Assignment Date : 27/08/2019
LED)
Date of Inspection : 02/09/2019 Est. Duration of Repair : 3 days
Inspection At : S M Spray Painting Pte Ltd (HQ)
25, Kaki Bukit Road 4, #08-30 Synergy@KB
Singapore 417800

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	20,904.60
Revised Amount	:S\$	2,664.00
Check Items (Estimated)	:S\$	0.00
Total	:S\$	2,664.00

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : TP : WP