

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel: 6366 2323 Fax: 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/1021/2019/GW
Date : 27-Aug-19

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Siau Kim Boon
Address : Apt Blk 874 Woodlands Street 82
#07-504
Singapore 730874
Telephone : 98159023
Type of Claim : Own Damage Claims
Policy No. : 2100499284-02
Vehicle No : **SKB 84 S**
Model Code : Audi A4 Sedan 1.4 TFSI
Model / Year : 23-01-17
Engine No : CVN022769
Chassis No : WAUZZZF43HA063446
Mileage :
Date In :
Liability :
Excess Cost :
Estimated By : Johnny Boo / Allan Wu
Accident Date : 27-Aug-19
Place of Accident : Tan Tock Beng Hospital Basement Car park Exit Ramp

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to information
- Third party survey is on a "No Fault Prejudice" basis
- No illegal modifications are allowed
- Supplementary items must be resurveyed and is subject to final approval from insurance company

Acknowledged by Repairer

Signature:

Date:

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKB 84 S

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and reinstall rear parking aid and rear lid kick sensor. Check function.	S/N \$ 360.00 ✓	
2	To renew rear windscreen and lhs 1/4 glass to facilitate fender renewal.	S/N \$ 600.00 ✓	
3	To remove and transfer lhs front door and lhs rear door's multi-lock system and power window devices. Inspect for damages.	S/N \$ 560.00 ✓	
4	To install rear windscreen solar film.	S/N \$ 400.00 ✓	7. sales agreement.
4	To dislodge and reinstall rear wire harness for lights, battery manager, fuse and relays, electrical and audio equipment.	S/N \$ 1,400.00 ✓	photo.
5	To remove and reinstall rear seat, back rest, hat tray, abcd pillar trims, luggage compartment trims. Dislodge roof liner and disengage curtain airbag etc.	S/N \$ 1,400.00 ✓	
6	To dismantle rear bumper, rear lid, lhs front door and lhs rear door. Cut out and weld lhs rear fender. Renew front lhs door and rear lhs door. To repair sill - 1/2 panel. Re-organize rear crash management components. Reinstall all parts removed.	\$ 7,350.00	2 4750

SUB LABOUR CHARGES

: \$ 12,070.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKB 84 S

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
7	To respray lhs rear fender, lhs front door, lhs rear door, door handles, door hinges, lhs sill panel, door entrances, roof channel, drain panel and end panelling. To carry out stone chip treatment and joint sealer works.	\$ 6,100.00	3775
8	To renew lhs rear rim and carry out wheel alignment.	S/N \$ 280.00	✓
10	To carry out diagnostic check.	S/N \$ 192.00	✓
SUB LABOUR CHARGES		: \$ 18,642.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax**Material List for Accident Vehicle Regn No. SKB 84 S**

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	REAR FENDER-LH	\$ 2,443.00	ht ✓
2	REAR WINDSCREEN	\$ 1,049.00	nei ✓
3	REAR WINDSCREEN PRIMER	\$ 19.00	nei ✓
4	REAR SIDE WINDOW-LH	\$ 561.00	nei ✓
5	REAR DOOR-LH	\$ 2,152.00	ht ✓
6	REAR OUTER DOOR SEAL-LH - photo	\$ 185.00	nei ✓
7	BONDING AGENT	\$ 45.00	nei ✓
8	CLEANING SOLUTION	\$ 65.00	nei ✓
9	APPLICATOR	\$ 7.00	nei ✓
10	REAR DOOR ATTACHMENT PARTS-LH	\$ 515.00	?
11	REAR DOOR CATCH-LH	\$ 109.00	X
12	REAR DOOR HINGE HALF UPPER PART- LH UPPER	\$ 41.00	?
13	REAR DOOR HINGE HALVES-LH LOWER	2 \$ 84.00	?
14	REAR DOOR HINGE HALVES-LH UPPER	\$ 42.00	?
15	REAR DOOR SEAL INNER-LH - photo	\$ 201.00	nei ✓
16	REAR DOOR HANDLE TRIM-LH	\$ 80.00	Rx
17	REAR DOOR HANDLE HOUSING-LH	\$ 7.00	?
18	FRONT DOOR	\$ 2,152.00	ht ✓
19	FRONT OUTER DOOR SEAL-LH - photo	\$ 185.00	nei ✓
20	BONDING AGENT	\$ 45.00	nei ✓
SUB FRONT SPARE PARTS		\$ 9,987.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax**Material List for Accident Vehicle Regn No.SKB 84 S**

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
21	CLEANING SOLUTION	\$ 65.00	new ✓
21	APPLICATOR	\$ 7.00	new ✓
22	FRONT DOOR ATTACHMENT PARTS -LH	\$ 488.00	?
23	FRONT DOOR CATCH-LH	\$ 96.00	?
24	FRONT DOOR HANDLE TRIM PLATE-LH	\$ 80.00	cut ✓
25	FRONT DOOR HANDLE HOUSING-LH	\$ 7.00	?
26	FRONT DOOR HANDLE COVER-LH	\$ 6.00	?
27	FRONT DOOR PERIPHERAL LIGHT-LH	\$ 66.00	X
28	FRONT DOOR HANDLE SENSOR-LH	\$ 208.00	X
29	FRONT DOOR HANDLE EXTERIOR-LH	\$ 35.00	?
30	FRONT DOOR HANDLE UNDERLAY-LH	\$ 4.00	?
31	FRONT DOOR HANDLE UNDERLAU-LH	\$ 4.00	?
32	FRONT DOOR MOUNTING BAR-LH	\$ 149.00	?
33	ACRYLIC SEALANT	S/N \$ 180.00	new ✓
34	CAVITY WAX	S/N \$ 140.00	new ✓
35	STONE CHIP	S/N \$ 180.00	new ✓
36	METAL FILLER POWDER	S/N \$ 280.00	new ✓
37	REAR W/S SEALANT	S/N \$ 200.00	new ✓
38	QUARTER GLASS SEALANT	S/N \$ 100.00	new ✓
39	SUNDRIES	\$ 400.00	?
FRONT TOTAL SPARE PARTS		: \$ 12,682.00	
FRONT TOTAL LABOUR CHARGES		: \$ 18,642.00	
GRAND TOTAL		: \$ 31,324.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel: 6366 2323 Fax: 6841 1183

Telefax

Name :

Surveyed Date :

Authorised Date :

Excess Cost :

Liability :

Remarks :

Tanpuk 9749544

Not authorise

28/8/92 1045

Resing before paint

surellkanto.com

14 days

Ex: to be advise

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel: 6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant