REF: CS/CTI 19015151 | GVf34V | Special Instruction: ASS. REC. BY: Surveyor = ASSIGNMENT (Office) From (Person): Iran Tay His Phy (71 Date/Time: 24-2-19 Estimated Cost: Bill to: OD FTP-WS/TP RES/OD RES/EVA/INV/MV/CS Skc 549m To Inspect Vehicle No: Insured: 96363905 at Workshop m/s Hing Lee moor of 397D woodland Road Policy No: DMPC SN 30161918,000 Claim No: SVM 190 2039 86 (02 Sum Insured: Excess: D.O.A. 23.8.2019 Make of Veh: (Client's Record) mupi CA / REV / REP. / REV 24 HRS H.O.D. Enforsement: Date/Time: 28.4.19 Person Contacted: Vehicle IN LOUT Action/Instruction Date/Time Estimate CC6/ AIG 14010578/ KS9 3W1 DOA-03/06/2014 SLX 256K - X

72/03/2002

REF: CI	
anregor Cox.	ASSIGNMENT (726
n Date:	Veh No: SKC549M Yr Regn: 19 Jul 2
From: Date:	Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
OD /TP) WS / TP RES / OD RES / EVA / INV / MV	Truck / Trailer or
To Inspect Vehicle No:	Make: Merce B160 c.c 1498
1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	0.1 1
at Workshop m/s Hing lee Nata	Sp.Reading 106056 T/Radio: Insured / Std / NI /
Insured: Laci - 963639 05	Eng/No:
Policy No.	C/NO: WOD 245 23/2J71987
Claims No.	Gen. Cond: Good / Fair / Poor / Burnt
Sum Insured: Excess:	Steering: Inorder / Jammed / Leaked / Burnt or
(Client's Record)	Brake: Ingrejer / Jammed / Leaked / Burnt or
Make of Veh:	Modi: Nil / S/Rim / STD A/Rim or
	Tyre Size: F: 215/45-2017
(Policy Condition)	Ŕ: (//
Remark: The veh had commenced its N/S	S O/S BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
repair at the time of inspection.	TOYO/YOKO or Citi
Bal. or Market Value: \$328.	Front Rear
IDAC Accident Rport: Consistent? : Yes or No	R/Bal mm R/Bal6
GIA / PR Seen: Consistent? : Yes or No	L/Bal. 6 mm L/Bal. 6
Est. Repairs: 6 days Res.: Yes or No	D.O.A. D.O.I. 28-08-
Lum Sum: 3 Val.: Yes or No	
CA / REV / REP. / 24 HRS	Des. of Damages : Frt / Reat / I O/S / N/S / U/C / Rooftop or
Date: Person Contacted:	le: IN / OUT
Date / Time Action / Instruction	The U/C / Chassis frame / Body Structure affected due to col
Cot 1 \$ 22 86 2	
2/9 = 1 + b/4	(IS)
101/ ringlish & S	CO WITH (A) (Red 7123, 56%)
RECEI	VED 2-6 SEP 2019
7.	
Date/Time, File Pass to? : Preli. Report	Days Of Repair: 6
i. i telli itepert	Resurvey No. of Trip: Survey Fee:
1) : Final Report	
1) : Final Report Date/Time, File Return to?	Transportation:
1) : Final Report	Add Fee: : Site Insp (\$)S+RS,SI
1) : Final Report Date/Time, File Return to? 2) >6/9 - typist	Add Fee: : Site Insp (\$)S + RS,SI : Interview (\$) Photos
1) : Final Report Date/Time, File Return to?	Add Fee: : Site Insp (\$)S+RS,SI

...CLAIM SUBFOLDER...(New Assignment)

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Authled	Status	
Main	28 Aug 2019		28 Aug 2019 13:05 Assign				New Assig Cancel Ca	A CONTRACTOR OF THE PARTY OF TH
	Main	Re	ference	Clai	m Details	Docum	ents	Show All

Main	Reference	Claim Details	Documents	Show All
CLAIM SUBFOLDER DETAIL	S		[Created by insu	rer]
Insured:				•
Main Claimant:	ROYAL BUSSAN SINGAPORE P	TE LTD		
Vehicle Reg. No.:	SKC549M	Date of Loss:	23/08/2019 09:00	- :59
Claim Type:	TP / SNM19D203986C02	Policy/Cover Note No.:	DMPCSN301619180	000
Vehicle Reg. No. (Insured):	SLX256K	Policy No. (Claimant):		
		Excess:	5\$0.00	
Repairer:	Hing Lee Motor Car Repair & V	Welder Works (HQ) 397D Wood	llands Road, 677996 Woodla	inds - Tel:
Handling Insurer:	China Taiping Insurance (Sing Ping - 638986192]	gapore) Pte. Ltd. (HQ) - Tel: 6	389 6111 [Handled by Ire	ene Tay Hui
Adjuster:	LKK Auto Consultants Pte Ltd	(HQ) - Tel: 6256-3561 [Final	al Rpt due 06/09/2019	1
Adj Asg. Remarks:	PLEASE SURVEY AND REVERT			
	ED		View All Compo	es Casa Mall
ASSOCIATED MAIL RECEIV				se case mail
There are no mail for this case.				se case Maii
There are no mail for this case.				se case maii
There are no mail for this case.		View All Search Ta	sks Create New Task	Complete

Nivitha (LKK Auto)

From:

Irene Tay <irene.tay@sg.cntaiping.com>

Sent:

Wednesday, 28 August 2019 12:53 PM advocates@legiste.com.sg; assignments

To: Cc:

assignments

Subject:

FW: YR REF: SNM19D203986C02 [FMC.12184.19.03]

Attachments:

FMC12184-CTPI_20190828095617.pdf

Dear Sir/Mdm (LKK),

Please get your surveyor to liaise with Hing Lee Motor to conduct a PRS.

Regards,

Irene Tay

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909

DID: (65) 63896192 | F: (65) 6222 1033

W: www.sg.cntaiping.com | FB: www.facebook.com/chinataipingsg/ | WeChat: 太平狮城 Taiping SG

From: Legiste Law Corporation [mailto:advocates@legiste.com.sg]

Sent: Wednesday, 28 August, 2019 10:08 AM To: Irene Tay <irene.tay@sg.cntaiping.com>

Subject: YR REF: SNM19D203986C02 [FMC.12184.19.03]

Dear Mdm

For your kind attention please

Gina Pat (secretary) M/s Legiste Law Corporation

Tel: 6227 9909 Fax: 6227 2767

This email has been scanned by the Symantec Email Security.cloud service. For more information please visit http://www.symanteccloud.com

Legiste Law Corporation

ADVOCATES & SOLICITORS NOTARIES PUBLIC COMMISSIONERS FOR OATHS INCORPORATED WITH LIMITED LIABILITY
Co Regn No 200305183Z

24 Peck Seah Street #04-06 Nehsons Building Singapore 079314 Telephone +65-62279909 Facsimile +65-62272767 E-mail advocates@legiste.com.sg

FOK MUN CHEONG TAN KIM KEE NG LAI LENG

Yr Ref

SNM19D203986C02

Email / Fax

irene.tay@sg.cntaiping.com / 6222 1033

Our Ref

FMC.12184.19.03

28th August 2019

URGENT

Motor Claims Department China Taiping Insurance (Singapore) Pte Ltd Attn: Ms Irene Tay

BY EMAIL & BY FAX

Dear Sirs

PRE-REPAIR SURVEY ("PRS")

ACCIDENT ON 23.08.19 INVOLVING SKC 549M & SLX 256K AT AYE TOWARDS DOWNTOWN NEAR ALEXANDRA HOSPITAL EXIT CLAIMANTS: ROYAL BUSSAN SINGAPORE PTE LTD (UEN NO. 199102774N)

We refer to your email dated 27th August 2019.

We write to confirm that our clients and their appointed workshop agree to the appointment of Mr Henry Ng as the Single Joint Expert ("SJE").

Pursuant to paragraph 2.5 of the Pre-Action Protocol for Non-Injury Motor Accident Cases, kindly instruct the SJE to complete the PRS by 30th August 2019 at our clients' workshop particularized as follows:

Name

M/s Hing Lee Motor Car Repair & Welder Works

Address

Block 7 Woodlands Road

Unit 397-D Yew Tee Industrial Estate

Singapore 677996

Contact Person:

Mr Lai Seng Peng

Mobile

9636 3905

Yours faithfully

Joseph Fok Mun Cheong Legiste Law Corporation

clients

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Company	
Owner ID:	774N	
通信的对象的人的变形的对象的特殊的	EVECTION.	
Vehicle No.:	SKC549M	
Vehicle to be Exported:	No	
Intended Deregistration Date:	28 Aug 2019	
Vehicle Make:	MERCEDES BENZ	
Vehicle Model:	B 160	
Primary Colour:	Black	
Manufacturing Year:	2011	
Engine No.:	26692030914384	
Chassis No.:	WDD2452312J719473	
Maximum Power Output:	70.0 kW (93 bhp)	
Open Market Value:	\$24,329.00	
Original Registration Date:	19 Jul 2011	
First Registration Date:	19 Jul 2011	
Transfer Count:	1	
Actual ARF Paid:	\$24,329.00	
		SA SA SANSA
PARF Eligibility:	Yes	
PARF Eligibility Expiry Date:	18 Jul 2021	
PARF Rebate Amount:	\$13,380.00	
COE Expiry Date:	18 Jul 2021	
COE Category:	A - Car (1600cc & below)	
COE Period(Years):	10	
QP Paid:	\$50,244.00	
COE Rebate Amount:	\$9,482.00	
Total Rebate Amount:	\$22,862.00	

The information contained herein is correct as at 28 Aug 2019

OK



Mercedes-Benz b160 Used Vehicle List (5 vehicles)

Availability Price Depreciation Reg Date Eng Cap Mileage Company Car Model Available

Mercedes-Benz B-Class B160 \$29,000

\$10,320 /yr

1,498 cc

14-Apr-2011

110,000 km Euro-Asia Motor

Office No. - 65150595

Alexis Ong - 90275656 | Alan Tan - 85338552 | Darren Tan - 93223322 | Keith - 97367333

Mercedes-Benz B-Class B160 \$29,000

\$9,800 /yr

16-May-2011 1,498 cc

114,700 km Autolink Holdings Pte

Available

Excellent Condition! Buy With A Peace Of Mind From Award Accredited Company! Attractive Loan At Interest Rate And Competitive Trade In Price! Call Now To Find Out More! GST Included In Price!

Office No. - 63463383

Erik Tan - 94500673 | Lee - 98468156

Mercedes-Benz B-Class B160 \$30,000

\$10,260 /yr

23-May-2011 1,498 cc

116,000 km Euro-Asia Motor

Available

Office No. - 65150595

Alexis Ong - 90275656 | Keith - 97367333 | Alan Tan - 85338552

Mercedes-Benz B-Class B160 \$33,000

\$11,490 /yr

20-Jun-2011 1,498 cc

113,000 km Bavarian Marques Pte Ltd

Available

Immaculate Conditon! Well Maintained By Careful Owner. Tyres, Brake Pads And Brake Disc Changed Recently. Under Workshop Warranty Till Oct 2019, Buy With A Piece Of Mind. Welcome Trade In/ STA Evaluat...

Eugene - 81333924 | Shawn - 88188544 | Jeremiah - 98807671 | Qai - 88148478

Mercedes-Benz B-Class B160 \$34,800

\$10,210 /yr

15-Nov-2011 1,498 cc

69,000 km Roadlink Auto Pte Ltd

Available

Low Mileage Of 69,000km. Agent Unit. One Of The Most Reliable Hatchback Commonly Seen On The Roads For Daily Usage, Very Well Maintained By Previous Owner! Spacious Interior With Generous Boot Space F...

Office No. - 66360538

Colin Lim - 82255588 | Tom - 91889988

sqCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, even for COE cars, OPC cars, vans, trucks, hybrid cars, sports cars or stationwagons. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions, and also motoring advice, car reviews & car news on the latest models. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

@ 2004-2019 sqCarMart, All rights reserved.

MSYH19111480 / Sin Yew Hup Auto Pte Lid - HQ ENTRY DATE & TIME: 24/08/2019 10:28 SUBMITTED BY: Teo Hong Eng

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of meterial facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for Investigation.
- 6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- By the ladgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available
 aforesaid.

	ACCIDENT STATEMENT
Date Of Report	24/08/2019 10:28
Date Of Accident	23/08/2019 09:30
Exact Location Of Accident	AYE TOWARDS DOWNTOWN NEAR ALEXANDRA HOSPITAL EXIT
Country/State of Loss	SINGAPORE

	DETAILS OF OWN VEHIC	
Vehicle Registration Number	SKC549M	

sured/Policyholder

Name Of Registered Owner ROYAL BUSSAN SINGAPORE PTE LTD

Co Reg No 199102774N

Email Address LESLIETAN@RBSINGAPORE.COM

Mobile Phone No

Alternative Phone No OFFICE-81184267

Vehicle Particulars

Manufacturer MERCEDES-BENZ

Model B160-1.5 (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy

for repair to your vehicle?

NO

If No, Please state action to be taken

THIRD PARTY

11 1 1 2 5

Vehicle Category

COMMERCIAL VEHICLE

nsurance Company

--- ame of Insurance Company

CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

PATH NOW WATER TO

Type Of Coverage COMPREHENSIVE

Fleet Policy NO

Policy Number DMPCSN3047451903

Cover Note Number

Driver

Name of Driver LOW SHIN LING

 NRIC No
 \$1790297J

 Date Of Birth
 08/01/1967

 Occupation
 INDOOR

 Date Of Driving Pass
 31/01/1991

Driving Experience 28 YEARS AND 6 MONTHS

Gender FEMALE

Mobile Number (LOCAL) +65-81184267

Fax Number

Contact Number

EMail Address PAMELA.LOW@GMAIL.COM

Address

51 HINDHEDE WALK #03-07

Postcode

587975

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured

OWNER

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

COLLISION - HEAD TO REAR

profesional and analysis of the part

TO SERVICE STATE OF A SERVICE TO BE WAS

Weather Conditions

CLEAR

Road Surface

DRY

Other Information.

Was any foreign vehicle involved in this accident?

Sold of the state of the state of the

NO

Number of vehicles (including own vehicle)

Involved in the accident

2

Was any body injured in the Accident?

NO

Was any injured conveyed to hospital by

NO

ambulance?

Was any other material or property damaged?

YES

I have been approached by unknown person(s)

soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

Details of Police Action

Was the accident reported to the police?

If Yes, Please state which Police Station

Was notice of Intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

PLEASE REFER TO SKETCH PLAN.

Attachment(s)

Are accident pholos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SLX256K

Vehicle Make/Model/Colour

Details Of Properties

PRIVATE CAR

Vehicle Category Name of Driver

SEAN VALLAVAN S/O PACKIRISAMY

NRIC/Passport Number

S1778554J

Contact Number

91114602

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Accident Sketch Plan Pg. 1

SKETCH PLAN

IMPORTART NOTICE

- 5. Stease report correctly the details of the social of the speed up the plain's protest
- 5. This Form in its he completed by the Policyholder and for the Authorites Driver
- 3 infer nation presided more be as troubful and accurate as possible, any which is a appearant according to material facts may allow insurance companies to republista policy Habillay.
- 4. The Issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the Insurers of the SIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgment of this report to the Insurers, you hereby consent to the erchiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- My insurer, my workshop and the General insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal information") and disclose and transfer such Personal information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shell be collectively referred to as the "insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) Investigating the accident and/or my claims;
 - (lii) carrying out and/or dealing with my instructions or responding to any enquiries by me:
 - (Iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of cortain personal date about me to bring about delivery of the same at well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my deirns (collectively the
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents(Including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- my Fersonal information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- 16) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government againsies as reasonably required for the purposes stated, or

(ii) for paraphying with requirements under any regulations, laws or court project,

Royal Bussan Singapore Pte Lto Blk 32, Defu Lane 10, #02-12 Singspore 5,39213 lel: 6280 3007 Box 3,6280 8852

Fex. 6280 8852 Tel: 6280

Podeynalber's St - 806 G. Timbe

Other's Sto etire.

Miche H doctors positivitated DAM & TITTE >4 46 7015

erronner's Fignature Farerty g Nerve KRIC THE RE.

Accident Sketch Plan Pg. 1

A: SKC 549 M Exit B: 51x356K DESCRIBE CIRCUMSTANCES OF THE ACCIDENT Ch >> fruen 2019, approx. 9:30 am. I was diving my retricke SKC 549 m, on Aye towards city. The historiany was consisted a very are traveling in slower Speed. Out of the plue I was neared a word bang and I was propelled stightly to the formt. When I worked back from my mirror, I sow the verticle SLX >5bk was bestind my vehicle
A
Bik 32 Defution 10, #02-12 Bik 32 Defution 10, #02-12 State State Time: Date British: 24 AUG 709 Date Brite British: 24 AUG 709 Date British: 24 AUG 709 Date British: 2



興利摩哆汽車燒奸敵

HING LEE MOTOR CAR REPAIR & WELDER WORKS

BLK 7 UNIT 397-D WOODLANDS ROAD YEW TEE INDUSTRIAL ESTATE SINGAPORE 677996
TEL: 762 1010, 763 9909 FAX: 760 2724 Email: hinglee@pacific.net.sg

	Royal Bussan singapore pre Ctd				
	SEC X49 M	2	7/8/19 NO		
/,	Rear Xai gate Assy / Buc.	*	2032.00	18	30.9
2.	Rear derif gote Sticker / St.	\$	98.00.	1 78	1.38
3,		9	30,00.	/	
4	Rear Kay gate Lock Top (With) Centre Lock /	31.	180.00.	287	44
7	Rear Boot rubben . L. Con.		255,00.		
6	Rem RH Keril gate lamp 1334 & LNN		238.00.		
7_	Rew RH Keing lamp Mary &	*	440.00.	X	
8	Rear Brasper 1 Ce.	\$	1288.00	/ 1118	3.78
	2 Rem bumper side Bracket \$480/08	. 4	96.00	150	
10	1 Riene LH burgen Garrish / Cut.	\$	175.00.	1511	155
#/	1 Rear CH Gamper Garnish Mounding of	C∮	130.00.	11	1312,
12	Rear Chrome top bamper see.	\$	248.00	176	.04
13	Rolen bumple Reinforement 187.	\$	560.00.	148	3,27
(4	Rear bruger LH Reflexter. D/ GUA	£	60.00.	/ 38	•
13	Rea RH Sumper Garnigh X GNN	\$	175.00	X	
16	Ren RH bamper Garrish Moulding X	4	130.00.	X	
7	Rear Sumper Cower. 1 GT.	\$	220,00.	/	
18	Reac Exhaust Chrome / at -	\$	158,00.	/	
19	Rear end Panel. Repair . X	\$	1335.00	X	
20	Rear end Panel Garnish XNN	1	260.00	XN	
21	Frim Board Clip / Mc.	*	80,00	1 50	
			486	9.31	
	(5.314)	7	0/. 438	238	
			1	.,,	



興利摩哆汽車燒奸敵

HING LEE MOTOR CAR REPAIR & WELDER WORKS

BLK 7 UNIT 397-D WOODLANDS ROAD YEW TEE INDUSTRIAL ESTATE SINGAPORE 677996 TEL: 762 1010, 763 9909 FAX: 760 2724 Email: hinglee@pacific.net.sg

	771	i onemoti»	
		• To them you we will be a Third to the state of the stat	
-	Royal Bussan Singaporce pte L	4	-
	SRC 549 M Dat	27/8/190A	
		10.0	
	5/~		
/.	Rear glass Sealan	9 65.00	640
)	Rear glass inner Seal / GMC	\$ 80.00.	710
3.	Rela Bumpen Sensor.	\$ 420.00	1. 250
4	Rear end panel joint Sealan. X NN	\$ 50.00	
.(Rear end panel joint Sealan. X NN Rom No plate / GCR.	\$ 10.00.	45
			335
	Labour Charge,		
1.	To spray Rear Damaged area.	\$ 1300,00	1000
	To Repair Rear fee Damaged Remove & Refit	1	,
	Cut & Weld & Straighten	\$ 1200,00.	700.
3	Rear Leng gate transfer.	\$ 120.00.	
4	Rear 9/435 to Remove & Refit	\$ 120,00.	100
1	Rear Exhuast Repair	\$ 150.00	60
б	Winip fee .	\$ 50.00.	30
7	To Refit Rea bumper Sensor.	\$ 120.00.	40
8	Anti Rust	\$ 60.00.	50.
_9	Rear Boot Trim Board Remove & Refit	9 100.00	60
10			40.
	Dans. (guo Qion -82880282	12,633	2/60
	1 28/8/19. 1 min	68	77.38
	UMPSIM 1910AL	20%: 59	00
	Days. Guo Qiag -82880282 Umpsim report 28/8/19.	10. 33	

Merimen e-Claims Page 1 of 1

...CLAIM SUBFOLDER...(Pending for Survey Report)

LAIM SUB	FOLDER TRA	CKING						_	
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Subn	nitted	Ins Auth'ed	Status	
Main	28 Aug 2019		28 Aug 2019 13:05 Edit Adj Rpt	S\$5,500.00 Edit Estimates	S\$5,500 View Rp			Pending for Report Cancel Ca	
	Main	ŊĹ R	teference	Claim De	ails		Documents		Show All
CLAIM SI	JBFOLDER DE	TAILS			[Cr	reated b	y insurer]		
Insured:	-, Co. Re	g. No.: -							
Main Claimant:	ROYAL BI	JSSAN SINGAPO	ORE PTE LTD						
Vehicle Re No.:	9. SKC549	SKC549M				23/08/2019 09:00 - :59 [97 Months and 4 Days From LTA Reg Date (Man Yr)]			(Man Yr)]
Claim Type	e: TP / SNM19D203986C02 Policy/Cover Note No.: DMPCSN30161918000								
Vehicle Re No. (Insured):	SLX256K			Policy N (Claima					
				Excess:	S\$0	0.00			
Repairer:	Hing Lee	Motor Car Repa	ir & Welder Works	(HQ) 397D Woodla	nds Road, (677996 W	/oodlands - Tel:		
Handling Insurer:		1 .50	(Singapore) Pte. Lt	1000 500			59	200	
Adjuster:	LKK Auto	Consultants Pte	e Ltd (HQ) - Tel: 625	6-3561 [Handled	by XING	GUO QI	ANG] [Final	Rpt due 06/	09/2019]
Adj Asg. Remarks:	PLEASE SU	JRVEY AND REVE	RT						
ASSOCIA	TED MAIL RE	CEIVED					Viev	v All Comp	ose Case Mail
There are	no mail for this	case.							
ALL ASS	OCIATED TAS	KS [□]			View	All Se	earch Tasks C	reate New Task	Complete
Due Da		Type Tasi	k Group Subject	Handler /	Assigned E	Ву	Completed On	Created (On Done

Claim Documents

*SKC549M (SNM19D203986C02)
[SLX256K]
TP
ROYAL BUSSAN SINGAPORE PTE LTD
Aug 23 2019 9:00AM

[-]
Hing Lee Motor Car Repair & Welder Works

Pho	otos/Images		3 per page	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnai	Print
1	29/08/19 13:02	General View	■ Load JPG	V
2	29/08/19 13:02	General View	■ Load JPG	V
3	29/08/19 13:02	General View	Load JPG	\mathbf{V}
4	29/08/19 13:02	General View	Load JPG	\mathbf{Z}
5	29/08/19 13:02	General View	€ Load JPG	V
6	29/08/19 13:02	General View	Load JPG	☑
7	29/08/19 13:02	General View	■ Load JPG	V
8	29/08/19 13:02	General View	Load JPG	V
9	29/08/19 13:02	General View	Load JPG	V
10	29/08/19 13:02	General View	■ Load JPG	V
11	29/08/19 13:02	General View	Load JPG	V
12	29/08/19 13:02	General View	Load JPG	V
13	29/08/19 13:02	General View	■ Load JPG	V
14	29/08/19 13:02	General View	■ Load JPG	V
15	29/08/19 13:02	General View	€ Load JPG	V
16	29/08/19 13:02	General View	Load JPG	V
17	29/08/19 13:02	General View	€ Load JPG	V
18	29/08/19 13:02	General View	€ Load JPG	V
19	29/08/19 13:02	General View	1 Load JPG	Ø
20	29/08/19 13:02	General View	Load JPG	Z
21	29/08/19 13:02	General View	Load JPG	Z
22	29/08/19 13:02	General View	1 Load JPG	V
23	CHARLES AND CONTROL SEC.	General View	■ Load JPG	☑
24	29/08/19 13:02	General View	1 Load JPG	∀
	29/08/19 13:02		1 Load JPG	V
25	29/08/19 13:02	General View	6 Load JPG	∀
26	29/08/19 13:02	General View	6 Load JPG	☑
27	29/08/19 13:02	General View		
28	29/08/19 13:02	General View		_
29	29/08/19 13:02	General View	Load JPG	
30	29/08/19 13:02	General View	Load JPG	
31	29/08/19 13:02	General View	Load JPG	
32	29/08/19 13:02	General View	Load JPG	
33	29/08/19 13:02	General View	■ Load JPG	_
34	29/08/19 13:02	General View	1 Load JPG	Ø
35	29/08/19 13:02	General View	1 Load JPG	V
36	29/08/19 13:02	General View	1 Load JPG	V
37	29/08/19 13:02	General View	1 Load JPG	<u>Z</u>
38	29/08/19 13:02	General View	1 Load JPG	
39	29/08/19 13:02	General View	1 Load JPG	<u>V</u>
40	29/08/19 13:02	General View	1 Load JPG	
41	29/08/19 13:02	General View	1 Load JPG	
42	29/08/19 13:02	General View	1 Load JPG	
43	29/08/19 13:02	General View	Load JPG	V

Pho	tos/Images		3 per	page 🔻	V
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
44	29/08/19 13:02	General View	0	Load JPG	V
45	29/08/19 13:02	General View	0	Load JPG	V
46	29/08/19 13:02	General View	0	Load JPG	V
47	29/08/19 13:02	General View	0	Load JPG	\mathbf{Z}
48	29/08/19 13:02	General View	0	Load JPG	V
49	29/08/19 13:02	General View	0	Load JPG	$ \mathbf{V} $
50	29/08/19 13:02	General View	0	Load JPG	$ \mathbf{Z} $
51	29/08/19 13:02	General View	0	Load JPG	V
52	29/08/19 13:02	General View	0	Load JPG	$ \mathbf{Z} $
53	29/08/19 13:02	General View	0	Load JPG	$\overline{\mathbf{v}}$
54	29/08/19 13:02	General View	0	Load JPG	V
55	29/08/19 13:02	General View	0	Load JPG	V
56	29/08/19 13:02	General View	0	Load JPG	V
57	29/08/19 13:02	General View	0	Load JPG	V
58	29/08/19 13:02	General View	0	Load JPG	V
59	29/08/19 13:02	General View	0	Load JPG	V
60	29/08/19 13:02	General View	6	Load JPG	V
61	29/08/19 13:02	General View	0	Load JPG	V
62	29/08/19 13:02	General View	0	Load JPG	V
63	29/08/19 13:02	General View	0	Load JPG	V
64	29/08/19 13:02	General View	0	Load JPG	V
65	29/08/19 13:02	General View	0	Load JPG	\mathbf{Z}
66	29/08/19 13:02	General View	6	Load JPG	\mathbf{Z}
67	29/08/19 13:02	General View	0	Load JPG	V
68	29/08/19 13:03	Odometer Reading	0	Load JPG	V
69	29/08/19 13:03	Chassis Number	0	Load JPG	V
70	26/09/19 14:34	Reinspection Photo	0	Load JPG	V
71	26/09/19 14:34	Reinspection Photo	0	Load JPG	V
72	26/09/19 14:34	Reinspection Photo	0	Load JPG	V
73	26/09/19 14:34	Reinspection Photo	0	Load JPG	V
74	26/09/19 14:34	Reinspection Photo	0	Load JPG	V

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
			-
			~
Show Remarks To: Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg. No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI19015151/GVF3E2

07/10/2019 Date:

REFERENCE

China Taiping Insurance Handling Insurer:

(Singapore) Pte. Ltd.

Policy No:

DMPCSN30161918000

Claimant Vehicle No:

SKC549M

Insured Vehicle No:

SLX256K

Date of Loss:

23/08/2019

Nature of Claim: TP

Claim No:

SNM19D203986C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SKC549M

Make & Model: Reg. Date:

MERCEDES-BENZ B160, 1.5 (A) 19/07/2011 (Man. Year: 2011)

Engine No: Chassis No: Odometer:

26692030914384 WDD2452312J719473

106056 km

Colour:

Black

Engine Capacity:

1498 cc

Market Value/New Car Price:

N/A

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Engine Modification:

Footbrake (Serviceable):

Pre-accident Condition:

Yes

56.43

Handbrake (Serviceable): CONDITION OF TYRES

Front Tyre Size:

215/45Z R17

Rear Tyre Size:

215/45Z R17

Front Left Side: Front Right Side: Citi 6 mm

Rear Left Side: Rear Right Side:

12,623.00

Citi 6 mm Citi 6 mm

Citi 6 mm The above values represent the remaining tyre treads depth

COST OF CLAIMS	3	Repairer's	Adjuster's	Difference	Diff %
Parts		9,253.00	4,717.38	4,535.62	49.02
Miscellaneous Items	S	0.00	0.00	0.00	
Labour		3,370.00	2,160.00	1,210.00	35.91
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	12,623.00	6,877.38	5,745.62	45.52
	Approved Total (Overridden) (S\$)		5,500.00		

INSPECTION

Date of Assignment:

28/08/2019

Date Inspected:

28/08/2019 Inspected At:

Nett Amount (S\$)

Hing Lee Motor Car Repair & Welder

7,123.00

Works (HQ)

5,500.00

397D Woodlands Road Singapore 677996

Estimated Period of Repair:

6.0 days

Adjuster: XING GUO QIANG Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Referen	ce				
Part Source: MRM-SG		Version: 1.0 (Last Synchronised: 07 Oct 2019)			
Parts:	144	MERCEDES-BENZ B160 1.5 (A) (Catalogue:Merimen Singapore 1.0)			
Labour:	Repairer's	(Price-denominated Standard List)			
Print Code:	(Unsubmitted	no print-code for SKC549M)			
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, runr numbers with the END OF ESTIMATES marker on the last estimate page				
Further Info	: Items/values	not in reference catalogue are prefixed with an asterisk *.			

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*REAR TAIL GATE ASSY	Buckled	2,032.00 F	*1,830.90 FL
2	1	*REAR B160 EMBLEM	Necessary	98.00 F	*78.38 FL
3	1	*REAR TAIL GATE STICKER	Necessary	30.00 F	*30.00 FL
4	1	*REAR TAIL GATE LOCK TOP (WITH) CENTRE LOCK	Bent	580.00 F	*287.44 FL
5	1	*REAR BOOT RUBBER	Twisted	255.00 F	*202.93 FL
6	1	*REAR RH TAIL GATE LAMP ASSY	Not Necessary	238.00 F	*-FL
7	1	*REAR RH TAIL LAMP ASSY	Not Necessary	440.00 F	*-FL
8	1	*REAR BUMPER	Deformed	1,288.00 F	*1,118.78 FL
9	2	*REAR BUMPER SIDE BRACKET	Deformed	96.00 F	*50.00 FL
10	1	*REAR LH BUMPER GARNISH }	Cut	175.00 F	*145.57 FL
11	1	*REAR LH BUMPER GARNISH MOULDING }	Necessary	130.00 F	*-FL
12	1	*REAR CHROME TOP BUMPER	Deformed	248.00 F	*176.04 FL
13	1	*REAR BUMPER REINFORCEMENT	Bent	560.00 F	*483.27 FL
14	1	*REAR BUMPER LH REFLECTOR	Cracked	60.00 F	*38.00 FL
15	1	*REAR RH BUMPER GARNISH	Not Necessary	175.00 F	*-FL
16	1	*REAR RH BUMPER GARNISH MOULDING	Not Necessary	130.00 F	*-FL
17	1	*REAR BUMPER LOWER	Cut	220.00 F	*220.00 FL
18	1	*REAR EXHAUST CHROME	Cut	158.00 F	*158.00 FL
19	1	*REAR END PANEL	Repair	1,335.00 F	*-FL
20	1	*REAR END PANEL GARNISH	Not Necessary	260.00 F	*-FL
21	1	*TRIM BOARD CLIP	Necessary	80.00 F	*50.00 FL
22	1	*REAR GLASS SEALANT }	Necessary	65.00 FS	*40.00 FS
23	1	*REAR GLASS INNER SEAL }	Necessary	80.00 FS	*-FS
24	1	*REAR BUMPER SENSOR	Necessary	420.00 FS	*250.00 FS
25	1	*REAR END PANEL JOINT SEALANT	Not Necessary	50.00 FS	*-FS
26	1	*REAR NO PLATE	Scratched	50.00 FS	*45.00 FS
F=Fra	anchise	part. S=SpcNett. L=ListItemDisc.	-		
			Sub Total (S\$)		5,204.31
		- List Item Discount on L Items 0.	.00/10.00% (S\$)	0.00	486.93
		1	Total Parts (S\$)	9,253.00	4,717.38

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO SPRAY REAR DAMAGED AREAS	New	1,300.00	1,000.00
2	TO REPAIR REAR ACC DAMAGED REMOVE & REFIT CUT & WELD & STRAIGHTEN	New	1,200.00	700.00
3	REAR GLASS TO REMOVE & REFIT	New	120.00	120.00
4	REAR EXHAUST REPAIR	New	150.00	60.00
5	WIRING FEE	New	50.00	30.00
6	TO REFIT REAR BUMPER SENSOR	New	120.00	40.00
7	ANTI RUST	New	60.00	50.00
8	REAR BOOT TRIM BOARD REMOVE & REFIT	New	100.00	60.00
9	CENTRE LOCKING RESET	New	150.00	40.00
10	REAR TAIL GATE TRANSFER	New	120.00	60.00
	Gross Labou	r Cost (S\$)	3,370.00	2,160.00
	Report was unsubmitted durin	g this print-out.		

< END OF ESTIMATES >