

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Chhia Nyuk Pui

Date: 05 Sep 2019

Preliminary Advice

Insured Vehicle No	: SLS7434T		
TP Vehicle No	: SHC2105H	Accident Date	: 26/08/2019
Make	: HYUNDAI IONIQ HYBRID	Assignment Date	: 28/08/2019
Date of Inspection	: 28/08/2019	Est. Duration of Repair	: 8 days
Inspection At	: Soon Hock Motor Pte Ltd (HQ) Blk 10 Ang Mo Kio Industrial Park 2A, #01-05/06 AMK Autopoint Singapore 568047		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s front, o/s front & o/s rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	39,979.72
Revised Amount	:S\$	35,815.40
Check Items (Estimated)	:S\$	0.00
Total	:S\$	35,815.40

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

() The vehicle is economical/not economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis.