

ASS. REC. BY:

REF: 08/40119015156/Usd3 | n2

Special Instruction:

Summary: Marcus

ASSIGNMENT (Office)

From (Person): Jenny Lew

of UOI

Date/Time: 27/8/2019 @ 4:50pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SDK 9933T

Insured:

at Workshop in/s Trans Eurocars

Tel: 9127 7928

of 5 ubi close

Policy No:

Claim No: M12D11431909

Sum Insured:

Excess: \$750.00

Make of Veh: (Client's Record)

D.O.A.

CA / (REV) / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 9:35am @ 28/8/19 Person Contacted: Ronald

Vehicle IN / OUT

Date/Time	Action/Instruction	Johny! ✓
	SDK 9933T - NA / UOI 19011948/h4	DOT: 23/8/19
30/08/19 @ 13:24 pm	remit to Jenny Lew via email.	
30/08/19 @ 16:34 pm	authorize repair approved by Jenny Lew via email.	
30/08/19 @ 16:46 pm	inform CIA to Ronald via email.	

ASS. REC. BY:

REF: UOI CS/UOI 19015156/USD3

ASSIGNMENT

From: _____ Date: 30/8/19

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SDK 99 33T

at Workshop m/s: Truns Eurokars

of: 5 ubi close

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: \$750.00

(Client's Record)

Make of Veh: 11am (waiting)

Ronald @ 9127 7928

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 77k.

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 8 days Res.: Yes or No

Lum Sum: 151 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS 358F

Date: _____ Person Contacted: Dep 9.500

Vehicle: IN / OUT

Veh No: SDK 9933T Yr Regn: 7 / 16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CA /

Make: Mazda 6 c.c. 1998

Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading: 76900 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JM66Y1072G0242242

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: _____ R: 225/55 R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI

TOYO / YOKO or

Front	Rear
R/Bal. 6 mm	R/Bal. 6 mm
L/Bal. 6 mm	L/Bal. 6 mm
D.O.A. _____	D.O.I. 30/8/19

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

at Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	21A 58084 by rs/mb. 10/10/19
2/10/19	confirm final by 8048.92 (\$ 9,708.19 Red - 55%)

RECEIVED 10 OCT 2019

Date/Time, File Pass to? 10/10/19

1) Typist Preli. Report Final Report

Date/Time, File Return to? _____

2) _____

Report Format: _____

Lump Sum / I.E.P. \$ 8,048.92

Days Of Repair: 8

Resurvey No. of Trip: 1

Add Fee: Site Insp (\$) Interview (\$) Tech. Invs (\$) Weekend (\$)

Survey Fee: 250 + 175 = 425

Transportation: 60

Stamps: 80

Other: 48

613



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAVA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: TBA

Date: 30 August 2019

Our Ref: CS/UOI19015156/Usd3

The Motor Claims Department
UNITED OVERSEAS INSURANCE LTD

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SDK 9933T .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 30/08/2019 at the premises of M/s Trans Eurokars Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$ <u>17,757.11</u> .
Revised Estimate Amount	: S\$ <u>8,134.18</u> .
"Check" Items Amount	: S\$ <u>34.74</u> .
Total	: S\$ <u>8,168.92</u> .
Market Value	: S\$ <u>77,000.00</u> .
LTA Reimbursement Value	: S\$ <u>58,084.00</u> .
Nett Value	: S\$ <u>18,916.00</u> .

Description of Damage:

The vehicle sustained damages at the n/s rear portion.



Comments/ Present Status:

Damages Consistent. Repair cost economical.
We have not authorize repair.
Repair days: 8 days

Yours faithfully

Marcus Chua
Automotive Assessor

Nivitha (LKK Auto)

From: LEW JENNY <jennylew@uoi.com.sg>
Sent: Tuesday, 27 August 2019 4:50 PM
To: 'ronald.yap@eurokars.com.sg'; assignments; SUR
Cc: 'jess.francis@eurokars.com.sg'
Subject: RE: ARRANGE FOR SURVEY / YOUR REF: SDK9933T
Attachments: 3790_190826183044_001.zip

Dear Ronald,

We will appoint LKK to survey the vehicle.

Dear Shiau Chan,

Please arrange to survey the vehicle at Trans Eurokars.
Excess: S\$750.00

Thank You.

Warmest Regards

Jenny Lew

Claims Division

United Overseas Insurance Limited

3 Anson Road, #28-01 Springleaf Tower, Singapore 079909
Main • (65) 6222 7733 | DID • (65) 6490 9329 | Fax • (65) 6327 3869 | Email • jennylew@uoi.com.sg

UOB EMAIL DISCLAIMER

Any person receiving this email and any attachment(s) contained, shall treat the information as confidential and not misuse, copy, disclose, distribute or retain the information in any way that amounts to a breach of confidentiality. If you are not the intended recipient, please delete all copies of this email from your computer system. As the integrity of this message cannot be guaranteed, neither UOB nor any entity in the UOB Group shall be responsible for the contents. Any opinion in this email may not necessarily represent the opinion of UOB or any entity in the UOB Group.

From: ronald.yap@eurokars.com.sg [mailto:ronald.yap@eurokars.com.sg]
Sent: Monday, 26 August, 2019 6:12 PM
To: LEW JENNY <jennylew@uoi.com.sg>
Cc: jess.francis@eurokars.com.sg
Subject: ARRANGE FOR SURVEY / YOUR REF: SDK9933T

Dear Jenny,

As attached / subject, kindly arrange the survey of your insured's car.

This is the 2nd OD claims.

Thank You,

*Ronald Yap
Insurance Claims*

Trans Eurokars Pte Ltd

5 Ubi Close, Singapore 408605

T: 6395 8899 H: 9127 7928

ronald.yap@eurokars.com.sg

This email, including any attachment, is intended for the sole use of the recipient(s) named above and may contain information that is confidential and/or proprietary to the Eurokars Group. If you have received it in error, please notify us immediately by reply email and then delete this message from your system. Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.

From: mazdacanon@mazda.com.sg <transeurokars@eurokars.com.sg>**Sent:** 26 August 2019 18:31**To:** Ronald Yap <ronald.yap@eurokars.com.sg>**Subject:** Attached Image

SDK 9933T OD (UOI) DOA - 23/08/2019

Shirley Hiew (LKK Auto)

Fri 30/8/2019 4:46 PM

To: ronald.yap@eurokars.com.sg <ronald.yap@eurokars.com.sg>

Cc: jess.francis@eurokars.com.sg <jess.francis@eurokars.com.sg>; SUR <sur@lkkauto.com>

 1 attachments (136 KB)

OD Template.pdf;

Hi Ronald,

As instructed by our client, please proceed to repair the insured vehicle **SDK 9933T (Excess S 750/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte LtdPhone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

RE: ARRANGE FOR SURVEY / YOUR REF: SDK9933T / M12D11431909

LEW JENNY <jennylew@uoi.com.sg>

Fri 30/8/2019 4:34 PM

To: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>

Cc: 'jess.francis@eurokars.com.sg' <jess.francis@eurokars.com.sg>; assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>

1 attachments (131 KB)

OD Template.zip;

Dear Shirley,

Please proceed to authorise the repair up to S\$8,168.92.

Excess: S\$750

Enclose the discharge voucher for client due execution.

Warmest Regards

Jenny Lew

Claims Division

United Overseas Insurance Limited

3 Anson Road, #28-01 Springleaf Tower, Singapore 079909

Main • (65) 6222 7733 | DID • (65) 6490 9329 | Fax • (65) 6327 3869 | Email • jennylew@uoi.com.sg

UOB EMAIL DISCLAIMER

Any person receiving this email and any attachment(s) contained, shall treat the information as confidential and not misuse, copy, disclose, distribute or retain the information in any way that amounts to a breach of confidentiality. If you are not the intended recipient, please delete all copies of this email from your computer system. As the integrity of this message cannot be guaranteed, neither UOB nor any entity in the UOB Group shall be responsible for the contents. Any opinion in this email may not necessarily represent the opinion of UOB or any entity in the UOB Group.

From: Shirley Hiew (LKK Auto) [mailto:ShirleyHiew@lkkauto.com]

Sent: Friday, 30 August, 2019 1:24 PM

To: LEW JENNY <jennylew@uoi.com.sg>

Cc: 'jess.francis@eurokars.com.sg' <jess.francis@eurokars.com.sg>; assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>

Subject: Re: ARRANGE FOR SURVEY / YOUR REF: SDK9933T

Dear Jenny,

Enclosed preliminary revised of vehicle SDK 9933T.

Date of survey: 30/08/2019

Number of days : 8 days

We have Not authorise repair.

Kindly let us have your approval and claim no. please.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

Re: ARRANGE FOR SURVEY / YOUR REF: SDK9933T

Shirley Hiew (LKK Auto)

Fri 30/8/2019 1:24 PM

To: LEW JENNY <jennylew@uoi.com.sg>

Cc: 'jess.francis@eurokars.com.sg' <jess.francis@eurokars.com.sg>; assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>

 1 attachments (81 KB)

PRELI ADVISE - SDK 9933T.pdf;

Dear Jenny,

Enclosed preliminary revised of vehicle SDK 9933T.

Date of survey: 30/08/2019

Number of days : 8 days

We have Not authorise repair.**Kindly let us have your approval and claim no. please.**

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte LtdPhone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: LEW JENNY <jennylew@uoi.com.sg>**Sent:** Tuesday, 27 August 2019 4:49 PM**To:** 'ronald.yap@eurokars.com.sg' <ronald.yap@eurokars.com.sg>; assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>**Cc:** 'jess.francis@eurokars.com.sg' <jess.francis@eurokars.com.sg>**Subject:** RE: ARRANGE FOR SURVEY / YOUR REF: SDK9933T

Dear Ronald,

We will appoint LKK to survey the vehicle.

Dear Shiau Chan,

Please arrange to survey the vehicle at Trans Eurokars.

Excess: S\$750.00

Thank You.

Warmest Regards

Jenny Lew

Claims Division

United Overseas Insurance Limited

3 Anson Road, #28-01 Springleaf Tower, Singapore 079909

Main • (65) 6222 7733 | DID • (65) 6490 9329 | Fax • (65) 6327 3869 | Email • jennylew@uoi.com.sg**UOB EMAIL DISCLAIMER**

Any person receiving this email and any attachment(s) contained, shall treat the information as confidential and not misuse, copy, disclose, distribute or retain the information in any way that amounts to a breach of confidentiality. If you are not the intended recipient, please delete all copies of this email from your computer system. As the integrity of this message cannot be guaranteed, neither UOB nor any entity in the UOB Group shall be responsible for the contents. Any opinion in this email may not necessarily represent the opinion of UOB or any entity in the UOB Group.

From: ronald.yap@eurokars.com.sg [<mailto:ronald.yap@eurokars.com.sg>]**Sent:** Monday, 26 August, 2019 6:12 PM**To:** LEW JENNY <jennylew@uoi.com.sg>**Cc:** jess.francis@eurokars.com.sg**Subject:** ARRANGE FOR SURVEY / YOUR REF: SDK9933T

Dear Jenny,

As attached / subject, kindly arrange the survey of your insured's car.

This is the 2nd OD claims.

Thank You,

Ronald Yap
Insurance Claims

Trans Eurokars Pte Ltd

5 Ubi Close, Singapore 408605

T: 6395 8899 H: 9127 7928

ronald.yap@eurokars.com.sg

This email, including any attachment, is intended for the sole use of the recipient(s) named above and may contain information that is confidential and/or proprietary to the Eurokars Group. If you have received it in error, please notify us immediately by reply email and then delete this message from your system. Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.

From: mazdacanon@mazda.com.sg <transeurokars@eurokars.com.sg>**Sent:** 26 August 2019 18:31**To:** Ronald Yap <ronald.yap@eurokars.com.sg>**Subject:** Attached Image

車之道 **CARWAY** **31 AUGUST-1 SEPTEMBER @ DOWNTOWN EAST** **THE ULTIMATE PRE-OWNED SALES**
ENJOY HUGE SAVINGS + FREE SERVICE & WARRANTY + FREE GROOMING

Post an Advertisement
 Sell it yourself! Advertise it at just **\$58 until it's SOLD!**

Post an Ad Advertiser Login Ways of Selling

Lexus LS350 Luxury MR at \$329,800.



5Yrs Warranty By Borneo Motor, Very Low Mileage, Immaculate Condition, Call Now! Speedo Motoring StarAd

- Free VICOM evaluation
- Free grooming and 6 months
- In-house workshop ensures
- Member of SVTA and hire p
- 100% deposit refund for unc



Browse by Category

Sort by Date Posted

12 vehicles

mazda 6

Advanced Search

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	V
Search Selection	mazda 6	Any	Any	2016	Any	Any	



Mazda 6 2.0A **\$77,800** \$9,610 /yr 26-Jul-2016 1,998 cc 71,867 km
 Special Offer 1.5% Interest Rate! 1 Owner With Immaculate Condition, Grand Luxury Sedan, Classy White Exterior, Spacious Legroom, Large Boots Space, Must View Act Fast! Call/Watsapp/Msg For Viewing Appointment

Republic Auto

Posted: 30-Aug-2019 Tags: 2016 Mazda 6, 2016 mazda 6, Mazda 6, mazda 6, Mazda, 6, Used Mazda



Mazda 6 2.5A **\$79,800** \$10,070 /yr 15-Apr-2016 2,488 cc 45,000 km
 Graded **B** by **STP**
 1 Owner, Immaculate, Best Condition In Town! Black On Black Interior! Low Mileage Done! Fully Maintained By Agent Since Day 1. Call Now To View/Test Drive Today.

SKL Automobile Pte Ltd

Posted: 26-Aug-2019 Tags: 2016 Mazda 6, 2016 mazda 6, Mazda 6, mazda 6, Mazda, 6, Used Mazda



Mazda 6 2.0A Executive **\$83,800** \$10,370 /yr 29-Aug-2016 1,998 cc 37,419 km
 Sporty Black High Spec Executive Model. 1 Owner, Low Mileage Done At 37419km. Agent Unit With Warranty Complete Agent Service History! Still In Original Paintwork And Condition. Tip Top Condition. 100% Accident Free. Call Now For Viewing.

Posted: 24-Aug-2019 Tags: 2016 Mazda 6, 2016 mazda 6, Mazda 6, mazda 6, Mazda, 6, Used Mazda



Mazda 6 2.5A **\$78,800** \$10,370 /yr 20-Jan-2016 2,488 cc 67,000 km
 Immaculate Condition, 1 Owner, Classy White Exterior, Road Tax Till Jan 2020, Attractive Interest Rate Of 2.28% Available, Loan/Trade Welcome, Contact Us For An Appointment Now!

Posted: 23-Aug-2019 Tags: 2016 Mazda 6, 2016 mazda 6, Mazda 6, mazda 6, Mazda, 6, Used Mazda

Car Buying

Car Selling

Car Ownership

Car Aftermarket

On The Move

Lifestyle



Mazda 6 2.0A **\$72,800** \$9,750 /yr 19-Jan-2016 1,998 cc
 1 Owner Only! Well Maintained, Unit In Excellent Condition! Don't Miss This Unit! Bank Or In House Loan Available. Call For More Enquiries!

Posted: 17-Aug-2019 Tags: 2016 Mazda 6, 2016 mazda 6, Mazda 6, mazda 6, Mazda, 6, Used Mazda

Compare

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	358F
Vehicle Details	
Vehicle No.:	SDK9933T
Vehicle to be Exported:	No
Intended Deregistration Date:	30 Aug 2019
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA6 4-DOOR SEDAN 2.0L SP.6EAT
Primary Colour:	Blue
Manufacturing Year:	2016
Engine No.:	PE20795877
Chassis No.:	JM6GJ1072G0242242
Maximum Power Output:	121.0 kW (162 bhp)
Open Market Value:	\$23,210.00
Original Registration Date:	28 Jul 2016
First Registration Date:	28 Jul 2016
Transfer Count:	0
Actual ARF Paid:	\$24,494.00 <i>12247</i>
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	27 Jul 2026
PARF Rebate Amount:	\$18,370.00
Intended COE Rebate Details	
COE Expiry Date:	27 Jul 2026
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$57,508.00
COE Rebate Amount:	\$39,714.00
Total Rebate Amount:	\$58,084.00

The information contained herein is correct as at 30 Aug 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	26/08/2019 13:47
Date Of Accident	23/08/2019 17:30
Exact Location Of Accident	KATONG PLAZA MULTI STOREY CARPARK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SDK9933T
Insured/Policyholder	
Name Of Registered Owner	LIM CHUY YOKE
NRIC No	S1540358F
Email Address	PETERLIM3000@GMAIL.COM
Mobile Phone No	(LOCAL) +65-97393960
Alternative Phone No	OFFICE-97393960

Vehicle Particulars

Manufacturer	MAZDA
Model	MAZDA6 4-DOOR SEDAN 2.0L SP.6EAT
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	UNITED OVERSEAS INSURANCE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DHOM120044251900
Cover Note Number	-

Driver

Name of Driver	LIM CHUY YOKE
NRIC No	S1540358F
Date Of Birth	03/01/1962
Occupation	OUTDOOR
Date Of Driving Pass	02/06/1981
Driving Experience	38 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97393960
Fax Number	
Contact Number	OFFICE-97393960
Email Address	PETERLIM3000@GMAIL.COM

Address	134 ST PATRICK RD #03-16
Postcode	424213
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLIDED INTO PROPERTY
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	1
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO STATEMENT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	WITH DRIVER
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	WALL
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	GOVERNMENT
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to reassess policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the (GIA) Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

3. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NIC/TIN No.:

Accident Sketch Plan

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

While turning down from the Katong Plaza multi storey carpark. My Vch left hand side accidentally grazed onto the left side wall

DECLARATION

I/we declare the foregoing particulars are true in every respect.


Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/IN No.:

62864315

LKH
20 Aug 11/11/11



TRANS EUROKARS PTE LTD

EUROKARS GROUP

ESTIMATE COST OF REPAIRS

not allowed

UNITED OVERSEAS INSURANCE LTD 3 ANSON ROAD #28-01 SPRINGLEAF TOWER SINGAPORE C70909 ATTN: MOTOR CLAIMS FAX:		NAME: Mr Lim Chuy Yoke ADDRESS: No. 134 St. Patrick's Road #03-16 Singapore 424213 TEL: 97393960	WIP: 61468 EXCESS: DATE: 26-Aug-19
VEH NO: SDK9933T	DATE IN:	CONTACT PERSON: Ronald 63957875	
CHASSIS NO: JM6G1072G0242242	MILEAGE:	TYPE OF CLAIM: THIRD PARTY CLAIM	<i>OP</i>
MODEL: MAZDA6	DATE REG.: 28-Jul-15	POLICY NO.:	

NATURE OF WORKS

Parts Description

NO	QTY	REVISED	PRICES
1	REAR BUMPER <i>claims only</i> 1	MGJR9-50-221ABB	1.1 \$ 1,231.50
2	RETAINER LHS 1	MGJR9-50-2J1	1.1 \$ 41.00
3	BRACKET CENTER 1	MKD53-50-2S1	1.1 \$ 5.40
4	SHIELD SPLASH LHS 1	MGHP9-50-350D	1.1 \$ 45.60
5	FASTENER, REAR BUMPER 6	MB45A-56-146A	1.1 \$ 18.00
6	GROMMET, REAR BUMPER 6	MH260-50-341	1.1 \$ 18.00
7	GROMMET, REAR BUMPER 2	M9991-00-501	1.1 \$ 6.00
8	CLIP, REAR BUMPER 4	MC274-50-133	1.1 \$ 14.80
9	REAR FENDER LHS 1	MGHY3-71-41X	1.1 \$ 1,312.50
10	GUARD STONE LHS 1	MGHP9-50-4R2A	1.1 \$ 17.40
11	REAR WINDSCREEN MOULDING 2	MGHK1-50-611B	1.1 \$ 117.10
12	SPACER, REAR WINDSCREEN 1	MGJ6A-50-897	1.1 \$ 12.80
13	REAR DOOR LHS 1	MGHY1-73-02XB	1.1 \$ 1,312.10
14	FASTENER, REAR DOOR 1	MGHP9-58-762A	1.1 \$ 3.20
15	FASTENER, REAR DOOR 1	MBBM6-58-762	1.1 \$ 3.20
16	FASTENER, REAR DOOR 1	MGHP9-73-762	1.1 \$ 12.30
17	GROMMET, REAR DOOR 2	MBF67-51-261	1.1 \$ 4.80
18	GROMMET, REAR DOOR 1	M9991-00-503	1.1 \$ 3.80
19	GROMMET, REAR DOOR 7	MGJ6A-58-975	1.1 \$ 21.00
20	FASTENER, REAR DOOR 1	MGD7A-50-EA1	1.1 \$ 3.20
21	CLIP, REAR DOOR 1	MGS1D-58-315A	1.1 \$ 2.40
22	STRIPE TOP LHS, REAR DOOR 1	MGHK1-50-8W4 00	1.1 \$ 23.90
23	STRIPE SIDE LHS, REAR DOOR 1	MGHP9-50-8W2 00	1.1 \$ 14.70
24	CLIP, DOOR GARNISH 8	MKD53-50-M38	1.1 \$ 98.40
25	CLIP, DOOR GARNISH 3	MTD11-51-SJ9A	1.1 \$ 36.00
26	GROMMET, REAR DOOR 7	MGJ6A-58-975	1.1 \$ 21.00
27	COVER HOLE LHS, ROCKER PANEL 1	MBBM4-56-061	1.1 \$ 11.40
28	REAR WHEEL RIM LHS 1	M9965-07-7570	1.1 \$ 1,341.00
29	GASKET LHS, TAILLAMP 1	MGJA1-51-163	1.1 \$ 27.70
30	GASKET RHS, TAILLAMP 1	MGJA1-51-153	1.1 \$ 27.70

		TOTAL PARTS		\$ 5,807.90
		LESS 10%		\$ 580.79
		TOTAL PARTS COST		\$ 5,227.11
<u>Labour Description</u>				
1	MZ-BR-FRONT1	TO REPLACE REAR BUMPER, REAR FENDER LH, REAR DOOR LH. TO REPAIR REAR WHEEL ARCH INNER LH AND ALL AREAS AFFECTED BY THE ACCIDENT. <i>660</i>	<i>1980</i>	\$ 4,290.00
2	MZ-SP-SFRTO1	TO RESPRAY REAR BUMPER, REAR FENDER LH, REAR DOOR LH AND REAR WHEEL ARCH INNER LH. (TO BLEND ROCKER PANEL LH AND CENTER PILLAR LH) <i>630</i>	<i>1890</i>	\$ 3,780.00
3	MZ-BR-GLASS1	TO REMOVE & REFIT THE WINDSCREEN GLASS AND CONDUCT WATER LEAK TEST.	NETT	\$ 560.00
4	MZ-BR-GLASS2	TO SUPPLY SEALER ON THE WINDSCREEN GLASS. <i>net</i>	NETT	\$ 120.00
5	MZ-BR-DOORME	TO TRANSFER THE DOOR MECHANISM.	NETT	\$ 330.00
6		TO SUPPLY 1 PC TIRE. <i>11</i>	X	\$ 480.00
7	MZ-BR-WHEBAL	TO MOUNT SPORT RIM AND CONDUCT WHEEL BALANCING. <i>11</i>	X NETT	\$ 120.00
8	MZ-BR-WHEAL	TO CHECK STEERING GEOMETRY & CONDUCT FULL WHEEL ALIGNMENT. <i>11</i>	X NETT	\$ 560.00
9	MZ-BR-TRIMS2	TO REMOVE & REFIT CARPET & TRIMS ON THE REAR SECTION TO GIVE WAY TO THE REPAIR ON THE REAR SECTION.	<i>200</i>	\$ 990.00
10	MZ-BR-SEALER	TO SUPPLY SPRAY TEROSTAT SEALANT ON THE CUTTING	<i>120</i>	\$ 350.00
11	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.	<i>150</i>	\$ 250.00
12	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	<i>120</i>	\$ 250.00
13	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	<i>111 X</i>	\$ 350.00
14		TO SUPPLY BODY COATING. <i>111 X</i>	NETT	TBA
15	MZ-BR-SUNDRI	SUNDRIES. <i>111 X</i>	NETT	\$ 100.00
		TOTAL LABOUR	\$ -	\$ 12,530.00
		TOTAL PARTS	\$ -	\$ 5,227.11
		TOTAL	\$ -	\$ 17,757.11
		LESS EXCESS	\$ -	\$ -
		TOTAL AFTER EXCESS	\$ -	
		GST 7%	\$ -	\$ -
		GRAND TOTAL	\$ -	\$ -



TRANS EUROKARS PTE LTD



ESTIMATE COST OF REPAIRS

62564315

LKH
30 Aug 11/14/14

not allowed

UNITED OVERSEAS INSURANCE LTD 3 ANSON ROAD #28-01 SPRINGLEAF TOWER SINGAPORE 079909 ATTN : MOTOR CLAIMS FAX :		NAME : Mr Lim Chuy Yoke ADDRESS : No. 134 St. Patrick's Road #03-16 Singapore 424213 TEL : 97393960	WIP : 61468 EXCESS : DATE: 26-Aug-19
VEH NO :	SDK9933T	DATE IN :	CONTACT PERSON : Ronald 63957875
CHASSIS NO :	JM6GJ1072G0242242	MILEAGE :	TYPE OF CLAIM : THIRD-PARTY CLAIM <i>OP</i>
MODEL :	MAZDA6	DATE REG.:	POLICY NO. :

EXCESS \$ 750

when the before policy

NATURE OF WORKS

Parts Description

NO	QTY	REVISED	PRICES
1	REAR BUMPER <i>cleans already</i> 1	MGJR9-50-221ABB	17 \$ 1,231.50
2	RETAINER LHS 1	MGJR9-50-2J1	17 \$ 41.00
3	BRACKET CENTER 1	MKD53-50-251	17 \$ 5.40
4	SHIELD SPLASH LHS 1	MGHP9-50-350D	17 \$ 45.60
5	FASTENER, REAR BUMPER 6	MB45A-56-146A	17 \$ 18.00
6	GROMMET, REAR BUMPER 6	MH260-50-841	17 \$ 18.00
7	GROMMET, REAR BUMPER 2	M9991-00-501	17 \$ 6.00
8	CLIP, REAR BUMPER 4	MC274-50-133	17 \$ 14.80
9	REAR FENDER LHS 1	MGHY3-71-41X	10/24 \$ 1,312.50
10	GUARD STONE LHS 1	MGHP9-50-4R2A	17 \$ 17.40
11	REAR WINDSCREEN MOULDING 1	MGHK1-50-611B	17 \$ 117.10
12	SPACER, REAR WINDSCREEN 1	MGJ6A-50-897	17 \$ 12.80
13	REAR DOOR LHS 1	MGHY1-73-02XB	10/24 \$ 1,312.10
14	FASTENER, REAR DOOR 1	MGHP9-58-762A	17 \$ 3.20
15	FASTENER, REAR DOOR 1	MBBM6-58-762	17 \$ 3.20
16	FASTENER, REAR DOOR 1	MGHP9-73-762	17 \$ 12.30
17	GROMMET, REAR DOOR 2	MBF67-51-261	17 \$ 4.80
18	GROMMET, REAR DOOR 1	M9991-00-503	17 \$ 3.80
19	GROMMET, REAR DOOR 7	MGJ6A-58-975	17 \$ 21.00
20	FASTENER, REAR DOOR 1	MGD7A-50-EA1	17 \$ 3.20
21	CLIP, REAR DOOR 1	MGS1D-58-315A	17 \$ 2.40
22	STRIPE TOP LHS, REAR DOOR 1	MGHK1-50-8W4 00	17 \$ 23.90
23	STRIPE SIDE LHS, REAR DOOR 1	MGHP9-50-8W2 00	17 \$ 14.70
24	CLIP, DOOR GARNISH 8	MKD53-50-M38	17 \$ 98.40
25	CLIP, DOOR GARNISH 3	MTD11-51-SJ3A	17 \$ 36.00
26	GROMMET, REAR DOOR 7	MGJ6A-58-975	17 \$ 21.00
27	COVER HOLE LHS, ROCKER PANEL 1	MBBM4-56-061	17 \$ 11.40
28	REAR WHEEL RIM LHS 1	M9965-07-7570	17 \$ 1,341.00
29	GASKET LHS, TAILLAMP 1	MGJA1-51-163	17 \$ 27.70
30	GASKET RHS, TAILLAMP 1	MGJA1-51-153	17 \$ 27.70

REMARKS:

*THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A **QUOTATION FEE OF \$400** WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.*

Authorised Signature



TRANS EUROKARS PTE LTD



FINALISED COST OF REPAIRS

UNITED OVERSEAS INSURANCE LTD 3 ANSON ROAD #28-01 SPRINGLEAF TOWER SINGAPORE 079909 ATTN. : MOTOR CLAIMS FAX :		NAME : Mr Lim Chuy Yoke ADDRESS : No. 134 St. Patrick's Road #03-16 Singapore 424213 TEL : 97393960		WIP : 61468 EXCESS : \$ 750.00 DATE: 26-Aug-19	
VEH NO :	SDK9933T	DATE IN :		CONTACT PERSON :	Ronald 63957875
CHASSIS NO :	JM6GJ1072G0242242	MILEAGE :		TYPE OF CLAIM :	THIRD PARTY CLAIM
MODEL :	MAZDA6	DATE REG.:	28-Jul-16	POLICY NO. :	
NATURE OF WORKS					
Parts Description					
NO	QTY			REVISED	PRICES
1	REAR BUMPER	1	MGJR9-50-221ABB		\$ 1,231.50
2	RETAINER LHS	1	MGJR9-50-2J1		\$ 41.00
3	BRACKET CENTER	1	MKD53-50-251		\$ 5.40
4	SHIELD SPLASH LHS	1	MGHP9-50-350D		\$ 45.60
5	FASTENER, REAR BUMPER	6	MB45A-56-146A		\$ 18.00
6	GROMMET, REAR BUMPER	6	MH260-50-841		\$ 18.00
7	GROMMET, REAR BUMPER	2	M9991-00-501		\$ 6.00
8	CLIP, REAR BUMPER	4	MC274-50-133		\$ 14.80
9	REAR FENDER LHS	1	MGHY3-71-41X	\$ 1,312.50	\$ 1,312.50
10	GUARD STONE LHS	1	MGHP9-50-4R2A	\$ 17.40	\$ 17.40
11	REAR WINDSCREEN MOULDING	1	MGHK1-50-611B	\$ 117.10	\$ 117.10
12	SPACER, REAR WINDSCREEN	1	MGJ6A-50-897	\$ 12.80	\$ 12.80
13	REAR DOOR LHS	1	MGHY1-73-02XB	\$ 1,312.10	\$ 1,312.10
14	FASTENER, REAR DOOR	1	MGHP9-58-762A	\$ 3.20	\$ 3.20
15	FASTENER, REAR DOOR	1	MBBM6-58-762	\$ 3.20	\$ 3.20
16	FASTENER, REAR DOOR	1	MGHP9-73-762	\$ 12.30	\$ 12.30
17	GROMMET, REAR DOOR	2	MBF67-51-261	\$ 4.80	\$ 4.80
18	GROMMET, REAR DOOR	1	M9991-00-503	\$ 3.80	\$ 3.80
19	GROMMET, REAR DOOR	7	MGJ6A-58-975	\$ 21.00	\$ 21.00
20	FASTENER, REAR DOOR	1	MGD7A-50-EA1	\$ 3.20	\$ 3.20
21	CLIP, REAR DOOR	1	MGS1D-58-315A	\$ 2.40	\$ 2.40
22	STRIPE TOP LHS, REAR DOOR	1	MGHK1-50-8W4 00	\$ 23.90	\$ 23.90
23	STRIPE SIDE LHS, REAR DOOR	1	MGHP9-50-8W2 00	\$ 14.70	\$ 14.70
24	CLIP, DOOR GARNISH	8	MKD53-50-M38	\$ 98.40	\$ 98.40
25	CLIP, DOOR GARNISH	3	MTD11-51-SJ3A	\$ 36.00	\$ 36.00
26	GROMMET, REAR DOOR	7	MGJ6A-58-975		\$ 21.00
27	COVER HOLE LHS, ROCKER PANEL	1	MBBM4-56-061		\$ 11.40
28	REAR WHEEL RIM LHS	1	M9965-07-7570		\$ 1,341.00
29	GASKET LHS, TAILLAMP	1	MGJA1-51-163		\$ 27.70
30	GASKET RHS, TAILLAMP	1	MGJA1-51-153		\$ 27.70

		TOTAL PARTS	\$ 2,998.80	\$ 5,807.90	
		LESS 10%	\$ 299.88	\$ 580.79	
		TOTAL PARTS COST	\$ 2,698.92	\$ 5,227.11	
Labour Description					
1	MZ-BR-FRONT1	TO REPLACE REAR FENDER LH, REAR DOOR LH. TO REPAIR REAR WHEEL ARCH INNER LH AND ALL AREAS AFFECTED BY THE ACCIDENT.	\$ 1,980.00	\$ 4,290.00	
2	MZ-SP-SFRT01	TO RESPRAY REAR FENDER LH, REAR DOOR LH AND REAR WHEEL ARCH INNER LH. (TO BLEND ROCKER PANEL LH AND CENTER PILLAR LH)	\$ 1,890.00	\$ 3,780.00	
3	MZ-BR-GLASS1	TO REMOVE & REFIT THE WINDSCREEN GLASS AND CONDUCT WATER LEAK TEST.	\$ 560.00	\$ 560.00	
4	MZ-BR-GLASS2	TO SUPPLY SEALER ON THE WINDSCREEN GLASS.	\$ 120.00	\$ 120.00	
5	MZ-BR-DOORME	TO TRANSFER THE DOOR MECHANISM.	\$ 330.00	\$ 330.00	
6		TO SUPPLY 1 PC TIRE.		\$ 480.00	
7	MZ-BR-WHEBAL	TO MOUNT SPORT RIM AND CONDUCT WHEEL BALANCING		\$ 120.00	
8	MZ-BR-WHEALI	TO CHECK STEERING GEOMETRY & CONDUCT FULL WHEEL ALIGNMENT.		\$ 560.00	
9	MZ-BR-TRIMS2	TO REMOVE & REFIT CARPET & TRIMS ON THE REAR SECTION TO GIVE WAY TO THE REPAIR ON THE REAR SECTION.	\$ 200.00	\$ 990.00	
10	MZ-BR-SEALER	TO SUPPLY SPRAY TEROSTAT SEALANT ON THE CUTTING	\$ 120.00	\$ 350.00	
11	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.	\$ 150.00	\$ 250.00	
12	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.		\$ 250.00	
13	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.		\$ 350.00	
14		TO SUPPLY BODY COATING..		TBA	
15	MZ-BR-SUNDRI	SUNDRIES.		\$ 100.00	
			TOTAL LABOUR	\$ 5,350.00	\$ 12,530.00
			TOTAL PARTS	\$ 2,698.92	\$ 5,227.11
			TOTAL	\$ 8,048.92	\$ 17,757.11
			LESS EXCESS	\$ 750.00	\$ -
			TOTAL AFTER EXCESS	\$ 7,298.92	
			GST 7%	\$ 510.92	\$ -
			GRAND TOTAL	\$ 7,809.84	\$ -

REMARKS:

8 REPAIR DAYS (exclude preparation of estimate, wait for survey/authorization)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
UNITED OVERSEAS INSURANCE LTD			Ref : CS/UOI19015156/Usd3n2	
3 ANSON ROAD #28-01 SPRINGLEAF TOWER SINGAPORE 079909			Date : 11-10-2019	
			Code : UOI2	
1. Policy Particulars :- OWN DAMAGE				
	Insured Veh.	Veh. Inspected	SDK 9933T	
	Policy No. DHOM120044251900	Coverage (\$)	0.00	
	Claim No. M12D11431909	Excess (\$)	750.00	
	Assign From JENNY LEW	Assign Date	27/08/2019	
2. Vehicle Particulars & Condition				
	Make & Model MAZDA 6 (A)	c.c	1998	
	Engine No. HIDDEN	Year of Reg.	2016	
	Chassis No. JM6GJ1072G0242242	Colour	BLUE	
	Odometer 76900	Steering	IN ORDER	
	Brakes IN ORDER	Modification	SPORTS RIM	
	General GOOD			
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	225/55 R17	YOKOHAMA	6 mm
	L/H Front Tyre	225/55 R17	YOKOHAMA	6 mm
	R/H Rear Tyre	225/55 R17	YOKOHAMA	6 mm
	L/H Rear Tyre	225/55 R17	YOKOHAMA	6 mm
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
	Accident Date 23/08/2019	Inspection Date	30/08/2019	
	Survey held at TRANS EUROKARS PTE LTD NO 5 UBI CLOSE SINGAPORE 408605			
5a. Remarks				
A) THE MARKET VALUE IS S\$77,000.00 (EST. AVERAGE) B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			8 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SDK 9933T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	NOT NECESSARY	1,231.50	-
1	RETAINER LHS	NOT NECESSARY	41.00	-
1	BRACKET CENTER	NOT NECESSARY	5.40	-
1	SHIELD SPLASH LHS	NOT NECESSARY	45.60	-
6	FASTENER,REAR BUMPER	NOT NECESSARY	18.00	-
6	GROMMET,REAR BUMPER	NOT NECESSARY	18.00	-
2	GROMMET,REAR BUMPER	NOT NECESSARY	6.00	-
4	CLIP,REAR BUMPER	NOT NECESSARY	14.80	-
1	REAR FENDER LHS	BADLY DENTED	1,312.50	1,312.50
1	GUARD STONE LHS	NECESSARY	17.40	17.40
1	REAR WINDSCREEN MOULDING	NECESSARY	117.10	117.10
1	SPACER,REAR WINDSCREEN	NECESSARY	12.80	12.80
1	REAR DOOR LHS	DENTED / BENT	1,312.10	1,312.10
1	FASTENER,REAR DOOR	NECESSARY	3.20	3.20
1	FASTENER,REAR DOOR	NECESSARY	3.20	3.20
1	FASTENER,REAR DOOR	NECESSARY	12.30	12.30
2	GROMMET,REAR DOOR	NECESSARY	4.80	4.80
1	GROMMET,REAR DOOR	NECESSARY	3.80	3.80
7	GROMMET,REAR DOOR	NECESSARY	21.00	21.00
1	FASTENER,REAR DOOR	NECESSARY	3.20	3.20
1	CLIP,REAR DOOR	NECESSARY	2.40	2.40
1	STRIPE TOP LHS,REAR DOOR	NECESSARY	23.90	23.90
1	STRIPE SIDE LHS,REAR DOOR	NECESSARY	14.70	14.70
8	CLIP,DOOR GARNISH	NECESSARY	98.40	98.40
3	CLIP,DOOR GARNISH	NECESSARY	36.00	36.00
7	GROMMET,REAR DOOR	NOT NECESSARY	21.00	-
1	COVER HOLE LHS,ROCKER PANEL	NOT NECESSARY	11.40	-
1	REAR WHEEL RIM LHS	NOT NECESSARY	1,341.00	-
1	GASKET LHS,TAILLAMP	NOT NECESSARY	27.70	-
1	GASKET RHS,TAILLAMP	NOT NECESSARY	27.70	-
	LESS 10% DISCOUNT		-580.79	-299.88
			5,227.11	2,698.92



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	SPECIAL NETT ITEMS			
1	SUNDRIES (SN)	NOT NECESSARY	100.00	-
1	TO SUPPLY 1 PC TIRE (SN)	NOT NECESSARY	480.00	-
			580.00	-
	LABOUR			
	TO SUPPLY SEALER ON THE WINDSCREEN GLASS.		120.00	120.00
	TO SUPPLY BODY COATING.(NPA)	NOT NECESSARY	-	-
	TO REPLACE REAR BUMPER,REAR FENDER LH,REAR DOOR LH.TO REPAIR REAR WHEEL ARCH INNER LH AND ALL AREAS AFFECTED BY THE ACCIDENT.		4,290.00	1,980.00
	TO RESPRAY REAR FENDER LH,REAR DOOR LH AND REAR WHEEL ARCH INNER LH.(TO BLEND ROCKER PANEL LH AND CENTER PILLAR LH).		3,780.00	1,890.00
	TO REMOVE & REFIT THE WINDSCREEN GLASS AND CONDUCT WATER LEAK TEST.		560.00	560.00
	TO TRANSFER THE DOOR MECHANISM.		330.00	330.00
	TO MOUNT SPORT RIM AND CONDUCT WHEEL BALANCING.	NOT NECESSARY	120.00	-
	TO CHECK STEERING GEOMETRY & CONDUCT FULL WHEEL ALIGNMENT.	NOT NECESSARY	560.00	-
	TO REMOVE & REFIT CARPET & TRIMS ON THE REAR SECTION TO GIVE WAY TO THE REPAIR ON THE REAR SECTION.		990.00	200.00
	TO SUPPLY SPRAY TEROSTAT SEALANT ON THE CUTTING.		350.00	120.00
	TO CARRY-OUT BODY CAVITY PRESERVATION.		250.00	150.00
	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	NOT NECESSARY	250.00	-
	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	NOT NECESSARY	350.00	-
			11,950.00	5,350.00
	GRAND TOTAL		17,757.11	8,048.92
	RECOMMENDED COST OF REPAIRS			8,048.92
	LESS EXCESS			-750.00
	NETT LIABILITY			7,298.92

Report Ref No. CS/UOI19015156/Usd3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.