

輝陽汽車有限公司 HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721
Tel: 64515752 (2 Lines) . Fax: 64514658
GST & Reg No. 201629438M

Indva
(LKK)
Kenneth
21/08/19
(Tuesday)

18/08/2019

Owner: LOH HUI SUAN

Not Notarised

Money After Paint
3 day

ESTIMATE TO REPAIR HONDA STREAM 1.8X - SJP2407U

1pc	rear RH door	R	\$	850.20	}	X
2pcs	rear RH door sticker @\$125.25	rr	\$	250.50		
1pc	rear RH inner rubber	rr	\$	185.50		
1pc	rear RH inner lock	R	\$	285.00		
1pc	rear RH fender	R	\$	952.50		
1pc	rear RH knuckle arm	rr	\$	267.40		
1pc	rear RH knuckle arm bearing	rr	\$	119.30		
1pc	rear RH lower arm	rr	\$	328.40		
1pc	rear RH absorber	rr	\$	328.60		
				<u>\$ 3,567.40</u>		
	less 20%			<u>\$ 713.48</u>		
	balance c/f			<u>\$ 2,853.92</u>		

1pc front RH sport rim *nd* s.nett \$ 550.00 *3800*

alignment	\$	80.00	<i>601</i>
remove & refit rear RH undercarriage	rr	\$ 380.00	<i>X</i>
remove & refit rear RH door glass & rear RH fender glass	rr	\$ 200.00	<i>X</i>
wiring	\$	120.00	<i>152</i>
tuffkote	rr	\$ 120.00	<i>X</i>
spray painting	\$	800.00	<i>4000</i>
labour charges	\$	1,000.00	<i>3000</i>
Total	\$	6,103.92	



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____