

ASS. REC. BY:

REF: CS/Smo19015163/ Rwf3

Special Instruction:

n2

Surveyor: RasuASSIGNMENT (Office)From (Person): Chan Shu Hui Agnes of Smo Date/Time: 28/08/2019

Merimen

Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLH 2129R Insured: FZ 2554Yat Workshop m/s Teamwork Garage Pte Ltd Tel: 6544 2475of 53 Ubi Ave 1 #01-24Policy No: D18MTMC01008316 Claim No: CMTD1904073

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

Make of Veh: \_\_\_\_\_ D.O.A. 25/08/2019  
(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement: \_\_\_\_\_

Date/Time: 9:45 a.m @ 28/08/2019 Person Contacted: Darren Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	FZ 2554Y NA/LIP19015015/24 D.O.A. 25/08/2019
	SLH 2129R NA/LIP19015015/24 D.O.A. 25/08/2019
29/8/19	Send preli revised via merimen
5/9/19	Rasu said part prices - OK
11/9/19	LS \$1650 confirmed by email (Red 5325.53, 769)

REF: sm0

7222

## ASSIGNMENT

From:

Date:

28.8.2019

Veh No.

SLH 2129R

Yt Regn:

2016 / 04

Estim. Net Cost:

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or

To inspect Vehicle No.

SLH 2129R

Make:

TOYOTA COROLLA ALTIS CLASSIC 1.6 1598

at Workshop n/s

Teamwork

Colour:

GREEN

A/C:

Insured / Std / NI / NA

of

53 ubi Ave 1 #01-24

Sp. Reading

152699

T/Radio:

Insured / Std / NI / NA

Insured

Eng/No:

Policy No.

C/No:

MRO53REH 104552052

Claims No.

Gen. Cond: Good / Fair / Poor / Burnt

Sum Insured:

Excess:

Steering: Morder / Jammed / Leaked / Burnt or

(Client's Record)

Brake: Morder / Jammed / Leaked / Burnt or

Make of Veh:

Modi: Nil / S/Rim / STD A/Rim or

(Policy Condition)


Tyre Size:

F:

205/55R16

R:

Remark: The veh had commenced its repair at the time of inspection.



BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

GITI

Bal. or Market Value:

Front

Rear

IDAC Accident Rpt:

Consistent? : Yes or No

R/Bal.

6

mm

R/Bal.

6

mm

GIA / PR Seen:

Consistent? : Yes or No

L/Bal.

6

mm

L/Bal.

6

mm

Est. Repairs:

days

Res.: Yes or No

D.O.A.

28/08/19

D.O.I.

28/08/19

Lum Sum:

%

3 Val.: Yes or No

Survey held at

Teamwork

CA / REV / REP. / 24 HRS

rup'

Vehicle: IN / OUT

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear O/S

Date:

Person Contacted:

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

RECEIVED 11 SEP 2019

Date/Time, File Pass to?

☐

Preli. Report

Days Of Repair:

4

1)

☐

Final Report

Resurvey No. of Trip:

1

Survey Fee:

Date/Time, File Return to?

Transportation

2) 11/9- typist

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Invs (\$)

☐

Weekend (\$)

Photos

Others

Report Format:

merimen

Lump Sum / L.B.I. (\$)

1650/2

TOTAL

250  
11

261

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Sompoo Insurance Singapore Pte. Ltd.  
50 Raffles Place  
#05-01/06, Singapore Land Tower  
Singapore 048623

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: CHAN SHU HUI AGNES

Date: 29 Aug 2019

**Preliminary Advice**

Insured Vehicle No	: FZ2554Y	Accident Date	: 25/08/2019
TP Vehicle No	: SLH2129R	Assignment Date	: 28/08/2019
Make	: TOYOTA COROLLA ALTIS	Est. Duration of Repair	:
Date of Inspection	: 28/8/2019		
Inspection At	: TEAMWORK GARAGE PTE LTD		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages rear o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	6,975.53
Revised Amount	:S\$	2,082.55
Check Items (Estimated)	:S\$	457.99
Total	:S\$	2,540.54

Lump Sum Repair	:S\$	
-----------------	------	--

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

**Remarks**

( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.

( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

( X ) Other comments : The above survey was conducted on a 'Without Prejudice' basis.

## ...CLAIM SUBFOLDER...(New Assignment)

## CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	26 Aug 2019		28 Aug 2019 08:30 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

## CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	MUHAMMAD FIRDHAUSE BIN AZMAN, ID: S9448006Z		
Main Claimant:	ROSET LIMOUSINE SERVICES PTE LTD, Co. Reg. No.: 200406722Z		
Vehicle Reg. No.:	SLH2129R	Date of Loss:	25/08/2019 13:00 - :59
Claim Type:	TP / CMTD1904073	Policy/Cover Note No.:	D18MTMC01008316 (Third Party Only)
Vehicle Reg. No. (Insured):	FZ2554Y	Policy No. (Claimant):	
		Excess:	
Repairer:	Teamwork Garage Pte Ltd (HQ) 53 Ubi Ave 1 #01-24, Paya Ubi Industrial Park, 408934 Ubi - Tel: 6844 2475		
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by CHAN SHU HUI AGNES - 6329 5327]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 06/09/2019]		
Driver/Custodian (Insured):	MUHAMMAD HAZIQQUE BIN AZMAN (), NRIC: T0033248D, Tel: +6591702246 Email:		
Adj Asg. Remarks:	WS: 68442475 DARREN		

## ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

## ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Veron Chen (LKKAUTO)

---

**From:** Veron Chen (LKKAUTO)  
**Sent:** Wednesday, 11 September 2019 3:27 PM  
**To:** claims@teamworkgarage.com; Rasul (LKKAUTO); SUR  
**Subject:** RE: SLH2129R TOYOTA ALTIS-DOA: 25/8/2019

Dear Letitia,

Kindly send Final invoice and all supporting documents directly to SOMPO INSURANCE

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** claims@teamworkgarage.com <claims@teamworkgarage.com>  
**Sent:** Wednesday, 11 September 2019 2:22 PM  
**To:** Veron Chen (LKKAUTO) <veronchen@lkkauto.com>; Rasul (LKKAUTO) <Rasul@lkkauto.com>; SUR <sur@lkkauto.com>  
**Cc:** 'TEAMWORK GARAGE CLAIMS' <claims@teamworkgarage.com>  
**Subject:** RE: SLH2129R TOYOTA ALTIS-DOA: 25/8/2019

Hi,

We confirm Lump Sum \$1650 @ 4 working days

*Thank you and have a nice day! 😊*

**Letitia**

*Teamwork Garage Pte Ltd*

Blk 53 Ubi Avenue 1 #01-24 Paya Ubi Industrial Park  
Singapore (408934)  
Tel: 6844 2475 | Fax: 6844 2474

---

**From:** Veron Chen (LKKAUTO) [mailto:veronchen@lkkauto.com]  
**Sent:** Tuesday, September 10, 2019 12:39 PM  
**To:** Darren <claims@teamworkgarage.com>; Rasul (LKKAUTO) <Rasul@lkkauto.com>; SUR <sur@lkkauto.com>  
**Subject:** RE: SLH2129R TOYOTA ALTIS-DOA: 25/8/2019

Dear Darren,

Can confirm?

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Veron Chen (LKKAuto)

**Sent:** Thursday, 5 September 2019 10:44 AM

**To:** Darren <claims@teamworkgarage.com>; Rasul (LKKAuto) <Rasul@lkkauto.com>; SUR <sur@lkkauto.com>

**Subject:** RE: SLH2129R TOYOTA ALTIS-DOA: 25/8/2019

Dear Darren,

WITHOUT PREJUDICE

Offer Lump Sum \$1650 @ 4 working days

Please check and confirm

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Darren <claims@teamworkgarage.com>

**Sent:** Wednesday, 4 September 2019 9:20 PM

**To:** Rasul (LKKAuto) <Rasul@lkkauto.com>

**Subject:** SLH2129R TOYOTA ALTIS

Hi Rasul,

FYNA

Based on estimate calculation:

COR @ \$1700

DOR @ 4 Days

Please revise and get back to us so that we can close the case.

Darren

Teamwork Garage Pte Ltd

53 Ubi Avenue 1

#01-24 Paya Ubi Industrial Park

Singapore 408934

Tel: 68442475

Fax: 68442474

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	26/08/2019 19:50
Date Of Accident	25/08/2019 13:15
Exact Location Of Accident	51 PUNGGOL CENTRAL
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLH2129R
<b>Insured/Policyholder</b>	
Name Of Registered Owner	ROSET LIMOUSINE SERVICES PTE LTD
Co Reg No	200406722Z
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-899999999

### Vehicle Particulars

Manufacturer	TOYOTA
Model	COROLLA ALTIS CLASSIC 1.6 CVT
Exact Purpose for which vehicle was being used at time of accident	COMMERCIAL USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

### Insurance Company

Name of Insurance Company	LIBERTY INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	SD18V12322/VPZ/R00
Cover Note Number	

### Driver

Name of Driver	MUHAMMAD HAMIRUL HAKIM BIN HASSAN
NRIC No	S9000425E
Date Of Birth	08/01/1990
Occupation	OUTDOOR
Date Of Driving Pass	11/10/2012
Driving Experience	6 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-92334287
Fax Number	
Contact Number	OFFICE-92334287
Email Address	NOEMAIL

Address	BLK 140 RIVERVALE STREET #11-784
Postcode	540140
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : - GENDER: : FEMALE

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO STATEMENT.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	VIDEO FOOTAGE WITH DRIVER
Was there any audio recorded?	NO


#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	FZ2554Y
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	MOTORCYCLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	



# Accident Sketch Plan

## SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was stationary at the most left lane waiting for cars to move off due to the jam. Suddenly, Vehicle B, a motorbike (FZ2554Y) lose control and fell off his bike and Vehicle B bike free wheel and collided onto my rear right portion of my vehicle.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policy holder's signature  
Date & time:

Driver's signature  
(if driver is not policy holder)  
Date & time:

reporting centre personnel's Signature  
Name:  
NRIC/FIN No.:



Pte Ltd

TeamWork Garage Pte Ltd

53 Ubi Avenue 1 #01-23/24 Spore 408934

Paya Ubi Industrial Park

Tel : 6844 2475

E-mail : claims@teamworkgarage.com

Register number : 201015366H

REPAIR PERFORMA INVOICE

SOMPO INSURANCE

Vehicle number	SLH2129R
Make / Model	TOYOTA ALTIS
Chassis number	MR053REH104552052
Accident date	25/8/2019
Reference	1908-62

Qty Particulars Unit Price - SGD \$

PARTS REPLACEMENT - LIST ITEMS

1	REAR BUMPER <i>de-</i>	557.75
1	REAR BUMPER SIDE RETAINER <i>new - RH</i>	276.00 138
2	REAR BUMPER REINFORCEMENT BRACKET <i>Xsue</i>	156.40
1	REAR BUMPER REINFORCEMENT <i>Xsue</i>	454.25
1	BOOTLID <i>repair</i>	792.75
1	BOOTLID LOCK <i>Xsue</i>	442.75
1	BOOTLID LOCK STIRKER <i>Xsue</i>	51.75
1	BOOTLID EMBLEM - LOGO <i>new</i>	69.00
1	BOOTLID EMBLEM - COROLLA <i>new</i>	55.20
1	BOOTLID EMBLEM - ALTIS <i>new</i>	55.20
1	BOOTLID LAMP <i>sc-</i>	408.25
1	TAILLAMP <i>Xsue</i>	454.25
1	TAILLAMP PANEL <i>Xsue</i>	123.05
1	TAILLAMP LOWER RETAINER <i>Xsue</i>	89.60
1	END PANEL <i>repair</i>	678.50
1	END PANEL TOP GARNISH <i>Xsue</i>	276.00

1283.40

25%

962.55

Less 25%

Subtotal

Balance C/F

PARTS REPLACEMENT - SPECIAL NETT ITEMS

Balance B/F

1 SET	REAR BUMPER CLIP <i>new</i>	50.00 30
1	REAR NUMBER PLATE <i>Xsue</i>	80.00
1 SET	REVERSE SENSOR <i>Xsue</i>	400.00
1	WINDSCREEN SEALANT <i>Xsue</i>	120.00

Subtotal

Balance C/F

S/No LABOUR AND MISCELLANEOUS CHARGES

Balance B/F

1	CHECK REAR WIRING AND LIGHTNING SYSTEM	150.00 30
2	REMOVE, RENEW & REFIT TRIM, GARNISH	200.00 60
3	TRANSFER OLD BOOTLID TO NEW	150.00 X
4	PANEL BEATING ON AFFECTED AREAS	1000.00 300 400
5	SPRAY PAINTING ON AFFECTED AREAS	1000.00 600
6	APPLY ANTI RUST ON AFFECTED AREAS	120.00 X 11

Subtotal

Grand total

6975.53

962.55  
30  
1090  
2082.55  
20%  
1650

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/SMO19015163/R1VF3N2

Date: 12/09/2019

### REFERENCE

<b>Handling Insurer:</b>	Sompo Insurance Singapore Pte. Ltd.	<b>Policy No:</b>	D18MTMC01008316
<b>Claimant Vehicle No :</b>	SLH2129R	<b>Insured Vehicle No :</b>	FZ2554Y
<b>Date of Loss:</b>	25/08/2019	<b>Nature of Claim:</b>	TP
		<b>Claim No:</b>	CMTD1904073

### DESCRIPTION & IDENTIFICATION OF VEHICLE

<b>Reg No:</b>	SLH2129R	<b>Engine No:</b>	1ZRX578069
<b>Make &amp; Model:</b>	TOYOTA COROLLA ALTIS, 1.6 CLASSIC CVT (A)	<b>Chassis No:</b>	MR053REH104552052
<b>Reg. Date:</b>	26/10/2016 (Man. Year: 2016)	<b>Odometer:</b>	152699 km
<b>Colour:</b>	Grey		
<b>Engine Capacity:</b>	1598 cc		
<b>Market Value/New Car Price:</b>	N/A		
<b>Sum Insured (\$\$):</b>	Market Value/New Car Price		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

<b>General Condition:</b>		<b>Steering (Serviceable):</b>	Yes	<b>Footbrake (Serviceable):</b>	Yes
<b>Handbrake (Serviceable):</b>	Yes	<b>Engine Modification:</b>	No	<b>Pre-accident Condition:</b>	

### CONDITION OF TYRES

<b>Front Tyre Size:</b>	205/55R16	<b>Rear Tyre Size:</b>	205/55R16
<b>Front Left Side:</b>	Giti 6 mm	<b>Rear Left Side:</b>	Giti 6 mm
<b>Front Right Side:</b>	Giti 6 mm	<b>Rear Right Side:</b>	Giti 6 mm

The above values represent the remaining tyre treads depth

### COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	4,355.52	992.55	3,362.97	77.21
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,620.00	1,090.00	1,530.00	58.40
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>6,975.52</b>	<b>2,082.55</b>	<b>4,892.97</b>	<b>70.14</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>1,650.00</b>		
<b>(\$\$)</b>	6,975.52	1,650.00	5,325.52	76.35
<b>+ GST 7.00/7.00% (\$\$)</b>	488.29	115.50	372.79	76.35
<b>Nett Amount (\$\$)</b>	<b>7,463.81</b>	<b>1,765.50</b>	<b>5,698.31</b>	<b>76.35</b>

### INSPECTION

<b>Date of Assignment:</b>	28/08/2019	
<b>Date Inspected:</b>	28/08/2019	<b>Inspected At:</b>
		Teamwork Garage Pte Ltd (HQ)
		53 Ubi Ave 1 #01-24, Paya Ubi
		Industrial Park
		Singapore 408934
<b>Estimated Period of Repair:</b>	4.0 days	

Adjuster: MOHD RASUL

Manager: VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 12 Sep 2019)
<b>Parts:</b>	143	TOYOTA COROLLA ALTIS 1.6 CLASSIC CVT (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLH2129R)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	557.75 FL	*557.75 FL
2	1		*REAR BUMPER SIDE RETAINER	O/s Necessary	276.00 FL	*138.00 FL
3	2		*REAR BUMPER REINFORCEMENT BRACKET	Serviceable	156.40 FL	*- FL
4	1		*REAR BUMPER REINFORCEMENT	Serviceable	454.25 FL	*- FL
5	1		*BOOTLID	Repair	792.75 FL	*- FL
6	1		*BOOTLID LOCK	Serviceable	442.75 FL	*- FL
7	1		*BOOTLID LOCK STRIKER	Serviceable	51.75 FL	*- FL
8	1		*BOOTLID EMBLEM-LOGO	Necessary	69.00 FL	*69.00 FL
9	1		*BOOTLID EMBLEM-COROLLA	Necessary	55.20 FL	*55.20 FL
10	1		*BOOTLID EMBLEM-ALTIS	Necessary	55.20 FL	*55.20 FL
11	1		*BOOTLID LAMP	Scratched	408.25 FL	*408.25 FL
12	1		*TAILLAMP	Serviceable	454.25 FL	*- FL
13	1		*TAILLAMP PANEL	Serviceable	123.05 FL	*- FL
14	1		*TAILLAMP LOWER RETAINER	Serviceable	89.60 FL	*- FL
15	1		*END PANEL	Repair	678.50 FL	*- FL
16	1		*END PANEL TOP GARNISH	Serviceable	276.00 FL	*- FL
17	1		*SET REAR BUMPER CLIP	Necessary	50.00 FS	*30.00 FS
18	1		*REAR NUMBER PLATE	Serviceable	80.00 FS	*- FS
19	1		*SET REVERSE SENSOR	Serviceable	400.00 FS	*- FS
20	1		*WINDSCREEN SEALANT	Serviceable	120.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>5,590.70</b>	<b>1,313.40</b>
<b>- List Item Discount on L Items 25.00/25.00% (S\$)</b>	<b>1,235.18</b>	<b>320.85</b>
<b>Total Parts (S\$)</b>	<b>4,355.52</b>	<b>992.55</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	CHECK REAR WIRING AND LIGHTING SYSTEM	New	150.00	30.00
2	REMOVE,RENEW & REFIT TRIM,GARNISH	New	200.00	60.00
3	TRANSFER OLD BOOTLID TO NEW	New	150.00	0.00
4	PANEL BEATING ON AFFECTED AREAS	New	1,000.00	400.00
5	SPRAY PAINTING ON AFFECTED AREAS	New	1,000.00	600.00
6	APPLY ANTI RUST ON AFFECTED AREAS	New	120.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,620.00</b>	<b>1,090.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >