



Main Office : No. 22, Jalan Kilang, Singapore 159419
Tel: 6476 3333 Fax: 6271 5891

Service Centre : Block 100B, Bukit Merah Lane 3,
#01-04/06/08/115, Singapore 159722
Tel: (65) 6476 3333 (8 Lines) Fax: (65) 6270 8314
www.mova.com.sg
GST Reg. No: M2-0088864-2

Mova Spray Centre
2K Oven Spray Painting System

Power-M Automotive Pte Ltd
Specialise In Car Air-con Services,
Car Audio & Hi-Fi System.

Hilton Car Rental Centre

Hilton Auto Trading
Dealing In New/Used Cars, Hire Purchase & Insurance.



TP INSURER:
UNKNOWN

India International Insurance Pte Ltd (HQ)

Singapore

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	22/08/2019
Vehicle Reg. No.:	SKQ5415J	Driveable?	
Party At Fault:	UNKNOWN		
Make/Model:	HONDA AIRWAVE, 1.5 M SKYROOF (A)	Vehicle Reg. Date:	27/06/2008
Vehicle Colour:	WHITE	Chassis No:	GJ11301055
Engine No:	L15A5201144		
Odometer:	0 KM		
Paint Type:			
List Item Discount:	20.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	6		

Present Location: MOVA AUTOMOTIVE PTE LTD (BUKIT MERAH)

COST OF CLAIMS	Amount
Parts	2,493.12
Miscellaneous Items	11.00
Labour	1,740.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	4,244.12
+ GST 7.00% (S\$)	297.09
Nett Amount (S\$)	4,541.21

This claim is handled by: KEONG

Generated using Merimen e-Claims Internet Estimation & Adjusting System

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tanjin 97495746
'WP'
Lumpsum
Resurvey after repair
2/9/19 @ 12pm
5 days
surve/klauto-ws

REPAIR DETAILS**Reference.****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 27 Aug 2019)**Parts:** M1-MPV HONDA AIRWAVE 1.5 M Skyroof (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** (Unsubmitted, no print-code for SKQ5415J)**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*LH SIDE MIRROR ASSY	20.00	0.00	can ✓ *895.30 FL
2	1		*FRONT DOOR GLASS LH	20.00	0.00	? ? *553.10 FL
3	1		*FRONT DOOR OUTER MOULDING	20.00	0.00	wt ✓ *150.60 FL
4	1		*REAR DOOR LH	20.00	0.00	bt ✓ *998.40 FL
5	1		*REAR DOOR BLACK TAPE	20.00	0.00	nb ✓ *175.60 FL
6	1		*REAR DOOR OUTER MOULDING	20.00	0.00	? *150.60 FL
7	1		*REAR DOOR OUTER HANDLE LH	20.00	0.00	dis ✓ *192.80 FL
8	1		*FRONT DOOR LH - REPAIR	20.00	0.00	-
9	1		*REAR FENDER LH - REPAIR	20.00	0.00	-
10	1		*FUEL TANK COVER - REPAIR	20.00	0.00	-

F=Franchise part. L=ListItemDisc.

Sub Total (S\$) 3,116.40

- List Item Discount on L Items (S\$) 623.28

Total Parts (S\$) 2,493.12

Report was unsubmitted during this print-out.
Generated using **Merimen e-Claims IEAS**

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	OD/TP Case (Insurer)	11.00
Sub Total (S\$)			11.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	TO REPAIR FRONT DOOR LH, REAR FENDER LH, REMOVE & REFIX DAMAGED PARTS, TO STRAIGHTEN AND REALIGN AFFECTED AREAS	New	600 750.00
2	TO SPRAY FRONT DOOR LH, SIDE MIRROR LH, REAR DOOR LH, REAR FENDER LH, FUEL LID COVER, REAR DOOR OUTER HANDLE AND AFFECTED AREAS	New	650 800.00
3	TO REMOVE & REFIX REAR DOOR MECHANISM, POWER WINDOW MOTOR & CENTRE LOCKING SYSTEM	New	60 100.00
4	TO RUST PROOF AFFECTED AREAS	New	30 40.00
5	TO REMOVE & REFIX FRONT DOOR GLASS	New	7.40 50.00
Gross Labour Cost (S\$)			1,740.00

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >