

Estimate Report



Main Office : No. 22, Jalan Klang, Singapore 159419
Tel: 6476 3333 Fax: 6271 5891

Service Centre : Block 1008, Bukit Merah Lane 3,
#01-04/06/08/115, Singapore 159722
Tel: (65) 6476 3333 (8 Lines) Fax: (65) 6270 8314
www.mova.com.sg
GST Reg. No: M2-0088864-2

Mova Spray Centre
2K Oven Spray Painting System

Power-M Automotive Pte Ltd
Specialise in Car Air-con Services,
Car Audio & Hi-Fi System.

Hilton Car Rental Centre
Hilton Auto Trading
Dealing in New/Used Cars, Hire Purchase & Insurance.



P INSURER:
UNKNOWN

India International Insurance Pte Ltd (HQ)

Singapore

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	22/08/2019
Vehicle Reg. No.:	SKQ5415J	Driveable?	
Party At Fault:	UNKNOWN		
Make/Model:	HONDA AIRWAVE, 1.5 M SKYROOF (A)	Vehicle Reg. Date:	27/06/2008
Vehicle Colour:	WHITE	Chassis No:	GJ11301055
Engine No:	L15A5201144		
Odometer:	0 KM		
Paint Type:			
List Item Discount:	20.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	6		
Present Location:	MOVA AUTOMOTIVE PTE LTD (BUKIT MERAH)		

COST OF CLAIMS

Parts	Amount
Miscellaneous Items	2,493.12
Labour	11.00
Paintwork Labour	1,740.00
Towing	0.00
	0.00
Gross Total (\$\$)	4,244.12
+ GST 7.00% (\$\$)	297.09
Nett Amount (\$\$)	4,541.21

This claim is handled by: KEONG

Generated using Merimen e-Claims Internet Estimation & Adjusting System

Tanjin 97495461
WP
Lumpsum
Besing after repair
2/9/19 @ 12pm
5 days
sure the auto was

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 27 Aug 2019)
 Parts: M1-MPV HONDA AIRWAVE 1.5 M Skyroof (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: (Unsubmitted, no print-code for SKQ5415J)
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*LH SIDE MIRROR ASSY	20.00	0.00	am ✓ 895.30 FL ✓
2	1		*FRONT DOOR GLASS LH	20.00	0.00	cut ✓ 553.10 FL ✓
3	1		*FRONT DOOR OUTER MOULDING	20.00	0.00	wt ✓ 150.60 FL ✓
4	1		*REAR DOOR LH	20.00	0.00	bt ✓ 998.40 FL ✓
5	1		*REAR DOOR BLACK TAPE	20.00	0.00	del ✓ 175.60 FL ✓
6	1		*REAR DOOR OUTER MOULDING	20.00	0.00	wt ✓ 150.60 FL ✓
7	1		*REAR DOOR OUTER HANDLE LH	20.00	0.00	del ✓ 192.80 FL ✓
8	1		*FRONT DOOR LH - REPAIR	20.00	0.00	
9	1		*REAR FENDER LH - REPAIR	20.00	0.00	
10	1		*FUEL TANK COVER - REPAIR	20.00	0.00	

F=Franchise part. L=List Item Disc.

Sub Total (\$\$) 3,116.40
 - List Item Discount on L Items (\$\$) 623.28
 Total Parts (\$\$) 2,493.12 #

Report was unsubmitted during this print-out.
 Generated using Merimen e-Claims IEAS

3116.40
 623.28 - 20%
 2493.12
 11.00 - Merimen
 1380.00 - LB
 \$ 3884.12
 LS \$ 3100/-
 5 days.*

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	OD/TP Case (Insurer)	11.00
Sub Total (S\$)			11.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	TO REPAIR FRONT DOOR LH, REAR FENDER LH, REMOVE & REFIX DAMAGED PARTS, TO STRAIGHTEN AND REALIGN AFFECTED AREAS	New	600 750.00
2	TO SPRAY FRONT DOOR LH, SIDE MIRROR LH, REAR DOOR LH, REAR FENDER LH, FUEL LID COVER, REAR DOOR OUTER HANDLE AND AFFECTED AREAS	New	650 800.00
3	TO REMOVE & REFIX REAR DOOR MECHANISM, POWER WINDOW MOTOR & CENTRE LOCKING SYSTEM	New	60 100.00
4	TO RUST PROOF AFFECTED AREAS	New	30 40.00
5	TO REMOVE & REFIX FRONT DOOR GLASS	New	740 50.00
Gross Labour Cost (S\$)			1300 1740.00

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >