

ASS. REC. BY:

REF: CS/C71 1905166 / At f302 Special Instruction:

Survivor *Adrain*

ASSIGNMENT (Office)

From (Person): ONG Chin Kiat of CTI Date/Time: 27 August 2019

minutes

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLE 6030E Insured: SLJ 51225R

at Workshop m/s 1st Autoworks Pte Ltd Tel: 6844 1965

of 23 Kaki Bukit Ave 4 #04-01

Policy No: DMPCSN31226118012 Claim No: SNM19D 2c3985c02

Sum Insured: _____ Except: _____

Make of Vch: _____ D.O.A. 24/08/2019

(Client's Record)

11. ω_2

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 26/08/2019 09:42 a.m. Person Contacted: Suhaimi Vehicle IN/OUT

Vehicle-IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SLS 50252 :X
	SLE 6026E :X
	Lump Sum \$6800 , 6days Cred: 8619.32; 55%

ASS. I. C. BY:

REF:

Adrian

ASSIGNMENT

Front: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 6 days Res.: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Vehicle: IN / OUT

Person Contacted: _____

Veh No: SLE6030 E Yr Regn: 2016 / July

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Vezel cc 1496

Colour: Black A/C: Insured / Std / Nil / NA

Sp. Reading: 66664 T/Radio: Insured / Std / Nil / NA

Eng/No: _____

C/No: RU11114S65

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/60 R16

R: 215/60 R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

Rear

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. _____ D.O.I. 29/08/19

Survey held at 1st Antwork

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP Chire.

RECEIVED 06 NOV 2019

MV :

PV :

Nett :

Date/Time, File Pass to?

1) 6/11 typist

3) _____

5) _____

Prel. Report

Final Report

Date/Time, File Return to?

2) _____

4) _____

6) _____

Part Prices Check:

IN

OUT

Survey Fee:

Basic & Add.

___ S + RS, ___ SI

Photos

Others

TOTAL

Date:

200

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est. Submitted	Adj. Assigned	Adj. Rpt	Adj. Submitted	Ins. Auth'd	Status
Main	27 Aug 2019		27 Aug 2019 17:26 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS		[Created by insurer]							
Insured:	INTAN AZURA BINTE MOKHTAR, ID: 57619921C								
Main Claimant:	THNG XUE TING, ID: S8118221C								
Vehicle Reg. No.:	SLE6030E	Date of Loss:	24/08/2019 09:00 - :59 [36 Months and 28 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM19D203985C02	Policy/Cover Note No.:	DMPCSN31226118022						
Vehicle Reg. No. (Insured):	SLJ5225R	Policy No. (Claimant):							
		Excess:	S\$0.00						
Repairer:	1st Autoworks Pte Ltd (HQ) 23 Kaki Bukit Ave 4, #04-01, 415933 Kaki Bukit - Tel: 68441985								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Ong Chin Kiat]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 05/09/2019]								
Adj. Asg. Remarks:	to assign Mr Adrian Ling for SJE. to contact Mr Suhaimi Ong at 6844 1985 to arrange. thank you.								
ASSOCIATED MAIL RECEIVED		View All Compose Case Mail							
There are no mail for this case.									
ALL ASSOCIATED TASKS		View All Search Tasks Create New Task Complete							
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

1st Autoworks Pte Ltd
23 Kaki Bukit Ave 4, #04-01 (South Wing) Singapore 415933

Repair Estimate

Date : 28/8/2019

Reference: SLE6030E
HONDA
VEZEL 1.5X
Make: CVT

To Whom It May Concern

Dear Sir,

RE: VEHICLE :SLE6030E
CHASSIS NO.:RU11114565
ENGINE NO.:L15B4034571

Name of insured :SLE6030E
Date of accident.: 24/08/2019

We append hereunder the estimated cost of repairs to be carried out to the above vehicle.

Parts

No.	Qty	Part Description	Price (SGD)	
1	1	Tailgate <i>Distorted</i>	\$ 1,285.70	✓ 1100
2	1	LHR Tailgate Lamp <i>crack</i>	\$ 385.50	✓
3	1	RHR Tailgate Lamp <i>new</i>	\$ 385.50	+
4	1	Honda Logo <i>new</i>	\$ 78.50	✓
5	1	Vezel Lettering <i>new</i>	\$ 78.50	✓
6	1	Rear Windscreen <i>new</i>	\$ 1,358.00	+
7	1	Rear Windscreen Moulding <i>new</i>	\$ 225.70	✓
8	1	Tailgate Switch Cover <i>new (crack)</i>	\$ 254.00	✓
9	1	Rear Wiper Motor <i>new</i>	\$ 245.60	+
10	1	Rear Tailgate Inner Trim <i>crack</i>	\$ 251.70	✓
11	1	Rear Tailgate Weatherstrip <i>cut</i>	\$ 180.60	✓
12	1	LHR Tailgate Hinge <i>2nd</i>	\$ 110.50	+
13	1	RHR Tailgate Hinge <i>1st</i>	\$ 110.50	+
14	1	Tailgate Latch <i>crack</i>	\$ 195.70	✓
15	1	Tailgate Striker <i>new</i>	\$ 95.10	✓
16	1	LHR Taillamp <i>cut</i>	\$ 425.30	✓
17	1	LHR Bumper Upper <i>Deformed</i>	\$ 198.60	✓
18	1	LHR Fender Protector <i>new</i>	\$ 135.70	+
19	1	LHR Fender Liner <i>new</i>	\$ 128.30	+
20	1	RHR Taillamp <i>cut</i>	\$ 425.30	✓
21	1	RHR Bumper Upper <i>new</i>	\$ 198.60	+
22	1	RHR Fender Protector <i>new</i>	\$ 135.70	+
23	1	RHR Fender Liner <i>new</i>	\$ 128.30	+
24	1	Rear Bumper <i>Distorted</i>	\$ 785.30	✓
25	1	LHR Bumper Reflector <i>2nd</i>	\$ 125.10	+
26	1	RHR Bumper Reflector <i>1st</i>	\$ 125.10	+

27	1	Rear End Panel	Distorted	\$	486.50	✓
28	1	Rear End Panel Trim	Del	\$	125.30	✓
29	1	LHR Fender Inner Trim	Del	\$	426.10	+
30	1	RHR Fender Inner Trim	Del	\$	426.10	+
31	1	Spare Tyre Panel	Distorted	\$	856.10	+
32	1	Spare Tyre Panel Mat	Del	\$	389.60	+
33	1	Tool box styrofoam	Del	\$	281.80	✓
34	1	LHR Bumper Bracket, Guide	Del	\$	68.10	-
35	1	RHR Bumper Bracket, Guide	Del	\$	68.10	-
36	1	Rear Exhaust	Del	\$	1,670.30	+

6563.70

5152.56

Parts Total: \$ 12,850.40

Less 20%: \$ 2,570.08

Total: \$ 10,280.32

Labour

No.

Labour Description

Price (SGD)

Rear portion

1	To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate and align repair / replacement parts. (\$200 per day)	\$ 1,400.00	1200
2	Carry out spray painting on accident affected area (\$200 per panel)	\$ 1,400.00	800 1000
3	To conduct anti rust of under carriage tuff coat	\$ 120.00	60
4	To disconnect wire harness of electrical component to facilitate repairs, reconnect and check electrical function after repair	\$ 60.00	30
5	Remove and refix seat cushion/upholstery & roof lining to facilitate repairs	\$ 250.00	80
6	To remove and refix reverse camera and conduct test	\$ 80.00	50
7	To conduct transfer of parts from old tailgate to new tailgate	\$ 80.00	✓
8	To conduct water leakage test after repairs of vehicle	\$ 80.00	x
9	To conduct realigning of exhaust pipe	\$ 80.00	+
10	To remove and refix rear tail gate windscreen	\$ 120.00	✓

2620

Labour Total: \$ 3,670.00

Others

Other Description

No. Qty

Price (SGD)

Rear portion

1	1	Rear number plate	Del	\$	80.00	+
2	10	Rear bumper clip	Del	\$	65.00	30
3	6	Rear fender liner clips	Del	\$	39.00	+
4	5	Rear end panel trim clip	Del	\$	32.50	10
5	1	Rear reverse camera	Del	\$	280.00	+
6	1	Rear end panel insulation seal	Del	\$	120.00	60

7	1	Rear floor panel insulation seal	new	\$	200.00	+
8	10	Rear fender inner trim clip	new	\$	65.00	+
9	10	Tail gate inner trim board clip	new	\$	65.00	30.
10	1	Rear Spoiler Sealant	new	\$	120.00	+
11	1	Tailgate windscreen sealant	new	\$	120.00	60.
12	1	Tailgate windscreen solar film	new	\$	250.00	+
13	5	Rear fender protector clip	new	\$	32.50	+

190

Other Total: \$ 1,469.00

Total: \$ 15,419.32
GST 7%: \$ 1,079.35
GRAND TOTAL: \$ 16,498.67

15842.76

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN. PARTS PRICES ARE SUBJECT TO CHANGES.

Yours faithfully

 Suhaimi C

Service Executive
Suhaimi Ong
HP : 8298 8933 Fax:6844 5185

Adrian Lj
L/S 29/08/19.

06 Days.

Supplementary: 423.44

Total: 8486
L/S: 6.8K

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

VEHICLE NO:

SE6030E

[illegible]

Adrian Pridemore

1st Autoworks Pte Ltd

23 Kaki Bukit Ave 4, #04-01 (South Wing) Singapore 415933

TAX INVOICE

CHINA TAIPING INSURANCE(SINGAPORE)PTE LTD

3 Anson Road, #16-00

Springleaf Tower

SINGAPORE 079909

GST Ref. No: 20-0000274-Z

Vehicle No: SLE6030E

Invoice No:

Chasis No: RU11114565

Engine No: L15B4034571

Invoice Date:

DESCRIPTION	AMOUNT	SGD
-------------	--------	-----

Parts

No.	Qty.	Description	Price (SGD)
1	1	Tailgate	\$ 1,100.00
2	1	LHR Tailgate Lamp	\$ 385.50
3	1	Honda Logo	\$ 78.50
4	1	Vezel Lettering	\$ 78.50
5	1	Rear Windscreen Moulding	\$ 225.70
6	1	Tailgate Switch Cover	\$ 254.00
7	1	Rear Tailgate Inner Trim	\$ 251.70
8	1	Rear Tailgate Weatherstrip	\$ 180.60
9	1	Tailgate Latch	\$ 195.70
10	1	Tailgate Striker	\$ 95.10
11	1	LHR Taillamp	\$ 425.30
12	1	LHR Bumper Upper	\$ 198.60
13	1	RHR Taillamp	\$ 425.30
14	1	Rear Bumper	\$ 785.30
15	1	Rear End Panel	\$ 486.50
16	1	Rear End Panel Trim	\$ 125.30
17	1	Spare Tyre Panel	\$ 856.10
18	1	Tool box styrofoam	\$ 281.80
19	1	LHR Bumper Bracket,	\$ 68.10
20	1	RHR Bumper Bracket,	\$ 68.10

Supplementary Items

21	1	Rear Spare Tyre Panel <i>under cover</i>	\$ 273.20
22	1	RR Reverse Sensor	\$ 118.70
23	1	Rear Tailgate Keyless	\$ 137.40

Total: \$ 7,095.00

Less 20%: \$ 1,419.00

Parts Total : \$ 5,676.00

Labour

<u>No.</u>	<u>Description</u>	<u>Price (SGD)</u>
<u>1</u>	To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate and align repair / replacement parts. (\$200 per day)	\$ 1,200.00
<u>2</u>	Carry out spray painting on accident affected area (\$200 per panel)	\$ 1,000.00
<u>3</u>	To conduct anti rust of under carriage tuff coat	\$ 60.00
<u>4</u>	To disconnect wire harness of electrical component to facilitate repairs, reconnect and check electrical function after repair	\$ 30.00
<u>5</u>	Remove and refix seat cushion/upholstery & roof lining to facilitate repairs	\$ 80.00
<u>6</u>	To remove and refix reverse camera and conduct test	\$ 50.00
<u>7</u>	To conduct transfer of parts from old tailgate to new tailgate	\$ 80.00
<u>8</u>	To remove and refix rear tail gate windscreen	\$ 120.00

Labour Total : \$ 2,620.00

Other

<u>No.</u>	<u>Other Description</u>	<u>Price (SGD)</u>
1	10 Rear bumper clip	\$ 30.00
2	5 Rear end panel trim clip	\$ 10.00
3	1 Rear end panel insulation seal	\$ 60.00
4	10 Tail gate inner trim board clip	\$ 30.00
5	1 Tailgate windscreen sealant	\$ 60.00

Other Total : \$ 190.00

Total : \$ 8,486.00

After Lump Sum 20% : \$ 6,800.00

GST (7%) \$ 476.00

Grand Total: \$ 7,276.00

Yours Faithfully,



Suhaimi Ong

Service Advisor

Tel: 68441985 Fax: 68445185

E & O E

- ALL CHEQUE PAYMENTS SHOULD BE CROSSED AND MADE PAYABLE TO "IST Autoworks Pte Ltd".
- PLEASE INDICATE THE INVOICE NO. ON THE REVERSE SIDE.

Please check and finalize with me this invoice

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607196R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT119015166/ATF3N2

Date: 11/11/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN31226118022	
Claimant Vehicle No :	SLE6030E	Insured Vehicle No :	SLJ5225R	
Date of Loss:	24/08/2019	Nature of Claim:	TP	Claim No: SNM19D203985C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLE6030E	Engine No:	L15B4034571
Make & Model:	HONDA VEZEL, 1.5 X CVT (A)	Chassis No:	RU11114565
Reg. Date:	27/07/2016 (Man. Year: 2016)	Odometer:	66664 km
Colour:	Black		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/60R16	Rear Tyre Size:	215/60R16
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	12,172.76	5,866.00	6,306.76	51.81
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,670.00	2,620.00	1,050.00	28.61
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	15,842.76	8,486.00	7,356.76	46.44
Approved Total (Overridden) (\$\$)		6,800.00		
Nett Amount (\$\$)	15,842.76	6,800.00	9,042.76	57.08

INSPECTION

Date of Assignment:	27/08/2019	Inspected At:	1st Autoworks Pte Ltd (HQ)
Date Inspected:	29/08/2019		23 Kaki Bukit Ave 4, #04-01
			Singapore 415933
Estimated Period of Repair:	6.0 days		

Adjuster: ADRIAN LING

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 11 Nov 2019)
Parts:	M1-SUV	HONDA VEZEL 1.5 X CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLE6030E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Distorted	1,285.70 FL	*1,100.00 FL
2	1		*LHR TAILGATE LAMP	Cracked	385.50 FL	*385.50 FL
3	1		*RHR TAILGATE LAMP	Not Necessary	385.50 FL	*- FL
4	1		*HONDA LOGO	Necessary	78.50 FL	*78.50 FL
5	1		*VEZEL LETTERING	Necessary	78.50 FL	*78.50 FL
6	1		*REAR WINDSCREEN	Not Necessary	1,358.00 FL	*- FL
7	1		*REAR WINDSCREEN MOULDING	Necessary	225.70 FL	*225.70 FL
8	1		*TAILGATE SWITCH COVER	Cracked	254.00 FL	*254.00 FL
9	1		*REAR WIPER MOTOR	Not Necessary	245.60 FL	*- FL
10	1		*REAR TAILGATE INNER TRIM	Cracked	251.70 FL	*251.70 FL
11	1		*REAR TAILGATE WEATHERSTRIP	Cut	180.60 FL	*180.60 FL
12	1		*LHR TAILGATE HINGE	Not Necessary	110.50 FL	*- FL
13	1		*RHR TAILGATE HINGE	Not Necessary	110.50 FL	*- FL
14	1		*TAILGATE LATCH	Damaged	195.70 FL	*195.70 FL
15	1		*TAILGATE STRIKER	Bent	95.10 FL	*95.10 FL
16	1		*LHR TAILLAMP	Cut	425.30 FL	*425.30 FL
17	1		*LHR BUMPER UPPER	Deformed	198.60 FL	*198.60 FL
18	1		*LHR FENDER PROTECTOR	Not Necessary	135.70 FL	*- FL
19	1		*LHR FENDER LINER	Not Necessary	128.30 FL	*- FL
20	1		*RHR TAILLAMP	Cut	425.30 FL	*425.30 FL
21	1		*RHR BUMPER UPPER	Not Necessary	198.60 FL	*- FL
22	1		*RHR FENDER PROTECTOR	Not Necessary	135.70 FL	*- FL
23	1		*RHR FENDER LINER	Not Necessary	128.30 FL	*- FL
24	1		*REAR BUMPER	Distorted	785.30 FL	*785.30 FL
25	1		*LHR BUMPER REFLECTOR	Not Necessary	125.10 FL	*- FL
26	1		*RHR BUMPER REFLECTOR	Not Necessary	125.10 FL	*- FL
27	1		*REAR END PANEL	Distorted	486.50 FL	*486.50 FL
28	1		*REAR END PANEL TRIM	Deformed	125.30 FL	*125.30 FL
29	1		*LHR FENDER INNER TRIM	Not Necessary	426.10 FL	*- FL
30	1		*RHR FENDER INNER TRIM	Not Necessary	426.10 FL	*- FL
31	1		*SPARE TYRE PANEL	Distorted	856.10 FL	*856.10 FL
32	1		*SPARE TYRE PANEL MAT	Not Necessary	389.60 FL	*- FL
33	1		*TOOL BOX STYROFOAM	Deformed	281.80 FL	*281.80 FL
34	1		*LHR BUMPER BRACKET,GUIDE	Necessary	68.10 FL	*68.10 FL
35	1		*RHR BUMPER BRACKET,GUIDE	Necessary	68.10 FL	*68.10 FL
36	1		*REAR EXHAUST	Not Necessary	1,670.30 FL	*- FL
37	1		*RR SPARE TYRE PANEL UNDER DUST COVER	Deformed	273.20 FL	*273.20 FL
38	1		*RR REVERSE SENSOR SPEAKER	Cracked	118.70 FL	*118.70 FL
39	1		*RR TAILGATE KEYLESS SENSOR	Cracked	137.40 FL	*137.40 FL
40	1		*REAR NUMBER PLATE	Not Necessary	80.00 FS	*- FS
41	10		*REAR BUMPER CLIP	Necessary	65.00 FS	*30.00 FS
42	6		*REAR FENDER LINER CLIPS	Not Necessary	39.00 FS	*- FS
43	5		*REAR END PANEL TRIM CLIP	Necessary	32.50 FS	*10.00 FS
44	1		*REAR REVERSE CAMERA	Not Necessary	280.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
45	1		*REAR END PANEL INSULATION SEAL	Necessary	120.00 FS	*60.00 FS
46	1		*REAR FLOOR PANEL INSULATION SEAL	Not Necessary	200.00 FS	*- FS
47	10		*REAR FENDER INNER TRIM CLIP	Not Necessary	65.00 FS	*- FS
48	10		*TAIL GATE INNER TRIM BOARD CLIP	Necessary	65.00 FS	*30.00 FS
49	1		*REAR SPOILER SEALANT	Not Necessary	120.00 FS	*- FS
50	1		*TAILGATE WINDSCREEN SEALANT	Necessary	120.00 FS	*60.00 FS
51	1		*TAILGATE WINDSCREEN SOLAR FILM	Not Necessary	250.00 FS	*- FS
52	5		*REAR FENDER PROTECTOR CLIP	Not Necessary	32.50 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	14,848.70	7,285.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	2,675.94	1,419.00
Total Parts (\$\$)	12,172.76	5,866.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE/RENEW THE ACCIDENT DAMAGED PORTION,TO PANEL BEATING,RESHAPE,STRAIGHTEN,ORIENTATE AND ALIGN REPAIR/REPLACEMENT PARTS	New	1,400.00	1,200.00
2	CARRY OUT SPRAY PAINTING ON ACCIDENT AFFECTED AREA	New	1,400.00	1,000.00
3	TO CONDUCT ANTI RUST OF UNDER CARRIAGE TUFF COAT	New	120.00	60.00
4	TO DISCONNECT WIRE HARNESS OF ELECTRICAL COMPONENT TO FACILITATE REPAIRS,RECONNECT AND CHECK ELECTRICAL FUNCTION AFTER REPAIR	New	60.00	30.00
5	REMOVE AND REFIX SEAT CUSHION/UPHOLSTERY & ROOF LINING TO FACILITATE REPAIRS	New	250.00	80.00
6	TO REMOVE AND REFIX REVERSE CAMERA AND CONDUCT TEST	New	80.00	50.00
7	TO CONDUCT TRANSFER OF PARTS FROM OLD TAILGATE TO NEW TAILGATE	New	80.00	80.00
8	TO CONDUCT WATER LEAKAGE TEST AFTER REPAIRS OF VEHICLE	New	80.00	0.00
9	TO CONDUCT REALIGNING OF EXHAUST PIPE	New	80.00	0.00
10	TO REMOVE AND REFIX REAR TAIL GATE WINDSCREEN	New	120.00	120.00
Gross Labour Cost (S\$)			3,670.00	2,620.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >