

Ceciliza



AMA AUTOCARE PTE LTD

36 Toh Guan Road East #01-36 Enterprise Hub Singapore 608580

Email :AMA.CLAIM@GMAIL.COM

(201735370W)

Page No. 1

Vehicle No. SMH2121A BMW CONVERTIBLE 325/WBADW 320506486 / 2011				
QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(S\$)	SURVEYOR'S ADJUSTMENT
PARTS (LIST ITEMS)				
1	Rear Bumper <i>de /</i>		2278.00	1450
1	Rear lower bumper <i>ut /</i>		963.00	423
1	Rear bumper under cover <i>X SUC</i>		642.00	X
2	Rear Bumper Side Retainer L/R @ \$138.80 <i>X SUC</i>	<i>X SUC</i>	277.60	X
1	Rear innershield L/R @ \$260.00 <i>X SUC</i>		520.00	X
1	Bootlid <i>repair</i>		2430.00	<i>X R</i>
1	Bootlid BMW logo badge <i>X AN</i>		520.00	X
1	Bootlid Inner Trim <i>X SUC</i>		725.00	X
1	Bootlid Mechanism Lock <i>X SUC</i>		139.40	X
2	Bootlid Hinges @294.00 <i>X SUC</i>		588.00	X
1	Bootlid Weatherstrip <i>X SUC</i>		472.00	X
1	Rear fender LHS <i>X SUC</i>		1644.00	X
1	Taillamp LHS <i>X SUC</i>		1565.00	X
1	Taillamp reflector LHS <i>X CA</i>		970.00	270
1	Rear reinforcement <i>? BT</i>		1080.00	520
1	Rear end panel <i>repair</i>		1763.00	<i>X R</i>
1	Rear end panel outer bracket <i>X SUC</i>		292.00	X
1	Rear end panel top garnish <i>X SUC</i>		678.00	X
1	Rear Exhaust silencer assembly <i>X SUC</i>		1850.00	X
1	Rear Exhaust silence heat shield <i>X SUC</i>		610.00	X
2	Rear Exhaust silencer assembly mountings <i>X SUC</i>	<i>X SUC</i>	298.00	X
			20305.00	
less 5%			1015.25	5%
			19289.75	
SPECIAL NETT ITEMS				
1set	Rear Bumper Clips <i>AN</i>		120.00	40
1	Reverse sensor <i>? AN</i>		420.00	200 S/U
1	LHS Rear fender glass sealant <i>X AN</i>		120.00	X
1	Rear innershield clips <i>X AN</i>		60.00	X
1set	Bootlid Inner Trim Board Clips <i>X AN</i>		80.00	X
1	Bootlid Windscreen Sealant <i>X AN</i>		150.00	X
1	Rear end panel sealant <i>X AN</i>		120.00	X
1	Rear number plate with holder <i>X AN</i>		75.00	X
			20434.75	

2663
59
2529.85

240



AMA AUTOCARE PTE LTD

36 Toh Guan Road East #01-36 Enterprise Hub Singapore 608580

Email : AMA.CLAIM@GMAIL.COM

(201735370W)

Page No. 2

Vehicle No. SJQ3881X VW TOURAN 1.4A

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (\$\$)	SURVEYOR'S ADJUSTMENT
	LABOUR		
1	To remove the affected parts & fittings to commence repairs; panel beat & reshape the affected areas and replace the damaged parts and components.	2000.00 400	1040
2	To supply paint materials, expandable items & putty, respray paint on parts replaced	1800.00 500	
3	To remove, refix wiring system at accident damaged areas and check for proper function	220.00 X ^m	
4	To remove / refix inner trims, fittings, garnish etc at rear compartment so as to facilitate repairs at rear.	200.00 60	
5	To remove and refix LHS rear fender glass	150.00 X ^m	
6	To remove and refix rear bootlid windscreen glass	220.00 X ^m	
7	To remove and replace reverse sensors and check for proper function	120.00 60	
9	To perform anti-rust treatment on affected areas	210.00 20	
10	To remove and replace rear exhaust silencer assembly, realign to fit and check system function	250.00 X ^m	
Labour Total :		5170.00	
TOTAL (PARTS & LABOUR):		22583.70	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

MELVIN WEE

2529.85

240.00

1040.00

3809.85

20%

3047.88

4/3 - 3,050

Rasul
Hp 90010068

4 days

W/S

28/08/19 P1310

Reg after paint

4 days