



AMA AUTOCARE PTE LTD

36 Toh Guan Road East #01-36 Enterprise Hub Singapore 608580

Email :AMA.CLAIM@GMAIL.COM

(201735370W)

Page No. 1

Vehicle No. SMH2121A BMW CONVERTIBLE 325

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(\$\$)	SURVEYOR'S ADJUSTMENT
<u>PARTS (LIST ITEMS)</u>				
1	Rear Bumper <i>de</i>		2278.00	
1	Rear lower bumper <i>ad</i>		963.00	
1	Rear bumper under cover X		642.00	
2	Rear Bumper Side Retainer L/R @ \$138.80 X		277.60	
1	Rear innershield L/R @ \$260.00 X		520.00	
1	Bootlid <i>repair</i>		2430.00	
1	Bootlid BMW logo badge <i>no</i> X		520.00	
1	Bootlid Inner Trim X		725.00	
1	Bootlid Mechanism Lock X		139.40	
2	Bootlid Hinges @294.00 X		588.00	
1	Bootlid Weatherstrip X		472.00	
1	Rear fender LHS X		1644.00	
1	Taillamp LHS X		1565.00	
1	Taillamp reflector LHS X		970.00	
1	Rear reinforcement X		1080.00	
1	Rear end panel <i>repair</i>		1763.00	
1	Rear end panel outer bracket X		292.00	
1	Rear end panel top garnish X		678.00	
1	Rear Exhaust silencer assembly X		1850.00	
1	Rear Exhaust silencer heat shield X		610.00	
2	Rear Exhaust silencer assembly mountings X		298.00	
			20305.00	
less 5%			1015.25	5%
			19289.75	
<u>SPECIAL NETT ITEMS</u>				
1set	Rear Bumper Clips <i>no</i>		120.00	<i>40</i>
1	Reverse sensor X		420.00	<i>200 s/u</i>
1	LHS Rear fender glass sealant X		120.00	
1	Rear innershield clips X		60.00	
1 set	Bootlid Inner Trim Board Clips X		80.00	
1	Bootlid Windscreen Sealant X		150.00	
1	Rear end panel sealant X		120.00	
1	Rear number plate with holder X		75.00	
			20434.75	



AMA AUTOCARE PTE LTD

36 Toh Guan Road East #01-36 Enterprise Hub Singapore 608580

Email :AMA.CLAIM@GMAIL.COM

(201735370W)

Page No. 2

Vehicle No. SJQ3881X VW TOURAN 1.4A

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (\$)	SURVEYOR'S ADJUSTMENT
	LABOUR		
1	To remove the affected parts & fittings to commence repairs; panel beat & reshape the affected areas and replace the damaged parts and components.	2000.00 400	
2	To supply paint materials, expandable items & putty, respray paint on parts replaced	1800.00 500	
3	To remove, refix wiring system at accident damaged areas and check for proper function	220.00 X	
4	To remove / refix inner trims, fittings, garnish etc at rear compartment so as to facilitate repairs at rear.	200.00 60	
5	To remove and refix LHS rear fender glass	150.00 X	
6	To remove and refix rear bootlid windscreen glass	220.00 X	
7	To remove and replace reverse sensors and check for proper function	120.00 60	
9	To perform anti-rust treatment on affected areas	210.00 20	
10	To remove and replace rear exhaust silencer assembly, realign to fit and check system function	250.00 X	
Labour Total :		5170.00	
TOTAL (PARTS & LABOUR):		22583.70	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

MELVIN WEE

Rasul

Hp 90010068

4 days

W/S

28/08/19 @ 1310

Reg after paint