


SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 27/8/19 at about 08:55 hrs, I was driving at above said location with a male pax onboard. Shortly a truck in front brake to stop and my taxi gradually to slow down. A few second later, I felt an impact from behind. Veh B motorcycle collided into the rear right portion of my taxi. No injury at the point of accident.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

DRIVER'S SIGNATURE

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature

Name:
NRIC/FIN No.:

27/8/19
Loke Wei Yeng

Attachment: Pp. 1 & 2 of 2

Enquire Vehicle Insurance Details

Vehicle No.	Incident Date/Time	Search Status	Insurance Company Code	Insurance Company Name
FBJ93635	27 Aug 2019 / 08:55:00	Successful	N12	NTUC INCOME INS CO-OP LTD

[Previous](#)[OK](#)

SHD 3260E

Our Job Ref No : 305328094

Date : 28/08/19

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK

Fax :

Attn : KALVIN

Vehicle Reg No : SHD3260E

27/08/2019

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: NTUC FBJ9363S
2. The finalized amount shall be:
- (a) Spare Parts after List discount
- (b) Labour Charges
- Total for Part-By-Part Repair Cost**
- (c.) Lumpsum Repair (if applicable)
Total for Lumpsum repair cost after Less:
Final Lumpsum Repair cost \$1,100.00

3. Estimated normal period for repairs: 2 working days.

4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days

5. Thank you for your assistance.

We confirm the estimates and
finalized amountSignature : 

Name : CHIANG

Tel : 62148314

Fax : 65468156

Signature : 

Name : Kalvin

Date : 29/8/19

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		N		
3. Survey Fees				
4. LTA Search Fee	7.49			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

[illegible]

REPAIR ESTIMATE*

DATE 27/8/2019 13:00

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Bumper			\$ 553.00
	Rear Bumper Clip 10 pcs			\$ 22.00
	<i>Rear Bumper under cover - cut</i>		<i>\$ 228</i>	
	SUB TOTAL			\$ 575.00
	LESS 20%			\$ 115.00
	DISCOUNTED TOTAL			\$ 460.00
				803
				642.40
	Rear Bumper Advertisement Logo			\$ 50.00
	Rear Bumper Rubber Mat			\$ 50.00
	Rear Fender Advertisement Logo (LH/RH)		\$ 100.00	\$ 200.00
				Nett Nett Nett
				\$ 300.00
	Labour Charge			
	Panel Beating			\$ 400.00
	Spray Painting Charge			\$ 300.00
	Wiring Charge			\$ 50.00
	Remove/Refix Reverse Sensor			\$ 80.00
	TOTAL LABOUR			\$ 830.00
	ESTIMATE TOTAL		1772.40	\$ 1,590.00
	Kaluh 1/1/14			
	M 27/8/17 1510 L			
	2 Pys			
	L/S Rm phts			
	This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.			



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC19015179/K1tf3s2

73 BRAS BASAH ROAD

#05-01 NTUC TRADE UNION HOUSESINGAPORE Date: 10-09-2019

189556



Code: INC4

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	FBJ 9363S	Veh. Inspected	SHD 3260E
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1060017-001	Excess (\$)	0.00
Assign From		Assign Date	27/08/2019

2. Vehicle Particulars & Condition

Make & Model	HYUNDAI I40	c.c	1685
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	KMHLB41UMGU091645	Colour	BLUE
Odometer	331970	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/60 R16	HANKOOK	7 mm
L/H Front Tyre	205/60 R16	HANKOOK	7 mm
R/H Rear Tyre	205/60 R16	HANKOOK	7 mm
L/H Rear Tyre	205/60 R16	HANKOOK	7 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	27/08/2019	Inspection Date	27/08/2019
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	2 Working Days
-------------------------------------	----------------

**National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 3260E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	CRACKED	553.00	553.00
10	REAR BUMPER CLIP	NECESSARY	22.00	22.00
1	REAR BUMPER UNDERCOVER	CUT	228.00	228.00
	LESS 20% DISCOUNT		-160.60	-160.60
			642.40	642.40
	<u>SPECIAL NETT ITEMS</u>			
1	REAR BUMPER ADVERTISEMENT LOGO (SN)	NECESSARY	50.00	50.00
1	REAR BUMPER RUBBER MAT (SN)	NECESSARY	50.00	50.00
2	REAR FENDER ADVERTISEMENT LOGO (LH/RH) @ \$100.00 (SN)	NECESSARY	200.00	200.00
			300.00	300.00
	<u>LABOUR</u>			
	PANEL BEATING.	NOT NECESSARY	400.00	200.00
	SPRAY PAINTING CHARGE.		300.00	200.00
	WIRING CHARGE.		50.00	-
	REMOVE / REFIX REVERSE SENSOR.		80.00	30.00
			830.00	430.00
GRAND TOTAL			1,772.40	1,372.40
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)				1,100.00

Report Ref No. NS/INC19015179/K1tf3s2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

K.K. LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE,
MinstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.