



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:WINNIE			Ref: CC4/ASM19015181/Bbs3q2 Date: 01/02/2021 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SML 791H	Veh. Inspected	SKZ 2613B	
Policy No.	GA465980/1	Coverage (\$)	0.00	
Claim No.	S9M01YHL	Excess (\$)	0.00	
Assign From		Assign Date	29/08/2019	
2. Vehicle Particulars & Condition				
Make & Model	AUDI A31.0 TFSI	c.c	999	
Engine No.	HIDDEN	Year of Reg.	2019	
Chassis No.	WAUZZZ8V2K1021024	Colour	BLACK	
Odometer	6487 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/55 R16	BRIDGESTONE	7 mm	
L/H Front Tyre	205/55 R16	BRIDGESTONE	7 mm	
R/H Rear Tyre	205/55 R16	BRIDGESTONE	7 mm	
L/H Rear Tyre	205/55 R16	BRIDGESTONE	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	26/08/2019	Inspection Date	29/08/2019	
Survey held at	TEAM AUTOPRO PTE LTD 160 SIN MING DRIVE #01-14 SINGAPORE 575722			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			5 Working Days	