

SJE : _____
 Date of Survey : _____
 Date of ReSurvey: _____ After-Paint: _____
 Contacts : _____

Vehicle Nos : **SKZ 2613 B**
 Make Audi
 Model A3
 Chassis No : WAUZZZ8V2K1021024

*** AGREED Cost Of Repair and Repair Day/s with SJE ***

Amount: _____

Working Day: _____

Nos.	PARTS	Qty	Unit S\$	TOTAL S\$	
1	Bootlid	1	\$ 1,564.00	\$ 1,564.00	DDV
2	Bootlid logo	1	\$ 112.00	\$ 86.40 112.00	NEC
3	Bootlid emblem 'A3'	1	\$ 42.00	\$ 42.00	
4	Bootlid weatherstrip	1	\$ 235.00	\$ 235.00	DIS
5	Bootlid Stopper	4	\$ 28.00	\$ 112.00	SVCX
6	Bootlid sensor	1	\$ 850.00	\$ 140.97 850.00	?BRU
7	Bootlid lock assembly	1	\$ 225.00	\$ 225.00	?NNA
8	Bootlid outer handle	1	\$ 274.00	\$ 274.00	SVCX
9	Bootlid inner trim	1	\$ 312.00	\$ 312.00	SVCX
10	Bootlid inner trim cover	1	\$ 186.00	\$ 186.00	NA
11	Bootlid lamp	2	\$ 382.60	\$ 425.00 765.20	?SCRU
12	Rear fender	1	\$ 1,841.00	\$ 1,841.00	SVCX
13	Rear fender air vent	1	\$ 183.50	\$ 183.50	?NNA
14	Rear fender inner cowl	1	\$ 248.00	\$ 248.00	
15	Rear fender inner trim	1	\$ 270.00	\$ 270.00	(SVC)
16	Rear fender quarter glass moulding	1	\$ 68.50	\$ 68.50	
17	Rear fender quarter glass garnish	1	\$ 102.30	\$ 102.30	
18	Rear bumper	1	\$ 1,664.00	\$ 1,664.00	DDV
19	Rear bumper lower	1	\$ 385.30	\$ 385.30	DLV
20	Rear bumper bracket	2	\$ 68.00	\$ 136.00	?BRU
21	Rear bumper retainer	2	\$ 75.00	\$ 150.00	NEC
22	Rear bumper tow cover	1	\$ 85.00	\$ 50.00 85.00	DLV
23	Rear bumper reinforcement	1	\$ 693.00	\$ 693.00	?DDV
24	Rear bumper reinforcement bracket	1	\$ 147.50	\$ 147.50	?NNA
25	Rear bumper reflector	1	\$ 88.50	\$ 88.50	?BRU
26	Rear end panel	1	\$ 625.00	\$ 625.00	?DRU
27	Rear end panel top garnish	1	\$ 266.00	\$ 266.00	SVCX
28	Taillamp	2	\$ 1,200.00	\$ 1,784.06 2,400.00	?BRU
29	Spare tyre panel	1	\$ 871.40	\$ 871.40	?SVC
30	Exhaust muffler	1	\$ 230.80	\$ 100.00 230.80	?RX
31	Reverse sensor	2	\$ 200.00	\$ 400.00 800.00	WTV

Parts Sub Total : \$8339.63 15,933.00

5% Discount \$ 416.98 796.65

PARTS TOTAL : \$7922.65 15,136.35

Nos.	SPECIAL NETT	Qty	Unit S\$	TOTAL S\$	
1	Sundries	1	\$ 60.00	\$ 60.00	NAX
2	Rear bumper clips	1	\$ 50.00	\$ 30.00 50.00	NEC
3	Rear end panel top garnish clips	1	\$ 50.00	\$ 50.00	SVCX
4	Rear fender inner cowl clips	1	\$ 50.00	\$ 50.00	SVCX
5	Rear fender inner trim clips	1	\$ 50.00	\$ 50.00	SVCX
6	Taillamp clips	1	\$ 50.00	\$ 30.00 50.00	?NEC
7	Taillamp inner seal	1	\$ 80.00	\$ 80.00	NAX

8	Rear end panel sealant	1	\$ 100.00	\$ 30.00	100.00	? NEC
9	Spare tyre panel sealant	1	\$ 100.00	\$	100.00	? NAX
SPECIAL NETT TOTAL :				\$ 90.00	590.00	

Nos.	LABOUR	S\$		
1	R&R reverse sensor	\$ 60.00	100.00	/
2	R&R bootlid component	\$ 80.00	100.00	/
3	R&R exhaust system to assist repair	\$	100.00	NAX
4	Rust proofing	\$ 30.00	100.00	?/
5	Panel beat rear	\$ 800.00	1,200.00	?
6	Spray painting rear	\$ 800.00	1,200.00	?
7	Bootlid water leaking test	\$	80.00	NAX
8	Spray reverse sensor	\$	50.00	✓
9	Resetting of fault code	\$	80.00	NAX
10	Rust proofing rear	\$ 30.00	150.00	? NEC
LABOUR TOTAL :		\$ 1850.00	3,240.00	

PARTS TOTAL : \$7922,6515,136.35

SPECIAL NETT TOTAL : \$ 90.00 590.00

LABOUR TOTAL : \$1850.00 3,240.00

GRAND TOTAL : \$9862.6518,966.35

@ 20% 1972.53

7890.12

L/S 7850/2

Survey on 29/8/19
Tgrim lin
15 30 hrs

? photo
Repair days 5

Tgrim
lin
29/19

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Resurvey on 30/8/19
Tgrim lin
1630 hrs