

SG 98 MOTOR PTE LTD

4001, Ang Mo Kio Industrial Park 1 #01-21 SINGAPORE 569622

Tel: 6452 4898 Fax: 6452 4868

Email: sg_motor_enterprise@yahoo.com.sg

Date: 9 September 2019

To : LKK

By Fax: 6256-4315

Attn : Bryan Ang

Tel: 97237799

VEHICLE NO : FBP 5505U

Sniper 150

ACCIDENT DATE: 4 August 2019

Description	Qty	Quotation \$
1 Brake Pedal <i>bst</i>	1	95.00 ✓
2 Footrest Bracket <i>bst</i>	1	135.00 ✓
3 Footrest <i>bst</i>	1	78.00 ✓
4 Kick Start <i>bst</i>	1	160.00 ✓
		<i>468.00</i>
		<i>421.20</i>
Sub-Total		468.00
Less 10%		46.80
Sub-Total		421.20

Nett Items

1 Towing fee <i>NAL</i>		40.00 <i>NAL</i>
2 Labour charge	<i>80.00</i>	<i>150.00</i> <i>80.00</i>
Sub-Total		190.00
Nett Total		611.20

NB: This estimate was made from a visual inspection only, any other damage parts or labour require when repair commences, we will advise you and submit supplementary item to you accordingly.

561.20
45 400/-

Kindly revert upon completion. Thank you

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts price is based on the market price
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

27/08/2019 @ 1600m

Nett Total

2 days

2 LKK Auto