



ZOOM AUTOWERKS PTE LTD

130 Bedok Reservoir Road
#08-1339 Singapore 470130
Tel: 9450 7920
* zoomautowerks@gmail.com

Not Authorized
hane

28 August 2019

REG NO.: SFP 8188 J
MAKE/MODEL: LEXUS ES300

JTHBW169

4/5 @ 7000

7 day. Take photo After rep -

ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

QTY	DESCRIPTION	AMT(\$)
<u>LIST ITEMS</u>		
1	Rear windscreen moulding <i>128.10</i>	\$ <i>na</i> 155.00
1	Rear boot lid	\$ <i>no/seat</i> 976.47
1	Rear boot lamp <i>15</i>	\$ <i>scat/cra</i> 328.00
1	Rear boot inner lock	\$ <i>17</i> 432.90 X
1	Rear boot logo <i>105.10</i>	\$ <i>na</i> 109.70
1	Rear boot rubber	\$ <i>17</i> 241.92 X
1	Rear boot "LEXUS" emblem	\$ <i>na</i> 106.25
1	Rear boot "ES300" emblem	\$ <i>na</i> 89.65
1	Rear taillamp -L/H <i>610.10</i>	\$ <i>cra</i> 688.60
1	Rear end panel	\$ <i>17</i> 682.75
1	Rear end panel inner garnish	\$ <i>17</i> 387.30 X
1	Rear bumper	\$ <i>D-5</i> 1,196.95
1	Rear bumper inner sponge	\$ <i>100</i> 137.20
2	Rear bumper PDC sensors <i>3.5</i>	\$ <i>shot</i> 656.00 <i>1pc</i>
1	Rear bumper reflector	\$ <i>320</i> 98.00
1	Rear bumper reinforcement <i>566.15</i>	\$ <i>Bel</i> 689.50
2	Rear bumper side retainers <i>84.65</i>	\$ <i>nk/bent</i> 169.30 <i>1pc</i>
1	Rear fender -L/H	<i>Body</i> \$ <i>no/seat</i> 1,230.50
1	Rear fender inner shield	\$ <i>17</i> 149.50
1	Rear fender inner trim	\$ <i>17</i> 682.50 X
		\$ 9,207.99
		\$ 920.80 <i>6654.87</i>
		\$ 8,287.19 <i>5989.38</i>
<u>SPECIAL NETT ITEMS</u>		
1	Rear windscreen sealant	\$ <i>na</i> 80.00 <i>40</i>
1	Rear bumper clip (1 set)	\$ <i>na</i> 35.00
		\$ 115.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey **Less 10%**
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No alterations/modifications is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

S/N LABOUR CHARGES

1	To remove, replaced damaged lamps and check up rear wiring.	\$ 80.00 <i>30</i>
2	To remove and refit inner garnishes.	\$ 150.00 <i>80</i>
3	To remove and refit rear reverse sensor.	\$ 150.00 <i>50</i>
4	To transfer boot lid mechanism and wiring assembly.	\$ 120.00 <i>60</i>
5	To remove and refit fuel tank assembly with all attachments.	\$ 150.00 <i>60</i>
6	To remove and refit rear windscreen glass.	\$ 180.00 <i>120</i>
7	To apply undercoating.	\$ 180.00 <i>90</i>
8	Panel beating.	\$ 1,800.00 <i>1100</i>
9	To re-spray painting on the affected areas.	\$ 1,600.00 <i>1100</i>
		\$ 4,410.00

GRAND TOTAL :

\$ 12,812.19

8784.38
7003.